

AGENDA
UNSAFE STRUCTURE
City Commission Meeting Room - City Hall
DECEMBER 19, 2002
3:00 P.M.

RETURN HEARING (OLD BUSINESS)

CASE NO: CE02031503
CASE ADDR: 607 NE 2 AV
OWNER: KEYSTONE HALL INC
INSPECTOR: WAYNE STRAWN

VIOLATIONS: FBC 111.1.1

THE SINGLE FAMILY DWELLING HAS BEEN SUBSTANTIALLY DAMAGED BY THE ELEMENTS AND BY MAJOR STRUCTURAL, PLUMBING AND ELECTRICAL ALTERATIONS PERFORMED WITHOUT PERMITS. THE BUILDING IS A FIRE HAZARD AND DOES NOT MEET THE REQUIREMENTS OF THE MINIMUM HOUSING CODE OF THE CITY OF FORT LAUDERDALE.

FBC 111.1.2

THE "TED'S SHED" IN THE REAR YARD HAS BEEN INSTALLED WITHOUT OBTAINING A PERMIT. THE BEDROOM ADDITION ON THE WEST END OF THE DWELLING, THE CONVERSION OF THE ATTIC TO UPSTAIRS BEDROOMS AND MAJOR STRUCTURAL ALTERATIONS HAVE ALL BEEN CONSTRUCTED/ALTERED WITHOUT OBTAINING PERMITS.

FBC 111.2.1.1.3

THE WINDOWS FOR THE UPSTAIRS BEDROOMS HAVE SECURITY BARS WHICH PREVENT THEIR USE FOR EMERGENCY ESCAPE.

FBC 111.2.1.2.1

SIDING, PLUMBING PIPES, ELECTRICAL CONDUIT, AND DOOR AND WINDOW FRAMES, AND AREAS OF THE CEILINGS ARE LOOSE, HANGING LOOSE OR HAVE FAILED.

FBC 111.2.1.2.2

THE FLOOR STRUCTURE ON THE SOUTH EXPOSURE HAS FAILED AND THE WALL IS SAGGING IN THIS AREA FORCING THE EXTERIOR SIDING TO BUCKLE. THE FLOOR ON THE WEST END IS SOFT AND SPRINGY WITH A PRONOUNCED SAG.

FBC 111.2.1.2.3

THE BUILDING IS PARTIALLY DESTROYED BY REMODELING WITHOUT PERMITS. BEARING WALLS HAVE BEEN REMOVED AND REPLACED BY POSTS AND BEAMS.

FBC 111.2.1.2.4

THE ELECTRICAL SYSTEM HAS BEEN ALTERED, ENLARGED AND REPLACED WITHOUT PERMITS. VERY LITTLE IF ANY OF THE ORIGINAL SYSTEM REMAINS. THE ENTIRE SYSTEM PRESENTS A HAZARD. IT IS PRESUMED AND DEEMED TO BE UNSAFE BY THE FLORIDA BUILDING CODE.

FBC 111.2.1.2.8

THE MEANS OF EGRESS FOR THE UPSTAIRS BEDROOMS IS PROVIDED BY A STAIRWAY WHICH DOES NOT HAVE CODE COMPLIANT HANDRAILS AND TREAD/RISER PROPORTION.

FBC 111.2.1.3.1

THE DWELLING HAS BEEN EXTENSIVELY ALTERED WITHOUT OBTAINING PERMITS. THE ALTERATIONS INCLUDE: STRUCTURAL ALTERATIONS OF SUPPORT WALLS ALONG WITH THE CONSTRUCTION OF AN ADDITION ON

AGENDA
UNSAFE STRUCTURE
City Commission Meeting Room - City Hall
DECEMBER 19, 2002
3:00 P.M.

THE WEST, THE CONVERSION OF THE ATTIC AREA INTO BEDROOMS, AND THE CONSTRUCTION OF A STAIRWAY TO ACCESS THIS AREA, THE ENCLOSURE OF THE REAR PORCH AND INSTALLATION OF A BATHROOM ON THE REAR PORCH, THE ALTERATION/REPLACEMENT OF THE ELECTRICAL SYSTEM, ALTERATION OF THE PLUMBING INCLUDING THE INSTALLATION OF A WATERHEATER, AND THE "TED'S SHED" IN THE REAR YARD HAS BEEN INSTALLED AND ELECTRIFIED WITHOUT OBTAINING PERMITS.

FBC 111.2.1.3.2

THE DWELLING DOES NOT MEET THE REQUIREMENTS FOR PROPER EGRESS FROM THE UPSTAIRS BEDROOMS AS PROVIDED FOR IN THIS CODE AND THE REQUIREMENTS FOR LIGHT AND VENTILATION ALONG WITH THE MAINTENANCE REQUIREMENTS PROVIDED FOR IN THE MINIMUM HOUSING CODE OF THE CITY OF FORT LAUDERDALE. THE HANDRAILS TO THE UPSTAIRS ARE LOOSE AND THE EAST BATHROOM CEILING IS FALLING.

FBC 111.2.2.1

THE COST TO REPAIR OR REPLACE THE DWELLING EXCEEDS 50% OF THE VALUE OF THE DWELLING.

FBC 111.2.2.4

INFORMATIONAL ONLY

CASE NO: CE02041083
CASE ADDR: 801 NW 19 AV
OWNER: VEGAZO, JOSEPH
INSPECTOR: ROBERT A PIGNATARO

VIOLATIONS: FBC 111.1.1

THE C.B.S. DUPLEX HAS DETERIORATED FROM THE ELEMENTS AND HAS NOT BEEN MAINTAINED ACCORDING TO THE REQUIREMENTS OF THE FLORIDA BUILDING CODE OR THE MINIMUM HOUSING CODE OF THE CITY OF FORT LAUDERDALE.

FBC 111.1.2

THE INTERIOR RENOVATION APPLICATION A99021978 HAS FAILED PLAN REVIEW, ON 3/11/99 AND HAS NOT BEEN PICKED UP FOR CHANGES, THUS IT IS NULL AND VOID.

FBC 111.2.1.1.1

THE BUILDING IS BOARDED AT THIS TIME AND HAS BEEN SINCE 1999.

FBC 111.2.1.2.2

THERE ARE SEVERAL LEAKS IN THE ROOFS, SEVERAL OF THE CEILING 3 X 6 BEAMS ARE ROTTED OR TERMITE DAMAGED, THE DOORS AND SEVERAL OF THE INTERIOR PARTITIONS ARE ROTTED OR TERMITE DAMAGED.

FBC 111.2.1.2.3

THE ROOF IS PARTIALLY DESTROYED DUE TO THE EXPOSURE TO THE ELEMENTS.

FBC 111.2.1.2.4

THE FASCIA, SOFFIT AND ROOF TAILS ARE ROTTED DUE TO EXPOSURE

AGENDA
UNSAFE STRUCTURE
City Commission Meeting Room - City Hall
DECEMBER 19, 2002
3:00 P.M.

TO THE ELEMENTS OR TERMITE DAMAGE AND SOME OF IT IS HANGING.

FBC 111.2.1.2.5

THE ELECTRICAL IS PARTIALLY DAMAGED DUE TO THE VANDALS.

FBC 111.2.1.2.6

THE PLUMBING IS PARTIALLY DESTROYED DUE TO VANDALS.

FBC 111.2.2.1

THE COST TO ALTER OR REPAIR THE BUILDING EXCEEDS 50% OF THE VALUE OF THE BUILDING.

FBC 111.2.2.2

THE COST OF THE STRUCTURAL REPAIRS EXCEEDS 33% OF THE VALUE OF THE BUILDING.

FBC 111.2.2.4

CASE NO: CE02061800
CASE ADDR: 1235 NE 2 AVE
OWNER: KEYSTONE HALLS INC
INSPECTOR: MOHAMMED MALIK

VIOLATIONS: FBC 111.1.1

THE CBS AND WOOD FRAME STRUCTURE HAS DETERIORATED FROM THE ELEMENTS, AND HAS NOT BEEN MAINTAINED ACCORDING TO THE REQUIREMENTS OF THE FLORIDA BUILDING CODE OR THE MINIMUM HOUSING CODE OF THE CITY OF FORT LAUDERDALE.

FBC 111.1.2

THE WOOD STRUCTURE IN THE BACK OF THE CBS STRUCTURE IS ADDED WITHOUT PERMITS AND IS NOT AS PER CODE AND IS UNSAFE.

FBC 111.2.1.2.1

THE WALL SIDING IS ROTTED AND TERMITE DAMAGED AND MISSING IN AREAS.

FBC 111.2.1.2.2

THE STRUCTURE IS PARTIALLY DESTROYED DUE TO TERMITE DAMAGE, SOME OF THE STRUCTURAL EXTERIOR WALLS AND WOOD SIDING ARE DETERIORATED AND ROTTED.

FBC 111.2.1.2.3

THE ROOF HAS BEEN DAMAGED DUE TO EXPOSURE TO THE ELEMENTS. THE ROOF IS LEAKING AND THE CEILING FALLING DOWN.

FBC 111.2.1.2.5

THE HOT WATER HEATER WAS INSTALLED WITHOUT PERMITS AND THE ELECTRICAL WIRES, HANGING ALL AROUND, ARE NOT TO CODE AND ARE UNSAFE.

FBC 111.2.2.1

THE COST TO ALTER OR REPAIR THE BUILDING EXCEEDS 50% OF THE VALUE OF THE BUILDING.

FBC 111.2.2.2

THE COST OF THE STRUCTURAL REPAIRS EXCEEDS 33% OF THE VALUE

AGENDA
UNSAFE STRUCTURE
City Commission Meeting Room - City Hall
DECEMBER 19, 2002
3:00 P.M.

OF THE BUILDING.

HEARING COMPUTER SCHEDULED

CASE NO: CE02061775
CASE ADDR: 505 NW 20 AV
OWNER: JACKSON,R & HATTIE B
INSPECTOR: MOHAMMED MALIK

VIOLATIONS: FBC 111.1.1

THE CBS AND WOOD STRUCTURE HAS DETERIORATED FROM THE ELEMENTS, AND HAS NOT BEEN MAINTAINED ACCORDING TO THE REQUIREMENTS OF THE FLORIDA BUILDING CODE OR THE MINIMUM HOUSING CODE OF THE CITY OF FORT LAUDERDALE.

FBC 111.1.2

THE WOOD STRUCTURE IN THE BACK OF THE CBS STRUCTURE WAS ADDED WITHOUT PERMITS AND IS NOT AS PER CODE AND UNSAFE.

FBC 111.2.1.2.1

THE INTERIOR WALLS ARE WET DUE TO RAIN WATER POURING IN FROM THE ROOF WHICH HAS HOLES IN ALMOST EVERY ROOM AND THE WALLS ARE ROTTED AND TERMITE DAMAGED.

FBC 111.2.1.2.2

WATER DAMAGE FROM ROOF LEAKS, HAS DAMAGED OR DESTROYED MOST OF THE INTERIOR DRYWALL AND WOOD FRAMING.

FBC 111.2.1.2.3

THE ROOF HAS BEEN DESTROYED DUE TO EXPOSURE TO THE ELEMENTS. THE ROOF HAS HOLES IN MOST OF THE ROOMS. THE KITCHEN CABINETS ARE DESTROYED, WIRES HANGING LOOSE MAKING IT UNSAFE.

FBC 111.2.1.2.5

THE ELECTRICAL WIRES HANGING ALL AROUND, IS NOT TO CODE AND IS UNSAFE.

FBC 111.2.1.2.6

THE WASTE DISPOSAL FOR WASHER INSTALLED WITHOUT PERMITS AND IS NOT PER CODE.

FBC 111.2.2.1

THE COST TO ALTER OR REPAIR THE BIUILDING EXCEEDS 50% OF THE VALUE OF THE BUILDING.

FBC 111.2.2.2

THE COST OF THE STRUCTURAL REPAIRS EXCEEDS 33% OF THE VALUE OF THE BUILDING.

