AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 10:00 AM

	HEARING COMPUTER SCHEDULED
CASE ADDR: OWNER:	CE05081133 RESCHEDULED 2300 E OAKLAND PARK BLVD RAJ GROUP INC WILFRET ANDERSON
VIOLATIONS:	NFPA 1 4.5.8.1 EMERGENCY LIGHTS TO ILLUMINATE ON AC/DC POWER.
	NFPA 10 6.3.1 HAVE FIRE EXTINGUISHER SERVICED AND TAGGED BY LICENSED COMPANY ON THIRD FLOOR.
	NFPA 101 7.8.1.1 MUST HAVE ILLUMINATED EXIT SIGN IN EGRESS PATHWAY FROM SECOND FLOOR ELEVATOR LOBBY.
	NFPA 101 7.9.2.2 REPAIR EXIT SIGN(s) TO ILLUMINATE IN EGRESS PATHWAYS THROUGHOUT.
OWNER:	CE05031219 521 N FT LAUD BEACH BLVD WATERFRONT MM LLC ROBERT KISAREWICH
VIOLATIONS:	NFPA 1 10.4.1 THE GAS HOT WATER HEATER IS NOT VENTED TO THE OUTSIDE.
	NFPA 1 10.3.4.1 HOTEL ROOM #306 HAS BEEN CHANGED TO A BUSINESS WITHOUT A CHANGE OF USE PERMIT.
CASE NO: CASE ADDR: OWNER: INSPECTOR:	CE05090702 1020 NW 4 AV SYNERGY ACQUISITIONS GROUP WAYNE STRAWN
VIOLATIONS:	FBC 104.1 BUILDING ALTERATIONS HAVE BEEN DONE WITHOUT OBTAINING THE REQUIRED PERMIT. THE WORK INCLUDES, BUT MAY NOT BE LIMITED TO:
	 THE ENCLOSURE OF THE CARPORT CONVERSION OF AN AREA AT THE REAR OF THE CARPORT INTO A BATHROOM INSTALLATION OF WINDOWS AND DOORS BATHROOM REMODEL AND KITCHEN REMODEL
	FBC 104.2.4 BATHROOM FIXTURES AND A SHOWER HAVE BEEN INSTALLED AND THE RELATED PIPING FOR A BATHROOM AT THE REAR OF THE CARPORT.

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 10:00 AM

FBC 104.2.5 THE ELECTRICAL SYSTEM HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT. THE WORK BEING CITED IS PREMISE WIRING EXPANSION. NEW CONDUIT IS NOTED ON THE EXTERIOR OF THE BUILDING TO ROUTE THE NEW CIRCUITRY. FBC 104.2.11 AN AIR CONDITIONING SYSTEM HAS BEEN INSTALLED WITHOUT OBTAINING THE REQUIRED PERMIT. _____ CASE NO: CE05031142 CASE ADDR: 2464 SW 8 ST OWNER: REYES.FEPNAN REYES, FERNANDO & QUINTANA, ESTHER INSPECTOR: KENNETH REARDON VIOLATIONS: 47-21.8.A. THE GRASS IS NOT BEING PROPERLY MAINTAINED. THERE ARE AREAS OF MISSING AND DEAD GRASS. 9-313(a) THE HOUSE NUMBERS ARE MISSING. FBC 104.1 INSTALLED A CHAIN LINK FENCE WITHOUT FIRST OBTAINING A BUILDING PERMIT. _____ _____ CE05040718 CASE NO: CASE ADDR: 1724 SW 12 CT WIMER, THOMAS & AMY OWNER: INSPECTOR: KENNETH REARDON VIOLATIONS: FBC 104.1 THE SHED HAS BEEN INSTALLED WITHOUT FIRST OBTAINING A BUILDING PERMIT. 47-34.1.A.1. THE SHED HAS BEEN INSTALLED IN THE SIDE YARD SET BACK. PER ULDR SECTION 47-5.31, THE MINIMUM SIDE YARD SET BACK IN ZONING DISTRICT RS-8 IS FIVE (5) FEET. _____ CASE NO: CE05051469 CASE ADDR: 1201 TANGELO ISLE REYNOLDS, FRANK A & NANCY S. OWNER: INSPECTOR: KENNETH REARDON VIOLATIONS: FBC 104.1 THE REAR AWNING HAS BEEN INSTALLED WITHOUT FIRST OBTAINING A BUILDING PERMIT. _____

OWNER:	CE05060221 1549 SW 27 TER MERCURIUS,VAUDINE KENNETH REARDON
VIOLATIONS:	FBC 104.2.5 ELECTRIC HAS BEEN ADDED IN THE LAUNDRY ROOM WITHOUT FIRST OBTAINING AN ELECTRICAL PERMIT.
	FBC 104.1 THIS BUILDING HAS BEEN ALTERED WITHOUT FIRST OBTAINING A BUILDING PERMIT, INCLUDING, BUT NOT LIMITED TO:
	 *AN EXTERIOR DOOR AND WINDOW HAVE BEEN ADDED TO THE SOUTHEAST BEDROOM. *ADDED WALLS AND A METAL ROOF AT THE REAR OF THE HOUSE. THIS IS A LAUNDRY ROOM AND A REAR BEDROOM. *FIBERGLASS ROOF AND WOOD STUD STORAGE AREA ATTACHED TO THE NORTH EXTERIOR WALL. *WALLS HAVE BEEN ADDED TO CREATE AN ADDITIONAL BEDROOM IN THE CONVERTED GARAGE.
	FBC 104.2.4 PLUMBING HAS BEEN ADDED WITHOUT FIRST OBTAINING A PLUMBING PERMIT IN THE FOLLOWING AREAS:
	*AT THE KITCHEN UNIT IN THE SOUTHEAST BEDROOM *AT THE LAUNDRY ROOM
	47-19.2.4.h. THERE IS A POD STORAGE UNIT IN THE DRIVEWAY IN EXCESS OF 14 DAYS.
OWNER:	CE05080409 3733 SW 12 CT FLORES,CARLOS JAVIER KENNETH REARDON
VIOLATIONS:	FBC 104.1 THE WINDOWS HAVE BEEN REPLACED WITHOUT FIRST OBTAINING A BUILDING PERMIT.
CASE NO: CASE ADDR: OWNER: INSPECTOR:	CE05082008 1260 SW 29 ST LIVINGSTON,THOMAS W & PEGGY S. KENNETH REARDON
VIOLATIONS:	FBC 104.2.11 INSTALLED A CENTRAL AIR CONDITIONING SYSTEM WITHOUT FIRST OBTAINING A MECHANICAL PERMIT.
	47-21.8

Page 4

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 10:00 AM

_____ _ _ _ _ _ _ CASE NO: CE05070568 CASE ADDR: 2201 MIDDLE RIVER DR SIGLER,LEE E & DEBORAH M OWNER: INSPECTOR: MOHAMMED MALIK VIOLATIONS: FBC 104.1 THE FOLLOWING PERMITS ARE EXPIRED AND VOIDED WITHOUT PASSING FINAL INSPECTION: 02011356, 05031429, 03082431, 03081489, 02050415, 03081121, 03031342, 02100614, 02100591, 02010247. _____ CASE NO: CE05080583 CASE ADDR: 5710 BAYVIEW DR OWNER: MALDONADO,AUGUSTO & VALERIE INSPECTOR: MOHAMMED MALIK VIOLATIONS: FBC 104.1 THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENT TO THE BUILDING WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PER-MIT. SUCH ITEMS INCLUDE, BUT ARE NOT LIMITED TO THE FOLLOW-TNG: 1- COMPLETE RENOVATION OF HOUSE 2- STRUCTURAL WORK 3- NEW DRYWALL WORK 4- NEW KITCHEN 5-NEW BATHROOM NEW DOORS 6-7- NEW WINDOWS 8- NEW PLUMBING 9- NEW ELECTRICAL 10 NEW AIR CONDITIONING 11 NEW ENTRANCE AT DOOR FBC 104.2.11 INSTALLED AIR CONDITIONING UNIT WITHOUT OBTAINING REQUIRED MECHANICAL PERMIT. FBC 104.2.4 COMPLETED NEW PLUMBING WORK FOR BATHROOMS AND KITCHEN WITHOUT FIRST OBTAINING REQUIRED PERMITS. FBC 104.2.5 _____ _ _ _ _ _ _ _ _ _ _ _ _ _ _ _ _ CASE NO: CE05090063 CASE ADDR: 1717 MIDDLE RIVER DR DAMERAU,DAVID F OWNER: INSPECTOR: MOHAMMED MALIK VIOLATIONS: FBC 104.1 INSTALLED/REPLACED NEW PILING WITHOUT OBTAINING REQUIRED PERMITS. _____

OWNER:	CE05090031 200 E LAS OLAS BLVD LAUDERDALE RIVER INC JORGE MEDEROS
VIOLATIONS:	NFPA 1 4.5.8.1 ELEVATOR RECALL DID NOT OPERATE.
	NFPA 1 13.7.3.4.1.2 FIRE ALARM PAST DUE FOR SERVICE.
	F-21.1.3 SMOKE CONTROL SYSTEM IS DUE FOR ANNUAL TEST AND BALANCE REPORT.
	CE05090047 RESCHEDULED 1901 NW 62 ST CITY OF FT LAUDERDALE JORGE MEDEROS
VIOLATIONS:	F-21.1.3 SMOKE CONTROL SYSTEM IS DUE FOR ANNUAL TEST AND BALANCE REPORT.
	NFPA 1 4.5.8.1 FIRE EXIT PANIC HARDWARE IS IN DISREPAIR, 1ST FLOOR NORTH.
	NFPA 1 4.4.3.1.1 STORAGE IN THE STAIRWELL, 1ST FLOOR NORTH.
CASE NO: CASE ADDR: OWNER:	CE05090049 1851 SE 10 AVE 17 STREET CAUSEWAY LLC JORGE MEDEROS
VIOLATIONS:	NFPA 1 4.5.8.1 ELEVATOR RECALL DID NOT OPERATE.
	F-21.1.3 SMOKE CONTROL SYSTEM IS DUE FOR ANNUAL TEST AND BALANCE REPORT.
OWNER:	CE05090050 110 E BROWARD BLVD PARMENTER CORP CENTER LP LLLP JORGE MEDEROS
VIOLATIONS:	F-21.1.3 SMOKE CONTROL SYSTEM IS DUE FOR ANNUAL TEST AND BALANCE REPORT.

OWNER:	CE05090051 RESCHEDULE 633 S FEDERAL HWY SCHERER,WILLIAM R TR JORGE MEDEROS
VIOLATIONS:	SMOKE CONTROL SYSTEM IS DUE FOR ANNUAL TEST AND BALANCE REPORT.
CASE ADDR: OWNER:	CE05090052 RESCHEDULE 17 S FT LAUD BEACH BLVD -TRANSWESTERN BEACH PLACE JORGE MEDEROS
VIOLATIONS:	SMOKE CONTROL SYSTEM IS DUE FOR ANNUAL TEST AND BALANCE REPORT.
CASE NO: CASE ADDR: OWNER:	CE05090054 1799 SE 17 ST ART INSTITUTE INVESTMENT JORGE MEDEROS
VIOLATIONS:	SMOKE CONTROL SYSTEM IS DUE FOR ANNUAL TEST AND BALANCE REPORT.
CASE NO: CASE ADDR: OWNER:	CE05090055 4901 NW 17 WAY SPECTRUM PARK I JOINT VENTURE JORGE MEDEROS
VIOLATIONS:	SMOKE CONTROL SYSTEM IS DUE FOR ANNUAL TEST AND BALANCE REPORT.
OWNER:	CE05090056 1100 SE 17 ST FELCOR/CSS HOLDING L P JORGE MEDEROS
VIOLATIONS:	F-21.1.3 SMOKE CONTROL SYSTEM IS DUE FOR ANNUAL TEST AND BALANCE REPORT.

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 10:00 AM

CASE NO: CE05090058 CASE ADDR: 3030 HOLIDAY DR NORTHWESTERN MUTUAL LIFE INS CO OWNER: INSPECTOR: JORGE MEDEROS VIOLATIONS: F-21.1.3 SMOKE CONTROL SYSTEM IS DUE FOR ANNUAL TEST AND BALANCE REPORT. _____ CASE NO: CE05090060 CASE ADDR: 200 E LAS OLAS BLVD OWNER: LAUDERDALE RIVER INC INSPECTOR: JORGE MEDEROS VIOLATIONS: F-21.1.3 SMOKE CONTROL SYSTEM IS DUE FOR ANNUAL TEST AND BALANCE REPORT. _____ _____ CASE NO: CE05090061 CASE ADDR: 3055 HARBOR DR OWNER: HARBOURAGE PLACE CONDO ASSOC. INSPECTOR: JORGE MEDEROS VIOLATIONS: F-21.1.3 SMOKE CONTROL SYSTEM IS DUE FOR ANNUAL TEST AND BALANCE REPORT. _____ CE05090062 CASE NO: CASE ADDR: 100 S BIRCH RD JACKSON TOWER LAS OLAS OWNER: INSPECTOR: JORGE MEDEROS VIOLATIONS: F-21.1.3 SMOKE CONTROL SYSTEM IS DUE FOR ANNUAL TEST AND BALANCE REPORT. _____ CASE NO: CE05081900 CASE ADDR: 709 SW 15 AV OWNER: WALD,WILLIAM INSPECTOR: THOMAS CLEMENTS VIOLATIONS: NFPA 1 1.7.6 THERE IS STORAGE IN THE METER ROOM. NFPA 1 13.6.6.1.1 FIRE EXTINGUISHER NOT PROVIDED. NFPA 1 11.1.2 METER BASE COVER MISSING IN THE METER ROOM RESULTING IN EXPOSED WIRING. NFPA 1 10.13.1.1 APARTMENT NUMBERS NOT OF A CONTRASTING COLOR TO THE BACKGROUND COLOR. _____ _____

OWNER:	CE05081901 700 sw 21 ter COLAIANNI INVESTMENTS OF FL INC. THOMAS CLEMENTS
VIOLATIONS:	NFPA 101 40.2.6 EXCESSIVE TRAVEL DISTANCE TO EXIT.
	NFPA 1 4.4.3.1.1 OBSTRUCTED EXIT.
	NFPA 101 7.10.1.1 SELF-ILLUMINATED EXIT SIGNS WITH BATTERY BACKUP NOT PROVIDED.
	NFPA 1 14.13.1.1 EMERGENCY LIGHTING NOT PROVIDED.
	NFPA 1 11.1.2 EXPOSED WIRING IN ELECTRICAL PANELS.
	NFPA 55 7.1.3.4 HIGH-PRESSURE CYLINDERS NOT SECURED AGAINST TIPPING.
OWNER:	CE05090464 900 SW 31 AVE FIRST ALLIANCE CHURCH OF FT. LAUDERDALE THOMAS CLEMENTS
VIOLATIONS:	NFPA 1 1.7.5.1 UNABLE TO GAIN ENTRY TO PERFORM FIRE SAFETY INSPECTION.
CASE NO: CASE ADDR: OWNER:	CE05090690 RESCHEDULED 204 SW 21 TER SAHAGIAN,GEORGE TR THOMAS CLEMENTS
VIOLATIONS:	NFPA 1 1.12.1 PERMIT FOR INSTALLATION OF EXIT/EMERGENCY LIGHTS NOT COMPLETELY EXECUTED.
OWNER:	CE05090691 2145 DAVIE BLVD # 106 DISKIN,LAURENCE TR THOMAS CLEMENTS
VIOLATIONS:	NFPA 1 1.12.1 PART OF INTERIOR WALL DEMOLISHED COMBINING TWO UNITS DONE WITHOUT FIRST OBTAINING A PERMIT.

OWNER:	CE05090703 RESCHEDULED 3216 W BROWARD BLVD FREDDIE PROPERTIES INC THOMAS CLEMENTS
VIOLATIONS:	NFPA 1 1.7.5.1 UNABLE TO GAIN ENTRY TO PERFORM FIRE SAFETY INSPECTION.
CASE ADDR: OWNER:	CE05090704 COMPLIED 1127 SW 2 CT JOHN WESLEY FREE MEHODIST THOMAS CLEMENTS
VIOLATIONS:	NFPA 1 1.7.5.1 UNABLE TO GAIN ENTRY TO PERFORM FIRE SAFETY INSPECTION.
	CE05090705 1611 SW 11 CT CULPEPPER,EDWARD H THOMAS CLEMENTS
VIOLATIONS:	NFPA 1 1.7.5.1 UNABLE TO GAIN ENTRY TO THE ELECTRICAL METER ROOM TO PERFORM FIRE SAFETY INSPECTION.
	CE05090706 1601 SW 11 CT CULPEPPER,EDWARD H THOMAS CLEMENTS
VIOLATIONS:	NFPA 1 1.7.5.1 UNABLE TO GAIN ENTRY TO THE ELECTRICAL METER ROOM TO PERFORM FIRE SAFETY INSPECTION.
CASE ADDR: OWNER: INSPECTOR:	CE05090707 RESCHEDULE 1190 SW 27 AV SUNLIGHT INVESTMENTS INC THOMAS CLEMENTS
VIOLATIONS:	FBC 104.1.1 RANGE HOOD FIRE EXTINGUISHER SYSTEM REPLACED WITHOUT A PERMIT.
CASE NO: CASE ADDR: OWNER:	CE05090711 COMPLIED 2880 SW 16 ST APOSTOLIC ALLIANCE CHURCH THOMAS CLEMENTS
VIOLATIONS:	NFPA 10 6.3.1 FIRE EXTINGUISHERS HAVE NOT BEEN SERVICED AND TAGGED BY A STATE LICENSED COMPANY WITHIN THE PAST 12 MONTHS.

CITY OF FORT LAUDERDALE Page 10 AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 10:00 AM NFPA 101 7.10.2 CHEVRONS ON EXIT SIGN DIRECT EGRESS AWAY FROM THE EXIT. NFPA 101 13.1.7.1.3 MAXIMUM CAPACITY CALCULATION NOT PROVIDED TO THE CITY OF FORT LAUDERDALE. NFPA 101 13.7.8.3.1 MAXIMUM CAPACITY SIGN NOT PROVIDED. _____ CASE NO: CE05090715 CASE ADDR: 2615 DAVIE BLVD SUNLIGHT INVESTMENTS INC OWNER: INSPECTOR: THOMAS CLEMENTS VIOLATIONS: FBC 104.1.1 INTERIOR RENOVATION PERFORMED WITHOUT PERMIT. NFPA 55 7.1.3.4 HIGH PRESSURE CYLINDER IS NOT PROTECTED FROM TIPPING. NFPA 10 6.3.1 FIRE EXTINGUISHER HAS NOT BEEN SERVICED AND TAGGED BY A STATE LICENSED COMPANY WITHIN THE PAST 12 MONTHS. _____ CE05090730 CASE NO: CASE ADDR: 1605 SW 11 CT CULPEPPER, EDWARD H OWNER: INSPECTOR: THOMAS CLEMENTS VIOLATIONS: NFPA 1 1.7.5.1 UNABLE TO GAIN ENTRY TO PERFORM FIRE SAFETY INSPECTION. _____ CASE NO: CE05090082 COMPLIED CASE ADDR: 1201 NW 65 PL OWNER: GOODMAN, PEARL C REV TR INSPECTOR: IVETT SPENCE-BROWN VIOLATIONS: NFPA 101 7.10.5.1 EXIT SIGN (REAR) WAREHOUSE DOES NOT ILLUMINATE. NFPA 101 7.9.2.1 THERE ARE NOT ENOUGH EMERGENCY LIGHTS PROVIDED. FBC 104.1.1 1) EXTENDED OFFICE, MERCHANDIZE AREA WAS INSTALLED WITHOUT A PERMIT. 2) EXIT DOOR TIED TO FIRE ALARM SYSTEM WAS DONE WITHOUT A PERMIT. _____

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 10:00 AM

CASE NO: CE05090104 CASE ADDR: 1305 NW 65 PL ZUCKER, ROBERT A TR OWNER: INSPECTOR: IVETT SPENCE-BROWN VIOLATIONS: NFPA 1 1.7.6 1) THERE ARE BLANKS MISSING FROM THE ELECTRIC CIRCUIT \setminus BREAKER PANEL. 2) OVERHEAD ELECTRIC LIGHTS HAVE EXPOSED WIRING. 3) SUPPORTING MEMBERS IN THE WAREHOUSE ARE MISSING THE PROTECTIVE COVERING. NFPA 1 4.4.3.1.2 SLIDE BOATS ARE ATTACHED TO THE EXIT DOOR. NFPA 1 14.5.1.5 EXIT DOORS ARE DIFFICULT TO OPEN (SEALED). _____ CASE NO: CE05090105 CASE ADDR: 1311 NW 65 PL JFP GROUP LLC OWNER: INSPECTOR: IVETT SPENCE-BROWN VIOLATIONS: NFPA 101 7.10.5.1 EXIT SIGNS DO NOT ILLUMINATE. NFPA 1 14.13.1.1 THERE IS NOT ENOUGH EMERGENCY LIGHTING PROVIDED. NFPA 101 40.3.4.1 THERE IS NO FIRE ALARM PROVIDED. NFPA 101 7.5.2.1 EXIT SIGN IS DIRECTING EGRESS FROM OFFICE THROUGH WAREHOUSE. _____ CASE NO: CE05090109 COMPLIED CASE ADDR: 2535 NW 55 CT CITY OF FT LAUDERDALE OWNER: INSPECTOR: IVETT SPENCE-BROWN VIOLATIONS: NFPA 101 7.10.1.1 THERE ARE NOT ENOUGH ILLUMINATED EXIT SIGNS PROVIDED. NFPA 1 4.4.3.1.2 KEYED LOCK IS ATTACHED TO EXIT DOORS IN THE HANGAR. _____

OWNER:	CE05090110 RESCHEDULED 3000 NW 59 ST CITY OF FT LAUDERDALE IVETT SPENCE-BROWN
VIOLATIONS:	NFPA 1 14.9.1.1 TWO OFFICES, 1ST FLOOR, DO NOT HAVE A LEGAL EXIT.
	NFPA 704 1.2.1 THERE IS NO PLACARD PROVIDED.
	FBC 104.1.1 DROP CEILING WITH ELECTRICAL WIRING WAS INSTALLED WITHOUT A PERMIT.
CASE ADDR: OWNER:	CE05090113 COMPLIED 3091 NW 62 ST ROSA'S PLAZA LLC IVETT SPENCE-BROWN
	NFPA 1 50.2.5 HOOD SYSTEM IS PAST DUE FOR SEMI-ANNUAL SERVICE.
CASE NO: CASE ADDR: OWNER:	CE05090114 RESCHEDULE 5930 NW 28 WAY CITY OF FT LAUDERDALE IVETT SPENCE-BROWN
VIOLATIONS:	NFPA 101 13.3.1 2ND FLOOR HAS UN-ENCLOSED, UN-PROTECTED VERTICAL OPENING.
	NFPA 101 8.3.3.1 WINDOW PANE GLASS, 2ND FLOOR, IS NOT FIRE-RATED.
OWNER:	CE05090123 730 NW 57 PL 57 PLACE HOLDINGS LLC IVETT SPENCE-BROWN
VIOLATIONS:	NFPA 1 14.9.1.1 THERE IS NOT A SECOND MEANS OF EGRESS FROM WAREHOUSE TO OUTSIDE.
	FBC 704.3.1 THERE IS NO TENANT SEPARATION BETWEEN ESSER GLASS AND AMBASSADOR AIR CONDITIONING.

OWNER:	CE05090142 1291 NW 65 PL # A ISCO PROPERTIES LLC IVETT SPENCE-BROWN
VIOLATIONS:	NFPA 1 13.6.6.1.1 THERE ARE NO FIRE EXTINGUISHERS PROVIDED.
	NFPA 1 4.4.3.1.2 SLIDE BOLTS ARE ATTACHED TO EXIT DOORS.
	NFPA 101 7.10.1.2 THERE ARE NO ILLUMINATED EXIT SIGNS PROVIDED.
	NFPA 101 7.2.1.5.1 KEYED LOCKS ARE ATTACHED TO THE FRONT EXIT DOOR.
	NFPA 101 7.5.2.1 THE EXIT SIGN IS DIRECTING EGRESS FROM THE OFFICE THROUGH THE WAREHOUSE.
	NFPA 101 7.9.2.1 THERE ARE NOT ENOUGH EMERGENCY LIGHTS PROVIDED.
	NFPA 1 13.7.3.2.7 FIRE ALARM PANEL NEEDS ANNUAL SERVICE.
	NFPA 1 11.1.2 1. THE ELECTRIC JUNCTION BOXES ARE FALLING OFF OF THE POLE. 2. THERE ARE VOIDS IN THE ELECTRIC CIRCUIT BREAKER PANEL N.WALL WAREHOUSE.
CASE NO:	
OWNER:	5307 NW 35 TER FORT LAUDERDALE BUSINESS PLAZA IVETT SPENCE-BROWN
VIOLATIONS:	FBC 104.1.1 FIRE ALARM PANEL WAS RELOCATED FROM SUITE 5311 TO SUITE 5307 WITHOUT A PERMIT.
CASE NO:	CE05090153
CASE ADDR: OWNER:	2775 NW 62 ST NOTICE FOUR L L C
INSPECTOR:	IVETT SPENCE-BROWN
VIOLATIONS:	FBC 104.1 STORAGE LOFT WAS BUILT BEFORE OBTAINING A PERMIT.

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 10:00 AM

CASE NO: CE05090156 CASE ADDR: 2701 NW 62 ST CALVARY CHAPEL OF FT LAUDERDALE OWNER: INSPECTOR: IVETT SPENCE-BROWN VIOLATIONS: FBC 104.1 INTERIOR ALTERATION IS BEING CONDUCTED WITHOUT A PERMIT. _____ CASE NO: CE05090162 WITHDRAWN CASE ADDR: 2661 NW 56 ST OWNER: CITY OF FT LAUDERDALE INSPECTOR: IVETT SPENCE-BROWN VIOLATIONS: FBC 104.1 WOOD/PLYWOOD STRUCTURE NOT ALLOWED IN HANGAR. NFPA 1 13.6.3.10 FIRE EXTINGUISHERS ARE NOT MOUNTED. NFPA 1 13.6.3.6 EXIT/EMERGENCY LIGHT IS DIRECTED EGRESS FROM THE OFFICE THROUGH THE HANGAR. NFPA 1 13.6.6.1.1 THERE ARE NO FIRE EXTINGUISHERS PROVIDED. NFPA 1 14.9.1.1 TWO (2) ILLUMINATED MEANS OF EGRESS ARE REQUIRED FROM HANGAR. NFPA 1 4.4.3.1.2 KEYED LOCK IS ATTACHED TO EXIT DOOR LEADING FROM HANGAR THROUGH OFFICE. _____ CASE NO: CE05031540 CASE ADDR: 600 CORPORATE DR OWNER: RADICE CORP CENTER I INC INSPECTOR: DALLAS SHUMAKER VIOLATIONS: NFPA 1 1.12.18.3 THE ISSUED PERMIT 03030063 HAS EXPIRED DUE TO LACK OF INSPECTIONS. NFPA 1 10.4.1 THE FIRE ALARM IS NOT FULLY OPERATIONAL AT THIS TIME. _____

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 10:00 AM

CASE NO:	CE05031570
CASE ADDR:	715 NW 14 WY
OWNER:	IMANUEL CHURCH OF GOD IN CHRIST
INSPECTOR:	DALLAS SHUMAKER

VIOLATIONS: NFPA 101 13.3.1 THERE IS AN UNENCLOSED OR UNPROTECTED VERTICAL OPENING THAT EXISTS WITHIN THE SANCTUARY.

CASE NO: CE05090465 CASE ADDR: 33 NE 2 ST OWNER: CLARIDGE HOMES DOWNTOWN LLC INSPECTOR: DALLAS SHUMAKER VIOLATIONS: NFPA 101 7.9.2.2 THERE ARE EMERGENCY LIGHTS THAT ARE NON-OPERATIONAL. NFPA 101 7.10.5.1 THERE ARE EXIT SIGNS THAT ARE NON-OPERATIONAL. _____ CE05090466 CASE NO: CASE ADDR: 901 NE 18 CT OWNER: SPOREA,ILIE & CLARA INSPECTOR: DALLAS SHUMAKER VIOLATIONS: NFPA 1 10.1.1 THERE ARE ITEMS BEING STORED UNDER THE MEANS OF EGRESS STAIRS. NFPA 1 4.4.3.1.1 THERE ARE ITEMS BEING STORED ON THE 2ND FLOOR EGRESS BALCONY. NFPA 101 7.9.2.2 THE EMERGENCY LIGHTS ARE NON-OPERATIONAL. NFPA 1 1.7.6 1. THERE ARE ITEMS BEING STORED IN THE METER ROOM. 2. UNABLE TO ACCESS ALL UNITS ON PROPERTY. _____ CASE NO: CE05090471 CASE ADDR: 633 NW 11 AV OWNER: WILSON, JEROME INSPECTOR: DALLAS SHUMAKER VIOLATIONS: NFPA 1 10.13.1.1 THE ADDRESS SHALL BE VISIBLE FROM THE STREET WITH 6-INCH NUMBERS CONTRASTING IN COLOR FROM THE BUILDING.

Page 16

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 10:00 AM NFPA 1 13.6.6.1.1 THERE ARE NO EXTINGUISHERS PROVIDED. NFPA 1 1.7.6 THERE ARE ITEMS BEING STORED IN THE METER ROOM. NFPA 1 10.4.1 THE SMOKE DETECTORS ARE PAST DUE FOR SERVICE. _____ CASE NO: CE05090473 CASE ADDR: 1125 NE 16 PL STEKEN LLC OWNER: INSPECTOR: DALLAS SHUMAKER VIOLATIONS: NFPA 1 1.7.6 THERE ARE ITEMS BEING STORED IN THE METER ROOM. NFPA 101 7.10.5.1 THE EXIT SIGNS DO NOT ILLUMINATE ON SECONDARY POWER. NFPA 1 14.13.1.1 THERE ARE NO EMERGENCY LIGHTS PROVIDED ON BUILDING THAT HAS MORE THAN 12 UNITS. _____ CE05090477 CASE NO: CASE ADDR: 2121 NW 7 ST WESTMONT CONSULTING & INVESTMENT INC. OWNER: INSPECTOR: DALLAS SHUMAKER VIOLATIONS: NFPA 10 6.3.1 THE EXTINGUISHER IS PAST DUE FOR ANNUAL SERVICE. FBC 104.1.1 THERE HAS BEEN WORK CONDUCTED ON THE PROPERTY WITHOUT PERMITS (INSTALLATION OF WINDOWS). _____ CASE NO: CE05090805 CASE ADDR: 1317 NE 7 AV CASALE, DOMINICK & FAZIO, VINCENT OWNER: INSPECTOR: DALLAS SHUMAKER VIOLATIONS: NFPA 101 7.9.2.2 THE EMERGENCY LIGHTS DO NOT ILLUMINATE. NFPA 101 7.2.1.4.5 THE 1ST FLOOR WEST EXIT DOOR DOES NOT OPEN. NFPA 1 4.5.8.1 THE SMOKE DETECTORS LOW BATTERY ALARM IS ACTIVATING (CHIRPING). _____ _____

OWNER:	CE05090879 700 NW 10 TER MAX LLC DALLAS SHUMAKER
VIOLATIONS:	NFPA 1 1.7.6 THERE ARE ITEMS BEING STORED IN THE METER ROOM.
	NFPA 101 7.10.5.1 THERE ARE EXIT SIGNS NOT ILLUMINATED ON PRIMARY AND SECONDARY POWER.
	NFPA 1 10.1.1 THERE ARE ITEMS BEING STORED UNDERNEATH THE PATH OF EGRESS STAIRS.
	CE05090926 711 NW 4 ST MT HERMON AFRICAN METHODIST DALLAS SHUMAKER
VIOLATIONS:	NFPA 1 1.7.5.1 THERE HAS BEEN A CHANGE OF USE FROM ITS ORIGINALLY PERMITTED USE. THE PARSONAGE IS NOW BEING USED AS AN OFFICE.
CASE NO:	CE05090928 COMPLIED
OWNER:	1375 PROGRESSO DR ROSEN,GERALD P & HADEWIG V W DALLAS SHUMAKER
VIOLATIONS:	NFPA 1 10.13.1.1 THERE IS NO ADDRESS VISIBLE FROM STREET WITH 6-INCH NUMBERS IN CONTRASTING COLOR FROM BUILDING.
OWNER:	CE05090930 400 NE 13 ST D & D RESOURCES LLC DALLAS SHUMAKER
VIOLATIONS:	NFPA 1 10.13.1.1 THERE IS NO ADDRESS VISIBLE FROM THE STREET WITH 6-INCH NUMBERS IN CONTRASTING COLOR FROM BUILDING.
OWNER:	CE05090931 COMPLIED 812 NW 3 ST UNITED CHURCH OF GOD FLA DIST DALLAS SHUMAKER
VIOLATIONS:	NFPA 1 1.7.5.1 UNABLE TO GAIN ACCESS TO CONDUCT ANNUAL FIRE INSPECTION.

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 10:00 AM

CASE NO: CE05090932 CASE NO. CLOCK CASE ADDR: 210 NW 6 AV OWNER: ST LUKES BAPTIST CHURCH INSPECTOR: DALLAS SHUMAKER VIOLATIONS: NFPA 1 1.7.5.1 UNABLE TO GAIN ACCESS TO CONDUCT ANNUAL FIRE INSPECTION. _____ CASE NO: CE05090934 CASE ADDR: 318 NW 6 AV ST CHRISTOPHERS EPISCOPAL OWNER: INSPECTOR: DALLAS SHUMAKER VIOLATIONS: NFPA 1 1.7.5.1 UNABLE TO GAIN ACCESS TO CONDUCT ANNUAL FIRE INSPECTION. _____ CASE NO: CE05090936 CASE ADDR: 1122 NW 9 AVE OWNER: RESTORING GRACE COMMUNITY CHURCH INSPECTOR: DALLAS SHUMAKER VIOLATIONS: NFPA 1 1.7.5.1 UNABLE TO GAIN ACCESS TO CONDUCT ANNUAL FIRE INSPECTION. _____ CE05090937 CASE NO: RESCHEDULE CASE ADDR: 1140 NE 7 AVE # 06 ALPINE MERCANTILE INC OWNER: INSPECTOR: DALLAS SHUMAKER VIOLATIONS: NFPA 101 7.1.10.2.1 THERE IS AN EXIT BLOCKED BY A TABLE. FBC 104.1 THERE HAS BEEN WORK DONE WITHOUT PERMITS. EXPANDED FROM ONE BAY INTO A SECOND BAY. _____ CASE NO: CE05090938 CASE ADDR: 623 NW 15 WY OWNER: TURNER, CHADMAN L INSPECTOR: DALLAS SHUMAKER VIOLATIONS: FBC 104.1 THERE HAS BEEN WORK DONE WITHOUT PERMITS. HOOD SYSTEM WITH SUPPRESSION SYSTEM HAS BEEN INSTALLED AND PERMIT NOT FINALED.

	RETURN HEARING (OLD BUSINESS)
CASE ADDR: OWNER:	CE05030768 REQUEST FOR EXTENSION 535 HENDRICKS ISLE BURTON POINT CONDO ASSOCIATION ROBERT KISAREWICH
VIOLATIONS:	FBC 104.1 DOCKS ON THE PROPERTY HAVE BEEN REBUILT WITHOUT FIRST OBTAINING PERMITS.
	BCA FFPC F-20.3 A FIRE LINE IS NOT PROVIDED FOR THE DOCKS AT THE PROPERTY.
CASE NO: CASE ADDR: OWNER:	CE04120455 REQUEST FOR EXTENSION 1238 NE 7 AVE KURLAND, PHILIP A MOHAMMED MALIK
VIOLATIONS:	FBC 104.1 THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENT TO THE BUILDING WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMIT. SUCH ITEMS INCLUDE, BUT ARE NOT LIMITED TO THE FOLLOWING:
	 DEMOLISHED INTERIOR CUT HOLES THROUGH CBS WALLS NEW DRY WALL INSIDE THE HOUSE NEW A/C INSTALLED NEW FENCE INSTALLED
	FBC 104.2.11 INSTALLED NEW AIR CONDITIONING UNIT AND DUCT WORK WITHOUT FIRST OBTAINING REQUIRED MECHANICAL PERMIT.
	FBC 104.2.4 PLUMBING WORK FOR BATHROOM WITHOUT FIRST OBTAINING REQUIRED PERMITS.
	FBC 104.2.5 ELECTRICAL WORK WITHOUT FIRST OBTAINING REQUIRED PERMITS.
VIOLATIONS:	NFPA 1 11.1.2 THERE ARE VOIDS IN THE ELECTRIC CIRCUIT BREAKER PANEL.
	NFPA 1 13.3.1.1 THERE IS NO FIRE SPRINKLER PROVIDED.

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 10:00 AM

NFPA 1 14.13.1.1 THERE ARE NO EMERGENCY LIGHTS PROVIDED IN SHIPPING.

NFPA 101 40.3.4.1 THERE IS NO FIRE ALARM PROVIDED.

NFPA 101 7.9.2.2 EMERGENCY LIGHTS DO NOT ILLUMINATE.

NFPA 1 4.4.3.1.2 KEYED LOCK IS ATTACHED TO THE EXIT DOOR.

FBC 104.1.1 OFFICE/SUITE EXTENSION WAS DONE WITHOUT A PERMIT.

NFPA 1 4.5.8.1 THERE IS NO LINT TRAP PROVIDED FOR THE ELECTRIC DRYER.

NFPA 101 7.1.3.2.2 2ND FLOOR ENCLOSED STORAGE DOES NOT HAVE A LEGAL EXIT.

CASE NO: CE05030750 **REQUEST FOR EXTENSION**

CASE NO: CE05030750 F CASE ADDR: 1624 NW 9 AV OWNER: KEYS RESIDENTIAL PROPERTIES INSPECTOR: ROBERT A PIGNATARO

VIOLATIONS: FBC 104.1 CONVERTED THE CARPORT OF HOME TO A ROOM WITHOUT PERMITS.

> FBC 104.2.5 INSTALLED ELECTRIC IN THIS ROOM WITHOUT PERMITS.

CASE NO: CE05030791 **REQUEST FOR EXTENSION** CASE ADDR: 323 NE 7 AV OWNER: MARCELINO,MARC R & KUEHNE, JOHN INSPECTOR: ROBERT A PIGNATARO

VIOLATIONS: FBC 104.1 CONVERTED THIS PROPERTY TO MULTI UNITS (4) WITHOUT PERMITS TO INCLUDE, BUT NOT LIMITED TO:

- 1. PAVED PARKING LOT WITH ASPHALT
- 2. INSTALLED WINDOWS & DOORS
- 3. SUBDIVIDED INTO SEPARATE APARTMENTS

Page 21

CASE NO:	9208029 REQUEST TO VACATE FIRST ORDER
ASE ADDR:	5181 NW 09 AV
	E SCOTT INC
	WAYNE STRAWN
	47-19.2(a) IT IS PROHIBITED IN B-3 DISTRICT FOR THE USE OF OPEN STORAGE WITHOUT A WALL CONSTRUCTED IN ACCORDANCE WITH SECTION 47-40.1, A MINIMUM OF SIX (6) FEET SIX (6)INCHES IN HEIGHT WHICH COMPLETELY SCREENS SUCH STORAGE AREA FROM ABUTTING PROPERTY AND ALL PUBLIC WAYS.
SE NO:	9306099 IMPOSITION OF FINE
SE ADDR: NER:	1010 SW 02 CT MOUSTAKIS,ALBERT & JEANNETTE WAYNE STRAWN
VIOLATIONS:	301(a) THE BUILDING HAS BEEN EXTENSIVELY ALTERED AND CHANGED IN USE FROM A SINGLE FAMILY TO A DUPLEX. THE ALTERATIONS INCLUDE, BUT ARE NOT LIMITED TO; THE INSTALLATION OF A KITCHEN AND BATHROOM, ENCLOSURE OF THE PORCH AND CONVERSION OF THE PORCH AND UTILITY ADDITION TO LIVING SPACE, AND AN ADDITION ON THE SOUTHWEST OF THE BUILDING ENLARGING THE FLOOR-PLAN. NO PERMITS HAVE BEEN ISSUED FOR THE WORK CITED.
	301.1(d) PLUMBING WORK HAS BEEN DONE WITHOUT THE REQUIRED PERMIT. A BATHROOM, SHOWER, AND KITCHEN PLUMBING HAVE BEEN ADDED.
	301.1(e) ELECTRICAL WORK HAS BEEN ADDED TO THE BUILDING IN THE PROCESS OF CONVERTING THE USE OF ROOMS AND ADDING FACILITIES FOR THE ADDED UNIT, WITHOUT OBTAINING THE REQUIRED PERMITS.
	105.1(a) THE BUILDING HAS DETERIORATED. ROT AND TERMITE DAMAGE ARE IN EVIDENCE. AREAS OF THE FLOORING ARE IN NEED OF REPAIR. INTERIOR WALLS AND SIDING ARE IN NEED OF REPAIR. ALL WORK DONE WITHOUT PERMITS IS PRESUMED TO BE UNSAFE.
	2904.1(a)(1) THE ROOF ON THE NEW ADDITION IS FRAMED WITH 2 X 4S WHICH IS CONTRARY TO THE SOUTH FLORIDA BUILDING CODE.
	307.1(a) THE BUILDING HAS BEEN CHANGED IN USE FROM A SINGLE FAMILY TO A DUPLEX WITHOUT OBTAINING A CERTIFICATE OF OCCUPANCY.
	9-281(b) THERE IS SCATTERED TRASH AND DEAD FLORA ON THE PROPERTY.

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 10:00 AM

CASE NO: CE04071925 REQUEST FOR EXTENSION CASE ADDR: 2491 NW 16 CT SULLIVAN,GERALDINE R & KLEM, ED & ANN OWNER: INSPECTOR: WAYNE STRAWN VIOLATIONS: FBC 104.1 A METAL STORAGE BUILDING APPROXIMATELY TWENTY (20) FEET LONG AND EIGHT (8) FEET WIDE HAS BEEN ERECTED/CONSTRUCTED AT THE REAR OF THE PROPERTY WITHOUT OBTAINING THE REQUIRED PERMIT. ALTERATIONS OF THE DWELLING ON THE PROPERTY HAVE ALSO BEEN ACCOMPLISHED WITHOUT OBTTAINING THE REQUIRED PERMIT. THE ALTERATIONS INCLUDE, BUT MAY NOT BE LIMITED TO THE ALTER-ATION OF THE FLOOR PLAN, ENCLOSURE OF THE FRONT PORCH, THE INSTALLATION OF WINDOWS AND DOORS, AND THE ENCLOSURE OF AN AREA AT THE REAR OF THE CARPORT. FBC 104.2.5 A CIRCUIT HAS BEEN ADDED TO POWER THE CENTRAL AIR CONDITIONING UNIT AT THE REAR OF THE BUILDING. _____ CASE NO: CE05021420 CONTINUED FROM 9/27/05 HEARING CASE ADDR: 6801 NW 28 AV OWNER: CALVO,PETER A INSPECTOR: WAYNE STRAWN VIOLATIONS: FBC 104.1 THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING THE REQUIRED PERMITS. THE ALTERATIONS INCLUDE, BUT MAY NOT BE LIMITED TO THE INSTALLATION OF FRENCH DOORS AND NEW KITCHEN CABINETS AND COUNTERS. FBC 104.2.4 A NEW KITCHEN SINK AND BATHROOM FIXTURES HAVE BEEN INSTALLED WITHOUT OBTAINING THE REQUIRED PERMIT. _____ CASE NO: CE05010593 REQUEST FOR EXTENSION CASE ADDR: 607 SW 20 AVE OWNER: MCMULLEN, DAWN & GALLI, GINO INSPECTOR: KENNETH REARDON VIOLATIONS: FBC 104.1 INSTALLED A WOOD FENCE WITHOUT FIRST OBTAINING A BUILDING PERMIT. _____

CASE NO: CASE ADDR: OWNER: INSPECTOR:	CE04061744 1129 NE 3 AV NICHOLLS,CHARLES A MOHAMMED MALIK	REQUEST FOR	ABATEMENT
VIOLATIONS:	FBC 104.1 THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE BUILDING WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PER- MIT. SUCH ITEMS INCLUDE, BUT ARE NOT LIMITED TO THE FOLLOW- ING:		
	 DEMO INTERIOR AND EXTE INSTALLED NEW EXTERIOR INSTALLED NEW WINDOWS INSTALLED NEW DRYWALL RENOVATION OF KITCHEN 	DOORS	
	FBC 104.2.4 THERE HAVE BEEN PHYSICAL BUILDING WITHOUT FIRST OB MIT. SUCH ITEMS INCLUDE, ING:	TAINING THE	REQUIRED PLUMBING PER-
	 PLUMBING WORK IN BATH KITCHEN CABINETS. 	ROOMS	
OWNER:	CE04121389 1920 NE 51 CT COLONY TERRACE APTS CO-OP MOHAMMED MALIK	REQUEST FOR	EXTENSION
VIOLATIONS:	STRUCTURAL CRACKS IN BALCONY NEED TO BE REPAIRED AND INSPECTED BY A PROFESSIONAL ENGINEER.		
CASE NO: CASE ADDR: OWNER:	CE05011420 2125 NE 33 AV HLAD,DOUGLAS & JOHNSON, DEB MOHAMMED MALIK	REQUEST AN A	ABATEMENT
VIOLATIONS:	INSTALLED NEW FENCE WITHO BUILDING PERMIT.		AINING THE REQUIRED
CASE NO: CASE ADDR: OWNER:	CE04032185 2901 E LAS OLAS BLVD WARD HARRIS PROPERTIES INC ROBERT A PIGNATARO	REQUEST FOR	EXTENSION
VIOLATIONS:	FBC 104.1 THERE HAVE BEEN PHYSICAL BUILDING TO INCLUDE BUT N INSTALLED SHELVES, COUNTE	OT LIMITED 7	20:

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 10:00 AM

FBC 104.2.11 INSTALLED A WALK IN COOLER WITHOUT PERMITS. FBC 104.2.5 THERE HAVE BEEN PHYSICAL ALTERATIONS TO THE ELECTRICAL SYSTEMS OF THIS BUILDING TO INCLUDE BUT NOT LIMITED TO: INSTALLED WIRING AND HOOKED UP APPLICANCES ALL WITHOUT PERMITS. FBC 104.2.7 INSTALLED SIGNS ON THE BUILDING ON THE WINDOWS AND ON THE FREE STANDING POLE SIGN WITHOUT PERMITS. FBC 11-4.6.1 THE ACCESSIBLE PARKING SPACE AT THIS BUILDING IS NOT TO CODE AND IS FADED. FBC 11-4.6.4 THE ACCESSIBLE SIGNAGE IS NOT PER CODE. _____ CASE NO: CE04101430 REQUEST FOR EXTENSION CASE ADDR: 2800 NW 62 ST PERFORMANCE TRADING INC. INSPECTOR: ROBERT A PIGNATARO VIOLATIONS: FBC 104.1 THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE INTERIOR AND EXTERIOR OF THIS STRUCTURE, TO INCLUDE, BUT NOT LIMITED TO:

- 1. COMPLETE BUILD OUT OF THE INTERIOR
- 2. INSTALLED FRAMING, DRYWALL, DOORS AND WINDOWS
- 3. SUBDIVIDED THE BUILDING FOR TWO (2) TENANTS
- 4. INSTALLED DECORATIVE PANELS; FOAM PANELS AND
- COLUMNS ON THE EXTERIOR OF THE BUILDING

OWNER:

INSTALLED PLUMBING TO INCLUDE, BUT NOT LIMITED TO:

- 1. PLUMBING FIXTURES
- PLUMBING PIPE
 INSTALLED NEW INSTALLED NEW PIPE FOR AIRLINES ON EXTERIOR OF THE BUILDING

FBC 104.2.11

INSTALLED AIR CONDITIONER IN THIS BUILDING TO INCLUDE, BUT NOT LIMITED TO:

1. INSTALLED CENTRAL AIR CONDITIONING UNITS WITHOUT PERMITS.

FBC 104.2.4

Page 25

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 10:00 AM

FMC 403.3 MECHANICAL VENTILATION IS REQUIRED FOR REPAIR GARAGES. FBC 104.2.5 INSTALLED ELECTRICAL IN THE BUILDING TO INCLUDE, BUT NOT LIMITED TO: 1. ELECTRICAL WIRING INSIDE AND OUTSIDE OF THE WALLS 2. INSTALLED LIGHT FIXTURES 3. INSTALLED ELECTRICAL FOR EXTERIOR AIR COMPRESSOR 4. INSTALLED ELECTRICAL FOR NEW AIR CONDITIONING UNIT ON EXTERIOR OF THE BUILDING. FBC 704.3.1 THE ONE HOUR TENANT SEPARATION BETWEEN TENANTS IS NOT PER CODE. FBC 11-4.6.1 THERE IS NO PERMITTED ACCESSIBLE PARKING SPACE FOR THIS BUILDING. FBC 11-4.6.4 THERE IS ACCESSIBLE SIGNAGE AT THIS BUILDING. FBC 11-4.8 THERE IS NO ACCESSIBLE RAMP TO THIS BUILDING. FBC 1503.4.4 THE DOWNSPOUTS NEXT TO THE COVERED PARKING ROOF ARE NOT PER CODE. 47-19.9 A.2. INSTALLED SEVERAL BOATS AND TRAILERS OUTSIDE IN THE PARKING LOT AND ON THE GRASS. INSTALLED STORAGE CONTAINERS OUTSIDE. HAS PILES OF TIRES AND MISCELLANEOUS STORAGE OUTSIDE. 47-19.9 A. REPAIRING BOATS OUTDOORS TO INCLUDE, BUT NOT LIMITED TO: 1. REPAIRING AND/OR REPLACING OF BOAT ENGINES

Page 26

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 1:00 PM

_____ RETURN HEARING (OLD BUSINESS) _____ CASE NO: CE04051739 REQUEST FOR EXTENSION CASE ADDR: 1424 HOLLY HEIGHTS DR OWNER: ZANNINI ENTERPRISES INC INSPECTOR: ROBERT A PIGNATARO VIOLATIONS: FBC 104.2.4 ALTERED THE PLUMBING TO INCLUDE, BUT NOT LIMITED TO: INSTALLED NEW: PLUMBING FIXTURES TUBS TOILETS SINKS WATER HEATERS FBC 104.2.5 ALTERED THE ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO: INSTALLED NEW: ELECTRICAL WIRING FIXTURES SWITCHES RECEPTACLES BREAKER PANELS NEW SERVICE FBC 104.9.3.1. PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS: SHUTTER - - - - - #05062503 INTERIOR REMODELING - #05050076 FBC 105.4 THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS AND WITHOUT INSPECTIONS. DRYWALL WAS INSTALLED WITHOUT IN-SPECTIONS, FENCING INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS, ELECTRICAL WIRING INSTALLED WITHOUT INSPECTIONS, PLUMBING INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPT. OF THE CITY OF FORT LAUDERDALE. FBC 2121.2.2.2 DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS.

AGENDA

Page 27

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 1:00 PM FBC 704.3 TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING. ULDR 47-20.13.E INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRES A FRENCH DRAIN STORMWATER SYSTEM TO BE INSTALLED IN THE SWALE. ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING. FBC 104.1 ALTERED THIS SIX (6) UNIT BUILDING TO INCLUDE, BUT NOT INSTALLED: FENCING LIMITED TO: DOORS WINDOWS BRICK PAVERS CABINETS _____ -----CASE NO: CE04051740 REQUEST FOR EXTENSION CASE ADDR: 1430 HOLLY HEIGHTS DR ZANNINI ENTERPRISES INC OWNER: INSPECTOR: ROBERT A PIGNATARO VIOLATIONS: FBC 104.1 ALTERED THIS SIX (6) UNIT BUILDING TO INCLUDE, BUT NOT LIMITED TO: BRICK PAVERS CABINETS FBC 104.9.3.1. PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS: POOL - - - #04090799 DOORS - - #04092026 PLUMBING - #04090800 FBC 105.4 THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT, WINDOWS INSTALLED WITHOUT BUCKS, DORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS AND WITHOUT INSPECTIONS. DRYWALL WAS INSTALLED WITHOUT INSPECTIONS, FENCING INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS, ELECTRICAL WIRING AND PLUMBING WERE INSTALLED WITHOUT INSPECTIONS AND

ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE

BUILDING DEPT. OF THE CITY OF FORT LAUDERDALE.

Page 28

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 1:00 PM

FBC 2121.2.2.2

DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS.

FBC 704.3

TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.

ULDR 47-20.13.E INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS WHICH REOUIRES A FRENCH DRAIN STORMWATER SYSTEM TO BE INSTALLED IN THE SWALE.

ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.

CASE NO: CE04111818 CASE ADDR: 1470 N DIXIE HWY

REQUEST FOR EXTENSION

OWNER: 1470 DIXIE LLC INSPECTOR: ROBERT A PIGNATARO

VIOLATIONS: FBC 104.1

ALTERED THIS FORTY-SIX (46) UNIT BUILDING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED: FENCING CABINETS

FBC 105.4

THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS AND WITHOUT INSPECTIONS. DRYWALL WAS INSTALLED WITHOUT INSPECTIONS AND FENCING WAS INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR CONDITIONING UNITS WERE RE-MOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS. ELECTRICAL WIRING AND PLUMBING WERE INSTALLED WITHOUT IN-SPECTIONS, AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPT. OF THE CITY OF FORT LAUD-ERDALE.

ULDR 47-21.9.A.1.

THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.

FBC 2121.2.2.2

DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS.

Page 29

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 1:00 PM

FBC 704.3

TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING. ULDR 47-20.13.E INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS WHICH REQUIRES A FRENCH DRAIN STORMWATER SYSTEM TO BE INSTALLED IN THE SWALE. FBC 104.9.3.1. PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS: ALUMINUM FENCING -#05032514 WINDOWS & DOORS - #04200391 INTERIOR REMODELING #04100391 PLUMBING - - - - #04100397 MECHANICAL - - - #04200395 APPLICATIONS #05032091 AND #01062068 HAVE FAILED PLAN REVIEW AND ARE THUS NULL AND VOID. _____ CASE NO: CE05021843 CASE ADDR: 1351 HOLLY HEIGHTS DR REQUEST FOR EXTENSION CARTWRIGHT, CHRISTOPHER G OWNER: INSPECTOR: ROBERT A PIGNATARO VIOLATIONS: FBC 104.1 ALTERED THIS FIVE (5) UNIT BUILDING TO INCLUDE, BUT NOT LIMITED TO: INSTALLED: FENCING DOORS WINDOWS BRICK PAVERS CABINETS FBC 104.2.4 ALTERED THE PLUMBING TO INCLUDE, BUT NOT LIMITED TO: INSTALLED NEW: PLUMBING FIXTURES TUBS TOILETS SINKS WATER HEATERS

Page 30

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 1:00 PM

FBC 104.2.5 ALTERED THE ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED NEW: ELECTRICAL WIRING FIXTURES SWITCHES RECEPTACLES BREAKER PANELS NEW SERVICE

FBC 105.4

THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS, AND WITHOUT INSPECTIONS. DRYWALL WAS INSTALLED WITHOUT IN-SPECTIONS, FENCING INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS. ELECTRICAL WIRING WAS INSTALLED WITHOUT INSPECTIONS, PLUMBING WAS INSTALLED WITHOUT INSPECTIONS, NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPT. OF THE CITY OF FORT LAUDERDALE.

FBC 104.2.11

INSTALLED MECHANICAL SYSTEMS INCLUDING, BUT NOT LIMITED TO:

INSTALLED NEW: AIR CONDITIONING UNITS DUCTS WIRING PLUMBING EXHAUST SYSTEMS

ULDR 47-21.9.A.1.

THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.

FBC 2121.2.2.2

DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS.

FBC 704.3

TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.

ULDR 47-20.13.E

INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRES A FRENCH DRAIN STORMWATER SYSTEM TO BE INSTALLED IN THE SWALE.

Page 31

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 1:00 PM FBC 104.9.3.1. PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS: ROOF - - - - # 05020809 ELECTRICAL -# 05031083 MECHANICAL -# 05031091 APPLICATIONS #05051909, #05031079, AND #05031071 HAVE FAILED PLAN REVIEW AND ARE THUS NULL AND VOID. _____ CASE NO: CE05080204 REQUEST FOR EXTENSION CASE ADDR: 1341 HOLLY HEIGHTS DR OWNER: CARTWRIGHT, CHRISTOPHER G INSPECTOR: ROBERT A PIGNATARO VIOLATIONS: FBC 104.1 ALTERED THIS FOUR (4) UNIT BUILDING TO INCLUDE, BUT NOT LIMITED TO: INSTALLED: FENCING DOORS WINDOWS BRICK PAVERS CABINETS FBC 104.2.4 ALTERED THE PLUMBING TO INCLUDE, BUT NOT LIMITED TO: INSTALLED: NEW PLUMBING FIXTURES TUBS TOILETS SINKS WATER HEATERS FBC 104.9.3.1. PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS. ELECTRICAL # 05031085 MECHANICAL # 05031089 APPLICATIONS #05051908, #05031081 AND #05031076 HAVE FAILED PLAN REVIEW AND ARE THUS NULL AND VOID. FBC 105.4 THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS, WITHOUT INSPECTIONS. DRYWALL WAS INSTALLED WITHOUT INSPECTIONS, FENCING INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR

PER CODE. WALL AIR CONDITIONING UNITS WERE REMOVED AND THE

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 1:00 PM

HOLES WERE BLOCKED UP WITHOUT INSPECTIONS. PLUMBING IN-STALLED WITHOUT INSPECTIONS. ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPT. OF THE CITY OF FORT LAUDERDALE.

FBC 2121.2.2.2 DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS.

FBC 704.3

TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.

ULDR 47-20.13.E

INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRES A FRENCH DRAIN STORMWATER SYSTEM TO BE INSTALLED IN THE SWALE.

ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.

CASE NO: CE05081210 **REQUEST FOR EXTENSION** CASE ADDR: 1330 HOLLY HEIGHTS DR OWNER: ASOKA CONDO ASSN INC INSPECTOR: ROBERT A PIGNATARO

VIOLATIONS: FBC 104.1 ALTERED THIS FOUR (4) UNIT BUILDING TO INCLUDE, BUT NOT LIMITED TO:

> INSTALLED: DOORS WINDOWS BRICK PAVERS

FBC 104.9.3.1.
PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE
THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON
THESE PERMITS:

WOOD FENCING - - - #04060791 INTERIOR REMODELING - #04060219

FBC 105.4

THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS, WITHOUT IN-SPECTIONS. DRYWALL WAS INSTALLED WITHOUT INSPECTIONS, FENCING INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR CONDITIONING UNITS WERE REMOVED AND THE

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 1:00 PM

HOLES WERE BLOCKED UP WITHOUT INSPECTIONS. ELECTRICAL WIRING WAS INSTALLED WITHOUT INSPECTIONS, PLUMBING IN-STALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPT. OF THE CITY OF FORT LAUDERDALE. ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING. FBC 2121.2.2.2 DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REOUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS. FBC 704.3 TENANT FIRE SEPARATIONS BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING. ULDR 47-20.13.E INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS, ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS WHICH REQUIRES A FRENCH DRAIN STORMWATER SYSTEM TO BE INSTALLED IN THE SWALE. _____ CASE NO: CE05080073 REQUEST FOR EXTENSION CASE ADDR: 1336 HOLLY HEIGHTS DR ASOKA CONDO ASSN INC INSPECTOR: ROBERT A PIGNATARO VIOLATIONS: FBC 104.1 ALTERED THIS FOUR (4) UNIT BUILDING TO INCLUDE, BUT NOT LIMITED TO: INSTALLED: BRICK PAVERS CABINETS FBC 105.4 THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS, WITHOUT INSPECTIONS. DRYWALL INSTALLED WITHOUT INSPECTIONS, FENCING INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS, ELECTRICAL WIRING INSTALLED WITHOUT INSPECTIONS, PLUMBING INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPT. OF THE CITY OF FORT LAUDERDALE.

ULDR 47-21.9.A.1.

OWNER:

THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.

Page 34

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 1:00 PM

FBC 2121.2.2.2 DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS. FBC 704.3 TENANT FIRE SEPARATION BETWEEN APARTMENTS IS REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING. ULDR 47-20.13.E INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS WHICH REOUIRES A FRENCH DRAIN STORMWATER SYSTEM TO BE INSTALLED IN THE SWALE. FBC 104.9.3.1 PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPETION HAS PASSED ON THESE PERMITS. WOOD FENCING - - - #05052505 POOL - - - - - #04042683 INTERIOR REMODEL - #04060220 _____ _____ CASE NO: CE05080021 REQUEST FOR EXTENSION CASE ADDR: 1342 HOLLY HEIGHTS DR ASOKA CONDO ASSN INC OWNER: INSPECTOR: ROBERT A PIGNATARO VIOLATIONS: FBC 104.1 ALTERED THIS FOUR (4) UNIT BUILDING TO INCLUDE, BUT NOT LIMITED TO: INSTALLED: BRICK PAVERS CABINETS FBC 105.4 THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS AND WITHOUT INSPECTIONS. DRYWALL WAS INSTALLED WITHOUT IN-SPECTIONS, FENCING INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS. ELECTRICAL WIRING INSTALLED WITHOUT INSPECTIONS, PLUMBING INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPT. OF THE CITY OF FORT LAUDERDALE. ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT

INCLUDING VUA LANDSCAPING.

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 1:00 PM

FBC 2121.2.2.2 DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS. FBC 704.3 TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING. ULDR 47-20.13.E INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS WHICH REQUIRE A FRENCH DRAIN STORMWATER SYSTEM TO BE INSTALLED IN THE SWALE. FBC 104.9.3.1 PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS: WOOD FENCING- - - #05052503 ALUMINUM FENCING- #04042463 ELECTRICAL - - - #05062025 _____ _____ CASE NO: CE05080022 REQUEST FOR EXTENSION CASE ADDR: 1348 HOLLY HEIGHTS DR ASOKA CONDO ASSN INC OWNER: INSPECTOR: ROBERT A PIGNATARO VIOLATIONS: FBC 104.1 ALTERED THIS FIVE (5) UNIT BUILDING TO INCLUDE, BUT NOT LIMITED TO: INSTALLED: FENCING BRICK PAVERS FBC 104.9.3.1 PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS: INTERIOR REMODELING #04060215 WOOD FENCING APPLICATION #05052504 HAS FAILED PLAN REVIEW AND THUS IS NULL AND VOID. FBC 105.4 THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS AND WITHOUT INSPECTIONS. DRYWALL WAS INSTALLED WITHOUT INSPECTIONS, FENCING WAS INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN

Page 36

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 1:00 PM

OR PER CODE. WALL AIR CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS. ELECTRICAL WIRING INSTALLED WITHOUT INSPECTIONS. PLUMBING INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUB-MITTED AND APPROVED BY THE BUILDING DEPT. OF THE CITY OF FORT LAUDERDALE.

FBC 2121.2.2.2

DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS.

FBC 704.3

TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.

ULDR 47-20.13.E

INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRES A FRENCH DRAIN STORMWATER SYSTEM TO BE INSTALLED IN THE SWALE.

ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.

Page 37

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 1:00 PM

_____ HEARING COMPUTER SCHEDULED _____ CASE NO: CE05092124 CASE ADDR: 720 NE 13 CT VILLA SUN RAY CONDO ASSN OWNER: INSPECTOR: ROBERT A PIGNATARO VIOLATIONS: FBC 2121.2.2.2 DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WIN-DOWS OR DOOR OPENINGS. FBC 104.2.11 INSTALLED MECHANICAL SYSTEMS, INCLUDING, BUT NOT LIMITED TO: INSTALLED NEW AIR CONDITIONING UNITS: DUCTS WIRING PLUMBING EXHAUST SYSTEMS FBC 104.9.3.1 PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS. FBC 704.3 TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING. FBC 104.2.4 ALTERED THE PLUMBING TO INCLUDE, BUT NOT LIMITED TO: INSTALLED: NEW PLUMBING FIXTURES TUBS TOILETS SINKS WATER HEATERS FBC 105.4 THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT, WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS, AND WITHOUT INSPECTIONS, DRYWALL INSTALLED WITHOUT INSPECTIONS, FENCING INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS, ELECTRICAL WIRING INSTALLED WITHOUT INSPECTIONS, PLUMBING INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPT. OF THE CITY OF FORT LAUDER-DALE.

Page 38

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 1:00 PM FBC 104.1 ALTERED THIS FOUR (4) UNIT BUILDING TO INCLUDE, BUT NOT LIMITED TO : INSTALLED: FENCING DOORS WINDOWS BRICK PAVERS CABINETS FBC 104.2.5 ALTERED THE ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO: INSTALLED: NEW ELECTRICAL WIRING FIXTURES SWITCHES RECEPTACLES BREAKER PANELS NEW SERVICE 47-20.13 E. INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRE A FRENCH DRAIN STORM WATER SYSTEM TO BE INSTALLED IN THE SWALE. ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING. _____ CASE NO: CE05092015 CASE ADDR: 720 NE 13 CT # 1 BLAND,MICHAEL INSPECTOR: ROBERT A PIGNATARO VIOLATIONS: FBC 2121.2.2.2 DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WIN-DOWS OR DOOR OPENINGS. FBC 104.2.11 INSTALLED MECHANICAL SYSTEMS, INCLUDING, BUT NOT LIMITED TO: INSTALLED NEW AIR CONDITIONING UNITS: DUCTS WIRING PLUMBING EXHAUST SYSTEMS FBC 104.9.3.1 PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS.

OWNER:

Page 39

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 **1:00 PM**

FBC 704.3 TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.

FBC 104.2.4 ALTERED THE PLUMBING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED: NEW PLUMBING FIXTURES TUBS TOILETS SINKS WATER HEATERS

FBC 104.1

ALTERED THIS FOUR (4) UNIT BUILDING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED: FENCING DOORS WINDOWS BRICK PAVERS CABINETS

FBC 104.2.5

ALTERED THE ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED: NEW ELECTRICAL WIRING FIXTURES SWITCHES RECEPTACLES BREAKER PANELS NEW SERVICE

47-20.13 E.

INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRE A FRENCH DRAIN STORM WATER SYSTEM TO BE INSTALLED IN THE SWALE.

ULDR 47-21.9.A.1.

THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.

FBC 105.4

THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT, WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS, AND WITHOUT INSPECTIONS, DRYWALL INSTALLED WITHOUT INSPECTIONS, FENCING INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS, ELECTRICAL WIRING INSTALLED WITHOUT INSPECTIONS, PLUMBING INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPT. OF THE CITY OF FORT LAUDERDALE.

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 1:00 PM

CASE NO: CE05092038 CASE ADDR: 720 NE 13 CT # 2 MARTIN, PABLO R. OWNER: INSPECTOR: ROBERT A PIGNATARO VIOLATIONS: FBC 2121.2.2.2 DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WIN-DOWS OR DOOR OPENINGS. FBC 104.9.3.1 PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS. FBC 704.3 TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING. FBC 104.2.4 ALTERED THE PLUMBING TO INCLUDE, BUT NOT LIMITED TO: INSTALLED: NEW PLUMBING FIXTURES TUBS TOTLETS SINKS WATER HEATERS FBC 105.4 THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT, WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS, AND WITHOUIT INSPECTIONS, DRYWALL INSTALLED WITHOUT INSPECTIONS, FENCING INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS, ELECTRICAL WIRING INSTALLED WITHOUT INSPECTIONS, PLUMBING INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPT. OF THE CITY OF FORT LAUDER-DALE. FBC 104.1 ALTERED THIS FOUR (4) UNIT BUILDING TO INCLUDE, BUT NOT LIMITED TO: INSTALLED: FENCING DOORS WINDOWS BRICK PAVERS CABINETS

Page 40

Page 41

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 1:00 PM

FBC 104.2.5 ALTERED THE ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO: INSTALLED: NEW ELECTRICAL WIRING FIXTURES SWITCHES RECEPTACLES BREAKER PANELS NEW SERVICE 47-20.13 E. INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRE A FRENCH DRAIN STORM WATER SYSTEM TO BE INSTALLED IN THE SWALE. ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING. FBC 104.2.11 INSTALLED MECHANICAL SYSTEMS, INCLUDING, BUT NOT LIMITED TO: INSTALLED NEW AIR CONDITIONING UNITS: DUCTS WIRING PLUMBING EXHAUST SYSTEMS _____ CASE NO: CE05092046 CASE ADDR: 720 NE 13 CT # 3 SCHETTER, JAMIE INSPECTOR: ROBERT A PIGNATARO VIOLATIONS: 47-20.13 E. INSTALLED MORE THAN THE REQUURED 50% BRICK PAVERS ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRE A FRENCH DRAIN STORM WATER SYSTEM TO BE INSTALLED IN THE SWALE. ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING. FBC 2121.2.2.2

OWNER:

DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WIN-DOWS OR DOOR OPENINGS.

Page 42

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 1:00 PM

FBC 104.2.11

INSTALLED MECHANICAL SYSTEMS, INCLUDING, BUT NOT LIMITED TO:

INSTALLED NEW AIR CONDITIONING UNITS: DUCTS WIRING PLUMBING EXHAUST SYSTEMS

FBC 104.9.3.1

PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS.

FBC 704.3

TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.

FBC 104.2.4

ALTERED THE PLUMBING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED: NEW PLUMBING FIXTURES TUBS TOILETS SINKS WATER HEATERS

FBC 105.4

THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT, WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS, AND WITHOUT INSPECTIONS, DRYWALL INSTALLED WITHOUT INSPECTIONS, FENCING INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS, ELECTRICAL WIRING INSTALLED WITHOUT INSPECTIONS, PLUMBING INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPT. OF THE CITY OF FORT LAUDER-DALE.

FBC 104.1

ALTERED THIS FOUR (4) UNIT BUILDING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED: FENCING DOORS WINDOWS BRICK PAVERS CABINETS

FBC 104.2.5 ALTERED THE ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED: NEW ELECTRICAL WIRING FIXTURES

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 1:00 PM

> SWITCHES RECEPTACLES BREAKER PANELS NEW SERVICE.

_____ CASE NO: CE05092051 CASE ADDR: 720 NE 13 CT # 4 OWNER: KARASCHCHAN, ERIC VON INSPECTOR: ROBERT A PIGNATARO VIOLATIONS: 47-20.13 E. INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRE A FRENCH DRAIN STORM WATER SYSTEM TO BE INSTALLED IN THE SWALE. ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING. FBC 2121.2.2.2 DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WIN-DOWS OR DOOR OPENINGS. FBC 104.2.11 INSTALLED MECHANICAL SYSTEMS, INCLUDING, BUT NOT LIMITED TO: INSTALLED NEW AIR CONDITIONING UNITS: DUCTS WIRING PLUMBING EXHAUST SYSTEMS FBC 104.9.3.1 PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS. FBC 704.3 TENANT FIRE SEPARATIONS BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING. FBC 104.2.4 ALTERED THE PLUMBING TO INCLUDE, BUT NOT LIMITED TO: INSTALLED: NEW PLUMBING FIXTURES TUBS TOILETS SINKS WATER HEATERS

Page 43

Page 44

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 1:00 PM

FBC 105.4

THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT, WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS, AND WITHOUT INSPECTIONS, DRYWALL INSTALLED WITHOUT INSPECTIONS, FENCING INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS, ELECTRICAL WIRING INSTALLED WITHOUT INSPECTIONS, PLUMBING INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPT. OF THE CITY OF FORT LAUDER-DALE.

FBC 104.1
ALTERED THIS FOUR (4) UNIT BUILDING TO INCLUDE, BUT NOT
LIMITED TO:

INSTALLED: FENCING DOORS WINDOWS BRICK PAVERS CABINETS

FBC 104.2.5

ALTERED THE ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED: NEW ELECTRICAL WIRING FIXTURES SWITCHES RECEPTACLES BREAKER PANELS NEW SERVICE

CASE NO: CE05092093 CASE ADDR: 720 NE 13 CT # 5 OWNER: KANTOR,MARC A INSPECTOR: ROBERT A PIGNATARO

VIOLATIONS: 47-20.13 E. INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRE A FRENCH DRAIN STORM WATER SYSTEM TO BE INSTALLED IN THE SWALE.

> ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.

FBC 2121.2.2.2

DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WIN-DOWS OR DOOR OPENINGS.

Page 45

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 1:00 PM

FBC 104.2.11 INSTALLED MECHANICAL SYSTEMS, INCLUDING, BUT NOT LIMITED TO: INSTALLED NEW AIR CONDITIONING UNITS: DUCTS WIRING PLUMBING EXHAUST SYSTEMS FBC 104.9.3.1 PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS. FBC 704.3 TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING. FBC 104.2.4 ALTERED THE PLUMBING TO INCLUDE, BUT NOT LIMITED TO: INSTALLED: NEW PLMBING FIXTURES TUBS TOILETS SINKS WATER HEATERS FBC 105.4 THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT, WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS, AND WITHOUT INSPECTIONS, DRYWALL INSTALLED WITHOUT INSPECTIONS, FENCING INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS, ELECTRICAL WIRING INSTALLED WITHOUT INSPECTIONS, PLUIMBING INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPT. OF THE CITY OF FORT LAUDER-DALE. FBC 104.1 ALTERED THIS FOUR (4) UNIT BUILDING TO INCLUDE, BUT NOT LIMITED TO: INSTALLED: FENCING

DOORS WINDOWS BRICK PAVERS CABINETS

Page 46

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 1:00 PM

FBC 104.2.5 ALTERED THE ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED: NEW ELECTRICAL WIRING FIXTURES SWITCHES RECEPTACLES BREAKER PANELS NEW SERVICE

_____ CASE NO: CE05100037 CASE ADDR: 728 NE 13 CT OWNER: VILLA SUN RAY CONDO ASSN INSPECTOR: ROBERT A PIGNATARO VIOLATIONS: FBC 104.1 ALTERED THIS BUILDING TO INCLUDE, BUT NOT LIMITED TO: INSTALLED: FENCING DOORS WINDOWS BRICK PAVERS CABINETS FBC 104.2.5 ALTERED THE ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO: INSTALLED NEW: ELECTRICAL WIRING FIXTURES SWITCHES RECEPTACLES BREAKER PANELS NEW SERVICE FBC 104.2.4 ALTERED THE PLUMBING TO INCLUDE, BUT NOT LIMITED TO: INSTALLED NEW: PLUMBING FIXTURES TUBS TOILETS SINKS WATER HEATERS FBC 104.2.11 INSTALLED MECHANICAL SYSTEMS INCLUDING, BUT NOT LIMITED TO: INSTALLED NEW: AIR CONDITIONING UNITS DUCTS WIRING PLUMBING EXHAUST SYSTEMS

Page 47

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 1:00 PM

FBC 104.9.3.1

PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS.

INTERIOR REMODELING #04100456 PLUMBING - - - - #04100457

APPLICATION #04100462 has failed plan review and is thus null and void.

FBC 105.4

THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS AND WITHOUT INSPECTIONS. DRYWALL WAS INSTALLED WITHOUT IN-SPECTIONS, FENCING INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS, ELECTRICAL WITRING INSTALLED WITHOUT INSPECTIONS. PLUMBING INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPT. OF THE CITY OF FORT LAUDERDALE.

FBC 2121.2.2.2

DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS.

FBC 704.3

TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.

ULDR 47-20.13.E

INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS, ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRES A FRENCH DRAIN STORM WATER SYSTEM TO BE INSTALLED IN THE SWALE.

ULDR 47-21.9.A.1.

THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.

Page 48

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 1:00 PM

_____ _ _ _ _ _ _ CASE NO: CE05092144 CASE ADDR: 728 NE 13 CT # 6 DARCY , BRUCE OWNER: INSPECTOR: ROBERT A PIGNATARO VIOLATIONS: FBC 104.1 ALTERED THIS BUILDING TO INCLUDE, BUT NOT LIMITED TO: INSTALLED: FENCING DOORS WINDOWS BRICK PAVERS CABINETS FBC 104.2.5 ALTERED THE ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO: INSTALLED NEW: ELECTRICAL WIRING FIXTURES SWITCHES RECEPTACLES BREAKER PANELS NEW SERVICE. FBC 2121.2.2.2 DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS. FBC 104.2.11 INSTALLED MECHANICAL SYSTEMS INCLUDING, BUT NOT LIMITED TO: INSTALLED NEW: AIR CONDITIONING UNITS DUCTS WIRING PLUMBING EXHAUST SYSTEMS FBC 104.9.3.1 PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS. INTERIOR REMODELING #04100456 PLUMBING - - - - #04100457 APPLICATION #04100462 HAS FAILED PLAN REVIEW AND IS THUS NULL AND VOID. FBC 704.3 TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.

Page 49

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 1:00 PM

FBC 104.2.4

ALTERED THE PLUMBING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED NEW: PLUMBING FIXTURES TUBS TOILETS SINKS WATER HEATERS

FBC 105.4

THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS AND WITHOUT INSPECTIONS. DRYWALL WAS INSTALLED WITHOUT IN-SPECTIONS, FENCING INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS, ELECTRICAL WIRING INSTALLED WITHOUT INSPECTIONS. PLUMBING INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPT. OF THE CITY OF FORT LAUDERDALE.

ULDR 47-20.13.E

INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS, ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRES A FRENCH DRAIN STORM WATER SYSTEM TO BE INSTALLED IN THE SWALE.

ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.

CASE NO: CE05100033

CASE ADDR:	728 NE 13 CT # 7
OWNER:	WEISS, JOHN M & LOBAR, MARK
INSPECTOR:	ROBERT A PIGNATARO

VIOLATIONS: FBC 104.1

ALTERED THIS BUILDING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED: FENCING DOORS WINDOWS BRICK PAVERS CABINETS

FBC 104.2.11

INSTALLED MECHANICAL SYSTEMS INCLUDING, BUT NOT LIMITED TO:

INSTALLED NEW: AIR CONDITIONING UNITS DUCTS WIRING PLUMBING EXHAUST SYSTEMS

Page 50

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 1:00 PM

FBC 104.2.4 ALTERED THE PLUMBING TO INCLUDE, BUT NOT LIMITED TO: INSTALLED NEW: PLUMBING FIXTURES TUBS TOILETS SINKS WATER HEATERS FBC 104.2.5 ALTERED THE ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO: INSTALLED NEW: ELECTRICAL WIRING FIXTURES SWITCHES RECEPTACLES BREAKER PANELS NEW SERVICE FBC 104.9.3.1 PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS. INTERIOR REMODELING #04100456 PLUMBING - - - - #04100457

APPLICATION #04100462 HAS FAILED PLAN REVIEW AND IS THUS NULL AND VOID.

FBC 105.4

THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNMS AND WITHOUT INSPECTIONS. DRYWALL WAS INSTALLED WITHOUT INSPECTIONS, FENCING INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS, ELECTRICAL WIRING INSTALLED WITHOUT INSPECTIONS. PLUMBING INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPT. OF THE CITY OF FORT LAUDERDALE.

FBC 2121.2.2.2

DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS.

FBC 704.3

TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.

Page 51

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 **1:00 PM**

ULDR 47-20.13.E INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS, ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRED A FRENCH DRAIN STORM WATER SYSTEM TO BE INSTALLED IN THE SWALE. ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING. _____ CASE NO: CE05100048 CASE ADDR: 728 NE 13 CT # 8 OWNER: RUBINO, FRANK INSPECTOR: ROBERT A PIGNATARO VIOLATIONS: FBC 104.1 ALTERED THIS BUILDING TO INCLUDE, BUT NOT LIMITED TO: INSTALLED: FENCING DOORS WINDOWS BRICK PAVERS CABINETS FBC 104.2.5 ALTERED THE ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO: INSTALLED NEW: ELECTRICAL WIRING FIXTURES SWITCHES RECEPTACLES BREAKER PANELS NEW SERVICE FBC 2121.2.2.2 DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS. FBC 104.2.11 INSTALLED MECHANICAL SYSTEMS INCLUDING, BUT NOT LIMITED TO: INSTALLED NEW: AIR CONDITIONING UNITS DUCTS WIRING PLUMBING EXHAUST SYSTEMS FBC 104.9.3.1. PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE

Page 52

CITY OF FORT LAUDERDALE AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 1:00 PM

THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS:

INTERIOR REMODELING #04100456 PLUMBING - - - - #04100457

APPLICATION #04100462 HAS FAILED PLAN REVIEW AND IS THUS NULL AND VOID.

FBC 704.3

TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.

FBC 104.2.4

ALTERED THE PLUMBING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED NEW: PLUMBING FIXTURES TUBS TOILETS SINKS WATER HEATERS

FBC 105.4

THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS AND WITHOUT INSPECTIONS. DRYWALL WAS INSTALLED WITHOUT IN-SPECTIONS, FENCING INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS, ELECTRICAL WIRING INSTALLED WITHOUT INSPECTIONS. PLUMBING INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPT. OF THE CITY OF FORT LAUDERDALE.

ULDR 47-20.13.E

INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS, ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRES A FRENCH DRAIN STORM WATER SYSTEM TO BE INSTALLED IN THE SWALE.

ULDR 47-21.9.A.1.

THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 1:00 PM

CASE NO: CE05100074 CASE ADDR: 728 NE 13 CT # 9 OWNER: GOODWIN,KENNETH & MAGARINOS, JESUS A INSPECTOR: ROBERT A PIGNATARO

VIOLATIONS: FBC 104.1 ALTERED THIS BUILDING TO INCLUDE, BUT NOT LIMITED TO:

> INSTALLED: FENCING DOORS WINDOWS BRICK PAVERS CABINETS

FBC 104.2.5

ALTERED THE ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED NEW: ELECTRICAL WIRING FIXTURES SWITCHES RECEPTACLES BREAKER PANELS NEW SERVICE

FBC 2121.2.2.2

DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS.

FBC 105.4

THERE HAS BEENM FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS AND WITHOUT INSPECTIONS. DRYWALL WAS INSTALLED WITHOUT IN-SPECTIONS, FENCING INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS, ELECTRICAL WIRING INSTALLED WITHOUT INSPECTIONS. PLUMBING INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPT. OF THE CITY OF FORT LAUDERDALE.

ULDR 47-20.13.E

INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS, ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRES A FRENCH DRAIN STORM WATER SYSTEM TO BE INSTALLED IN THE SWALE.

ULDR 47-21.9.A.1.

THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.

Page 53

Page 54

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 1:00 PM

FBC 104.2.11 INSTALLED MECHANICAL SYSTEMS INCLUDING, BUT NOT LIMITED TO: INSTALLED NEW: AIR CONDITIONING UNITS DUCTS WIRING PLUMBING EXHAUST SYSTEMS FBC 104.9.3.1. PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS. INTERIOR REMODELING #04100456 PLUMBING - - - - #04100457 APPLICATION #04100457 HAS FAILED PLAN REVIEW AND IS THUS NULL AND VOID. FBC 704.3 TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING. FBC 104.2.4 ALTERED THE PLUMBING TO INCLUDE, BUT NOT LIMITED TO: INSTALLED NEW: PLUMBING FIXTUIRES TUBS TOILETS SINKS WATER HEATERS _____ CASE NO: CE05100097 CASE ADDR: 728 NE 13 CT # 10 BERNARD, TONY INSPECTOR: ROBERT A PIGNATARO VIOLATIONS: FBC 104.1 ALTERED THIS BUILDING TO INCLUDE, BUT NOT LIMITED TO: INSTALLED: FENCING DOORS WINDOWS BRICK PAVERS CABINETS FBC 104.2.5 ALTERED THE ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO: INSTALLED NEW: ELECTRICAL WIRING

OWNER:

Page 55

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 **1:00 PM**

> FIXTURES SWITCHES RECEPTACLES BREAKER PANELS NEW SERVICE

FBC 2121.2.2.2

DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS.

FBC 104.2.11 INSTALLED MECHANICAL SYSTEMS INCLUDING, BUT NOT LIMITED TO:

INSTALLED NEW: AIR CONDITIONING UNITS' DUCTS WIRING PLUMBING EXHAUST SYSTEMS

FBC 104.9.3.1

PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS:

INTERIOR REMODELING #04100456 PLUMBING - - - - # 04100457

APPLICATION #04100462 HAS FAILED PLAN REVIEW AND IS THUS NULL AND VOID.

FBC 704.3

TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.

FBC 104.2.4

ALTERED THE PLUMBING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED NEW: PLUMBING FIXTURES TUBS TOILETS SINKS WATER HEATERS

FBC 105.4

THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS AND WITHOUT INSPECTIONS. DRYWALL WAS INSTALLED WITHOUT IN-SECTIONS, FENCING INSTALLED WITHOUT INSPECTIONS AND NOT

Page 56

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 1:00 PM

PER PLAN OR PER CODE. WALL AIR CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS, ELECTRICAL WIRING INSTALLED WITHOUT INSPECTIONS. PLUMBING INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON AN PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPT. OF THE CITY OF FORT LAUDERDALE. ULDR 47-20.13.E INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS, ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRES A FRENCH DRAIN STORM WATER SYSTEM TO BE INSTALLED IN THE SWALE. ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING. _____ CASE NO: CE05100374 CASE ADDR: 728 NE 13 CT # 11 OWNER: SULLIVAN, SANDRA INSPECTOR: ROBERT A PIGNATARO VIOLATIONS: FBC 104.2.11 INSTALLED MECHANICAL SYSTEMS INCLUDING, BUT NOT LIMITED TO: INSTALLED NEW: AIR CONDITIONING UNITS DUCTS WIRING PLUMBING EXHAUST SYSTEMS FBC 104.1 ALTERED THIS BUILDING TO INCLUDE, BUT NOT LIMITED TO: INSTALLED: FENCING DOORS WINDOWS BRICK PAVERS CABINETS FBC 104.2.5 ALTERED THE ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO: INSTALLED NEW: ELECTRICAL WIRING FIXTURES SWITCHES RECEPTACLES BREAKER PANELS NEW SERVICE

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 1:00 PM

FBC 2121.2.2.2

DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS.

FBC 104.9.3.1

PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS.

INTERIOR REMODELING #04100456 PLUMBING - - - - #04100457

APPLICATION #04100462 HAS FAILED PLAN REVIEW AND IS THUS NULL AND VOID.

FBC 704.3

TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.

FBC 104.2.4

ALTERED THE PLUMBING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED NEW: PLUMBING FIXTURES TUBS TOILETS SINKS WATER HEATERS

FBC 105.4

THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS AND WITHOUT INSPECTIONS. DRYWALL WAS INSTALLED WITHOUIT IN-SPECTIONS, FENCING INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS, ELECTRICAL WIRING INSTALLED WITHOUT INSPECTIONS. PLUMBING INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPT. OF THE CITY OF FORT LAUDERDALE.

ULDR 47-20.13.E

INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS, ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRES A FRENCH DRAIN STORM WATER SYSTEM TO BE INSTALLED IN THE SWALE.

ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 1:00 PM

- CASE NO: CE05100380
- CASE ADDR: 728 NE 13 CT # 12 OWNER: IRISH,KEVIN D & MCCLURE, MICHAEL W INSPECTOR: ROBERT A PIGNATARO
- INSPECIOR: ROBERI A PIGNAIARO

VIOLATIONS: FBC 104.1

ALTERED THIS BUILDING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED: FENCING DOORS WINDOWS BRICK PAVERS CABINETS

FBC 2121.2.2.2

DOOR AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS.

FBC 104.2.11 INSTALLED MECHANICAL SYSTEMS INCLUDING, BUT NOT LIMITED TO:

INSTALLED NEW: AIR CONDITIONING UNITS DUCTS WIRING PLUMBING EXHAUST SYSTEMS

FBC 104.9.3.1

PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS.

INTERIOR REMODELING #04100456 PLUMBING - - - - #04100457

APPLICATION #04100462 HAS FAILED PLAN REVIEW AND IS THUS NULL AND VOID.

FBC 704.3

TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.

FBC 104.2.4

ALTERED THE PLUMBING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED NEW: PLUMBING FIXTURES TUBS TOILETS SINKS WATER HEATERS Page 58

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 1:00 PM

FBC 105.4

THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS AND WITHOUT INSPECTIONS. DRYWALL WAS INSTALLED WITHOUT IN-SPECTIONS, FENCING INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS, ELECTRICAL WIRING INSTALLED WITHOUT INSPECTIONS. PLUMBING INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPT. OF THE CITY OF FORT LAUDERDALE.

ULDR 47-20.13.E

INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS, ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRES A FRENCH DRAIN STORM SYSTEM TO BE INSTALLED IN THE SWALE.

ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.

FBC 104.2.5 ALTERED THE ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED NEW: ELECTRICAL WIRING FIXTURES SWITCHES RECEPTACLES BREAKER PANELS NEW SERVICE

_____ CASE NO: CE05100382 CASE ADDR: 728 NE 13 CT # 13 OWNER: IRISH,KEVIN D INSPECTOR: ROBERT A PIGNATARO VIOLATIONS: FBC 104.1 ALTERED THIS BUILDING TO INCLUDE, BUT NOT LIMITED TO: INSTALLED: FENCING DOORS WINDOWS BRICK PAVERS CABINETS FBC 104.2.5 ALTERED ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO: INSTALLED NEW ELECTRICAL WIRING FIXTURES

Page 60

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 **1:00 PM**

SWITCHES RECEPTACLES BREAKER PANELS NEW SERVICE

FBC 2121.2.2.2

DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OF DOOR OPENINGS.

FBC 104.2.11

INSTALLED MECHANICAL SYSTEMS INCLUDING, BUT NOT LIMITED TO:

INSTALLED NEW: AIR CONDITIONING UNITS DUCTS WIRING PLUMBING EXHAUST SYSTEMS

FBC 104.9.3.1

PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS.

INTERIOR REMODELING #04100456 PLUMBING - - - - - #04100457

APPLICATION #04100462 HAS FAILED PLAN REVIEW AND IS THUS NULL AND VOID.

FBC 704.3

TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.

FBC 104.2.4 ALTERED THE PLUMBING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED NEW: PLUMBING FIXTURES TUBS TOILETS SINKS WATER HEATERS

FBC 105.4

THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOPR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS AND WITHOUT INSPECTIONS. DRYWALL WAS INSTALLED WITHOUT IN-SPECTIONS, FENCING INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS, ELECTRICAL WIRING INSTALLED WITHOUT INSPECTIONS. PLUMBING

Page 61

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 1:00 PM

INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPT. OF THE CITY OF FORT LAUDERDALE

ULDR 47-20.13.E INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS, ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRES A FRENCH DRAIN STORM WATER SYSTEM TO BE INSTALLED IN THE SWALE.

ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.

- CASE NO: CE05100391 CASE ADDR: 728 NE 13 CT # 14
- CASE ADDR:728 NE 13 CI # 14OWNER:SUN RAY INVESTMENTS INCINSPECTOR:ROBERT A PIGNATARO
- VIOLATIONS: FBC 104.1 ALTERED THIS BUILDING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED: FENCING DOORS WINDOWS BRICK PAVERS CABINETS

FBC 104.2.4 ALTERED THE PLUMBING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED NEW: PLUMBING FIXTURES TUBS TOILETS SINKS WATER HEATERS

FBC 2121.2.2.2 DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS.

FBC 104.2.5 ALTERED THE ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED NEW: ELECTRICAL WIRING FIXTURES SWITCHES RECEPTACLES BREAKER PANELS NEW SERVICE

Page 62

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 1:00 PM

FBC 104.2.11

INSTALLED MECHANICAL SYSTEMS INCLUDING, BUT NOT LIMITED TO:

INSTALLED NEW: AIR CONDITIONING UNITS DUCTS WIRING PLUMBING EXHAUST SYSTEMS

FBC 104.9.3.1

PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS.

INTERIOR REMODELING #04100456 PLUMBING - - - - - - #04100457

APPLICATION #04100462 HAS FAILED PLAN REVIEW AND IS THUS NULL AND VOID.

FBC 704.3

TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.

FBC 105.4

THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS AND WITHOUT INSPECTIONS. DRYWALL WAS INSTALLED WITHOUT IN-SPECTIONS, FENCING INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR CONDITINING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS, ELECTRICAL WIRING INSTALLED WITHOUT INSPECTIONS. PLUMBING INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPT. OF THE CITY OF FORT LAUDERDALE.

ULDR 47-20.13.E INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS, ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRES A FRENCH DRAIN STORM

WATER SYSTEM TO BE INSTALLED IN THE SWALE.

ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 1:00 PM

CASE NO:	CE05100446
CASE ADDR:	736 NE 13 CT
OWNER:	VILLA SUN RAY CONDO ASSN
INSPECTOR:	ROBERT A PIGNATARO

VIOLATIONS: FBC 104.1 ALTERED THIS EIGHT (8) UNIT BUILDING TO INCLUDE, BUT NOT LIMITED TO:

> INSTALLED: FENCING DOORS WINDOWS BRICK PAVERS CABINETS

FBC 105.4

THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS AND WITHOUT INSPECTIONS. DRYWALL WAS INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS. ELECTRICAL WIRING WAS INSTALLED WITHOUT INSPECTIONS. PLUMBING WAS INSTALLED WITHOUT INSPECTIONS. NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPT. OF THE CITY OF FORT LAUDERDALE.

FBC 104.9.3.1

PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS. APPLICATIONS #04100464. #04100466, #04100467 AND #04100469 HAVE FAILED PLAN REVIEW AND THUS ARE NULL AND VOID.

FBC 104.2.4 ALTERED THIS PLUMBING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED NEW: PLUMBING FIXTURES TUBS TOILETS SINKS WATER HEATERS

FBC 2121.2.2.2

DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS.

FBC 104.2.11

INSTALLED MECHANICAL SYSTEMS INCLUDING, BUT NOT LIMITED TO:

Page 63

Page 64

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 **1:00 PM**

INSTALLED NEW: AIR CONDITIONING UNITS DUCTS WIRING PLUMBING EXHAUST SYSTEMS

FBC 104.2.5 ALTERED THE ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED NEW: ELECTRICAL WIRING FIXTURESS SWITCHES RECEPTACLES BREAKER PANELS NEW SERVICE

FBC 704.3

TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.

ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.

ULDR 47-20.13.E INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRES A FRENCH DRAIN STORMWATER SYSTEM TO BE INSTALLED IN THE SWALE.

CASE NO: CE05100394 CASE ADDR: 736 NE 13 CT # 15 OWNER: SUN RAY INVESTMENTS INC INSPECTOR: ROBERT A PIGNATARO VIOLATIONS: FBC 104.1 ALTERED THIS EIGHT (8) UNIT BUILDING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED: FENCING DOORS WINDOWS BRICK PAVERS CABINETS

FBC 105.4 THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS AND WITHOUT IN-SPECTIONS. DRYWALL WAS INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS

Page 65

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 1:00 PM

ELECTRICAL WIRING WAS INSTALLED WITHOUT INBSPECTIONS. PLUMBING WAS INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPT. OF THE CITY OF FORT LAUDERDALE.

FBC 104.9.3.1

PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS. APPLICATIONS #04100464, #04100466, #04100467 AND #04100469 HAVE FAILED PLAN REVIEW AND THUS ARE NULL AND VOID

FBC 104.2.4

ALTERED THE PLUMBING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED NEW: PLUMBING FIXTURES TUBS TOILETS SINKS WATER HEATERS

FBC 2121.2.2.2

DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS.

FBC 104.2.11

INSTALLED MECHANICAL SYSTEMS INCLUDING, BUT NOT LIMITED TO:

INSTALLED NEW: AIR CONDITIONING UNITS DUCTS WIRING PLUMBING EXHAUST SYSTEMS

FBC 104.2.5

ALTERED THE ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED NEW: ELECTRICAL WIRING FIXTURES SWITCHES RECEPTACLES BREAKER PANELS NEW SERVICE

FBC 704.3

TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.

ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.

Page 66

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 1:00 PM

ULDR 47-20.13.E INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRES A FRENCH DRAIN STORMWATER SYSTEM TO BE INSTALLED IN THE SWALE. _____ CASE NO: CE05100462 CASE ADDR: 736 NE 13 CT # 16 OWNER: KANTOR, MARC A INSPECTOR: ROBERT A PIGNATARO VIOLATIONS: FBC 104.1 ALTERED THIS EIGHT (8) UNIT BUILDING TO INCLUDE, BUT NOT LIMITED TO : INSTALLED : FENCING DOORS WINDOWS BRICK PAVERS CABINETS FBC 105.4 THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS AND WITHOUT INSPECTIONS. DRYWALL WAS INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS. ELECTRICAL WIRING WAS INSTALLED WITHOUT INSPECTIONS. PLUMBING WAS INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPT. OF THE CITY OF FORT LAUDERDALE.

FBC 104.9.3.1

PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS. APPLICATIONS # 04100464, #04100466, #04100467 AND #04100469 HAVE FAILED PLAN REVIEW AND THUS ARE NULL AND VOID.

FBC 104.2.4
ALTERED THE PLUMBING TO INCLUDE, BUT NOT LIMITED TO:
 INSTALLED NEW : PLUMBING
 FIXTURES
 TUBS
 TOILETS
 SINKS
 WATER HEATERS

FBC 2121.2.2.2

DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS.

Page 67

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 1:00 PM

FBC 104.2.11 INSTALLED MECHANICAL SYSTEMS INCLUDING, BUT NOT LIMITED TO: INSTALLED NEW: AIR CONDITIONING UNITS DUCTS WIRING PLUMBING EXHAUST SYSTEMS FBC 104.2.5 ALTERED THE ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO: INSTALLED NEW: ELECTRICAL WIRING FIXTURES SWITCHES RECEPTACLES BREAKER PANELS NEW SERVICE FBC 704.3 TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING. ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REOUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING. ULDR 47-20.13.E INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRES A FRENCH DRAIN STORMWATER SYSTEM TO BE INSTALLED IN THE SWALE. _____ CASE NO: CE05100465 CASE ADDR: 736 NE 13 CT # 17 MATOCAMACHO, MIGUEL INSPECTOR: ROBERT A PIGNATARO VIOLATIONS: ULDR 47-20.13.E INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRES A FRENCH DRAIN STORMWATER SYSTEM TO BE INSTALLED IN THE SWALE. FBC 104.1 ALTERED THIS EIGHT (8) UNIT BUILDING TO INCLUDE , BUT NOT LIMITED TO : INSTALLED : FENCING DOORS WINDOWS BRICK PAVERS CABINETS

OWNER:

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 1:00 PM

FBC 105.4

THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS AND WITHOUT INSPECTIONS. DRYWALL WAS INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS. ELECTRICAL WIRING WAS INSTALLED WITHOUT INSPECTIONS. PLUMBING WAS INSTALLED WITHOUT INSPECTIONS. NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPT. OF THE CITY OF FORT LAUDERDALE.

FBC 104.9.3.1

PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS. APPLICATIONS # 04100464, #04100466, #04100467 AND #04100469 HAVE FAILED PLAN REVIEW AND THUS ARE NULL AND VOID.

FBC 104.2.4
ALTERED THIS PLUMBING TO INCLUDE, BUT NOT LIMITED TO :
 INSTALLED NEW : PLUMBING
 FIXTURES
 TUBS
 TOILETS
 SINKS

WATER HEATERS

FBC 2121.2.2.2 DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS.

FBC 104.2.11 INSTALLED MECHANICAL SYSTEMS INCLUDING, BUT NOT LIMITED TO: INSTALLED NEW: AIR CONDITIONING UNITS DUCTS WIRING PLUMBING

EXHAUST SYSTEMS

FBC 104.2.5

ALTERED THE ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO: INSTALLED NEW: ELECTRICAL WIRING FIXTURES SWITCHES RECEPTACLES BREAKER PANELS NEW SERVICE

Page 69

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 1:00 PM

FBC 704.3 TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING. ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.

CASE ADDR: 736 NE 13 CT # 18 OWNER: ROBINSON,MICHAEL INSPECTOR: ROBERT A PIGNATARO

VIOLATIONS: FBC 104.1 ALTERED THIS EIGHT (8) UNIT BUILDING TO INCLUDE , BUT NOT LIMITED TO : INSTALLED : FENCING

DOORS WINDOWS BRICK PAVERS CABINETS

FBC 105.4

THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS AND WITHOUT INSPECTIONS. DRYWALL WAS INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS. ELECTRICAL WIRING WAS INSTALLED WITHOUT INSPECTIONS. PLUMBING WAS INSTALLED WITHOUT INSPECTIONS. NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPT. OF THE CITY OF FORT LAUDERDALE.

FBC 104.9.3.1

PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS. APPLICATIONS # 04100464, #04100466, #04100467 AND #04100469 HAVE FAILED PLAN REVIEW AND THUS ARE NULL AND VOID.

FBC 104.2.4

ALTERED THIS PLUMBING TO INCLUDE, BUT NOT LIMITED TO : INSTALLED NEW : PLUMBING FIXTURES TUBS TOILETS SINKS WATER HEATERS

Page 70

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 1:00 PM

FBC 2121.2.2.2 DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS. FBC 104.2.11 INSTALLED MECHANICAL SYSTEMS INCLUDING, BUT NOT LIMITED TO: INSTALLED NEW: AIR CONDITIONING UNITS DUCTS WIRING PLUMBING EXHAUST SYSTEMS FBC 104.2.5 ALTERED THE ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO: INSTALLED NEW: ELECTRICAL WIRING FIXTURES SWITCHES RECEPTACLES BREAKER PANELS NEW SERVICE FBC 704.3 TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING. ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING. ULDR 47-20.13.E INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REOUIRES A FRENCH DRAIN STORMWATER SYSTEM TO BE INSTALLED IN THE SWALE. _____ CASE NO: CE05100471 CASE ADDR: 736 NE 13 CT # 19 OWNER: CHARLEYS COLUMBIAN LLC INSPECTOR: ROBERT A PIGNATARO VIOLATIONS: FBC 104.1 ALTERED THIS EIGHT (8) UNIT BUILDING TO INCLUDE , BUT NOT LIMITED TO : INSTALLED : FENCING DOORS WINDOWS BRICK PAVERS CABINETS

Page 71

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 1:00 PM

FBC 104.2.11
INSTALLED MECHANICAL SYSTEMS INCLUDING, BUT NOT LIMITED TO:
INSTALLED NEW: AIR CONDITIONING UNITS
DUCTS
WIRING
PLUMBING
EXHAUST SYSTEMS
FBC 104.2.4

ALTERED THIS PLUMBING TO INCLUDE, BUT NOT LIMITED TO : INSTALLED NEW : PLUMBING FIXTURES TUBS TOILETS SINKS WATER HEATERS

FBC 104.2.5

ALTERED THE ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO: INSTALLED NEW: ELECTRICAL WIRING FIXTURES SWITCHES RECEPTACLES BREAKER PANELS NEW SERVICE

FBC 104.9.3.1

PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS. APPLICATIONS # 04100464, #04100466, #04100467 AND #04100469 HAVE FAILED PLAN REVIEW AND THUS ARE NULL AND VOID.

FBC 105.4

THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS AND WITHOUT INSPECTIONS. DRYWALL WAS INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS. ELECTRICAL WIRING WAS INSTALLED WITHOUT INSPECTIONS. PLUMBING WAS INSTALLED WITHOUT INSPECTIONS. NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPT. OF THE CITY OF FORT LAUDERDALE.

FBC 2121.2.2.2

DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS.

FBC 704.3

TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.

Page 72

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 **1:00 PM**

ULDR 47-20.13.E INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRES A FRENCH DRAIN STORMWATER SYSTEM TO BE INSTALLED IN THE SWALE. ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING. _____ CE05100474 CASE NO: CASE ADDR: 736 NE 13 CT # 20 SCHIAFFINO,MIGUEL A & AUBRY, ANA T OWNER: INSPECTOR: ROBERT A PIGNATARO VIOLATIONS: FBC 104.1 ALTERED THIS EIGHT (8) UNIT BUILDING TO INCLUDE , BUT NOT LIMITED TO : INSTALLED : FENCING DOORS WINDOWS BRICK PAVERS CABINETS FBC 105.4

> THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS AND WITHOUT INSPECTIONS. DRYWALL WAS INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS. ELECTRICAL WIRING WAS INSTALLED WITHOUT INSPECTIONS. PLUMBING WAS INSTALLED WITHOUT INSPECTIONS. NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPT. OF THE CITY OF FORT LAUDERDALE.

FBC 104.9.3.1

PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS. APPLICATIONS # 04100464, #04100466, #04100467 AND #04100469 HAVE FAILED PLAN REVIEW AND THUS ARE NULL AND VOID.

FBC 104.2.4

ALTERED THIS PLUMBING TO INCLUDE, BUT NOT LIMITED TO : INSTALLED NEW : PLUMBING FIXTURES TUBS TOILETS SINKS WATER HEATERS

FBC 104.2.11 INSTALLED MECHANICAL SYSTEMS INCLUDING, BUT NOT LIMITED TO:

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 1:00 PM

INSTALLED NEW: AIR CONDITIONING UNITS DUCTS WIRING PLUMBING EXHAUST SYSTEMS

FBC 104.2.5
ALTERED THE ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO:
 INSTALLED NEW: ELECTRICAL WIRING
 FIXTURES
 SWITCHES
 RECEPTACLES
 BREAKER PANELS
 NEW SERVICE

FBC 704.3 TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.

ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.

ULDR 47-20.13.E INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRES A FRENCH DRAIN STORMWATER SYSTEM TO BE INSTALLED IN THE SWALE.

FBC 2121.2.2.2 DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS.

CASE NO: CE05100479 CASE ADDR: 736 NE 13 CT # 21 OWNER: SCHINDLER,RAY J & LACKEY, WILLIAM INSPECTOR: ROBERT A PIGNATARO

VIOLATIONS: FBC 104.1 ALTERED THIS EIGHT (8) UNIT BUILDING TO INCLUDE , BUT NOT LIMITED TO : INSTALLED : FENCING DOORS WINDOWS BRICK PAVERS CABINETS

FBC 105.4 THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS AND WITHOUT

INSPECTIONS. DRYWALL WAS INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS. ELECTRICAL WIRING WAS INSTALLED WITHOUT INSPECTIONS. PLUMBING WAS INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPT. OF THE CITY OF FORT LAUDERDALE.

FBC 104.9.3.1

PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS. APPLICATIONS # 04100464, #04100466, #04100467 AND #04100469 HAVE FAILED PLAN REVIEW AND THUS ARE NULL AND VOID.

FBC 104.2.4

ALTERED THIS PLUMBING TO INCLUDE, BUT NOT LIMITED TO : INSTALLED NEW : PLUMBING FIXTURES TUBS TOILETS SINKS WATER HEATERS

FBC 2121.2.2.2

DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS.

FBC 104.2.11

INSTALLED MECHANICAL SYSTEMS INCLUDING, BUT NOT LIMITED TO: INSTALLED NEW: AIR CONDITIONING UNITS DUCTS WIRING PLUMBING EXHAUST SYSTEMS

FBC 104.2.5 ALTERED THE ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO: INSTALLED NEW: ELECTRICAL WIRING FIXTURES SWITCHES RECEPTACLES BREAKER PANELS NEW SERVICE

FBC 704.3

TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.

ULDR 47-21.9.A.1.

THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.

Page 75

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 1:00 PM

ULDR 47-20.13.E INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRES A FRENCH DRAIN STORMWATER SYSTEM TO BE INSTALLED IN THE SWALE. _____ CASE NO: CE05100483 CASE ADDR: 736 NE 13 CT # 22 OWNER: WALKER, RONALD E INSPECTOR: ROBERT A PIGNATARO VIOLATIONS: FBC 104.1 ALTERED THIS EIGHT (8) UNIT BUILDING TO INCLUDE , BUT NOT LIMITED TO : INSTALLED : FENCING DOORS WINDOWS BRICK PAVERS CABINETS FBC 104.2.11 INSTALLED MECHANICAL SYSTEMS INCLUDING, BUT NOT LIMITED TO: INSTALLED NEW: AIR CONDITIONING UNITS DUCTS WIRING PLUMBING EXHAUST SYSTEMS FBC 104.2.4 ALTERED THIS PLUMBING TO INCLUDE, BUT NOT LIMITED TO : INSTALLED NEW : PLUMBING FIXTURES TUBS TOILETS SINKS WATER HEATERS FBC 104.2.5 ALTERED THE ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO: INSTALLED NEW: ELECTRICAL WIRING FIXTURES SWITCHES RECEPTACLES BREAKER PANELS NEW SERVICE FBC 104.9.3.1 PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS. APPLICATIONS # 04100464, #04100466, #04100467 AND #04100469 HAVE FAILED PLAN REVIEW AND THUS ARE NULL AND

VOID.

FBC 105.4

THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS AND WITHOUT INSPECTIONS. DRYWALL WAS INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS. ELECTRICAL WIRING WAS INSTALLED WITHOUT INSPECTIONS. PLUMBING WAS INSTALLED WITHOUT INSPECTIONS. NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPT. OF THE CITY OF FORT LAUDERDALE.

FBC 2121.2.2.2

DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS.

FBC 704.3 TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.

ULDR 47-20.13.E

ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.

CASE	NO:	CE0!	5100)484	1	
CASE	ADDR:	736	NE	13	СТ	#

OWNER:	JAMILA, SIDNEY		
INSPECTOR:	ROBERT	А	PIGNATARO

VIOLATIONS: FBC 104.1 ALTERED THIS EIGHT (8) UNIT BUILDING TO INCLUDE , BUT NOT LIMITED TO : INSTALLED : FENCING DOORS

23

WINDOWS BRICK PAVERS CABINETS

FBC 105.4

THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS AND WITHOUT INSPECTIONS. DRYWALL WAS INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS. ELECTRICAL WIRING WAS INSTALLED WITHOUT INSPECTIONS. PLUMBING WAS INSTALLED WITHOUT INSPECTIONS. NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPT. OF THE CITY OF FORT LAUDERDALE.

FBC 104.9.3.1

PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS. APPLICATIONS # 04100464, #04100466, #04100467 AND #04100469 HAVE FAILED PLAN REVIEW AND THUS ARE NULL AND VOID. FBC 104.2.4 ALTERED THIS PLUMBING TO INCLUDE, BUT NOT LIMITED TO : INSTALLED NEW : PLUMBING FIXTURES TUBS TOILETS SINKS WATER HEATERS FBC 2121.2.2.2 DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS. FBC 104.2.11 INSTALLED MECHANICAL SYSTEMS INCLUDING, BUT NOT LIMITED TO: INSTALLED NEW: AIR CONDITIONING UNITS DUCTS WIRING PLUMBING EXHAUST SYSTEMS FBC 104.2.5 ALTERED THE ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO: INSTALLED NEW: ELECTRICAL WIRING FIXTURES SWITCHES RECEPTACLES BREAKER PANELS NEW SERVICE FBC 704.3 TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING. ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING. ULDR 47-20.13.E INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRES A FRENCH DRAIN STORMWATER SYSTEM TO BE INSTALLED

IN THE SWALE.

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 1:00 PM

CASE NO: CE05092098 CASE ADDR: 758 NE 13 CT # 1 NEEB, VOLKMAR O & HERBERT J HOHMANN OWNER: INSPECTOR: ROBERT A PIGNATARO VIOLATIONS: FBC 104.1 ALTERED THIS BUILDING TO INCLUDE, BUT NOT LIMITED TO: INSTALLED: BRICK PAVERS FBC 2121.2.2.2 DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS. ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING. FBC 704.3 TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING. ULDR 47-20.13.E INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRES A FRENCH DRAIN STORM WATER SYSTEM TO BE INSTALLED IN THE SWALE. _____ CASE NO: CE05092100 CASE ADDR: 758 NE 13 CT # 2 BURCHETT, CHARLES OWNER: INSPECTOR: ROBERT A PIGNATARO VIOLATIONS: FBC 104.1 ALTERED THIS BUILDING TO INCLUIDE, BUT NOT LIMITED TO: INSTALLED: BRICK PAVERS FBC 2121.2.2.2 DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENING. FBC 704.3 TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING. ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.

Page 79

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 **1:00 PM**

ULDR 47-20.13.E INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRES A FRENCH DRAIN STORM WATER SYSTEM TO BE INSTALLED IN THE SWALE.

CASE NO:	CE05092106
CASE ADDR:	758 NE 13 CT # 3
OWNER:	KIELY,JOHN F
INSPECTOR:	ROBERT A PIGNATARO

VIOLATIONS: FBC 104.1 ALTERED THIS BUILDING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED: BRICK PAVERS

FBC 2121.2.2.2

DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS.

FBC 704.3

TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.

ULDR 47-21.9.A.1.

THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.

ULDR 47-20.13.E INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRES A FRENCH DRAIN STORM WATER SYSTEM TO BE INSTALLED IN THE SWALE.

CASE NO: CE05092112 CASE ADDR: 758 NE 13 CT # 4

OWNER:	KITTY,RAYMOND & MARIAN REV TR	
INSPECTOR:	ROBERT A PIGNATARO	

VIOLATIONS: FBC 104.1

ALTERED THIS BUILDING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED: BRICK PAVERS

FBC 2121.2.2.2 DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS.

Page 80

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 **1:00 PM**

FBC 704.3 TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING. ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING. ULDR 47-20.13.E INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRES A FRENCH DRAIN STORM WATER SYSTEM TO BE INSTALLED IN THE SWALE. _____ CASE NO: CE05092117 CASE ADDR: 758 NE 13 CT # 5 OWNER: IRISH, KEVIN D INSPECTOR: ROBERT A PIGNATARO VIOLATIONS: FBC 104.1 ALTERED THIS BUILDING TO INCLUDE, BUT NOT LIMITED TO: INSTALLED: BRICK PAVERS FBC 2121.2.2.2 DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS. FBC 704.3 TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING. ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING. ULDR 47-20.13.E INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REOUIRES A FRENCH DRAIN STORM WATER SYSTEM TO BE INSTALLED IN THE SWALE. _____ CASE NO: CE05092118 CASE ADDR: 758 NE 13 CT # 6 OWNER: GARCES, JOSE INSPECTOR: ROBERT A PIGNATARO VIOLATIONS: FBC 104.1 ALTERED THIS BUILDING TO INCLUDE, BUT NOT LIMITED TO: INSTALLED: BRICK PAVERS

FBC 2121.2.2.2 DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS. FBC 704.3 TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE ANOUNT OF WORK BEING DONE ON THIS BUILDING. ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING. ULDR 47-20.13.E INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRES A FRENCH DRAIN STORM WATER SYSTEM TO BE INSTALLED IN THE SWALE. _____ CASE NO: CE05092120 CASE ADDR: 758 NE 13 CT # 7 CANTOR, KIMBERLY INSPECTOR: ROBERT A PIGNATARO VIOLATIONS: FBC 104.1 ALTERED THIS BUILDING TO INCLUDE, BUT NOT LIMITED TO: INSTALLED: BRICK PAVERS FBC 2121.2.2.2 DOORS AND WINDOWS HAVE BEEN NSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS. FBC 704.3 TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING. ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING. ULDR 47-20.13.E INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRES A FRENCH DRAIN STORM WATER SYSTEM TO BE INSTALLED IN THE SWALE.

OWNER:

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 1:00 PM

	CE05100540 768 NE 13 CT ASOKA BALI EAST CONDO ASSN ROBERT A PIGNATARO
VIOLATIONS:	FBC 104.1 ALTERED THIS SIX (6) UNIT BUILDING TO INCLUDE , BUT NOT LIMITED TO : INSTALLED : FENCING BRICK PAVERS
	FBC 704.3 TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.
	FBC 105.4 THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS AND WITHOUT INSPECTIONS. DRYWALL WAS INSTALLED WITHOUT INSPECTIONS, FENCING INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS, ELECTRICAL WIRING INSTALLED WITHOUT INSPECTIONS, PLUMBING INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPT. OF THE CITY OF FORT LAUDERDALE.
	FBC 2121.2.2.2 DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS.
	ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.
	ULDR 47-20.13.E INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRES A FRENCH DRAIN STORMWATER SYSTEM TO BE INSTALLED IN THE SWALE.
OWNER:	CE05100518 768 NE 13 CT # 1 LACHIMIA,JOSEPH & ARSENAULT, RICHARD R ROBERT A PIGNATARO
VIOLATIONS:	FBC 104.1 ALTERED THIS SIX (6) UNIT BUILDING TO INCLUDE, BUT NOT LIMITED TO: INSTALLED: FENCING BRICK PAVERS

Page 82

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 1:00 PM

FBC 704.3

TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.

FBC 105.4

THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS AND WITHOUT INSPECTIONS. DRYWALL WAS INSTALLED WITHOUT INSPECTIONS, FENCING INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS. ELECTRICAL WIRING INSTALLED WITHOUT INSPECTIONS, PLUMBING INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPT. OF THE CITY OF FORT LAUDERDALE.

FBC 2121.2.2.2

DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS.

ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.

ULDR 47-20.13.E INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRES A FRENCH DRAIN STORMWATER SYSTEM TO BE INSTALLED IN THE SWALE.

CASE NO:	CE05100521
CASE ADDR:	768 NE 13 CT # 2
OWNER:	SCHAFFER, LORRAINE
INSPECTOR:	ROBERT A PIGNATARO

VIOLATIONS: FBC 104.1 ALTERED THIS SIX (6) UNIT BUILDING TO INCLUDE, BUT NOT LIMITED TO: INSTALLED: FENCING

BRICK PAVERS

FBC 2121.2.2.2

DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS.

FBC 704.3

TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.

FBC 105.4

THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS AND WITHOUT INSPECTIONS. DRYWALL WAS INSTALLED WITHOUT INSPECTIONS, FENCING INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS, ELECTRICAL WIRING INSTALLED WITHOUT INSPECTIONS, PLUMBING INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPT. OF THE CITY OF FORT LAUDERDALE.

ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.

ULDR 47-20.13.E

INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRES A FRENCH DRAIN STORMWATER SYSTEM TO BE INSTALLED IN THE SWALE.

CASE NO.	CE05100520
CASE ADDR:	768 NE 13 CT # 3
OWNER:	INFINITI ENTERPRISES LLC
INSPECTOR:	ROBERT A PIGNATARO

VIOLATIONS: FBC 104.1 ALTERED THIS SIX (6) UNIT BUILDING TO INCLUDE , BUT NOT LIMITED TO : INSTALLED : FENCING BRICK PAVERS

FBC 704.3

TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.

FBC 105.4

THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS AND WITHOUT INSPECTIONS. DRYWALL WAS INSTALLED WITHOUT INSPECTIONS, FENCING INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS, ELECTRICAL WIRING INSTALLED WITHOUT INSPECTIONS, PLUMBING INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPT. OF THE CITY OF FORT LAUDERDALE.

Page 85

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 1:00 PM

FBC 2121.2.2.2

DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS.

ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT

INCLUDING VUA LANDSCAPING IN THE FRONT

ULDR 47-20.13.E

INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRES A FRENCH DRAIN STORMWATER SYSTEM TO BE INSTALLED IN THE SWALE.

- CASE NO: CE05100528 CASE ADDR: 768 NE 13 CT # 4 OWNER: LONGWELL,JEFFREY T INSPECTOR: ROBERT A PIGNATARO
- VIOLATIONS: FBC 104.1 ALTERED THIS SIX (6) UNIT BUILDING TO INCLUDE , BUT NOT LIMITED TO : INSTALLED : FENCING BRICK PAVERS

FBC 105.4

THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS AND WITHOUT INSPECTIONS. DRYWALL WAS INSTALLED WITHOUT INSPECTIONS, FENCING INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS, ELECTRICAL WIRING INSTALLED WITHOUT INSPECTIONS, PLUMBING INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPT. OF THE CITY OF FORT LAUDERDALE.

FBC 704.3

TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.

FBC 2121.2.2.2

DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS.

Page 86

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 1:00 PM

ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING. ULDR 47-20.13.E INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRES A FRENCH DRAIN STORMWATER SYSTEM TO BE INSTALLED IN THE SWALE. CASE NO: CE05100531

CASE NO: CE05100531 CASE ADDR: 768 NE 13 C

CASE ADDR: 768 NE 13 CT # 5 OWNER: SCHINDLER,RAY J & LACKEY, WILLIAM INSPECTOR: ROBERT A PIGNATARO

VIOLATIONS: FBC 104.1 ALTERED THIS SIX (6) UNIT BUILDING TO INCLUDE , BUT NOT LIMITED TO : INSTALLED : FENCING BRICK PAVERS

FBC 704.3

TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.

FBC 105.4

THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS AND WITHOUT INSPECTIONS. DRYWALL WAS INSTALLED WITHOUT INSPECTIONS, FENCING INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS, ELECTRICAL WIRING INSTALLED WITHOUT INSPECTIONS, PLUMBING INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPT. OF THE CITY OF FORT LAUDERDALE.

FBC 2121.2.2.2 DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS.

ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING. ULDR 47-20.13.E

INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRES A FRENCH DRAIN STORMWATER SYSTEM TO BE INSTALLED IN THE SWALE.

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM-CITY HALL OCTOBER 25, 2005 1:00 PM

OWNER:	CE05100535 768 NE 13 CT # 6 STROEBEL,KIRK ROBERT A PIGNATARO
VIOLATIONS:	FBC 104.1 ALTERED THIS SIX (6) UNIT BUILDING TO INCLUDE , BUT NOT LIMITED TO : INSTALLED : FENCING BRICK PAVERS
	FBC 704.3 TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.
	FBC 105.4 THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS AND WITHOUT INSPECTIONS. DRYWALL WAS INSTALLED WITHOUT INSPECTIONS, FENCING INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS, ELECTRICAL WIRING INSTALLED WITHOUT INSPECTIONS, PLUMBING INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND

INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPT. OF THE CITY OF FORT LAUDERDALE. FBC 2121.2.2.2

DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS.

ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.

ULDR 47-20.13.E INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRES A FRENCH DRAIN STORMWATER SYSTEM TO BE INSTALLED IN THE SWALE.