FORT LAUDERDALE

CODE ENFORCEMENT BOARD HEARING AGENDA

MAY 25, 2010 9:00 AM

CITY COMMISSION MEETING ROOM - CITY HALL 100 N ANDREWS AVENUE FT. LAUDERDALE, FL 33301

CODE ENFORCEMENT BOARD

Code of Ordinances: Sec. 11-3.

PURPOSE: Hear and decide cases in which violations are alleged of any provision of the Florida Building Code, Broward County Amendments and violations of the Code of Ordinances of the City of Fort Lauderdale when alleged together with a violation of the Florida Building Code.

Note: If any person decides to appeal any decision made with respect to any matter considered at this public meeting or hearing he/she will need a record of the proceedings and for such purpose, he/she may need to ensure that a verbatim record of the proceedings is made, which record includes the testimony and evidence upon which the appeal is to be based.

Board Members: Sam Mitchell, **Chair** • Howard Nelson, **Vice Chair** • Genia Ellis • Jan Sheppard • Joan Hinton • Howard Elfman • Chad Thilborger • Paul Dooley (alternate) • Frank Marino (alternate) • Joshua Miron (alternate) • **Board Attorney:** Bruce Jolly

TWO OR MORE FORT LAUDERDALE CITY COMMISSIONERS OR MEMBERS OF A CITY OF FORT LAUDERDALE ADVISORY BOARD MAY BE IN ATTENDANCE AT THIS MEETING.

COMMUNICATION TO THE CITY COMMISSION WILL BE ADDRESSED AT THE END OF THE HEARING.

CITY OF FORT LAUDERDALE Page 1 CODE ENFORCEMENT BOARD AGENDA CITY COMMISION MEETING ROOM - CITY HALL MAY 25, 2010 - 9:00 AM

NEW BUSINESS

CASE NO: CE02100379

CASE ADDR: 1 ISLA BAHIA DR

OWNER: SRUN CONSULTANTS INC

C/O KURT BOSSHARDT & ASSOC

INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC(2007) 105.4.1

A CONCRETE FOUNTAIN HAS BEEN INSTALLED ON THE PROPERTY WITHOUT OBTAINING THE REQUIRED PERMITS.

FBC(2007) 105.4.4

PLUMBING PIPING FOR THE FOUNTAIN HAS BEEN

INSTALLED WITHOUT A PERMIT.

FBC(2007) 105.4.5

AN ELECTRICAL SUPPLY AND CONNECTION FOR THE FOUNTAIN HAS BEEN PROVIDED WITHOUT A PERMIT.

CASE NO: CE04032445

CASE ADDR: 2606 DEL MAR PL
OWNER: DELMAR HOLDINGS LTD

INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC(2007) 105.4.1

A CONCRETE BLOCK RETAINING WALL HAS BEEN CONSTRUCTED ON THE PROPERTY WITHOUT A PERMIT.

FBC(2007) 1612.1.2

A CONCRETE BLOCK RETAINING WALL WAS CONSTRUCTED

AND HAS NOT BEEN PROVEN TO BE OF SUFFICIENT

STRENGTH TO SUPPORT DEAD, LIVE, WIND AND ANY OTHER

LOADS SPECIFIED BY THE FLORIDA BUILDING CODE.

CITY OF FORT LAUDERDALE Page 2 CODE ENFORCEMENT BOARD AGENDA CITY COMMISION MEETING ROOM - CITY HALL

MAY 25, 2010 - 9:00 AM

CASE NO: CE08120179 CASE ADDR: 1045 NW 5 AVE

OWNER: DARGENSON, YVENOLINE

INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC(2007) 105.4.1

THE DUPLEX BUILDING HAS BEEN MODIFIED AND ALTERED BY CONVERTING THE TWO GARAGES INTO EFFICIENCY

SUITES WITHOUT PERMITS.

FBC(2007) 105.4.4

PLUMBING WORK WAS DONE TO PROVIDE BATHROOM AND KITCHEN FACILITIES FOR THE EFFICIENCY APARTMENTS

WITHOUT PERMITS.

FBC(2007) 105.4.5

ELECTRICAL WIRING WAS DONE TO PROVIDE BATHROOM AND KITCHEN FACILITIES FOR THE EFFICIENCY APARTMENTS WITHOUT PERMITS.

FBC(2007) 110.1.1

THE DUPLEX BUILDING HAS BEEN CHANGED FROM ITS EXISTING OCCUPANCY CLASSIFICATION WITHOUT AN APPROVAL OR THE ISSUANCE OF A CERTIFICATE OF

OCCUPANCY.

CASE NO: CE09041840
CASE ADDR: 3006 SW 15 AVE
OWNER: EILER, DAVID &
STEVENS, DONALD

INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC(2007) 105.4.18

SECTIONS OF WOOD FENCING HAVE BEEN INSTALLED ON

THE PROPERTY WITHOUT OBTAINING A PERMIT.

CASE NO: CE09062465
CASE ADDR: 3565 SW 17 ST
OWNER: GAMBRILL, SARAH

RILEY, ROBERT B & RILEY, ROBERT M

INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC(2007) 105.4.18

A WOOD FENCE HAS BEEN INSTALLED ON THE PROPERTY

WITHOUT A PERMIT.

CASE NO: CE09082031

CASE ADDR: 2400 E LAS OLAS BLVD OWNER: IDLEWOOD PLACE LLC

INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC(2007) 105.4.11

A NEW CONDENSING UNIT HAS BEEN INSTALLED WITHOUT

OBTAINING A PERMIT.

CASE NO: CE07020968

CASE ADDR: 5890 NE 22 AVE

OWNER: SANCLEMENT, ANTONIO &

TEUSCH, INGRID

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.10.3.1

THE FOLLOWING PERMIT APPLICATIONS HAVE BEEN

SUBMITTED:

1. 06040527 FOR A PRIVACY WALL.

THE FOLLOWING PERMITS WERE ISSUED, BUT NO FINAL

INSPECTION APPROVALS WERE OBTAINED:

1. 04062357 FOR WINDOWS.

2. 05021065 FOR SHUTTERS.

3. 05071398 FOR A REROOF.

CITY OF FORT LAUDERDALE Page 4 CODE ENFORCEMENT BOARD AGENDA CITY COMMISION MEETING ROOM - CITY HALL MAY 25, 2010 - 9:00 AM

CASE NO: CE08020083
CASE ADDR: 1750 NE 52 ST
OWNER: MILLER, CHRISTINE

INSPECTOR: BURT FORD

VIOLATIONS: FBC 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS, INCLUDING BUT NOT LIMITED TO:

- 1. THE FRONT DOOR WAS REPLACED. A PERMIT WAS APPLIED FOR, BUT NEVER OBTAINED.
- 2. THE KITCHEN HAS BEEN REMODELED.

FBC 105.2.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS, INCLUDING BUT NOT LIMITED TO:

1. THE KITCHEN PLUMBING HAS BEEN ALTERED.

FBC 105.2.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS, INCLUDING BUT NOT LIMITED TO:

1. THE KITCHEN CIRCUITRY HAS BEEN ALTERED.

CASE NO: CE08070456
CASE ADDR: 1217 NE 16 AVE

OWNER: CHARLES EDWARD MEYER TR

MEYER, CHARLES EDWARD TRSTEE

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.10.3.1

STAMPED CONCRETE DRIVEWAY PERMIT 05060540 AND GAS LINE PERMIT 02051289 EXPIRED WITHOUT HAVING OBTAINED THE REQUIRED APPROVALS IN THE ALLOWED TIME FRAME.

FBC(2007) 105.4.11

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. A CENTRAL A/C SYSTEM WAS ADDED TO UNIT 1215.

Page 5

CITY OF FORT LAUDERDALE CODE ENFORCEMENT BOARD AGENDA

CITY COMMISION MEETING ROOM - CITY HALL MAY 25, 2010 - 9:00 AM

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. CIRCUITS FOR THE CENTRAL A/C FOR UNIT 1215 WERE ADDED.

CASE NO: CE09101786

CASE ADDR: 155 ISLE OF VENICE # 303 OWNER: NATIONAL CITY MORTGAGE CO

% NATIONAL CITY MORTGAGE CO

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

1. A KITCHEN AND BATH REMODELING HAS BEEN DONE. AFTER THE FACT PERMITS WERE APPLIED FOR BUT WERE NEVER ISSUED AND HAVE BEEN VOIDED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. PIPING, FIXTURES, AND APPLIANCES HAVE BEEN INSTALLED DURING THE KITCHEN AND BATH REMODELING.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. CIRCUITS HAVE BEEN ALTERED DURING THE KITCHEN AND BATH REMODELING.

FBC(2007) 109.10

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

CITY OF FORT LAUDERDALE Page 6 CODE ENFORCEMENT BOARD AGENDA COMMISSION MEETING ROOM - CITY HALL

CITY COMMISION MEETING ROOM - CITY HALL MAY 25, 2010 - 9:00 AM

CASE NO: CE10021770

CASE ADDR: 5930 NE 18 AVE

OWNER: EIGHTEEN CYPRESS CREEK LLC

INSPECTOR: BURT FORD

VIOLATIONS: 47-19.4.D.1.

ALL RESIDENTIAL PROPERTIES OF THREE(3) OR MORE UNITS AND ALL BUSINESS AND INDUSTRIAL PROPERTIES, WHICH ELECT TO USE BULK CONTAINERS, SHALL PROVIDE AN ON-SITE ENCLOSURE FOR BULK CONTAINERS OR WASTE

RECEPTACLES, EXCEPT AS PROVIDED HEREIN.

FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

1. A WOODEN DUMPSTER ENCLOSURE HAS BEEN BUILT ON THE NORTH SIDE OF THE BUILDING.

FBC(2007) 109.10

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

THE WOODEN DUMPSTER ENCLOSURE HAS NOT BEEN PROVEN TO SUFFICIENTLY WITHSTAND ESTIMATED OR ACTUAL IMPOSED DEAD, LIVE, WIND, OR ANY OTHER LOADS THROUGH THE PERMIT AND INSPECTION PROCESS.

CASE NO: CE08120473

CASE ADDR: 1029 W BROWARD BLVD OWNER: BAKER, JAMIE R &

BAKER, JOHN H

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC 105.1

1. PARCEL CONVERTED INTO A PARKING LOT WITHOUT THE PROPER PERMITS AND REQUIREMENTS FROM THE BUILDING AND ZONING DEPARTMENT.

2. A CHAINLINK FENCE WAS INSTALLED ON THE NORTH SIDE OF THE LOT WITH AN APPLIED PERMIT #09110976 ONLY FROM NOVEMBER 17, 2009.

CITY OF FORT LAUDERDALE Page 7 CODE ENFORCEMENT BOARD AGENDA CITY COMMISION MEETING ROOM - CITY HALL MAY 25, 2010 - 9:00 AM

CASE NO: CE09031083

CASE ADDR: 949 PENNSYLVANIA AVE
OWNER: ORNATOWSKI, MALGORZATA &

ORNATOWSKI, ZBIGNIEW

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

- 1. RENOVATIONS IN THE KITCHEN AND BATHROOMS WITH NEW CABINETS AND FIXTURES.
- 2. SLIDING GLASS DOORS WERE REPLACED WITH NEW GLASS DOORS.
- 3. A GAS WATER HEATER WAS INSTALLED OR REPLACED.
- 4. ENTRANCE DOORS WERE REPLACED AND NEW WINDOWS WERE INSTALLED.
- 5. THREE MINI SPLIT CENTRAL A/C'S WERE INSTALLED.
- 6. PAVERS FOR DRIVEWAY AND WALKWAYS WERE PLACED.

FBC(2007) 105.4.11

THE MECHANICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. THREE MINI SPLIT CENTRAL A/C'S WERE INSTALLED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. FIXTURES FOR THE KITCHEN AND BATHROOMS WERE REPLACED.

FBC(2007) 109.10

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS THROUGH THE PERMITTING AND INSPECTION PROCESS.

FBC(2007) 1612.1.2

ALL THE WINDOWS AND DOOR INSTALLATIONS HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS.

CITY OF FORT LAUDERDALE CODE ENFORCEMENT BOARD AGENDA

CITY COMMISION MEETING ROOM - CITY HALL

MAY 25, 2010 - 9:00 AM

CASE NO: CE09092100 CASE ADDR: 3409 SW 24 CT

OWNER: DAWSON, LEONORA BLOWE

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR

INSPECTIONS:

1. SOME OF THE WINDOWS ARE BEING REPLACED.

FBC(2007) 1612.1.2

ALL THE WINDOW INSTALLATIONS HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS.

FBC(2007) 1626.1

THE NEW WINDOWS AND DOOR WITH GLASS NEED TO BE IMPACT RESISTANT OR BE PROTECTED BY AN APPROVED

HURRICANE PROTECTION SYSTEM.

CASE NO: CE09102490 CASE ADDR: 2837 SW 3 CT

OWNER: BUCHANAN, DENNIS C

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR

INSPECTIONS:

1. SOME PROPERTY WINDOWS WERE REPLACED.

FBC(2007) 1612.1.2

ALL THE WINDOWS, SHUTTERS, AND DOOR INSTALLATIONS HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING

PROCESS.

FBC(2007) 1626.1

THE NEW WINDOWS AND DOOR WITH GLASS NEED TO BE IMPACT RESISTANT OR BE PROTECTED BY AN APPROVED

HURRICANE PROTECTION SYSTEM.

Page 9 CITY OF FORT LAUDERDALE CODE ENFORCEMENT BOARD AGENDA CITY COMMISION MEETING ROOM - CITY HALL

MAY 25, 2010 - 9:00 AM

CASE NO: CE10020493

CASE ADDR: 3000 STATE ROAD 84 OWNER: VY MARINA MILE LLC

% RUDEN, MCCLOSKY, SMITH,

SCHUSTER & RUSSELL, PA

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

- 1. OFFICES ON THE FIRST AND SECOND FLOORS WERE REMODELED.
- 2. THE WINDOWS WERE REPLACED.
- 3. PLUMBING REMODELING WORK ON THE FIRST AND SECOND FLOOR BATHROOMS.

FBC(2007) 105.10.3.1

THERE ARE FIVE EXPIRED PERMITS:

- 1. ATF PLUMBING P#0210119.
- 2. ELECTRIC P#02100185.
- 3. REPLACE 25 WINDOWS P#02091349.
- 4. ATF REMODELING 1ST AND 2ND FLOOR OFFICES P#02052127.

FBC(2007) 109.10

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS THROUGH THE PERMITTING AND INSPECTION PROCESS.

CITY OF FORT LAUDERDALE CODE ENFORCEMENT BOARD AGENDA

CITY COMMISION MEETING ROOM - CITY HALL

MAY 25, 2010 - 9:00 AM

RETURN HEARING (OLD BUSINESS)

CASE NO: CE02110849 CASE ADDR: 618 NW 9 AVE OWNER: BANTON, DEXTER INSPECTOR: JORG HRUSCHKA

VIOLATIONS: FBC 11-4.6.1

PARKING AREA DOES NOT PROVIDE THE REQUIRED

HANDICAP ACCESSIBLE PARKING SPACES.

FBC 3401.6

FAILURE TO MAINTAIN THE BUILDING AND PROPERTY. VERMIN HOLES NEED TO BE SEALED. DOOR SCREEN DOES NOT CLOSE PROPERLY. LIGHT FIXTURES HAVE NO PROTECTIVE COVERS OR LENSES. EXPOSED FRAMING AT

STOREFRONT. EXPOSED ELECTRICAL WIRING. MIRROR IN

MENS ROOM NOT SECURED.

FBC 704.3.1

TENANT FIRE SEPARATION WALL (1 HOUR) WAS REMOVED.

CASE NO: CE05111570 CASE ADDR: 3051 NE 32 AVE OWNER: ANNIEOPA LLC INSPECTOR: BURT FORD

VIOLATIONS: 47-21 G.1.

A LANDSCAPE PLAN IS REQUIRED TO BE ON FILE WITH THE CITY OF FORT LAUDERDALE. THIS PLAN MUST DEMONSTRATE COMPLIANCE WITH THE 50% RETROACTIVE REOUIREMENT FOR LANDSCAPING. THIS LANDSCAPE PLAN IS NOT ON FILE WITH THE CITY OF FORT LAUDERDALE.

THE PROPERTY DOES NOT HAVE THE REQUIRED

RETROACTIVE LANDSCAPING.

FBC 105.1

- 1. ROOF STRUCTURES WERE BUILT ON THE SOUTH SIDE OF PROPERTY.
- 2. CANVAS AWNINGS WERE ERECTED.
- 3. AN AWNING STRUCTURE WAS CONVERTED INTO A STORAGE ROOM, INCLUDING, BUT NOT LIMITED TO AN ASPHALT SHINGLE ROOF, WOOD FRAME WALLS AND ROOF STRUCTURE, SEVERAL DOORS, CONCRETE FLOORS, AND INTERIOR BUILD OUT.
- 4. A WALK IN COOLER WAS INSTALLED.

CITY OF FORT LAUDERDALE Page 11 CODE ENFORCEMENT BOARD AGENDA CITY COMMISION MEETING ROOM - CITY HALL MAY 25, 2010 - 9:00 AM

- 5. A FENCE WAS CONSTRUCTED.
- 6. A TRELLIS WAS ERECTED OVER FRONT ENTRANCE.
- 7. AN A/C SUPPORT STRUCTURE WAS ERECTED.
- 8. THE FIRE SPRINKLER SYSTEM WAS ALTERED, SPRINKLER HEADS WERE ADDED.

FBC 105.2.11

1. CENTRAL A/C UNITS AND OTHER MECHANICAL SYSTEMS HAVE BEEN INSTALLED, RELOCATED AND/OR REPLACED.

FBC 105.2.4

- 1. A SINK WAS INSTALLED.
- 2. A WATER HEATER WAS INSTALLED.
- 3. THE FIRE SPRINKLER SYSTEM WAS ALTERED AND ENLARGED.

FBC 105.2.5

- 1. EXTERIOR AND INTERIOR LIGHTING AND GENERAL POWER OUTLETS.
- 2. CIRCUITS TO A/C UNITS.
- 3. CIRCUITS TO ICE MACHINES AND WALK IN COOLERS
- 4. CIRCUIT TO WATER HEATER.

FBC 109.6

WORK WAS DONE AND COVERED UP WITHOUT HAVING PASSED THE REQUIRED INSPECTIONS

FBC 1604.1

THE ROOF STRUCTURES, STORAGE AND THE A/C SUPPORT STRUCTURE ARE NOT DESIGNED AND CONSTRUCTED ACCORDING TO THE STRENGTH REQUIREMENTS FOR THE LOADS IMPOSED AND DO NO CONFORM WITH ANY BUILDING CODES PAST OR PRESENT.

CITY OF FORT LAUDERDALE Page 12 CODE ENFORCEMENT BOARD AGENDA CITY COMMISION MEETING ROOM - CITY HALL

MAY 25, 2010 - 9:00 AM

CASE NO: CE08100515

CASE ADDR: 2197 N OCEAN BLVD OWNER: BAHRAMI, ZAHRA

INSPECTOR: BURT FORD

VIOLATIONS: FBC 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. NEW ENTRY DOORS HAVE BEEN INSTALLED ON ALL OF THE ROOMS.
- 2. THE WINDOWS AT THE REAR AND SIDES OF THE ROOMS AND THE WINDOWS BELOW THE LARGE PICTURE WINDOWS IN THE FRONT OF THE ROOMS HAVE BEEN FRAMED IN AND THEN COVERED WITH INSULATION AND DRYWALL.
- 3. THE EXTERIOR OF THE WINDOW UNDER THE PICTURE WINDOW HAS BEEN COVERED ON THE OUTSIDE WITH $T-111\ WOOD$.
- 4. WALLS HAVE BEEN ALTERED IN THE REMODELED SHOWERS AND BATHROOMS.
- 5. NEW CABINETS ARE BEING INSTALLED THAT WILL HOUSE PLUMBING IN THE ROOMS OUTSIDE THE BATHROOMS.

FBC 105.2.11

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. WINDOW A/C UNITS HAVE BEEN INSTALLED.

FBC 105.2.4

THE PLUMBING SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

- 1. NEW PIPING AND FIXTURES HAVE BEEN INSTALLED IN THE BATHROOM REMODELS.
- 2. NEW SINKS AND FIXTURES ARE BEING INSTALLED IN THE ROOMS OUTSIDE OF THE BATHROOMS.

FBC 105.2.5

THE ELECTRICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. OUTLETS, SWITCHES, AND FIXTURES ARE BEING INSTALLED.

FBC 109.6

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

CITY OF FORT LAUDERDALE PA CODE ENFORCEMENT BOARD AGENDA CITY COMMISION MEETING ROOM - CITY HALL MAY 25, 2010 - 9:00 AM

FBC 1612.1.2

THE WINDOW AIR CONDITIONING UNITS, NEW ENTRY DOORS, AND FRAMED-IN WINDOWS HAVE NOT BEEN PROVEN TO SUFFICIENTLY WITHSTAND ESTIMATED OR ACTUAL IMPOSED DEAD, LIVE, WIND, OR ANY OTHER LOADS, BY THE PERMIT AND INSPECTION PROCESS.

CASE NO: CE08021545 CASE ADDR: 900 NE 26 AV

OWNER: SUNRISE INTRACOASTAL DENTAL CTR

INSPECTOR: BURT FORD

VIOLATIONS: FBC 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

1. THE ENTIRE FIRST FLOOR IS BEING REMODELED.

- 2. INTERIOR WALLS HAVE BEEN FRAMED.
- 3. DRYWALL HAS BEEN INSTALLED AND TAPED.
- 4. NEW EXTERIOR DOORS HAVE BEEN INSTALLED.

FBC 105.2.11

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. WORK HAS BEEN DONE ON THE A/C SYSTEM.

FBC 105.2.4

THE PLUMBING SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. NEW PIPING AND FIXTURES ARE BEING REPLACED IN THE REMODELED BATHROOMS AND KITCHEN.

FBC 105.2.5

THE ELECTRICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. CIRCUITS HAVE BEEN ADDED/ALTERED DURING THE FIRST FLOOR REMODELING.

FBC 106.10.3.1

THE FOLLOWING PERMITS HAVE EXPIRED:

- 1. 00021729 DEMO 800SF OF EXTERIOR WALL.
- 2. 05050161 ELECTRICAL WORK AFTER FIRE.

CITY OF FORT LAUDERDALE CODE ENFORCEMENT BOARD AGENDA

CITY COMMISION MEETING ROOM - CITY HALL MAY 25, 2010 - 9:00 AM

FBC 109.6

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REOUIRED APPROVALS.

FBC 1612.1.2

THE EXTERIOR DOORS HAVE NOT BEEN PROVEN TO SUFFICIENTLY WITHSTAND ESTIMATED OR ACTUAL IMPOSED DEAD, LIVE, WIND, OR ANY OTHER LOADS THROUGH THE PERMIT AND INSPECTION PROCESS.

CASE NO: CE07100352

CASE ADDR: 2401 NE 27 AVE

OWNER: BAC HOME LOANS SERVICING LP

% BUTLER & HOSCH PA

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS: 1. THE SECOND FLOOR REMODELING DOES NOT HAVE A PERMIT.

FBC(2007) 105.4.11

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. REMODELING HOME WITHOUT PERMITS WHICH HAVE EXPIRED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. REMODELING HOME WITHOUT PERMITS WHICH HAVE EXPIRED.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. REMODELING HOME WITHOUT PERMITS WHICH HAVE EXPIRED.

CITY OF FORT LAUDERDALE PORT CODE ENFORCEMENT BOARD AGENDA CITY COMMISION MEETING ROOM - CITY HALL MAY 25, 2010 - 9:00 AM

CASE NO: CE07031444

CASE ADDR: 2491 STATE ROAD 84 OWNER: RICHARDSON, BILL TR

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC 1012.1

SAFEGUARDS HAVE BEEN INSTALLED ON THE TOP OF THE CBS OFFICE BUILDING AND ON THE BALCONY OVERLOOKING THE SOUTH OVERWATER BAY. THE STRENGTH REQUIREMENT FOR THE SAFEGUARDS HAS NOT BEEN DEMONSTRATED THROUGH THE PERMITTING PROCESS.

FBC 1012.3

THE SAFEGUARDS INSTALLED ON THE UPPER DECK OF THE CBS OFFICE BUILDING AND ON THE BALCONY OVERLOOKING THE SOUTH OVERWATER BOAT SLIP DO NOT HAVE THE REQUIRED BALUSTERS OR PATTERN TO PREVENT AN OBJECT OF FOUR INCH DIAMETER TO PASS THROUGH AND FALL FROM THE DECK.

FBC 105.1

THE FACILITY HAS BEEN EXPANDED BY CONSTRUCTION OF BUILDINGS. EXISTING FACILITIES HAVE BEEN ALTERED AND/OR EXPANDED IN SIZE. THE REQUIRED PERMITS FOR THIS WORK WERE NOT OBTAINED. THE CONSTRUCTION, ALTERATIONS, AND EXPANSIONS INCLUDE THE FOLLOWING:

- 1. CONSTRUCTION OF A LARGE WOOD FRAMED ENCLOSURE INSIDE THE YACHT REPAIR BUILDING.
- 2. CONSTRUCTION OF A SHADE PAVILION WITH A RED STREET SIGN ON IT. THE SIGN READS "DALE EARNHART JR DR.
- 3. REMOVAL OF LARGE SECTIONS OF BLOCK WALL FROM THE WEST EXPOSURE OF THE COVERED BOAT DOCKS.
- 4. INSTALLATION OF SEVERAL SMALL ACCESSORY
 BUILDINGS ADJOINING THE WEST EXPOSURE OF THE
 COVERED BOAT DOCKS. THIS AREA HAS BEEN APPROVED
 AS A PARKING AREA.
- 5. CONSTRUCTION OF A CARPENTRY SHOP BUILDING ON THE WEST SIDE OF THE PROPERTY. THIS BUILDING IS ATTACHED TO THE SOUTH END OF AN ORIGINAL MASONRY BUILDING NOW USED AS A TOOL ROOM.
- 6. CONSTRUCTION OF A DUST COLLECTION TOWER ON THE WEST EDGE OF THE PROPERTY.
- 7. THE PLACEMENT OF FREIGHT CONTAINERS UTILIZED AS ACCESSORY BUILDINGS COMPLETE WITH ELECTRICAL POWER AND AIR CONDITIONING EQUIPMENT.
- 8. ENTRANCE GATES INSTALLED.

- 9. SAFEGUARDS INSTALLED ON THE ROOF OF THE OFFICE BUILDING.
- 10. OFFICE TRAILER INSTALLED AS A PERMANENT FACILITY COMPLETE WITH HANDICAP RAMP. THE NORTH SIDE IS AN OFFICE AND THE SOUTH SIDE IS A RESTROOM. IT IS CONSTRUCTED IN THE AREA APPROVED FOR OVERFLOW PARKING.
- 11. A ROOF STRUCTURE CONNECTING TWO MASONRY STRUCTURES ON THE WEST SIDE OF THE PROPERTY. THE BATTERY SHOP AND THE ORIGINAL SHOP ARE CONNECTED BY THIS ROOF.
- 12. A TUBE AND MEMBRANE STRUCTURE BEING USED FOR SPRAY PAINTING.
- 13. A BALCONY HAS BEEN CONSTRUCTED OVERLOOKING THE SOUTH BAY OF THE COVERED DOCKS. THE BALCONY FACES NORTH.
- 14. A DOOR HAS BEEN INSTALLED HIGH IN THE MASONRY WALL WHICH ALLOWS ACCESS TO THE BALCONY NOTED IN ITEM 13 ABOVE.
- 15. A STEEL SUPPORT SYSTEM HAS BEEN DEVISED TO SUPPORT A FREE AIR WIRING METHOD.

FBC 105.2.11

AIR CONDITIONING EQUIPMENT HAS BEEN INSTALLED THROUGHOUT THE FACILITY WITHOUT OBTAINING THE REQUIRED PERMIT. THE LOCATIONS INCLUDE, BUT ARE NOT LIMITED TO: THE MAIN OFFICE BUILDING, IN FREIGHT CONTAINERS USED AS ACCESSORY STRUCTURES, ACCESSORY SHEDS, THE OFFICE TRAILER AND THE ENCLOSURE INSIDE THE YACHT REPAIR BUILDING.

FBC 105.2.4

PLUMBING INSTALLATIONS HAVE BEEN DONE WITHOUT PERMITS. THE WORK INCLUDES:

- 1. THE PLUMBING CONNECTIONS FOR THE OFFICE TRAILER.
- 2. A MISTING SYSTEM FOR THE PAVILION.
- 3. A COMPRESSED AIR DELIVERY SYSTEM.

FBC 105.2.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN EXPANDED, ALTERED AND OR REPAIRED REPEATEDLY WITHOUT OBTAINING THE REQUIRED PERMITS. THE WORK THAT HAS NOT BEEN PERMITTED AND NOT INSPECTED AS REQUIRED INCLUDES THE FOLLOWING:

1. THE OPEN WIRING SYSTEM HAS BEEN REPAIRED/REPLACED.

CITY OF FORT LAUDERDALE F CODE ENFORCEMENT BOARD AGENDA CITY COMMISION MEETING ROOM - CITY HALL

MAY 25, 2010 - 9:00 AM

- 2. THE CARPENTER SHOP PREMISE WIRING.
- 3. ALL WIRING, FIXTURES AND OUTLETS INSTALLED IN SHEDS AND FREIGHT CONTAINERS.
- 4. ALL WIRING, FIXTURES AND OUTLETS INSTALLED IN THE LARGE FRAMED ENCLOSURE INSIDE THE YACHT REPAIR BUILDING.
- 5. ALL ELECTRICAL CONNECTIONS TO THE OFFICE TRAILER.
- 6. ALL ELECTRICAL ALTERATIONS CONNECTED TO THE INSTALLATION OF AIR CONDITIONING INSTALLED IN THE ORIGINAL CBS OFFICE.

FBC 1612.1.2

ALL THE CONSTRUCTION DONE WITHOUT PERMITS (SEE LIST SPECIFIED FOR F.B.C. 105.1) THAT IS SUBJECT TO WIND LOADING, GRAVITY LOADING AND ANY OTHER LOADING HAS NOT DEMONSTRATED THE REQUIRED STRENGTH OF MATERIAL AND DESIGN THROUGH THE PERMITTING PROCESS.

FBC-P 303.2

THE COMPRESSED AIR DELIVERY SYSTEM THAT HAS BEEN INSTALLED DOES NOT UTILIZE APPROVED PIPE. THE SYSTEM IS MADE FROM P.V.C. PIPE.

NEC 110-12(a)

ELECTRICAL EQUIPMENT IS NOT PROPERLY CONNECTED TO THE SYSTEM. MANY UNUSED OPENINGS IN THIS EQUIPMENT ARE NOT PROPERLY COVERED.

NEC 225.19(D)(1)

THE REQUIRED CLEARANCE FROM THE CONDUCTORS FASTENED TO THE WALL IS NOT PROVIDED WHERE THE DOORWAY PROVIDES ACCESS TO THE BALCONY WHICH OVERLOOKS THE COVERED BOAT SLIP ON THE SOUTH.

NEC 240.21(B)(1)(1)

THE TAP CONDUCTORS UTILIZED FOR THE OPEN FREE AIR WIRING SYSTEM ARE NOT FUSED ACCORDING TO APPROVED METHODS. THE OVER FUSING CONDITION DOES NOT PROVIDE THE DEGREE OF SAFETY REQUIRED BY THE CODE.

NEC 310.8(D)(2)

THE CONDUCTORS USED FOR THE OPEN FREE AIR WIRING SYSTEM ARE NOT APPROVED FOR THIS USE. THE CONDUCTORS ARE NOT RESISTANT TO U.V. LIGHT AS REQUIRED.

NEC 90.1 (A)

THE ELECTRICAL SYSTEM OF THE BUILDING IS NOT BEING MAINTAINED ACCORDING TO THE MINIMUM SAFETY STANDARD OF THE NATIONAL ELECTRICAL CODE. DEFICIENCIES PERVADE THE ENTIRE SYSTEM.

NEC 90.1 (B)

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN EXPANDED REPEATEDLY WITHOUT PROPER PLANNING. WIRING SYSTEMS HAVE BEEN OVERLOADED BY METHODS AND USAGE NOT IN CONFORMITY TO THE NATIONAL ELECTRICAL CODE. THIS HAS OCCURED BECAUSE THE INITIAL WIRING DID NOT PROVIDE ADEQUATELY FOR FUTURE INCREASES OF ELECTRICAL USE.

NFPA 101:39.2.4.1

TWO EXITS ARE NOT PROVIDED FROM THE 2ND FLOOR OFFICE AREA.

NFPA 1:18.2.2.5.8

FIRE LANE SIGNS ARE NOT PROVIDED CONSISTENT WITH THE CODE.

NFPA 303:2.1

NO SMOKING SIGNS ARE NOT PROVIDED IN ACCORDANCE WITH THE CODE.

NFPA 303:4.10.2

FIRE DETECTORS ARE NOT PROVIDED IN ACCORDANCE WITH THE CODE.

NFPA 303:4.3.2

AN APPROVED FIRE SPRINKLER SYSTEM IS NOT PROVIDED FOR ALL MARINA AND BOATYARD BUILDINGS IN EXCESS OF 5000 SQUARE FT.

NFPA 303:4.4.1

DOCK FIRE LINE IS NOT PROVIDED.

NFPA 303:4.5

FIRE HYDRANTS ARE NOT PROVIDED IN ACCORDANCE WITH THE CODE.

NFPA 33:5.1

TARPS, PLASTIC SHEETING AND OTHER COMBUSTIBLE MATERIALS ARE BEING USED IN THE PLACE OF A SPRAY BOOTH.

NFPA 33:6.3.1

DISPENSING, TRANSFER, MIXING AND FILLING CONTAINERS WITH FLAMMABLE LIQUIDS IS BEING DONE OUTSIDE OF MIXING ROOMS OR SPRAY AREAS.

NFPA 33:7.1

SPRAY AREAS ARE NOT PROTECTED BY AN APPROVED FIRE PROTECTION SYSTEM.

CASE NO: CE07060475 CASE ADDR: 1380 SW 34 AV

OWNER: RODRIGUEZ, BERNARDO &

MOREIRA, MARENA

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

- 1. THERE ARE TWO ROOM ADDITIONS THAT WERE DONE ILLEGALLY, ONE BETWEEN 2005 AND 2007 AND THE OTHER BETWEEN 2007 AND 2009.
- 2. THE FRONT PORCH AND CARPORT JOIST WERE REPLACED AND COVERED WITH DRYWALL WORK WAS BETWEEN 2007 AND 2009.
- 3. WINDOWS AND DOORS WERE INSTALLED ON THE ADDITIONS.

FBC 105.2.11

THE MECHANICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. THERE IS A CENTRAL A/C WITH DUCT WORK AND ELECTRIC HEATER.
- 2. KITCHEN AND BATHROOM(S) VENTILATIONS.

FBC 105.2.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. KITCHEN AND BATHROOM(S) FIXTURES WERE REPLACED, AND PLUMBING LINES WERE ADDED TO THE ADDITIONS.

FBC 105.2.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

CITY OF FORT LAUDERDALE CODE ENFORCEMENT BOARD AGENDA CITY COMMISION MEETING ROOM - CITY HALL MAY 25, 2010 - 9:00 AM

- 1. ELECTRICAL LOAD DEMAND WAS INCREASED BY ADDING ADDITIONAL LIGHTS AND WALL OUTLETS IN THE ADDITIONS THAT HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED AMPERAGE LOADING THROUGH THE PERMITTING PROCESS.
- 2. ELECTRICAL SUPPLY TO THE A/C WITH ELECTRIC HEATER.

FBC 109.6

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REOUIRED APPROVALS THROUGH THE PERMITTING AND INSPECTION PROCESS.

FBC 1604.1

THE STRUCTURES FOR THE TWO ADDITIONS, FRONT PORCH AND CARPORT DO NOT MEET THE STANDARD FOR GRAVITY LOADING AND HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS.

FBC 1612.1.2

ALL THE WINDOWS AND DOOR INSTALLATIONS HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS.

CASE NO: CE07070192 CASE ADDR: 1231 NW 18 CT

OWNER: SPANN, GWENDOLYN EST

INSPECTOR: GEORGE OLIVA

VIOLATIONS: 25-13

PERMIT REQUIRED TO CONSTRUCT PAVED DRIVEWAY OR PARKING STRIP ADJACENT TO STREET. BEFORE ANY PERSON SHALL BE PERMITTED TO CONSTRUCT A ROCK OR PAVED DRIVEWAY OR PARKING STRIP ADJACENT TO THE PAVEMENT ON ANY OF THE PUBLIC STREETS, AVENUES OR BOULEVARDS IN THE CITY, PERMISSION FOR SUCH

CONSTRUCTION SHALL BE OBTAINED.

FBC 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

- 1. WORK WITHOUT A PERMIT FOR DRIVEWAY ON THE WEST
- 2. FENCE ON THE FRONT WITH TWO GATES.

CITY OF FORT LAUDERDALE Page 21 CODE ENFORCEMENT BOARD AGENDA CITY COMMISION MEETING ROOM - CITY HALL

MAY 25, 2010 - 9:00 AM

CASE NO: CE07110906 CASE ADDR: 1132 NW 5 CT

OWNER: MCCULLOUGH, JOHNNY

HALL, ODESSA

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

- 1. WINDOWS AND THE FRONT DOORS WERE REPLACED.
- 2. THERE ARE TWO CENTRAL A/C'S THAT REPLACED THE WALL UNITS.
- 3. INTERIOR REMODELING WORK INCLUDING ELECTRICAL, PLUMBING, AND DRYWALL.
- 4. NEW CHAIN LINK FENCE.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. THERE ARE NEW PIPES AND PLUMBING CONNECTIONS IN THE KITCHENS AND BATHROOMS. FIXTURES WERE REPLACED.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. ELECTRICAL LOAD DEMAND WAS INCREASED BY ADDING TWO ADDITIONAL CENTRAL A/C'S WITH ELECTRICAL HEATER, PLUS LIGHTS AND WALL OUTLETS THAT HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED AMPERAGE LOADING THROUGH THE PERMITTING PROCESS.

FBC(2007) 109.10

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS THROUGH THE PERMITTING AND INSPECTION PROCESS.

FBC(2007) 1612.1.2

ALL THE WINDOWS AND DOOR INSTALLATIONS HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS.

Page 22

CITY OF FORT LAUDERDALE Page CODE ENFORCEMENT BOARD AGENDA CITY COMMISION MEETING ROOM - CITY HALL MAY 25, 2010 - 9:00 AM

FBC(2007) 1626.1

THE NEW WINDOWS AND DOOR WITH GLASS NEED TO BE IMPACT RESISTANT OR BE PROTECTED BY AN APPROVED HURRICANE PROTECTION SYSTEM.

CASE NO: CE08100511
CASE ADDR: 1211 NW 12 ST
OWNER: WARNER, PAUL
INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC 105.1

THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING THE REQUIRED PERMITS. THE ALTERATIONS INCLUDE:

- 1. THE ENCLOSURE OF THE FLORIDA ROOM BUILT IN 1960.
- 2. THE REMOVAL AND REPLACEMENT OF THE WINDOWS.
- 3. RE-ROOF OF THE BUILDING.
- 4. REMOVAL OF THE WINDOW LOOKING INTO THE CARPORT AND THE INSTALLATION OF A FIREPLACE AT THIS LOCATION.

FBC 105.2.11

A CENTRAL AIR CONDITIONING SYSTEM HAS BEEN INSTALLED IN THE BUILDING WITHOUT OBTAINING THE REQUIRED PERMIT.

FBC 105.2.4

THE PLUMBING SYSTEM HAS BEEN EXPANDED BY THE INSTALLATION OF A WASTE PIPE AND VENT PIPE ON THE REAR OF THE BUILDING.

FBC 105.2.5

THE ELECTRICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING THE REQUIRED PERMITS. THE ALTERATIONS INCLUDE THE EXPANSION OF THE SYSTEM BY ADDED CIRCUITS TO POWER THE CENTRAL AIR CONDITIONING SYSTEM AND POWER SUPPLY THROUGH THE WALL FOR THE SOUTHEAST BEDROOM.

FBC 1612.1.2

THE WINDOWS THAT HAVE BEEN INSTALLED HAVE NOT DEMONSTRATED THE RESISTANCE TO WIND LOADING THAT IS REQUIRED IN A HIGH VELOCITY HURRICANE ZONE.

CITY COMMISION MEETING ROOM - CITY HALL
MAY 25, 2010 - 9:00 AM

FBC 1626.1

THE WALLS AND WINDOWS THAT HAVE BEEN
CONSTRUCTED/INSTALLED HAVE NOT DEMONSTRATED
COMPLIANCE WITH THE REQUIRED RESISTANCE TO IMPACT
FROM WINDBORNE DEBRIS. THIS REQUIREMENT IS
ADDRESSED WHEN A PERMIT IS APPLIED FOR. A SHUTTER
SYSTEM HAS NOT BEEN PROVIDED AND THE WINDOWS ARE
NOT IMPACT RESISTANT.

CASE NO: CE09020950
CASE ADDR: 210 SW 29 AV
OWNER: PAUL, OMINIGUE
INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

- 1. WINDOWS AND FRONT DOOR WERE REPLACED.
- 2. THERE IS STUCCO WORK BEING DONE.

FBC 105.2.11

THE MECHANICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. A CENTRAL A/C WAS INSTALLED WITH DUCT WORK AND ELECTRIC HEATERS.

FBC 105.2.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. ELECTRICAL LOAD DEMAND WAS INCREASED BY ADDING A CENTRAL A/C WITH ELECTRIC HEATERS, ADDITIONAL LIGHTS AND WALL OUTLETS THAT HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED AMPERAGE LOADING THROUGH THE PERMITTING PROCESS.

FBC 109.6

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS THROUGH THE PERMITTING AND INSPECTION PROCESS.

CITY OF FORT LAUDERDALE F CODE ENFORCEMENT BOARD AGENDA CITY COMMISION MEETING ROOM - CITY HALL

MAY 25, 2010 - 9:00 AM

FBC 1612.1.2

ALL THE WINDOWS, SHUTTERS AND DOOR INSTALLATIONS HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS.

FBC 1626.1

THE NEW WINDOWS AND DOOR WITH GLASS NEED TO BE IMPACT RESISTANT OR BE PROTECTED BY AN APPROVED HURRICANE PROTECTION SYSTEM.

CASE NO: CE08020172 CASE ADDR: 3221 SW 20 CT

OWNER: HSBC BANK USA TRSTEE

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS, INCLUDING BUT NOT LIMITED TO: 1. THE KITCHEN AND BATHS WERE REMODELED AFTER A

- FIRE.
 2. WINDOWS AND THE FRONT DOOR WERE REPLACED AFTER
- THE FIRE.

 3. FIRE DAMAGED STRUCTURAL COMPONENTS ON THE ROOF TRUSS (DUE TO A FIRE ON SEPT 15, 2004) WERE REPAIRED, AND INTERIOR PARTITIONS.

FBC 105.2.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. THE GENERAL ELECTRICAL SYSTEM HAS BEEN ALTERED. CIRCUITS WERE REPAIRED OR REPLACED AFTER THE FIRE.

FBC 109.6

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS THROUGH THE PERMITTING AND INSPECTION PROCESS.

FBC 1604.1

THE STRUCTURE FOR THE ROOF TRUSS AND SUPPORTING WALLS DOES NOT MEET THE STANDARD FOR GRAVITY LOADING AND HAS NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS AFTER THE FIRE.

Page 25

CITY OF FORT LAUDERDALE Page CODE ENFORCEMENT BOARD AGENDA CITY COMMISION MEETING ROOM - CITY HALL MAY 25, 2010 - 9:00 AM

CASE NO: CE09031524

CASE ADDR: 1009 NW 5 ST

OWNER: SPARKS, STEPHEN

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

- 1. FIRE RECOVERY WORK HAS BEEN DONE WITHOUT PERMITS. STOP WORK ORDER WAS ISSUED.
- 2. KITCHEN AND BATHROOM AREAS ARE BEING REPAIRED.
- 3. DAMAGED DRYWALL WAS REPLACED IN THE CELLING AND WALLS.
- 4. ALL THE WINDOWS ARE BEING REPLACED.

FBC(2007) 105.4.11

THE MECHANICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. CENTRAL A/C AND DUCT WORK. BATHROOM VENTILATIONS WERE DAMAGED BY FIRE.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. THE KITCHEN AND BATHROOM FIXTURES ARE BEING REPLACED.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. ELECTRICAL CIRCUITS ARE BEING REPLACED OR REPAIRED AFTER A FIRE DESTROYED THE INTERIOR OF THE PROPERTY.

FBC(2007) 109.10

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS THROUGH THE PERMITTING AND INSPECTION PROCESS.

CITY OF FORT LAUDERDALE Page 26 CODE ENFORCEMENT BOARD AGENDA CITY COMMISION MEETING ROOM - CITY HALL MAY 25, 2010 - 9:00 AM

FBC(2007) 1604.1

THE STRUCTURES THAT WERE REPAIRED FOR THE ROOF TRUSS AFTER THE FIRE DOES NOT MEET THE STANDARD FOR GRAVITY LOADING AND HAS NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS. ALL THE STRUCTURES THAT WERE DONE ILLEGALLY ARE UNSAFE AND THEY MUST BE REMOVED.

FBC(2007) 1612.1.2

ALL THE WINDOWS AND DOOR INSTALLATIONS HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS.

FBC(2007) 1626.1

THE NEW WINDOWS AND DOOR WITH GLASS NEED TO BE IMPACT RESISTANT OR BE PROTECTED BY AN APPROVED HURRICANE PROTECTION SYSTEM.

CASE NO: CE04061463 CASE ADDR: 3081 HARBOR DR OWNER: RAJ HOTELS LLC INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC(2007) 105.1

- 1. THE PARKING LOT HAS BEEN RESURFACED AND RESTRIPED WITHOUT A PERMIT.
- 2. THE DESIGNATED HANDICAPPED SPACE DOES NOT CONFORM TO THE REQUIREMENTS OF CHAPTER 11 OF THE FLORIDA BUILDING CODE.

FBC(2007) 105.4.7

A REQUIRED HANDICAP PARKING SIGN HAS BEEN REMOVED.

FBC(2007) 11-4.6.4

THE HANDICAP SIGN HAS BEEN REMOVED FROM THE DESIGNATED HANDICAPPED PARKING SPACE ALLOWING COMMON PARKING TO OCCUR.

CITY OF FORT LAUDERDALE Page 27 CODE ENFORCEMENT BOARD AGENDA

CITY COMMISION MEETING ROOM - CITY HALL MAY 25, 2010 - 9:00 AM

CASE NO: CE08050335

CASE ADDR: 1061 NW 25 AVE

OWNER: LINDER, JERON F JR

INSPECTOR: GERRY SMILEN

VIOLATIONS: 9-280(b)

THE FOLLOWING BUILDING COMPONENTS HAVE BEEN

INSTALLED AND ARE NOT STRUCTURALLY SOUND, WEATHER

TIGHT, OR RODENT PROOF:

- 1. WINDOWS.
- 2. DOORS.
- 3. WOOD EXTERIOR WALLS.
- 4. ROOF RAFTERS.

FBC 105.1

THE SINGLE FAMILY DWELLING HAS BEEN REPAIRED AND ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. THE KITCHEN HAS BEEN REMOVED.
- 2. NEW WINDOWS AND DOORS HAVE BEEN INSTALLED.
- 3. STRUCTURAL BEAMS IN THE CARPORT HAVE BEEN REPLACED AND/OR REPAIRED.
- 4. WALL SHEATHING HAS BEEN REPLACED.
- 5. NEW 2 X 4 EXTERIOR WALLS HAVE BEEN INSTALLED.
- 6. A SCREEN PORCH HAS BEEN ENCLOSED.

FBC 105.2.4

THE FOLLOWING PLUMBING WORK HAS BEEN PERFORMED WITHOUT A PERMIT:

- 1. A NEW HOT WATER HEATER HAS BEEN INSTALLED.
- 2. PLUMBING FOR THE KITCHEN HAS BEEN DISCONNECTED FOR CABINET REMOVAL.

FBC 105.2.5

THE FOLLOWING ELECTRICAL WORK HAS BEEN DONE WITHOUT A PERMIT:

- 1. A 220 VOLT CONNECTION FOR A NEW HOT WATER HEATER.
- 2. PREMISE WIRING.
- 3. KITCHEN WIRING HAS BEEN DISCONNECTED.

FBC 1626.1

THE FOLLOWING BUILDING COMPONENTS DO NOT MEET THE IMPACT TEST CRITERIA REQUIRED FOR A HIGH VELOCITY HURRICANE ZONE:

- 1. THE ENCLOSED SCREEN PORCH.
- 2. WINDOW INSTALLATIONS.
- 3. DOOR INSTALLATION.

Page 28

CITY OF FORT LAUDERDALE CODE ENFORCEMENT BOARD AGENDA

CITY COMMISION MEETING ROOM - CITY HALL

MAY 25, 2010 - 9:00 AM

CASE NO: CE08101135 CASE ADDR: 1826 SW 29 ST

OWNER: PROVENZALE, ANTHONY &

PROVENZALE, DOMINIC

INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC 105.1

AN ADDITION AND RENOVATION WORK HAVE BEEN DONE WITHOUT PERMITS.

FBC(2007) 105.4.11

THE AIR CONDITIONING SYSTEM HAS BEEN ALTERED TO ACCOMODATE THE ADDITIONS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO:

- 1. A NEW CONDENSING UNIT HAS BEEN INSTALLED.
- 2. A NEW AIR HANDLER HAS BEEN INSTALLED.
- 3. A WALL A/C UNIT HAS BEEN INSTALLED.

FBC(2007) 105.4.4

THE PLUMBING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO:

- 1. INSTALLATION OF NEW BATHROOM FIXTURES.
- 2. RELOCATION OF A HOT WATER HEATER.
- 3. RELOCATION OF A WASHING MACHINE.
- 4. PLUMBING FOR A NEW KITCHEN.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED WITHOUT PERMITS IN THE FOLLOWING MANNER TO ACCOMODATE THE ADDITION TO THE EXISTING HOUSE INCLUDING BUT NOT LIMITED TO:

- 1. PREMISE WIRING FOR THE ADDITION.
- 2. ADDITIONAL CIRCUITRY AND CONNECTION FOR A HOT WATER HEATER.
- 3. ADDITIONAL CIRCUITRY AND CONNECTIONS FOR THE A/C SYSTEM.
- 4. ADDITIONAL CIRCUITRY AND CONNECTIONS FOR A WASHER AND DRYER.
- 5. WIRING FOR SECURITY LIGHTING.
- 6. WIRING FOR A NEW KITCHEN.

CITY OF FORT LAUDERDALE Page 29 CODE ENFORCEMENT BOARD AGENDA CITY COMMISION MEETING ROOM - CITY HALL

MAY 25, 2010 - 9:00 AM

CASE NO: CE09010920 CASE ADDR: 1904 SW 4 AVE OWNER: FORT LAUDERDALE

LEARNING CENTER LLC

INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC 105.1

THE SCHOOL BUILDING HAS BEEN ALTERED AND MODIFIED

IN THE FOLLOWING MANNER WITHOUT PERMITS:

1. A NEW KITCHEN HAS BEEN ADDED.

- 2. DRYWALL AND PARTITIONS HAVE BEEN ADDED.
- 3. BATHROOMS HAVE BEEN REMODELED.

FBC 105.2.4

PLUMBING WORK WITHOUT PERMITS WAS PERFORMED IN THE FOLLOWING MANNER:

- 1. PLUMBING FOR THE ADDED KITCHEN.
- 2. BATHROOM REMODELING.

FBC 105.2.5

ELECTRICAL WORK WAS DONE WITHOUT PERMITS IN THE FOLLOWING MANNER:

- 1. WIRING FOR THE ADDED KITCHEN.
- 2. WIRING FOR THE BATHROOM REMODELING.

CASE NO: CE09011955
CASE ADDR: 1440 SW 30 ST
OWNER: KIRKLAND, SYNDLE
INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC(2007) 105.1

THE SINGLE FAMILY DWELLING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. THE GARAGE IS ENCLOSED.
- 2. THE FRONT PORCH IS ENCLOSED.
- 3. A WOOD DECK HAS BEEN CONSTRUCTED IN THE REAR.
- 4. A WOOD FENCE GATE WIDER THAN 3 FEET HAS BEEN INSTALLED.

FBC(2007) 105.4.11

THE FOLLOWING MECHANICAL WORK HAS BEEN COMPLETED WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. A NEW CONDENSING UNIT WAS INSTALLED.
- 2. DUCT WORK FOR THE ENCLOSED GARAGE HAS BEEN INSTALLED.

CITY OF FORT LAUDERDALE Page 30 CODE ENFORCEMENT BOARD AGENDA CITY COMMISION MEETING ROOM - CITY HALL MAY 25, 2010 - 9:00 AM

FBC(2007) 105.4.4

THE FOLLOWING PLUMBING WORK HAS BEEN PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. THE IRRIGATION SYSTEM HAS BEEN ALTERED.
- 2. A NEW VANITY AND TOP HAVE BEEN INSTALLED.

FBC(2007) 105.4.5

THE FOLLOWING ELECTRICAL WORK HAS BEEN INSTALLED WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PREMISE WIRING.
- 2. NEW ELECTRICAL CONNECTION FOR A NEW CONDENSING
- 3. NEW ELECTRICAL CONNECTION FOR THE IRRIGATION SYSTEM.
- 4. EXTERIOR LIGHTING.

CASE NO: CE09011970 CASE ADDR: 1133 SW 5 PL OWNER: ACREE, BARBARA INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC(2007) 105.4.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT PERMITS INCLUDING BUT NOT LIMITED

- 1. A CARPORT HAS BEEN ENCLOSED.
- 2. NEW DOORS HAVE BEEN INSTALLED.
- 3. NEW WINDOWS HAVE BEEN INSTALLED.

FBC(2007) 105.4.4

PLUMBING FOR A BATHROOM AND KITCHEN HAS BEEN COMPLETED WITHOUT A PERMIT.

FBC(2007) 105.4.5

ELECTRICAL PREMISE WIRING WAS COMPLETED WITHOUT OBTAINING A PERMIT.

FBC(2007) 1612.1.2

THE WINDOW AIR CONDITIONING UNITS HAVE NOT BEEN PROVEN TO SUFFICIENTLY WITHSTAND ESTIMATED OR ACTUAL IMPOSED DEAD, LIVE, WIND, OR ANY OTHER LOADS THROUGH THE PERMIT AND INSPECTION PROCESS.

CITY OF FORT LAUDERDALE Page 31 CODE ENFORCEMENT BOARD AGENDA CITY COMMISION MEETING ROOM - CITY HALL

MAY 25, 2010 - 9:00 AM

CASE NO: CE09031279 CASE ADDR: 721 SW 8 TER

OWNER: G 4 A HOLDINGS CORP

INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC(2007) 105.10.3.5

THE TWO STORY DUPLEX REMAINS INCOMPLETE WITH THE

FOLLOWING PERMITS THAT HAVE EXPIRED:

1. 07052447.

2. 07052514.

3. 07052515.

4. 07052517.

5. 07052518.

FBC(2007) 3306.4

THE PROPERTY IS NOT SUFFICIENTLY PROTECTED FROM PEDESTRIAN TRAFFIC AND POSES A LIFE SAFETY ISSUE.

CASE NO: CE09072678
CASE ADDR: 1109 NW 19 ST

OWNER: SOUFFRANT, SONIA &

DORELIEN, WILKY

INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC(2007) 105.4.4

THE FOLLOWING PLUMBING WORK HAS BEEN COMPLETED

WITHOUT OBTAINING THE REQUIRED PERMITS:

1. A FULL BATHROOM HAS BEEN INSTALLED IN THE GARAGE.

2. A WATER HEATER HAS BEEN INSTALLED IN THE GARAGE.

FBC(2007) 105.1

THE SINGLE FAMILY DWELLING HAS HAD THE FOLLOWING WORK COMPLETED WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. NEW FRONT DOOR INSTALLED.
- 2. NEW WINDOWS INSTALLED.
- 3. SECURITY BARS INSTALLED ON WINDOWS.
- 4 AN EFFICIENCY APARTMENT IN THE GARAGE.

FBC(2007) 105.4.5

THE FOLLOWING ELECTRICAL WORK HAS BEEN COMPLETED WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. AN ELECTRICAL CIRCUIT AND CONNECTION WAS COMPLETED FOR A WATER HEATER.
- 2. ELECTRICAL WIRING WAS INSTALLED FOR A BATHROOM.

CITY OF FORT LAUDERDALE Page 32 CODE ENFORCEMENT BOARD AGENDA CITY COMMISION MEETING ROOM - CITY HALL MAY 25, 2010 - 9:00 AM

FBC(2007) 110.1.1

THE OCCUPANCY OF THE SINGLE FAMILY DWELLING HAS BEEN CHANGED TO A DUPLEX BY CONVERTING THE GARAGE INTO AN EFFICIENCY APARTMENT. A CERTIFICATE OF OCCUPANCY REVISING THE CLASSIFICATION AND USE FROM A SINGLE FAMILY HOME TO A DUPLEX WAS NOT ISSUED.

CITY OF FORT LAUDERDALE CODE ENFORCEMENT BOARD AGENDA CITY COMMISION MEETING ROOM - CITY HALL MAY 25, 2010 - 9:00 AM

HEARING TO IMPOSE FINES

CHAPTER 11, FORT LAUDERDALE CODE OF ORDINANCES

CASE NO: CE09020331

CASE ADDR: 361 DELAWARE AVE OWNER: WRIGHT, JAMES R INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

- 1. WINDOWS AND THE FRONT DOOR HAVE BEEN REPLACED. HURRICANE SHUTTERS WERE INSTALLED IN SOME OF THE OPENINGS.
- 2. NEW CENTRAL A/C WAS INSTALLED WITH DUCT WORK AND AN ELECTRICAL HEATER.
- 3. INTERIOR REMODELLING WORK IN KITCHEN AND BATHROOM AREA.

FBC 105.2.11

THE MECHANICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. CENTRAL A/C WAS INSTALLED WITH DUCT WORK AND AN ELECTRICAL HEATER.

FBC 105.2.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. KITCHEN AND BATHROOMS FIXTURES HAVE BEEN REPLACED.

FBC 105.2.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. ELECTRICAL LOAD DEMAND WAS INCREASED BY REPLACING OR ADDING ADDITIONAL LIGHTS AND WALL OUTLETS THAT HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED AMPERAGE LOADING THROUGH THE PERMITTING PROCESS.
- 2. POWER SUPPLIED TO THE A/C WITH A ELECTRIC HEATER.

CITY OF FORT LAUDERDALE PER CODE ENFORCEMENT BOARD AGENDA CITY COMMISION MEETING ROOM - CITY HALL MAY 25, 2010 - 9:00 AM

FBC 109.6

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS THROUGH THE PERMITTING AND INSPECTION PROCESS.

FBC 1612.1.2

ALL THE WINDOWS, SHUTTERS, AND DOOR INSTALLATIONS HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS.

FBC 1626.1

THE NEW WINDOWS AND DOOR WITH GLASS NEED TO BE IMPACT RESISTANT OR BE PROTECTED BY AN APPROVED HURRICANE PROTECTION SYSTEM.

CASE NO: CE09021706
CASE ADDR: 2780 SW 3 CT
OWNER: ECKARD, JOHN E
INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

1. THE WOOD FENCE WAS REPLACED WITH A PVC FENCE.

FBC 105.2.11

THE MECHANICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. THERE IS A NEW CENTRAL A/C CONDENSOR UNIT THAT WAS INSTALLED REPLACING THE EXISTING ONE ACCORDING TO THE OWNER, BUT THERE IS NO RECORD OF ANY PERMIT TO INSTALL A CENTRAL A/C UNIT WITH DUCT WORK AND ELECTRIC HEATER ON THE PROPERTY.

FBC 105.2.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. ELECTRICAL LOAD DEMAND WAS INCREASED BY ADDING A CENTRAL A/C UNIT WITH AN ELECTRICAL HEATER THAT HAS NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED AMPERAGE LOADING THROUGH THE PERMITTING PROCESS.

CITY OF FORT LAUDERDALE CODE ENFORCEMENT BOARD AGENDA CITY COMMISION MEETING ROOM - CITY HALL MAY 25, 2010 - 9:00 AM

FBC 109.6

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REOUIRED APPROVALS THROUGH THE PERMITTING AND INSPECTION PROCESS.

FBC 1604.1

THE STRUCTURE FOR THE PVC FENCE DOES NOT MEET THE STANDARD FOR GRAVITY LOADING AND HAS NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS.

CASE NO: CE08071083 CASE ADDR: 1559 NW 10 PL OWNER: HERTZ, BRADLEY INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC 105.1

THE BUILDING HAS BEEN ALTERED/REPAIRED WITHOUT OBTAINING THE REQUIRED PERMITS. THE REPAIRS/ALTERATIONS ARE AS FOLLOWS:

- 1. NEW WINDOWS AND DOORS HAVE BEEN INSTALLED.
- 2. THE EXTERIOR WALLS HAVE BEEN RE-SURFACED WITH STUCCO.
- 3. THE BUILDING HAS BEEN RE-ROOFED.

FBC 105.2.11

A CENTRAL AIR CONDITIONING SYSTEM HAS BEEN INSTALLED WITHOUT OBTAINING THE REQUIRED PERMIT.

FBC 105.2.5

THE BUILDING HAS BEEN ALTERED ELECTRICALLY WITHOUT OBTAINING THE REQUIRED PERMITS OR ALLOWING THE PERMIT TO EXPIRE SO THAT IT IS NO LONGER VALID. THE WORK INCLUDES:

- 1. THE INSTALLATION OF A CIRCUIT TO POWER A CENTRAL AIR CONDITIONING SYSTEM.
- 2. PERMIT #05030362 FOR A SERVICE CHANGE TO A 200 AMP SERVICE HAS EXPIRED WITHOUT PASSING FINAL INSPECTION. THE PERMIT IS NULL AND VOID AND THE WORK DONE UNDER THE AUSPICES OF THIS PERMIT NOW EXISTS AS WITHOUT A PERMIT.

FBC 106.10.3.1

ELECTRICAL PERMIT # 05030362 (SERVICE CHANGE) AND BUILDING PERMIT # 06053685 (HURRICANE SHUTTERS) HAVE BOTH EXPIRED WITHOUT PASSING ALL REQUIRED FIELD INSPECTIONS.

FBC 1612.1.2

THE WINDOWS AND DOORS INSTALLED HAVE NOT DEMONSTRATED COMPLIANCE WITH THE STRENGTH REQUIREMENTS OF INSTALLATIONS IN A HIGH VELOCITY HURRICANE ZONE. COMPLIANCE SHOULD BE DEMONSTRATED THROUGH THE PERMITTING PROCESS.

FBC 1626.1

THE WINDOWS INSTALLED HAVE NOT BEEN PROVIDED WITH A SHUTTER SYSTEM. THE WINDOWS DO NOT MEET THE RESISTANCE TO IMPACT OF WINDBORNE DEBRIS REQUIREMENTS.

CASE NO: CE05120725 CASE ADDR: 1430 NW 7 ST

OWNER: GREENWICH CAPITAL LLC

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

- 1. NEW ELECTRICAL BREAKER PANEL IN THE KITCHEN WHERE A FUSE PANEL USED TO BE.
- 2. WINDOWS AND ENTRANCE DOORS WERE REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM AT THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. PLUMBING FIXTURES WERE REPLACED IN THE KITCHEN AND BATHROOM.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM AT THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. FUSE PANEL WAS REPLACED WITH BREAKERS.
- 2. THE ELECTRICAL LOAD DEMAND WAS INCREASED BY ADDING ADDITIONAL LIGHTS AND WALL OUTLETS IN THE KITCHEN AREA WHICH HAS NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED AMPERAGE LOADING THROUGH THE PERMITTING PROCESS.

FBC(2007) 1612.1.2

ALL THE WINDOWS AND DOOR INSTALLATIONS HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS.

FBC(2007) 1626.1

THE NEW WINDOWS NEED TO BE IMPACT RESISTANT OR BE PROTECTED BY AN APPROVED HURRICANE PROTECTION SYSTEM.

CASE NO: CE06020654 CASE ADDR: 2828 SW 2 CT

OWNER: SAINT LOUIS, GIRONIE & MORTIMER, EDIT

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

- 1. THE CARPORT HAS BEEN ENCLOSED INTO A LIVING SPACE AND THE STRUCTURAL DAMAGE WAS REPAIRED.
- 2. WINDOWS AND THE ENTRANCE DOOR WERE REPLACED.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. ELECTRICAL LOAD DEMAND WAS INCREASED BY ADDING ADDITIONAL LIGHTS AND WALL OUTLETS IN THE ENCLOSED CARPORT THAT HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED AMPERAGE LOADING THROUGH THE PERMITTING PROCESS.

FBC(2007) 1604.1

THE STRUCTURE FOR THE CARPORT CONVERSION DOES NOT MEET THE STANDARD FOR GRAVITY LOADING AND HAS NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS. ALL THE STRUCTURES THAT WERE DONE ILLEGALLY ARE UNSAFE AND THEY MUST BE REMOVED.

CITY OF FORT LAUDERDALE PACTOR CODE ENFORCEMENT BOARD AGENDA CITY COMMISION MEETING ROOM - CITY HALL

MAY 25, 2010 - 9:00 AM

CASE NO: CE08121499
CASE ADDR: 1525 NW 14 CT
OWNER: GLASSBURN, SCOTT
INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

1. THERE WAS REMODELING WORK DONE IN THE KITCHEN, BATHROOM AND A CENTRAL A/C WAS INSTALLED.

FBC(2007) 105.4.11

THE MECHANICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. A CENTRAL A/C WITH DUCT WORK AND ELECTRIC HEATER WAS INSTALLED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. PLUMBING FIXTURES WERE REPLACED IN THE KITCHEN AND BATHROOM.
- 2. WATER HEATER WAS REPLACED AND WATER PIPES HAS BEEN REROUTED.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. ELECTRICAL LOAD DEMAND WAS INCREASED BY ADDING A CENTRAL A/C WITH AN ELECTRICAL HEATER.
- 2. ADDITIONAL LIGHTS AND WALL OUTLETS HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED AMPERAGE LOADING THROUGH THE PERMITTING PROCESS.

CITY OF FORT LAUDERDALE CODE ENFORCEMENT BOARD AGENDA CITY COMMISION MEETING ROOM - CITY HALL MAY 25, 2010 - 9:00 AM

CASE NO: CE09061057 CASE ADDR: 430 SW 22 AV OWNER: YOUNG, ALGETHA INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 115.1.1

THE STRUCTURE FOR THE FRONT PORCH DOES NOT MEET THE STANDARD FOR GRAVITY LOADING DUE TO THE DAMAGE

SUFFERED BY THE CAR ACCIDENT AND HAS NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND

LOADING BECAUSE A SUPPORTING COLUMN IS MISSING AND

THE TIE BEAM IS CRACKING IN DIFFERENT PLACES. EMERGENCY REPAIR WAS DONE BUT NOT THROUGH THE PERMITTING PROCESS; ALL THE STRUCTURES THAT WERE DAMAGED AND THE REPAIR THAT WAS DONE ILLEGALLY ARE

UNSAFE AND THEY MUST BE REMOVED.

CASE NO: CE09080140 CASE ADDR: 1624 SW 28 WAY OWNER: MTG FINANCE LLC INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

- 1. THE PROPERTY WAS CHANGED INTO A THREE APARTMENT RENTAL.
- 2. THERE IS A CARPORT ENCLOSED INTO LIVING SPACE.
- 3. INTERIOR WALLS WERE CREATED AND SOME WERE REMOVED TO BUILD THE THREE APARTMENTS.
- 4. THERE ARE ADDITIONAL KITCHEN AREAS AND BATHROOMS THAT WERE CREATED.
- 5. THERE ARE STRUCTURAL AREAS THAT WERE BUILT OUT OF 2X4'S AND PLYWOOD THAT DO NOT MEET ANY CURRENT OR PAST CODE. THERE ARE TWO SHEDS ON THE EAST SIDE AND ONE IN THE NORTH SIDE OF THE PROPERTY.
- 6. OUTSIDE DOORS WERE INSTALLED TO MAKE ONE ENTRANCE TO ONE OF THE APARTMENTS AND ANOTHER WAS PLACED INTO THE ENCLOSED CARPORT.

FBC(2007) 105.4.11

THE MECHANICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. CENTRAL A/C PACKAGE UNIT TYPE SUPPORTING PLATFORM NOT TO CODE.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. HOT AND COLD WATER SUPPLIED TO ALL THE ILLEGAL KITCHENS, BATHROOMS AND LAUNDRY AREAS.
- 2. DRAIN LINES AND VENT STACK FROM KITCHEN AND BATHROOMS. LAUNDRY IS DRAINING GRAY WATER INTO THE GROUND.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. ELECTRICAL LOAD DEMAND WAS INCREASED BY ADDING ADDITIONAL KITCHENS, LIGHTS AND WALL OUTLETS THAT HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED AMPERAGE LOADING THROUGH THE PERMITTING PROCESS.

FBC(2007) 109.10

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS THROUGH THE PERMITTING AND INSPECTION PROCESS.

FBC(2007) 1604.1

THE STRUCTURE FOR THE CARPORT CONVERSION, SHED AND LAUNDRY DOES NOT MEET THE STANDARD FOR GRAVITY LOADING AND HAS NOT BEEN DEMONSTRATED TO WITHSTAND THE REOUIRED WIND LOADING THROUGH THE PERMITTING PROCESS.

CASE NO: CE09081461
CASE ADDR: 2009 NW 21 AVE
OWNER: TUCHOW, TYLER
INSPECTOR: GEORGE OLIVA

VIOLATIONS: 9-313(a)

HOUSE NUMBERS ARE NOT VISIBLE.

FBC(2007) 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

- 1. WINDOWS AND DOORS WERE REPLACED. THE OPENING FOR THE WINDOWS WERE REDESIGNED TO FIX THE NEW WINDOWS WITH 2X4, PLYWOOD AND STUCCO.
- 2. THE KITCHEN AND BATHROOMS WERE REMODELED; NEW CABINETS WITH NEW FIXTURES WERE REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. PLUMBING FIXTURES WERE REPLACED IN THE KITCHEN AND BATHROOMS. NEW PVC VENT PIPES WERE INSTALLED ON THE OUTSIDE WALL.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. ELECTRICAL LOAD DEMAND WAS INCREASED BY ADDING ADDITIONAL LIGHTS AND WALL OUTLETS IN THE KITCHEN AREA THAT HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED AMPERAGE LOADING THROUGH THE PERMITTING PROCESS.

FBC(2007) 1604.1

THE NEW STRUCTURES FOR THE WINDOW OPENINGS DO NOT MEET THE STANDARD FOR GRAVITY LOADING AND HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS.

FBC(2007) 1612.1.2

ALL THE WINDOWS AND DOOR INSTALLATIONS HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS.

CITY OF FORT LAUDERDALE Pa CODE ENFORCEMENT BOARD AGENDA CITY COMMISION MEETING ROOM - CITY HALL MAY 25, 2010 - 9:00 AM

FBC(2007) 1626.1

THE NEW WINDOWS AND DOOR WITH GLASS NEED TO BE IMPACT RESISTANT OR BE PROTECTED BY AN APPROVED HURRICANE PROTECTION SYSTEM.

CASE NO: CE09091113
CASE ADDR: 360 SW 30 TER
OWNER: SENEXAN, MICHEL
INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

- 1. THE WINDOWS WERE REPLACED ON THE PROPERTY.
 2. THE KITCHEN AND BATHROOMS WERE REMODELED.
- FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED BY ADDING AN ILLEGAL BATHROOM WITH ALL NEW PLUMBING FIXTURES. THE KITCHEN FIXTURES WERE ALSO REPLACED.

FBC(2007) 105.4.5

- 1. THE ELECTRICAL SYSTEM HAS BEEN ALTERED BY ADDING NEW CIRCUITS IN THE KITCHEN AND IN THE ILLEGAL BATHROOM.
- 2. THE ELECTRICAL SURGES CAUSED DAMAGE TO APPLIANCES. TENANT CALLED FPL TO CHECK PROBLEM AND WAS INFORMED BY FPL THAT THE ELECTRICAL WORK WAS IMPROPERLY REPAIRED. PER TENANT THE ELECTRICAL WORK IS CURRENTLY BEING COMPLETED BY AN UNLICENSED CONTRACTOR WITHOUT PERMITS.

FBC(2007) 1612.1.2

ALL THE WINDOWS, SHUTTERS AND DOOR INSTALLATIONS HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS.

FBC(2007) 1626.1

THE NEW WINDOWS AND DOOR WITH GLASS NEED TO BE IMPACT RESISTANT OR BE PROTECTED BY AN APPROVED HURRICANE PROTECTION SYSTEM.

CASE NO: CE09092377 CASE ADDR: 631 SW 28 AV

OWNER: TIMOTHEE, SILVANIE 1/2 INT

EXAVIER, CERVILLE

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR

INSPECTIONS:

1. THE WINDOWS AND THE FRONT DOOR WERE REPLACED.

FBC(2007) 105.4.11

THE MECHANICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. CENTRAL A/C WAS REPLACED.

FBC(2007) 1612.1.2

ALL THE WINDOWS AND DOOR INSTALLATIONS HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS.

FBC(2007) 1626.1

THE NEW WINDOWS AND DOOR WITH GLASS NEED TO BE IMPACT RESISTANT OR BE PROTECTED BY AN APPROVED HURRICANE PROTECTION SYSTEM.

CASE NO: CE09120477 CASE ADDR: 1032 NW 1 AVE

OWNER: DRAGOSLAVIC, GORAN INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

- 1. THE BUILDING HAS BEEN REPAIRED/IMPROVED WITHOUT OBTAINING THE REQUIRED BUILDING PERMIT.
- 2. THE KITCHENS OF ALL THREE APARTMENTS WERE REMODELED WITH NEW CABINETS, COUNTERS AND SINKS.

FBC(2007) 105.4.11

A NEW AIR CONDITIONING CONDENSOR HAS BEEN INSTALLED IN THE APARTMENT. A PERMIT WAS NOT ISSUED FOR THE WORK THAT WAS DONE.

MAY 25, 2010 - 9:00 AM

FBC(2007) 105.4.4

NEW KITCHEN SINKS HAVE BEEN INSTALLED IN THE PROCESS OF REMODELING THE KITCHENS OF THE THREE UNIT APARTMENT BUILDING. WATER HEATERS WERE REPLACED AND THE REQUIRED PLUMBING PERMIT WAS NOT ISSUED.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. ELECTRICAL LOAD DEMAND WAS INCREASED BY ADDING A CENTRAL A/C WITH ELECTRICAL HEATERS AND ADDITIONAL LIGHTS AND WALL OUTLETS THAT HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED AMPERAGE LOADING THROUGH THE PERMITTING PROCESS.

CASE NO: CE09011358
CASE ADDR: 1040 SW 17 ST

OWNER: MCKENNEY, KRISTOPHER J

INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC 105.1

THE FOLLOWING WORK HAS BEEN COMPLETED WITHOUT

- 1. NEW KITCHEN CABINETS AND COUNTERTOPS HAVE BEEN INSTALLED.
- 2. A SHED HAS BEEN PLACED IN THE REAR OF THE PROPERTY.
- 3. VINYL EAVES HAVE BEEN INSTALLED IN THE OVERHANGS.
- 4. NEW WINDOWS AND DOORS HAVE BEEN INSTALLED.
- 5. FASCIA BOARD HAS BEEN REPLACED.

FBC 105.2.18

1. A VINYL FENCE HAS BEEN INSTALLED AT THE REAR OF THE CARPORT WITH A GATE.

FBC 105.2.4

THE PLUMBING FOR THE NEW KITCHEN HAS BEEN DONE WITHOUT A PERMIT.

FBC 105.2.5

ELECTRICAL WORK HAS BEEN PERFORMED TO CONNECT AND COMPLETE THE NEW KITCHEN WITHOUT A PERMIT.

CITY OF FORT LAUDERDALE CODE ENFORCEMENT BOARD AGENDA CITY COMMISION MEETING ROOM - CITY HALL

MAY 25, 2010 - 9:00 AM

FBC 105.2.8

NEW AWNINGS HAVE BEEN INSTALLED ON THE SINGLE FAMILY DWELLING WITHOUT A PERMIT.

CASE NO: CE09060371 CASE ADDR: 1800 SW 10 CT OWNER: BERNSTEIN, ROBERT

% SAAVEDRA PELOSI GOODWIN & HEMAN

INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC(2007) 105.1

THE SINGLE FAMILY DWELLING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. A NEW KITCHEN HAS BEEN INSTALLED.
- 2. THE REAR PATIO HAS BEEN STRUCTURALLY RENOVATED.
- 3. BATHROOMS HAVE BEEN REMODELED.
- 4. DRYWALL AND FRAMING HAS BEEN REPLACED.
- 5. THE GARAGE HAS BEEN ENCLOSED.

FBC(2007) 105.4.4

THE FOLLOWING PLUMBING WORK HAS BEEN DONE WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. NEW WASTE LINES FOR THE KITCHEN REMODELING.
- 2. NEW WATER SUPPLY LINES FOR THE KITCHEN REMODELING.
- 3. A NEW KITCHEN SINK WAS INSTALLED.
- 4. NEW BATHROOM FIXTURES WERE INSTALLED.
- 5. NEW WASTE LINES WERE INSTALLED FOR THE BATHROOM REMODELING.
- 6. NEW WATER SUPPLY LINES WERE INSTALLED FOR THE BATHROOM REMODELING.

FBC(2007) 105.4.5

ALTERATIONS TO THE PREMISE WIRING AND ELECTRICAL PANEL HAVE BEEN DONE WITHOUT OBTAINING THE REQUIRED PERMITS.

CASE NO: CE07071088

CASE ADDR: 3500 VISTA PARK
OWNER: FAHEY, DANA A
INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS, INCLUDING BUT NOT LIMITED TO:

1. THE SINGLE FAMILY RESIDENCE WAS BUILT WITHOUT HAVING OBTAINED FINAL INSPECTIONS AND A VALID CERTIFICATE OF OCCUPANCY.

FBC 106.10.3.1

THE FOLLOWING PERMITS WERE VOIDED OR EXPIRED BEFORE THE FINAL INSPECTIONS WERE APPROVED THROUGH THE INSPECTION PROCESS:

- 1. 03042097, BUILDING PERMIT FOR A 2 STORY, 5 BATH SFR.
- 2. 03081918, ELECTRICAL PERMIT FOR 03042097.
- 3. 03081953, PLUMBING PERMIT FOR 03042097.
- 4. 06020837, PERMIT FOR GLASS RAILINGS.

FBC 110.1.1

THE RESIDENCE HAS BEEN OCCUPIED WITHOUT A VALID CERTIFICATE OF OCCUPANCY.

CASE NO: CE08031925 CASE ADDR: 1640 NW 25 AV OWNER: BANKS, ROBERTA

INSPECTOR: BURT FORD

VIOLATIONS: FBC 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. THE KITCHEN IS BEING REMODELED.
- 2. NEW DRYWALL WAS INSTALLED ON THE KITCHEN CEILING.
- 3. THE MASTER BATHROOM HAS BEEN REMODELED AND THE SECOND BATHROOM IS IN THE PROCESS OF BEING DONE
- 4. NEW DOORS HAVE BEEN INSTALLED.

FBC 105.2.4

THE PLUMBING SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. PLUMBING FIXTURES AND PIPING HAS BEEN ALTERED/ADDED DURING THE KITCHEN AND BATH REMODELS.

FBC 105.2.5

THE ELECTRICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATH REMODELS.
- 2. RECESSED LIGHTING WAS INSTALLED IN THE LIVING ROOM AND KITCHEN CEILINGS.
- 3. AN OUTLET WAS ADDED TO POWER THE WALL MOUNTED TELEVISION.

FBC 109.6

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

CASE NO: CE08100204 CASE ADDR: 5890 NE 21 DR OWNER: BARONE, NINO INSPECTOR: BURT FORD

VIOLATIONS: FBC 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS, INCLUDING BUT NOT LIMITED TO:

- 1. THE KITCHEN WAS REMODELED.
- 2. THE BATHS WERE REMODELED.
- 3. THE KITCHEN AREA WAS OPENED TO LIVING AREA.
- 4. A WET BAR WAS INSTALLED.
- 5. A SHED WAS INSTALLED IN THE SIDE SETBACK.

FBC 105.2.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS, INCLUDING BUT NOT LIMITED TO:

- 1. KITCHEN AND BATH FIXTURES WERE REPLACED.
- 2. PLUMBING FOR A WET BAR WAS INSTALLED.

FBC 105.2.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS, INCLUDING BUT NOT LIMITED TO:

- 1. KITCHEN AND BATH CIRCUITS WERE ALTERED AND ADDITIONAL CIRCUITS WERE INSTALLED IN KITCHEN AREA.
- 2. A LARGE NUMBER OF HI-HAT FIXTURES WERE INSTALLED IN THE LIVING/DINING AREA.
- 3. NEW CIRCUITS WERE INSTALLED FOR A WET BAR.

FBC 109.6

WORK WAS COVERED UP WITHOUT FIRST OBTAINING THE REQUIRED APPROVALS THROUGH THE PERMITTING AND INSPECTION PROCESS.