FORT LAUDERDALE

CODE ENFORCEMENT BOARD HEARING AGENDA

MARCH 22, 2011 9:00 AM

CITY COMMISSION MEETING ROOM - CITY HALL 100 N ANDREWS AVENUE FT. LAUDERDALE, FL 33301

CODE ENFORCEMENT BOARD Code of Ordinances: Sec. 11-3.

PURPOSE: Hear and decide cases in which violations are alleged of any provision of the Florida Building Code, Broward County Amendments and violations of the Code of Ordinances of the City of Fort Lauderdale when alleged together with a violation of the Florida Building Code.

Note: If any person decides to appeal any decision made with respect to any matter considered at this public meeting or hearing he/she will need a record of the proceedings and for such purpose, he/she may need to ensure that a verbatim record of the proceedings is made, which record includes the testimony and evidence upon which the appeal is to be based.

Board Members: Jan Sheppard, **Chair •** Howard Nelson, **Vice Chair •** Genia Ellis • Sam Mitchell • Joan Hinton • Howard Elfman • Chad Thilborger • Paul Dooley (alternate) • Joshua Miron (alternate) • **Board Attorney:** Bruce Jolly

TWO OR MORE FORT LAUDERDALE CITY COMMISSIONERS OR MEMBERS OF A CITY OF FORT LAUDERDALE ADVISORY BOARD MAY BE IN ATTENDANCE AT THIS MEETING.

COMMUNICATION TO THE CITY COMMISSION WILL BE ADDRESSED AT THE END OF THE HEARING.

CODE ENFORCEMENT BOARD AGENDA
CITY COMMISSION MEETING ROOM - CITY HALL

MARCH 22, 2011 - 9:00 AM

NEW BUSINESS

CASE NO: CE08080979

CASE ADDR: 3061 NE 49 ST # 01 OWNER: 3061 NE 49 STREET LLC

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

1. KITCHEN AND BATHROOMS HAVE BEEN REMODELED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. PIPING AND FIXTURES HAVE BEEN ALTERED/REPLACED DURING THE KITCHEN AND BATHROOM REMODELING.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELING.

CASE NO: CE08080981

CASE ADDR: 3061 NE 49 ST # 02

OWNER: BRAWLEY, THOMAS JR & GAIL M

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

1. KITCHEN AND BATHROOMS HAVE BEEN REMODELED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. PIPING AND FIXTURES HAVE BEEN ALTERED/REPLACED DURING THE KITCHEN AND BATHROOM REMODELING.

MARCH 22, 2011 - 9:00 AM

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELING.

CASE NO: CE08080992

CASE ADDR: 3061 NE 49 ST # 09 KLUCSERITS, DAVID J OWNER:

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS: 1. KITCHEN AND BATHROOMS HAVE BEEN REMODELED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. PIPING AND FIXTURES HAVE BEEN ALTERED/REPLACED DURING THE KITCHEN AND BATHROOM REMODELING.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELING.

CASE NO: CE09072550 CASE ADDR: 2012 NE 19 AV OWNER: GRANT, DANIEL INSPECTOR: BURT FORD

VIOLATIONS: 47-5.31.

THE AWNING STRUCTURE HAS BEEN BUILT WITHIN THE FRONT SETBACK OF 25 FEET.

FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS: 1. A LARGE SQUARE AWNING STRUCTURE HAS BEEN BUILT IN THE DRIVEWAY.

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

THE AWNING STRUCTURE HAS NOT BEEN PROVEN TO SUFFICIENTLY WITHSTAND ESTIMATED OR ACTUAL IMPOSED DEAD, LIVE, WIND, OR ANY OTHER LOADS THROUGH THE PERMIT AND INSPECTION PROCESS.

CASE NO: CE10020708

CASE ADDR: 1400 NE 56 ST # 213

OWNER: ISLES AT CORAL RIDGE DEVELOPMENT

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. WOODEN FENCES HAVE BEEN INSTALLED.
- 2. THE DOCK HAS BEEN REBUILT.
- 3. EXTERIOR DOORS HAVE BEEN REPLACED.
- 4. THE POOL BATHROOMS HAVE BEEN REMODELED.
- 5. THE PARKING LOT HAS BEEN REPAVED AND RESTRIPED.
- 6. RAILINGS HAVE BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PIPING AND FIXTURES HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELINGS INCLUDING THE BATHS LOCATED AT THE COMMUNITY POOL.
- 2. AN EXTERIOR SHOWER WAS INSTALLED/REPLACED ON THE WALL OF THE POOL BATHROOM BUILDING.

FBC(2007) 105.4.5

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING ALL OF THE KITCHEN AND BATH REMODELINGS, INCLUDING THE POOL BATHS.
- 2. MISCELLANEOUS EXTERIOR LIGHTING HAS BEEN INSTALLED.

WORK WAS COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

THE EXTERIOR DOORS, DOCK, WOOD FENCES, AND RAILINGS HAVE NOT BEEN PROVEN TO SUFFICIENTLY WITHSTAND ESTIMATED OR ACTUAL IMPOSED DEAD, LIVE, WIND, OR ANY OTHER LOADS THROUGH THE PERMIT AND INSPECTION PROCESS.

CASE NO: CE10020709

CASE ADDR: 1400 NE 56 ST # 214

OWNER: ISLES AT CORAL RIDGE DEVELOPMENT

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. WOODEN FENCES HAVE BEEN INSTALLED.
- 2. THE DOCK HAS BEEN REBUILT.
- 3. EXTERIOR DOORS HAVE BEEN REPLACED.
- 4. THE POOL BATHROOMS HAVE BEEN REMODELED.
- 5. THE PARKING LOT HAS BEEN REPAVED AND RESTRIPED.
- 6. RAILINGS HAVE BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PIPING AND FIXTURES HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELINGS, INCLUDING THE BATHS LOCATED AT THE COMMUNITY POOL.
- 2. AN EXTERIOR SHOWER WAS INSTALLED/REPLACED ON THE WALL OF THE POOL BATHROOM BUILDING.

FBC(2007) 105.4.5

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING ALL OF THE KITCHEN AND BATH REMODELINGS, INCLUDING THE POOL BATHS.
- 2. MISCELLANEOUS EXTERIOR LIGHTING HAS BEEN INSTALLED.

5

FBC(2007) 109.10

WORK WAS COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

THE EXTERIOR DOORS, DOCK, WOOD FENCES, AND RAILINGS HAVE NOT BEEN PROVEN TO SUFFICIENTLY WITHSTAND ESTIMATED OR ACTUAL IMPOSED DEAD, LIVE, WIND, OR ANY OTHER LOADS THROUGH THE PERMIT AND INSPECTION PROCESS.

CASE NO: CE10020711

CASE ADDR: 1400 NE 56 ST # 302

OWNER: ISLES AT CORAL RIDGE DEVELOPMENT

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. WOODEN FENCES HAVE BEEN INSTALLED.
- 2. THE DOCK HAS BEEN REBUILT.
- 3. EXTERIOR DOORS HAVE BEEN REPLACED.
- 4. THE POOL BATHROOMS HAVE BEEN REMODELED.
- 5. THE PARKING LOT HAS BEEN REPAVED AND RESTRIPED.
- 6. RAILINGS HAVE BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PIPING AND FIXTURES HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELINGS, INCLUDING THE BATHS LOCATED AT THE COMMUNITY POOL.
- 2. AN EXTERIOR SHOWER WAS INSTALLED/REPLACED ON THE WALL OF THE POOL BATHROOM BUILDING.

FBC(2007) 105.4.5

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING ALL OF THE KITCHEN AND BATH REMODELINGS, INCLUDING THE POOL BATHS.
- 2. MISCELLANEOUS EXTERIOR LIGHTING HAS BEEN INSTALLED.

WORK WAS COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

THE EXTERIOR DOORS, DOCK, WOOD FENCES, AND RAILINGS HAVE NOT BEEN PROVEN TO SUFFICIENTLY WITHSTAND ESTIMATED OR ACTUAL IMPOSED DEAD, LIVE, WIND, OR ANY OTHER LOADS THROUGH THE PERMIT AND INSPECTION PROCESS.

CASE NO: CE10020712

CASE ADDR: 1400 NE 56 ST # 303

OWNER: ISLES AT CORAL RIDGE DEVELOPMENT

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. WOODEN FENCES HAVE BEEN INSTALLED.
- 2. THE DOCK HAS BEEN REBUILT.
- 3. EXTERIOR DOORS HAVE BEEN REPLACED.
- 4. THE POOL BATHROOMS HAVE BEEN REMODELED.
- 5. THE PARKING LOT HAS BEEN REPAVED AND RESTRIPED.
- 6. RAILINGS HAVE BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PIPING AND FIXTURES HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELINGS, INCLUDING THE BATHS LOCATED AT THE COMMUNITY POOL.
- 2. AN EXTERIOR SHOWER WAS INSTALLED/REPLACED ON THE WALL OF THE POOL BATHROOM BUILDING.

FBC(2007) 105.4.5

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING ALL OF THE KITCHEN AND BATH REMODELINGS, INCLUDING THE POOL BATHS.
- 2. MISCELLANEOUS EXTERIOR LIGHTING HAS BEEN INSTALLED.

WORK WAS COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

THE EXTERIOR DOORS, DOCK, WOOD FENCES, AND RAILINGS HAVE NOT BEEN PROVEN TO SUFFICIENTLY WITHSTAND ESTIMATED OR ACTUAL IMPOSED DEAD, LIVE, WIND, OR ANY OTHER LOADS THROUGH THE PERMIT AND INSPECTION PROCESS.

CASE NO: CE10020714

CASE ADDR: 1400 NE 56 ST # 305

OWNER: ISLES AT CORAL RIDGE DEVELOPMENT

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. WOODEN FENCES HAVE BEEN INSTALLED.
- 2. THE DOCK HAS BEEN REBUILT.
- 3. EXTERIOR DOORS HAVE BEEN REPLACED.
- 4. THE POOL BATHROOMS HAVE BEEN REMODELED.
- 5. THE PARKING LOT HAS BEEN REPAVED AND RESTRIPED.
- 6. RAILINGS HAVE BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PIPING AND FIXTURES HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELINGS, INCLUDING THE BATHS LOCATED AT THE COMMUNITY POOL.
- 2. AN EXTERIOR SHOWER WAS INSTALLED/REPLACED ON THE WALL OF THE POOL BATHROOM BUILDING.

FBC(2007) 105.4.5

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING ALL OF THE KITCHEN AND BATH REMODELINGS, INCLUDING THE POOL BATHS.
- 2. MISCELLANEOUS EXTERIOR LIGHTING HAS BEEN INSTALLED.

WORK WAS COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

THE EXTERIOR DOORS, DOCK, WOOD FENCES, AND RAILINGS HAVE NOT BEEN PROVEN TO SUFFICIENTLY WITHSTAND ESTIMATED OR ACTUAL IMPOSED DEAD, LIVE, WIND, OR ANY OTHER LOADS THROUGH THE PERMIT AND INSPECTION PROCESS.

CASE NO: CE10020715

CASE ADDR: 1400 NE 56 ST # 306

OWNER: ISLES AT CORAL RIDGE DEVELOPMENT

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. WOODEN FENCES HAVE BEEN INSTALLED.
- 2. THE DOCK HAS BEEN REBUILT.
- 3. EXTERIOR DOORS HAVE BEEN REPLACED.
- 4. THE POOL BATHROOMS HAVE BEEN REMODELED.
- 5. THE PARKING LOT HAS BEEN REPAVED AND RESTRIPED.
- 6. RAILINGS HAVE BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PIPING AND FIXTURES HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELINGS, INCLUDING THE BATHS LOCATED AT THE COMMUNITY POOL.
- 2. AN EXTERIOR SHOWER WAS INSTALLED/REPLACED ON THE WALL OF THE POOL BATHROOM BUILDING.

FBC(2007) 105.4.5

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING ALL OF THE KITCHEN AND BATH REMODELINGS, INCLUDING THE POOL BATHS.
- 2. MISCELLANEOUS EXTERIOR LIGHTING HAS BEEN INSTALLED.

WORK WAS COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

THE EXTERIOR DOORS, DOCK, WOOD FENCES, AND RAILINGS HAVE NOT BEEN PROVEN TO SUFFICIENTLY WITHSTAND ESTIMATED OR ACTUAL IMPOSED DEAD, LIVE, WIND, OR ANY OTHER LOADS THROUGH THE PERMIT AND INSPECTION PROCESS.

CASE NO: CE10020717

CASE ADDR: 1400 NE 56 ST # 308

OWNER: ISLES AT CORAL RIDGE DEVELOPMENT

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. WOODEN FENCES HAVE BEEN INSTALLED.
- 2. THE DOCK HAS BEEN REBUILT.
- 3. EXTERIOR DOORS HAVE BEEN REPLACED.
- 4. THE POOL BATHROOMS HAVE BEEN REMODELED.
- 5. THE PARKING LOT HAS BEEN REPAVED AND RESTRIPED.
- 6. RAILINGS HAVE BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PIPING AND FIXTURES HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELINGS, INCLUDING THE BATHS LOCATED AT THE COMMUNITY POOL.
- 2. AN EXTERIOR SHOWER WAS INSTALLED/REPLACED ON THE WALL OF THE POOL BATHROOM BUILDING.

FBC(2007) 105.4.5

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING ALL OF THE KITCHEN AND BATH REMODELINGS, INCLUDING THE POOL BATHS.
- 2. MISCELLANEOUS EXTERIOR LIGHTING HAS BEEN INSTALLED.

MARCH 22, 2011 - 9:00 AM

FBC(2007) 109.10

WORK WAS COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

THE EXTERIOR DOORS, DOCK, WOOD FENCES, AND RAILINGS HAVE NOT BEEN PROVEN TO SUFFICIENTLY WITHSTAND ESTIMATED OR ACTUAL IMPOSED DEAD, LIVE, WIND, OR ANY OTHER LOADS THROUGH THE PERMIT AND INSPECTION PROCESS.

CASE NO: CE10020719

CASE ADDR: 1400 NE 56 ST # 310

OWNER: ISLES AT CORAL RIDGE DEVELOPMENT

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. WOODEN FENCES HAVE BEEN INSTALLED.
- 2. THE DOCK HAS BEEN REBUILT.
- 3. EXTERIOR DOORS HAVE BEEN REPLACED.
- 4. THE POOL BATHROOMS HAVE BEEN REMODELED.
- 5. THE PARKING LOT HAS BEEN REPAVED AND RESTRIPED.
- 6. RAILINGS HAVE BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PIPING AND FIXTURES HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELINGS, INCLUDING THE BATHS LOCATED AT THE COMMUNITY POOL.
- 2. AN EXTERIOR SHOWER WAS INSTALLED/REPLACED ON THE WALL OF THE POOL BATHROOM BUILDING.

FBC(2007) 105.4.5

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING ALL OF THE KITCHEN AND BATH REMODELINGS, INCLUDING THE POOL BATHS.
- 2. MISCELLANEOUS EXTERIOR LIGHTING HAS BEEN INSTALLED.

WORK WAS COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

THE EXTERIOR DOORS, DOCK, WOOD FENCES, AND RAILINGS HAVE NOT BEEN PROVEN TO SUFFICIENTLY WITHSTAND ESTIMATED OR ACTUAL IMPOSED DEAD, LIVE, WIND, OR ANY OTHER LOADS THROUGH THE PERMIT AND INSPECTION PROCESS.

CASE NO: CE10020720

CASE ADDR: 1400 NE 56 ST # 311

OWNER: ISLES AT CORAL RIDGE DEVELOPMENT

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. WOODEN FENCES HAVE BEEN INSTALLED.
- 2. THE DOCK HAS BEEN REBUILT.
- 3. EXTERIOR DOORS HAVE BEEN REPLACED.
- 4. THE POOL BATHROOMS HAVE BEEN REMODELED.
- 5. THE PARKING LOT HAS BEEN REPAVED AND RESTRIPED.
- 6. RAILINGS HAVE BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PIPING AND FIXTURES HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELINGS, INCLUDING THE BATHS LOCATED AT THE COMMUNITY POOL.
- 2. AN EXTERIOR SHOWER WAS INSTALLED/REPLACED ON THE WALL OF THE POOL BATHROOM BUILDING.

FBC(2007) 105.4.5

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING ALL OF THE KITCHEN AND BATH REMODELINGS, INCLUDING THE POOL BATHS.
- 2. MISCELLANEOUS EXTERIOR LIGHTING HAS BEEN INSTALLED.

WORK WAS COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

THE EXTERIOR DOORS, DOCK, WOOD FENCES, AND RAILINGS HAVE NOT BEEN PROVEN TO SUFFICIENTLY WITHSTAND ESTIMATED OR ACTUAL IMPOSED DEAD, LIVE, WIND, OR ANY OTHER LOADS THROUGH THE PERMIT AND INSPECTION PROCESS.

CASE NO: CE10020721

CASE ADDR: 1400 NE 56 ST # 312

OWNER: ISLES AT CORAL RIDGE DEVELOPMENT

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. WOODEN FENCES HAVE BEEN INSTALLED.
- 2. THE DOCK HAS BEEN REBUILT.
- 3. EXTERIOR DOORS HAVE BEEN REPLACED.
- 4. THE POOL BATHROOMS HAVE BEEN REMODELED.
- 5. THE PARKING LOT HAS BEEN REPAVED AND RESTRIPED.
- 6. RAILINGS HAVE BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PIPING AND FIXTURES HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELINGS, INCLUDING THE BATHS LOCATED AT THE COMMUNITY POOL.
- 2. AN EXTERIOR SHOWER WAS INSTALLED/REPLACED ON THE WALL OF THE POOL BATHROOM BUILDING.

FBC(2007) 105.4.5

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING ALL OF THE KITCHEN AND BATH REMODELINGS, INCLUDING THE POOL BATHS.
- 2. MISCELLANEOUS EXTERIOR LIGHTING HAS BEEN INSTALLED.

MARCH 22, 2011 - 9:00 AM

FBC(2007) 109.10

WORK WAS COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

THE EXTERIOR DOORS, DOCK, WOOD FENCES, AND RAILINGS HAVE NOT BEEN PROVEN TO SUFFICIENTLY WITHSTAND ESTIMATED OR ACTUAL IMPOSED DEAD, LIVE, WIND, OR ANY OTHER LOADS THROUGH THE PERMIT AND INSPECTION PROCESS.

CASE NO: CE10020722

CASE ADDR: 1400 NE 56 ST # 313

OWNER: ISLES AT CORAL RIDGE DEVELOPMENT

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. WOODEN FENCES HAVE BEEN INSTALLED.
- 2. THE DOCK HAS BEEN REBUILT.
- 3. EXTERIOR DOORS HAVE BEEN REPLACED.
- 4. THE POOL BATHROOMS HAVE BEEN REMODELED.
- 5. THE PARKING LOT HAS BEEN REPAVED AND RESTRIPED.
- 6. RAILINGS HAVE BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PIPING AND FIXTURES HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELINGS, INCLUDING THE BATHS LOCATED AT THE COMMUNITY POOL.
- 2. AN EXTERIOR SHOWER WAS INSTALLED/REPLACED ON THE WALL OF THE POOL BATHROOM BUILDING.

FBC(2007) 105.4.5

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING ALL OF THE KITCHEN AND BATH REMODELINGS, INCLUDING THE POOL BATHS.
- 2. MISCELLANEOUS EXTERIOR LIGHTING HAS BEEN INSTALLED.

CODE ENFORCEMENT BOARD AGENDA CITY COMMISSION MEETING ROOM - CITY HALL MARCH 22, 2011 - 9:00 AM

FBC(2007) 109.10

WORK WAS COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

THE EXTERIOR DOORS, DOCK, WOOD FENCES, AND RAILINGS HAVE NOT BEEN PROVEN TO SUFFICIENTLY WITHSTAND ESTIMATED OR ACTUAL IMPOSED DEAD, LIVE, WIND, OR ANY OTHER LOADS THROUGH THE PERMIT AND INSPECTION PROCESS.

CASE NO: CE10020723

CASE ADDR: 1400 NE 56 ST # 314

OWNER: ISLES AT CORAL RIDGE DEVELOPMENT

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. WOODEN FENCES HAVE BEEN INSTALLED.
- 2. THE DOCK HAS BEEN REBUILT.
- 3. EXTERIOR DOORS HAVE BEEN REPLACED.
- 4. THE POOL BATHROOMS HAVE BEEN REMODELED.
- 5. THE PARKING LOT HAS BEEN REPAVED AND RESTRIPED.
- 6. RAILINGS HAVE BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PIPING AND FIXTURES HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELINGS, INCLUDING THE BATHS LOCATED AT THE COMMUNITY POOL.
- 2. AN EXTERIOR SHOWER WAS INSTALLED/REPLACED ON THE WALL OF THE POOL BATHROOM BUILDING.

FBC(2007) 105.4.5

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING ALL OF THE KITCHEN AND BATH REMODELINGS, INCLUDING THE POOL BATHS.
- 2. MISCELLANEOUS EXTERIOR LIGHTING HAS BEEN INSTALLED.

CITY OF FORT LAUDERDALE CODE ENFORCEMENT BOARD AGENDA CITY COMMISSION MEETING ROOM - CITY HALL MARCH 22, 2011 - 9:00 AM

FBC(2007) 109.10

WORK WAS COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

THE EXTERIOR DOORS, DOCK, WOOD FENCES, AND RAILINGS HAVE NOT BEEN PROVEN TO SUFFICIENTLY WITHSTAND ESTIMATED OR ACTUAL IMPOSED DEAD, LIVE, WIND, OR ANY OTHER LOADS THROUGH THE PERMIT AND INSPECTION PROCESS.

CASE NO: CE10021025

CASE ADDR: 2666 E OAKLAND PARK BLVD

OWNER: EAST OAKLAND PARK ASSOCIATES LLC

INSPECTOR: BURT FORD

VIOLATIONS: 9-280(q)

COVERS ARE MISSING IN THE OLD INTERIOR BREAKER PANEL ON SOME OF THE SPARES EXPOSING WIRES.

FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. INTERIOR WALLS HAVE BEEN REMOVED AND NEW WALLS HAVE BEEN BUILT TO PARTITION THE AREA FOR A SALON.
- 2. A RECEPTION AREA HAS BEEN BUILT AT THE FRONT OF THE UNIT.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

- 1. FIXTURES HAVE BEEN INSTALLED IN THE INDIVIDUAL WORK AREAS.
- 2. A WATER HEATER HAS BEEN INSTALLED.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

- 1. CIRCUITS HAVE BEEN ADDED FOR THE INTERIOR BUILD OUT AND LIGHTING.
- 2. AN INTERIOR BREAKER PANEL HAS BEEN INSTALLED EXPANDING THE SERVICE TO THE UNIT.

CITY OF FORT LAUDERDALE Page CODE ENFORCEMENT BOARD AGENDA CITY COMMISSION MEETING ROOM - CITY HALL MARCH 22, 2011 - 9:00 AM

FBC(2007) 109.10

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

CASE NO: CE10040725 CASE ADDR: 2675 SW 6 CT

OWNER: RODRIGUEZ, MANUEL & SELVA CALVO

INSPECTOR: GEORGE OLIVA

VIOLATIONS: 25-100(a)

EXCEPT AS OTHERWISE PROVIDED IN THE CODE, NO PERSON MAY CONSTRUCT IN ANY RIGHTS-OF-WAY WITHOUT FIRST HAVING OBTAINED A PERMIT FROM THE OFFICE OF THE CITY ENGINEER.

PART OF THE SWALE IS BLOCKED BY A CHAIN BETWEEN TWO POLES.

FBC 708.3

- 1. FIRE SEPARATIONS BETWEEN RESIDENTIAL UNITS ARE NOT MAINTAINED.
- 2. THE ORIGINAL FLOOR PLAN LAYOUT OF THIS SIX APARTMENT BUILDING WAS CHANGED INTO EIGHT APARTMENTS WITHOUT PROVIDING THE REQUIRED FIRE WALLS.

FBC(2007) 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

- 1. SOME OF THE PROPERTY WINDOWS WERE REPLACED.
- 2. ENTRANCE DOORS WERE INSTALLED.
- 3. THE APPROVED FLOOR PLAN FOR THE BUILDING WAS CHANGED FROM SIX APARTMENTS TO EIGHT RENTAL UNITS.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. A PLUMBING PERMIT TO INSTALL TWO EXTRA WATER HEATERS MUST BE OBTAINED.
- 2. FIXTURES WERE REPLACED IN THE APARTMENT BATHROOMS AND KITCHEN.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. ELECTRICAL LOAD DEMAND WAS INCREASED BY ADDING TWO ADDITIONAL APARTMENTS TO THE SIX EXISTING ELECTRICAL METERS. WALL A/C UNITS, ELECTRICAL OUTLETS FOR THE COOK-TOPS AND REFRIGERATORS ARE PART OF THE EXTRA LOAD THAT HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED AMPERAGE LOADING THROUGH THE PERMITTING PROCESS.
- 2. THE ELECTRIC FOR THE TWO WATER HEATERS WAS DONE WITH A PERMIT ISSUED JUNE 24,2010 P#10061870, BUT ALLOWED TO EXPIRED JAN. 2, 2011 WITHOUT ANY INSPECTIONS.

FBC(2007) 110.1.1

THE USE AND THE OCCUPANCY OF THE BUILDING HAVE CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION WITHOUT OBTAINING THE REQUIRED CERTIFICATE OF OCCUPANCY.

THE CERTIFICATE OF OCCUPANCY #8906 ISSUED MARCH 11, 1970 WAS FOR SIX RENTALS APARTMENT, NOT EIGHT APARTMENTS AS THEY EXIST TODAY.

FBC(2007) 1612.1.2

ALL THE WINDOWS AND DOOR INSTALLATIONS HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS.

FBC(2007) 1626.1

THE NEW WINDOWS AND DOOR WITH GLASS NEED TO BE IMPACT RESISTANT OR BE PROTECTED BY AN APPROVED HURRICANE PROTECTION SYSTEM.

18

CITY COMMISSION MEETING ROOM - CITY HALL

MARCH 22, 2011 - 9:00 AM

CASE NO: CE10062442 CASE ADDR: 2440 NW 31 AVE

OWNER: HANOY HOLDINGS 8 INC

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

- 1. KITCHEN AND BATHROOMS WERE REMODELED WITH NEW FIXTURES AND CABINETS.
- 2. THE WINDOWS FACING THE SOUTH SIDE ON THE DWELLING WERE REPLACED WITH SOME TYPE OF HOMEMADE WINDOWS THAT DO NOT MEET THE FLORIDA BUILDING CODE.
- 3. THE PROPERTY IS BEING OFFERED FOR RENT AS A 4/3. BCPA HAS IT LISTED AS A 3/2. THE FLOOR PLAN HAS BEEN CHANGED.

FBC(2007) 105.4.11

THE MECHANICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. A CENTRAL A/C WAS INSTALLED WITH ELECTRIC HEATER AND DUCT WORK.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. REMODELING OF THE KITCHEN AND BATHROOMS WITH NEW PLUMBING FIXTURES.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. THE ELECTRICAL LOAD DEMAND WAS INCREASED BY ADDING A CENTRAL A/C WITH ELECTRIC 7.5 HEATERS AND ADDITIONAL LIGHTS AND WALL OUTLETS THAT HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED AMPERAGE LOADING THROUGH THE PERMITTING PROCESS.

FBC(2007) 1604.1

THE STRUCTURES FOR THE WINDOWS THAT WERE BUILT FACING THE SOUTH SIDE DO NOT MEET THE STANDARD FOR GRAVITY LOADING AND HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS. ALL THE STRUCTURES THAT WERE DONE ILLEGALLY ARE DEEMED TO BE UNSAFE AND THE CONSTRUCTION IS UNDERDESIGNED.

FBC(2007) 1612.1.2

ALL THE WINDOWS AND DOOR INSTALLATIONS HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS.

FBC(2007) 1626.1

THE NEW WINDOWS WITH GLASS NEED TO BE IMPACT RESISTANT OR BE PROTECTED BY AN APPROVED HURRICANE PROTECTION SYSTEM.

CASE NO: CE10070020 CASE ADDR: 1300 SW 21 TER

OWNER: HOLLAND MOBILE HOME PARK LLC

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

1. THERE IS AN ADDITION BEING BUILT ON THE WEST SIDE OF LOT 1389 IN THE TRAILER PARK TO BE USED AS A BEDROOM WITH A BATHROOM. IT DOES NOT MEET ANY STANDARD CONSTRUCTION METHODS BEING USED TODAY.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. A BATHROOM IS BEING BUILT INSIDE AN ILLEGAL ADDITION TO A TRAILER WITH ALL NEW PLUMBING PIPES, WASTE LINES AND FIXTURES.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. THE ELECTRICAL LOADS IMPOSED ON THE CIRCUITS INCLUDING BUT NOT LIMITED TO THE NEW BEDROOM ADDITION, ALL THE WINDOW A/C'S THAT WERE PLACED IN THE TRAILER AND THE COOKING APPLIANCES, EXCEED THE CAPACITY OF THE EXISTING CIRCUITRY AND ARE CREATING AN ELECTRICAL FIRE HAZARD.

20

FBC(2007) 1604.1

THE STRUCTURES FOR THE ADDITION DO NOT MEET THE STANDARD FOR GRAVITY LOADING AND HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS. ALL THE STRUCTURES THAT WERE DONE ILLEGALLY ARE DEEMED TO BE UNSAFE AND THE CONSTRUCTION IS UNDERDESIGNED. THEY WOULD NOT PROVIDE THE REQUIRED RESISTANCE TO UPLIFT WHICH THE CODE PROTECTS ITS NEIGHBORS FROM FLYING DEBRIS IN A STORM AND WHICH THIS STRUCTURE MAY BECOME, SO THEY MUST BE REMOVED.

CASE NO: CE10071991
CASE ADDR: 2600 NW 20 CT
OWNER: PIERCE, RICKY
INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

- 1. THE ADDITION ON THE WEST SIDE OF THE DWELLING WAS DONE WITH A CANCELLED PERMIT FROM BROWARD COUNTY FOR THE FOLLOWING STRUCTURAL WORK:
- A. A NEW BATHROOM AND BEDROOM.
- B. INTERIOR REMODELING OF KITCHEN AND THE EXISTING BATHROOM.
- C. THE INSTALLATION OF A CENTRAL A/C WITH DUCTWORK.
- 2. WORK CONTINUED WITHOUT A PERMIT AS NEW WINDOWS WERE INSTALLED, STUCCOED THE OUTSIDE WALLS OF THE BUILDING, AND FINISHING THE INTERIOR REMODELING WORK.

FBC(2007) 105.10.3.1

THERE IS A BUILDING PERMIT WHICH FAILED INSPECTION AND/OR WAS LEFT TO EXPIRE:

1. CANCELED MASTER PERMIT 04-12587 FOR THE INTERIOR REMODELING WORK AND THE ADDITION ON THE WEST SIDE THAT FAILED REVIEW. THE JOB WAS FINISHED AS WORK WITHOUT PERMIT.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. THE ADDITION OF AN EXTRA BATHROOM.
- 2. THE REMODELING OF THE EXISTING BATHROOM AND KITCHEN.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. ELECTRICAL LOAD DEMAND WAS INCREASED BY ADDING A CENTRAL A/C WITH ELECTRIC HEATER AND ADDITIONAL LIGHTS AND WALL OUTLETS FOR THE ILLEGAL ADDITION THAT HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED AMPERAGE LOADING THROUGH THE PERMITTING PROCESS.

CASE NO: CE10092090 CASE ADDR: 1125 NW 16 CT

OWNER: PHD DEVELOPMENT LLC

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN
CHANGED WITHOUT OBTAINING A PERMIT IN THE
FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:
1. WASTE PIPES, COLD AND HOT WATER SUPPLY LINES
WERE INSTALLED IN THE ILLEGAL APARTMENT KITCHEN

AND BATHROOM AREAS.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. ELECTRICAL LOAD DEMAND WAS INCREASED BY ADDING ADDITIONAL LIGHTS AND WALL OUTLETS INSIDE THE ILLEGAL ENCLOSURE THAT HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED AMPERAGE LOADING THROUGH THE PERMITTING PROCESS.

FBC(2007) 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

- 1. THE LEGAL OPEN PORCH WAS ENCLOSED AND CONVERTED INTO AN ILLEGAL APARTMENT WITH A BATHROOM AND KITCHEN AREA.
- 2. THE SINGLE FAMILY HOME WAS CONVERTED INTO A DUPLEX WHICH IS A PROHIBITED LAND USE IN THIS RS-8 ZONING DISTRICT.

FBC(2007) 1604.1

THE STRUCTURES FOR THE ILLEGAL ENCLOSED PORCH DO NOT MEET THE STANDARD FOR GRAVITY LOADING AND HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS. ALL THE STRUCTURES THAT WERE DONE ILLEGALLY ARE DEEMED TO BE UNSAFE AND THE CONSTRUCTION IS UNDERDESIGNED. IT WOULD NOT PROVIDE THE REQUIRED RESISTANCE TO UPLIFT WHICH THE CODE PROTECTS ITS NEIGHBORS FROM FLYING DEBRIS IN A STORM AND WHICH THIS STRUCTURE MAY BECOME, SO THEY MUST BE REMOVED.

23

CASE NO: CE10092111 CASE ADDR: 1018 NW 2 AVE

OWNER: COUNTRYWIDE HOME LOANS INC

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

1. THE FOUR GAS WATER HEATERS WERE REPLACED WITH FOUR ELECTRIC HEATERS.

FBC(2007) 105.10.3.1

THERE IS A BUILDING PERMIT, WHICH FAILED INSPECTION AND/OR WAS LEFT TO EXPIRE, FOR REROOFING, #07032323 ISSUED 3/27/07 AND IS MISSING A FINAL INSPECTION.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. THE EXISTING WATER HEATERS WERE REPLACED AND NEW PIPES WERE INSTALLED FOR THE WATER SUPPLY LINES.
- 2. THE GAS LINES WERE DISCONNECTED AND SEALED.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. ELECTRICAL LOAD DEMAND WAS INCREASED BY ADDING THE ADDITIONAL FOUR WATER HEATERS. THEY HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED AMPERAGE LOADING THROUGH THE PERMITTING PROCESS.

FBC(2007) 1604.1

THE STRUCTURES FOR THE ROOF DO NOT MEET THE STANDARD FOR GRAVITY LOADING AND HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS. ALL THE STRUCTURES THAT WERE DONE ILLEGALLY ARE DEEMED TO BE UNSAFE.

CITY COMMISSION MEETING ROOM - CITY HALL MARCH 22, 2011 - 9:00 AM

CASE NO: CE10050973

CASE ADDR: 1116 W BROWARD BLVD

OWNER: NOOR INVESTMENTS REALTY LLC

INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC(2007) 105.1

THE FOLLOWING WORK HAS BEEN COMPLETED WITHOUT

PERMITS:

1. ATTACHED PLYWOOD STORAGE SHEDS HAVE BEEN ERECTED ON THE REAR OF THE BUILDING.

2. A WOOD FENCE HAS BEEN INSTALLED.

FBC(2007) 105.4.4

WATER SUPPLIES AND WASTE LINES HAVE BEEN INSTALLED TO PROVIDE FOR A WASHING MACHINE WITHOUT OBTAINING

PERMITS.

FBC(2007) 105.4.5

THE FOLLOWING ELECTRICAL WORK HAS BEEN COMPLETED WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. A 110 VOLT OUTLET HAS BEEN INSTALLED FOR A WASHING MACHINE.
- 2. A 220 OUTLET HAS BEEN INSTALLED FOR A DRYER.
- 3. AN ELECTRICAL CONNECTION HAS BEEN PROVIDED FOR RELOCATED A/C EQUIPMENT.

FBC(2007) 105.4.11

AIR CONDITIONING EQUIPMENT HAS BEEN REPLACED AND RELOCATED FROM THE ROOF TO THE REAR OF THE BUILDING WITHOUT THE REQUIRED PERMITS ISSUED.

CASE NO: CE10062082 CASE ADDR: 1536 SW 19 AV

OWNER: RADANOF, BARRY ROBERT

INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC(2007) 105.4.18

A CHAIN LINK FENCE WITH GATES HAS BEEN INSTALLED ON THE PROPERTY WITHOUT OBTAINING THE REQUIRED

PERMITS.

CODE ENFORCEMENT BOARD AGENDA

CITY COMMISSION MEETING ROOM - CITY HALL

MARCH 22, 2011 - 9:00 AM

CASE NO: CE10082096
CASE ADDR: 2705 NW 20 ST
OWNER: BANK OF AMERICA

% LAW OFFICES OF DAVID STERN PA

INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC(2007) 105.1

THE SINGLE FAMILY DWELLING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. A FRONT PORCH OVERHANG HAS BEEN ADDED.
- 2. NEW WINDOWS AND DOORS HAVE BEEN INSTALLED.
- 3. A CARPORT AND STORAGE ROOM HAVE BEEN ADDED.

FBC(2007) 105.4.5

THE FOLLOWING ELECTRICAL WORK HAS BEEN INSTALLED WITHOUT PERMITS:

- 1. EXTERIOR SECURITY LIGHTING.
- 2. PREMISE WIRING FOR THE STORAGE ROOM.
- 3. WASHER AND DRYER OUTLETS.

FBC(2007) 1626.1

THE CONSTRUCTION OF THE CARPORT, STORAGE ROOM AND FRONT PORCH DO NOT MEET THE IMPACT TEST CRITERIA IN A HIGH VELOCITY HURRICANE ZONE.

CASE NO: CE10090609
CASE ADDR: 216 SE 8 ST
OWNER: COURT PARK INC
INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC(2007) 105.1

THE FOLLOWING WORK HAS BEEN COMPLETED ON THE

OFFICE BUILDING WITHOUT PERMITS:

- 1. HURRICANE SHUTTERS HAVE BEEN INSTALLED.
- 2. THE ROOF MANSARD HAS BEEN REPLACED.
- 3. A REROOF HAS BEEN COMPLETED.

FBC(2007) 105.4.8

A FREE STANDING AWNING HAS BEEN ERECTED IN THE REAR PARKING LOT AS A CAR SHELTER WITHOUT OBTAINING A PERMIT.

CITY COMMISSION MEETING ROOM - CITY HALL

MARCH 22, 2011 - 9:00 AM

CASE NO: CE10100765 CASE ADDR: 1311 SE 2 AVE

OWNER: GOTTLIEB, MICHAEL & GEORGIA &

MOLDOF, HILLIARD & ZEENA

INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC(2007) 105.1

THE HANDICAP RAMP LOCATED IN THE REAR OF THE PROPERTY WAS ALTERED BY THE INSTALLATION OF NEW

RAILINGS WITHOUT A PERMIT.

FBC(2007) 105.4.8

AN AWNING HAS BEEN INSTALLED OVER THE HANDICAP RAMP LOCATED ON THE REAR OF THE PROPERTY WITHOUT

OBTAINING THE REQUIRED PERMITS.

CASE NO: CE10110921
CASE ADDR: 115 SW 19 AVE
OWNER: HUSBAND, DANIEL
INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC(2007) 105.4.18

A WOOD FENCE HAS BEEN REMOVED AND REPLACED WITH A

NEW WOOD FENCE WITHOUT A PERMIT.

CASE NO: CE11010558
CASE ADDR: 608 SW 5 AVE
OWNER: MTB FL LLC
INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC(2007) 105.1

A NEW SHINGLE ROOF HAS BEEN INSTALLED ON THE BUILDING WITHOUT OBTAINING THE REQUIRED PERMITS.

FBC(2007) 105.4.18

A PVC FENCE HAS BEEN INSTALLED ON THE PROPERTY

WITHOUT OBTAINING A PERMIT.

CITY OF FORT LAUDERDALE Page

CODE ENFORCEMENT BOARD AGENDA

CITY COMMISSION MEETING ROOM - CITY HALL MARCH 22, 2011 - 9:00 AM

RETURN HEARING (OLD BUSINESS)

27

CASE NO: CE07031580 CASE ADDR: 209 SW 22 ST

OWNER: US BANK NATIONAL ASSN

% FIDELITY/SELECT

INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC 105.1

THE SINGLE FAMILY DWELLING HAS BEEN ALTERED IN THE FOLLOWING WAY WITHOUT OBTAINING THE REQUIRED

PERMITS:

1. NEW WINDOWS HAVE BEEN INSTALLED.

2. A NEW FRONT DOOR HAS BEEN INSTALLED.

3. NEW DRYWALL HAS BEEN INSTALLED ON CEILINGS AND WALLS.

4. GLASS BLOCK HAS BEEN INSTALLED.

FBC 105.2.11

WALL A/C UNITS HAVE BEEN INSTALLED WITHOUT OBTAINING THE REQUIRED PERMITS.

FBC 105.2.5

ELECTRICAL WIRING HAS BEEN INSTALLED FOR HI-HAT CEILING LIGHTING WITHOUT OBTAINING THE REQUIRED PERMITS.

CASE NO: CE09011358 CASE ADDR: 1040 SW 17 ST

OWNER: MCKENNEY, KRISTOPHER J

INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC 105.1

THE FOLLOWING WORK HAS BEEN COMPLETED WITHOUT

- 1. NEW KITCHEN CABINETS AND COUNTERTOPS HAVE BEEN INSTALLED.
- 2. A SHED HAS BEEN PLACED IN THE REAR OF THE PROPERTY.
- 3. VINYL EAVES HAVE BEEN INSTALLED IN THE OVERHANGS.
- 4. NEW WINDOWS AND DOORS HAVE BEEN INSTALLED.
- 5. FASCIA BOARD HAS BEEN REPLACED.

Page CITY OF FORT LAUDERDALE CODE ENFORCEMENT BOARD AGENDA CITY COMMISSION MEETING ROOM - CITY HALL MARCH 22, 2011 - 9:00 AM

FBC 105.2.18

1. A VINYL FENCE HAS BEEN INSTALLED AT THE REAR OF THE CARPORT WITH A GATE.

FBC 105.2.4

THE PLUMBING FOR THE NEW KITCHEN HAS BEEN DONE WITHOUT A PERMIT.

FBC 105.2.5

ELECTRICAL WORK HAS BEEN PERFORMED TO CONNECT AND COMPLETE THE NEW KITCHEN WITHOUT A PERMIT.

FBC 105.2.8

NEW AWNINGS HAVE BEEN INSTALLED ON THE SINGLE FAMILY DWELLING WITHOUT A PERMIT.

CASE NO: CE10031191 CASE ADDR: 1621 SW 5 ST OWNER: STURM, SHAWN A INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC(2007) 105.4.1

THE FOLLOWING WORK HAS BEEN COMPLETED WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. A CARPORT HAS BEEN ENCLOSED.
- 2. A PAVER DRIVEWAY HAS BEEN INSTALLED.
- 3. TWO PAVER WALKWAYS HAVE BEEN INSTALLED.

FBC(2007) 109.10

THE FOLLOWING WORK HAS BEEN COMPLETED WITHOUT OBTAINING THE REQUIRED APPROVALS:

- 1. NEW WINDOWS HAVE BEEN INSTALLED.
- 2. A NEW SPA HAS BEEN INSTALLED WITH A RAISED WATITI
- 3. A PAVER DECK HAS BEEN INSTALLED.
- 4. A PAVER PATIO HAS BEEN INSTALLED.

29

CITY COMMISSION MEETING ROOM - CITY HALL

MARCH 22, 2011 - 9:00 AM

CASE NO: CE10040803
CASE ADDR: 1117 NW 2 AVE
OWNER: GINSBURG, LEON
INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC(2007) 105.1

THE FOLLOWING WORK HAS BEEN COMPLETED WITHOUT

OBTAINING THE REQUIRED PERMITS:

- 1. A SHED HAS BEEN INSTALLED ON THE REAR OF THE PROPERTY.
- 2. A BATHROOM HAS BEEN REMODELED.
- 3. A KITCHEN HAS BEEN ADDED.
- 4. A KITCHEN HAS BEEN REMODELED.
- 5. A WOOD FENCE HAS BEEN INSTALLED.
- 6. THE CARPORT WAS CONVERTED TO AN ILLEGAL EFFICIENCY UNIT.

FBC(2007) 105.4.4

THE FOLLOWING PLUMBING WORK HAS BEEN COMPLETED WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. A NEW WATER HEATER WAS INSTALLED.
- 2. PIPING AND FIXTURE INSTALLATIONS FOR A BATHROOM.
- 3. PLUMBING FOR A KITCHEN REMODEL.
- 4. PLUMBING FOR AN ADDED KITCHEN.

FBC(2007) 105.4.5

THE FOLLOWING ELECTRICAL WORK HAS BEEN COMPLETED WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. ELECTRICAL CONNECTION FOR THE WATER HEATER.
- 2. NEW WIRING FOR THE KITCHEN REMODEL.
- 3. NEW WIRING FOR THE ADDED KITCHEN.
- 4. NEW WIRING FOR THE BATHROOM REMODEL.

FBC(2007) 708.1 1.

FIRE SEPARATIONS BETWEEN INDIVIDUAL RESIDENTIAL UNITS HAVE NOT BEEN VERIFIED THROUGH THE PERMIT AND INSPECTION PROCESS.

CITY COMMISSION MEETING ROOM - CITY HALL

MARCH 22, 2011 - 9:00 AM

CASE NO: CE09060371
CASE ADDR: 1800 SW 10 CT
OWNER: BERNSTEIN, ROBERT

% SAAVEDRA PELOSI GOODWIN & HEMAN

INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC(2007) 105.1

THE SINGLE FAMILY DWELLING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. A NEW KITCHEN HAS BEEN INSTALLED.
- 2. THE REAR PATIO HAS BEEN STRUCTURALLY RENOVATED.
- 3. BATHROOMS HAVE BEEN REMODELED.
- 4. DRYWALL AND FRAMING HAVE BEEN REPLACED.
- 5. THE GARAGE HAS BEEN ENCLOSED.

FBC(2007) 105.4.4

THE FOLLOWING PLUMBING WORK HAS BEEN DONE WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. NEW WASTE LINES FOR THE KITCHEN REMODELING.
- 2. NEW WATER SUPPLY LINES FOR THE KITCHEN REMODELING.
- 3. A NEW KITCHEN SINK WAS INSTALLED.
- 4. NEW BATHROOM FIXTURES WERE INSTALLED.
- 5. NEW WASTE LINES WERE INSTALLED FOR THE BATHROOM REMODELING.
- 6. NEW WATER SUPPLY LINES WERE INSTALLED FOR THE BATHROOM REMODELING.

FBC(2007) 105.4.5

ALTERATIONS TO THE PREMISE WIRING AND ELECTRICAL PANEL HAVE BEEN DONE WITHOUT OBTAINING THE REQUIRED PERMITS.

31

CITY COMMISSION MEETING ROOM - CITY HALL

MARCH 22, 2011 - 9:00 AM

CASE NO: CE09072678 CASE ADDR: 1109 NW 19 ST

OWNER: SOUFFRANT, SONIA H/E

DORELIEN, WILKY

INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC(2007) 105.1

THE SINGLE FAMILY DWELLING HAS HAD THE FOLLOWING WORK COMPLETED WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. NEW FRONT DOOR INSTALLED.
- 2. NEW WINDOWS INSTALLED.
- 3. SECURITY BARS INSTALLED ON WINDOWS.
- 4. AN EFFICIENCY APARTMENT IN THE GARAGE.

FBC(2007) 105.4.4

THE FOLLOWING PLUMBING WORK HAS BEEN COMPLETED WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. A FULL BATHROOM HAS BEEN INSTALLED IN THE GARAGE.
- 2. A WATER HEATER HAS BEEN INSTALLED IN THE GARAGE.

FBC(2007) 105.4.5

THE FOLLOWING ELECTRICAL WORK HAS BEEN COMPLETED WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. AN ELECTRICAL CIRCUIT AND CONNECTION WAS COMPLETED FOR A WATER HEATER.
- 2. ELECTRICAL WIRING WAS INSTALLED FOR A BATHROOM.

FBC(2007) 110.1.1

THE OCCUPANCY OF THE SINGLE FAMILY DWELLING HAS BEEN CHANGED TO A DUPLEX BY CONVERTING THE GARAGE INTO AN EFFICIENCY APARTMENT. A CERTIFICATE OF OCCUPANCY REVISING THE CLASSIFICATION AND USE FROM A SINGLE FAMILY HOME TO A DUPLEX WAS NOT ISSUED.

32

CITY COMMISSION MEETING ROOM - CITY HALL

MARCH 22, 2011 - 9:00 AM

CASE NO: CE09060387 CASE ADDR: 1408 NW 9 AVE

OWNER: B & H REAL ESTATE MANAGEMENT LLC

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

- 1. THE SCREEN WAS REMOVED FROM THE REAR PORCH AND ENCLOSED WITH WINDOWS.
- 2. SOME WINDOWS WERE REPLACED AROUND THE PROPERTY AND THE OPENINGS WERE ENCLOSED TO FIX THE NEW WINDOWS.
- 3. KITCHEN AND BATHROOMS WERE REMODELED WITH NEW CABINETS AND FIXTURES.
- 4. DRYWALL WAS REPLACED ON SOME AREAS OF THE CEILING AND WALLS TO REPAIR WATER DAMAGE.

FBC(2007) 105.4.11

THE MECHANICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. A CENTRAL A/C WAS INSTALLED WITH DUCT WORK AND AN ELECTRICAL HEATER.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. FIXTURES IN THE KITCHEN AND BATHROOMS WERE REPLACED.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. ELECTRICAL LOAD DEMAND WAS INCREASED BY INSTALLING A CENTRAL A/C WITH ELECTRIC HEATER AND ADDING ADDITIONAL LIGHTS AND WALL OUTLETS THAT HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED AMPERAGE LOADING THROUGH THE PERMITTING PROCESS.

CODE ENFORCEMENT BOARD AGENDA CITY COMMISSION MEETING ROOM - CITY HALL MARCH 22, 2011 - 9:00 AM

FBC(2007) 109.10

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS THROUGH THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE09091388 CASE ADDR: 1629 NW 7 AVE

OWNER: CAPITAL HOMES & INVESTMENTS INC

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

THE SINGLE FAMILY DWELLING HAS BEEN ALTERED IN THE FOLLOWING WAY:

- 1. ELECTRICAL, MECHANICAL, STRUCTURAL, AND PLUMBING WORK WITHOUT PERMITS.

 STOP WORK ORDER HAS BEEN ISSUED.
- 2. NEW WINDOWS AND DOORS WERE INSTALLED.
- 3. KITCHEN AND BATHROOMS WERE REMODELED.
- 4. ONE WINDOW HAS BEEN REMOVED AND THE OPENING WAS BLOCKED UP.

FBC(2007) 105.4.11

THE MECHANICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. A CENTRAL A/C UNIT WAS INSTALLED WITH DUCT WORK AND AN ELECTRICAL HEATER.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER:

- 1. THE INSTALLATION OF PVC PIPING ON THE NORTH WALL FOR THE VENTILATION WASTE STACK.
- 2. SUPPLY WATER PIPING CONNECTED TO THE KITCHEN AND BATH REMODEL.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED BY THE INSTALLATION OF NEW CIRCUITS WITHOUT PERMITS IN THE FOLLOWING MANNER:

- 1. NEW ELECTRICAL PANEL HAS BEEN INSTALLED TO UPGRADE THE SERVICE.
- 2. NEW FLOOD LIGHTS WERE INSTALLED.
- 3. NEW ELECTRICAL CIRCUITS WERE INSTALLED FOR THE A/C SYSTEM.

CITY COMMISSION MEETING ROOM - CITY HALL

MARCH 22, 2011 - 9:00 AM

FBC(2007) 1612.1.2

ALL THE WINDOWS AND SHUTTER INSTALLATIONS HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS.

FBC(2007) 1626.1

THE NEW WINDOWS AND DOOR WITH GLASS NEED TO BE IMPACT RESISTANT OR BE PROTECTED BY AN APPROVED HURRICANE PROTECTION SYSTEM.

CASE NO: CE09120485 CASE ADDR: 2450 SW 7 ST

OWNER: LONG, LITTLEQUNYA

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC 704.3

THE REQUIRED FIRE-RESISTANCE RATINGS AND SEPARATIONS BETWEEN THE SEPARATE UNITS HAVE NOT BEEN PROVIDED.

FBC(2007) 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

- 1. THE HOUSE SUFFERED GREAT DAMAGE FROM AN ELECTRICAL FIRE. THE ROOF TRUSSES AND DECK WERE BURNED MAKING THE ROOF UNSAFE.
- 2. THE PROPERTY HAS BEEN CONVERTED INTO FOUR ILLEGAL RENTAL APARTMENTS. THERE ARE 2 ILLEGAL BATHROOMS AND 3 ILLEGAL KITCHEN AREAS.
- 3. TWO OUTSIDE DOORS WERE INSTALLED TO GRANT ENTRANCE TO THE ILLEGAL APARTMENT.

FBC(2007) 105.4.11

THE MECHANICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. A CENTRAL FIVE TON A/C WAS INSTALLED WITH DUCT WORK AND ELECTRICAL HEATERS.
- 2. ILLEGAL BATHROOM VENTILLATION.

CODE ENFORCEMENT BOARD AGENDA
CITY COMMISSION MEETING ROOM - CITY HALL
MARCH 22, 2011 - 9:00 AM

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. KITCHEN AREAS AND BATHROOMS WERE ADDED TO THE PROPERTY WITH ALL NEW FIXTURES AND PLUMBING PIPES.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. ELECTRICAL LOAD DEMAND WAS INCREASED BY ADDING A CENTRAL A/C WITH ELECTRICAL HEATER, ADDITIONAL LIGHTS AND WALL OUTLETS THAT HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED AMPERAGE LOADING THROUGH THE PERMITTING PROCESS.

FBC(2007) 110.1.1

THE USE AND THE OCCUPANCY OF THIS RESIDENTIAL DWELLING HAVE BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION WITHOUT OBTAINING THE REQUIRED PERMITS AND CERTIFICATE OF OCCUPANCY INTO FOUR RENTAL APARTMENTS.

FBC(2007) 1604.1

THE STRUCTURE FOR THE ROOF DECK DOES NOT MEET THE STANDARD FOR GRAVITY LOADING AND HAS NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS. ALL THE STRUCTURES THAT WERE DAMAGED BY FIRE ARE DEEMED TO BE UNSAFE AND THE CONSTRUCTION IS UNDERDESIGNED. IT WOULD NOT PROVIDE THE REQUIRED RESISTANCE TO UPLIFT FOR WHICH THE CODE PROTECTS HIS NEIGHBORS FROM FLYING DEBRIS IN A STORM AND WHICH THE ROOF MAY BECOME. IT MUST BE REMOVED.

CITY COMMISSION MEETING ROOM - CITY HALL MARCH 22, 2011 - 9:00 AM

CASE NO: CE10012193
CASE ADDR: 1181 SW 25 AV
OWNER: GIRALT, ELIO &

FERNANDEZ, MIRIAM

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

- 1. ILLEGAL ADDITION TO THE PROPERTY ACROSS THE REAR OF THE DWELLING.
- 2. A CHAIN LINK FENCE WAS INSTALLED WITH A EXPIRED PERMIT FROM 2002.

FBC(2007) 105.10.3.1

THERE IS A BUILDING PERMIT, WHICH FAILED INSPECTION AND/OR WAS LEFT TO EXPIRE:

1. A CHAIN LINK FENCE WAS INSTALLED WITH A EXPIRED PERMIT #02060181 FROM 2002. IT FAILED FINAL INSPECTION ON JULY 3, 2002.

FBC(2007) 1604.1

THE STRUCTURE FOR THE REAR ADDITION DOES NOT MEET THE STANDARD FOR GRAVITY LOADING AND HAS NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS. THE STRUCTURE THAT WAS DONE ILLEGALLY IS DEEMED TO BE UNSAFE. THE CONSTRUCTION IS UNDERDESIGNED AND WILL NOT PROVIDE THE REQUIRED RESISTANCE TO UPLIFT FOR WHICH THE CODE PROTECTS ITS NEIGHBORS FROM FLYING DEBRIS IN A STORM AND WHICH THIS STRUCTURE MAY BECOME. THEY MUST BE REMOVED.

37

CITY COMMISSION MEETING ROOM - CITY HALL MARCH 22, 2011 - 9:00 AM

CASE NO: CE10020466
CASE ADDR: 1391 SW 33 TER
OWNER: GORDON, ALAN DAVID

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

- 1. INTERIOR REMODELING WORK IS BEING DONE IN THE KITCHEN, LAUNDRY AND BATHROOM AREAS.
- 2. DRYWALL HAS BEEN REMOVED FROM THE FRAME. ALL THE ELECTRICAL CIRCUITS, AND THE PLUMBING PIPES ARE EXPOSED.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. ELECTRICAL LOAD DEMAND WAS INCREASED BY ADDING ADDITIONAL LIGHTS AND WALL OUTLETS THAT HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED AMPERAGE LOADING THROUGH THE PERMITTING PROCESS.

FBC(2007) 109.10

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS THROUGH THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE10050006 CASE ADDR: 204 NW 16 ST

OWNER: LARA & BLENDI LLC

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

- 1. CARPORT ENCLOSED INTO A GARAGE.
- 2. GARAGE DOOR WAS INSTALLED.
- 3. PROPERTY WINDOWS AND DOUBLE GLASS DOOR IN THE REAR WERE REPLACED.
- 4. KITCHEN WAS REMODELED WITH NEW CABINETS AND FIXTURES.

FBC(2007) 105.4.11

THE MECHANICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO: 1. CENTRAL A/C WAS INSTALLED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. PLUMBING STACKS ARE REROUTED AROUND THE ROOF.
- 2. FIXTURES WERE REPLACED IN THE KITCHEN. WASHER HOOK-UP TO NEW DRAIN AND SUPPLY LINES.
- 3. A TRAP WAS INSTALLED INGROUND WITH THE ELECTRICAL AND PLUMBING SUPPLY.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. ELECTRICAL LOAD DEMAND WAS INCREASED BY ADDING A CENTRAL A/C WITH AN ELECTRIC HEATER AND ADDITIONAL LIGHTS AND WALL OUTLETS THAT HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED AMPERAGE LOADING THROUGH THE PERMITTING PROCESS.

FBC(2007) 109.10

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS THROUGH THE PERMITTING AND INSPECTION PROCESS.

FBC(2007) 1612.1.2

ALL THE WINDOWS AND DOOR INSTALLATIONS HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS.

FBC(2007) 1626.1

THE NEW WINDOWS AND DOOR WITH GLASS NEED TO BE IMPACT RESISTANT OR BE PROTECTED BY AN APPROVED HURRICANE PROTECTION SYSTEM.

CITY COMMISSION MEETING ROOM - CITY HALL MARCH 22, 2011 - 9:00 AM

CASE NO: CE09051930 CASE ADDR: 3513 SW 12 CT

OWNER: FL ATTAINABLE HOME CO LLC

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

- 1. A SHED HAS BEEN BUILT ON THE REAR OF THE PROPERTY.
- 2. STUCCO WORK WAS DONE ON THE OUTSIDE OF THE PROPERTY.
- 3. RE-ROOF WITH SHINGLES WAS DONE.
- 4. STORM SHUTTERS WERE INSTALLED ON THE PREMISES.

FBC(2007) 105.10.3.1

THERE IS AN EXPIRED BUILDING PERMIT, WHICH FAILED INSPECTION AND/OR WAS LEFT TO EXPIRE:

- 1. P#06011690 FOR SHUTTERS, NO INSPECTIONS.
- 2. P#06011691 FOR STUCCO WORK FAILED INSPECTION 2/14/06.
- 3. P#03041613 REROOF WITH SHINGLES APPROVED BUT NEVER ISSUED EXPIRED 4/18/03.

FBC(2007) 109.10

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS THROUGH THE PERMITTING AND INSPECTION PROCESS.

FBC 1604.1

THE STRUCTURE FOR THE SHED AND ROOF DOES NOT MEET THE STANDARD FOR GRAVITY LOADING AND HAS NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS.

FBC 1612.1.2

ALL THE SHUTTER INSTALLATIONS HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS.

FBC 1626.1

THE NEW WINDOWS WITH GLASS NEED TO BE IMPACT RESISTANT OR BE PROTECTED BY AN APPROVED HURRICANE PROTECTION SYSTEM.

CITY COMMISSION MEETING ROOM - CITY HALL

MARCH 22, 2011 - 9:00 AM

CASE NO: CE10080653
CASE ADDR: 2001 NW 28 AVE
OWNER: PIERCE, RICKY
INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

- 1. FRONT ENTRANCE DOOR WAS REPLACED.
- 2. EXTERIOR WALLS WERE STUCCOED.
- 3. INTERIOR REMODELING IN THE KITCHEN AND BATHROOM WITH NEW FIXTURES AND CABINETS.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. PLUMBING FIXTURES WERE REPLACED IN THE KITCHEN AND BATHROOM.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. ELECTRICAL LOAD DEMAND WAS INCREASED BY ADDING ADDITIONAL LIGHTS AND WALL OUTLETS IN THE KITCHEN AND BATHROOM AREAS THAT HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED AMPERAGE LOADING THROUGH THE PERMITTING PROCESS.

FBC(2007) 1626.1

THE NEW ENTRANCE DOOR WITH GLASS NEED TO BE IMPACT RESISTANT OR BE PROTECTED BY AN APPROVED HURRICANE PROTECTION SYSTEM.

CITY COMMISSION MEETING ROOM - CITY HALL MARCH 22, 2011 - 9:00 AM

CASE NO: CE09030895 CASE ADDR: 1369 SE 14 ST

OWNER: CHAMBERLAIN, KENT T

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. INSTALLED NEW WINDOWS AND DOORS.
- 2. INSTALLED DRIVEWAY PAVERS.
- 3. INSTALLED A WOODEN TRELLIS.
- 4. INSTALLED A WOODEN DECK.

FBC(2007) 105.10.3.1

THE FOLLOWING PERMIT HAS EXPIRED:

1. FENCE PERMIT, 01021208, WAS ISSUED 2/15/2001. IT FAILED BOTH THE ZONING FINAL INSPECTION AND THE BUILDING FINAL INSPECTION. A RE-INSPECTION WAS NOT SCHEDULED.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. EXTERIOR LIGHTING HAS BEEN INSTALLED AT TRELLIS AREA.

FBC(2007) 109.10

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

THE WINDOWS, DOORS, DECKS, AND TRELLIS HAVE NOT BEEN PROVEN TO SUFFICIENTLY WITHSTAND ESTIMATED OR ACTUAL IMPOSED DEAD, LIVE, WIND, OR ANY OTHER LOADS THROUGH THE PERMIT AND INSPECTION PROCESS.

FBC(2007) 1626.1

THE NEW WINDOWS AND NEW DOORS WITH GLASS NEED TO BE IMPACT RESISTANT OR BE PROTECTED BY AN APPROVED HURRICANE PROTECTION SYSTEM.

CITY COMMISSION MEETING ROOM - CITY HALL

MARCH 22, 2011 - 9:00 AM

CASE NO: CE10020688

CASE ADDR: 1400 NE 56 ST # 105

OWNER: ISLES AT CORAL RIDGE DEVELOPMENT

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. WOODEN FENCES HAVE BEEN INSTALLED.
- 2. THE DOCK HAS BEEN REBUILT.
- 3. EXTERIOR DOORS HAVE BEEN REPLACED.
- 4. THE POOL BATHROOMS HAVE BEEN REMODELED.
- 5. THE PARKING LOT HAS BEEN REPAVED AND RESTRIPED.
- 6. RAILINGS HAVE BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PIPING AND FIXTURES HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELINGS, INCLUDING THE BATHS LOCATED AT THE COMMUNITY POOL.
- 2. AN EXTERIOR SHOWER WAS INSTALLED/REPLACED ON THE WALL OF THE POOL BATHROOM BUILDING.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING ALL OF THE KITCHEN AND BATH REMODELINGS, INCLUDING THE POOL BATHS.
- 2. MISCELLANEOUS EXTERIOR LIGHTING HAS BEEN INSTALLED.

FBC(2007) 109.10

WORK WAS COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

CITY COMMISSION MEETING ROOM - CITY HALL

MARCH 22, 2011 - 9:00 AM

CASE NO: CE10020689

CASE ADDR: 1400 NE 56 ST # 106

OWNER: ISLES AT CORAL RIDGE DEVELOPMENT

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REOUIRED PERMITS:

- 1. WOODEN FENCES HAVE BEEN INSTALLED.
- 2. THE DOCK HAS BEEN REBUILT.
- 3. EXTERIOR DOORS HAVE BEEN REPLACED.
- 4. THE POOL BATHROOMS HAVE BEEN REMODELED.
- 5. THE PARKING LOT HAS BEEN REPAVED AND RESTRIPED.
- 6. RAILINGS HAVE BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PIPING AND FIXTURES HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELINGS, INCLUDING THE BATHS LOCATED AT THE COMMUNITY POOL.
- 2. AN EXTERIOR SHOWER WAS INSTALLED/REPLACED ON THE WALL OF THE POOL BATHROOM BUILDING.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING ALL OF THE KITCHEN AND BATH REMODELINGS, INCLUDING THE POOL BATHS.
- 2. MISCELLANEOUS EXTERIOR LIGHTING HAS BEEN INSTALLED.

FBC(2007) 109.10

WORK WAS COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

44

CODE ENFORCEMENT BOARD AGENDA

CITY COMMISSION MEETING ROOM - CITY HALL

MARCH 22, 2011 - 9:00 AM

CASE NO: CE10020690

CASE ADDR: 1400 NE 56 ST # 109

OWNER: ISLES AT CORAL RIDGE DEVELOPMENT

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REOUIRED PERMITS:

- 1. WOODEN FENCES HAVE BEEN INSTALLED.
- 2. THE DOCK HAS BEEN REBUILT.
- 3. EXTERIOR DOORS HAVE BEEN REPLACED.
- 4. THE POOL BATHROOMS HAVE BEEN REMODELED.
- 5. THE PARKING LOT HAS BEEN REPAVED AND RESTRIPED.
- 6. RAILINGS HAVE BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PIPING AND FIXTURES HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELINGS, INCLUDING THE BATHS LOCATED AT THE COMMUNITY POOL.
- 2. AN EXTERIOR SHOWER WAS INSTALLED/REPLACED ON THE WALL OF THE POOL BATHROOM BUILDING.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING ALL OF THE KITCHEN AND BATH REMODELINGS, INCLUDING THE POOL BATHS.
- 2. MISCELLANEOUS EXTERIOR LIGHTING HAS BEEN INSTALLED.

FBC(2007) 109.10

WORK WAS COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

THE EXTERIOR DOORS, DOCK, WOOD FENCES, AND RAILINGS HAVE NOT BEEN PROVEN TO SUFFICIENTLY WITHSTAND ESTIMATED OR ACTUAL IMPOSED DEAD, LIVE, WIND, OR ANY OTHER LOADS THROUGH THE PERMIT AND INSPECTION PROCESS.

CITY COMMISSION MEETING ROOM - CITY HALL

MARCH 22, 2011 - 9:00 AM

CASE NO: CE10020691

CASE ADDR: 1400 NE 56 ST # 110

OWNER: ISLES AT CORAL RIDGE DEVELOPMENT

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. WOODEN FENCES HAVE BEEN INSTALLED.
- 2. THE DOCK HAS BEEN REBUILT.
- 3. EXTERIOR DOORS HAVE BEEN REPLACED.
- 4. THE POOL BATHROOMS HAVE BEEN REMODELED.
- 5. THE PARKING LOT HAS BEEN REPAVED AND RESTRIPED.
- 6. RAILINGS HAVE BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PIPING AND FIXTURES HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELINGS, INCLUDING THE BATHS LOCATED AT THE COMMUNITY POOL.
- 2. AN EXTERIOR SHOWER WAS INSTALLED/REPLACED ON THE WALL OF THE POOL BATHROOM BUILDING.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING ALL OF THE KITCHEN AND BATH REMODELINGS, INCLUDING THE POOL BATHS.
- 2. MISCELLANEOUS EXTERIOR LIGHTING HAS BEEN INSTALLED.

FBC(2007) 109.10

WORK WAS COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

46

CITY COMMISSION MEETING ROOM - CITY HALL

MARCH 22, 2011 - 9:00 AM

CASE NO: CE10020692

CASE ADDR: 1400 NE 56 ST # 111

OWNER: ISLES AT CORAL RIDGE DEVELOPMENT

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REOUIRED PERMITS:

- 1. WOODEN FENCES HAVE BEEN INSTALLED.
- 2. THE DOCK HAS BEEN REBUILT.
- 3. EXTERIOR DOORS HAVE BEEN REPLACED.
- 4. THE POOL BATHROOMS HAVE BEEN REMODELED.
- 5. THE PARKING LOT HAS BEEN REPAVED AND RESTRIPED.
- 6. RAILINGS HAVE BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PIPING AND FIXTURES HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELINGS, INCLUDING THE BATHS LOCATED AT THE COMMUNITY POOL.
- 2. AN EXTERIOR SHOWER WAS INSTALLED/REPLACED ON THE WALL OF THE POOL BATHROOM BUILDING.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING ALL OF THE KITCHEN AND BATH REMODELINGS, INCLUDING THE POOL BATHS.
- 2. MISCELLANEOUS EXTERIOR LIGHTING HAS BEEN INSTALLED.

FBC(2007) 109.10

WORK WAS COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

47

CITY COMMISSION MEETING ROOM - CITY HALL

MARCH 22, 2011 - 9:00 AM

CASE NO: CE10020693

CASE ADDR: 1400 NE 56 ST # 112

OWNER: ISLES AT CORAL RIDGE DEVELOPMENT

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. WOODEN FENCES HAVE BEEN INSTALLED.
- 2. THE DOCK HAS BEEN REBUILT.
- 3. EXTERIOR DOORS HAVE BEEN REPLACED.
- 4. THE POOL BATHROOMS HAVE BEEN REMODELED.
- 5. THE PARKING LOT HAS BEEN REPAVED AND RESTRIPED.
- 6. RAILINGS HAVE BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PIPING AND FIXTURES HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELINGS, INCLUDING THE BATHS LOCATED AT THE COMMUNITY POOL.
- 2. AN EXTERIOR SHOWER WAS INSTALLED/REPLACED ON THE WALL OF THE POOL BATHROOM BUILDING.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING ALL OF THE KITCHEN AND BATH REMODELINGS, INCLUDING THE POOL BATHS.
- 2. MISCELLANEOUS EXTERIOR LIGHTING HAS BEEN INSTALLED.

FBC(2007) 109.10

WORK WAS COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

CITY COMMISSION MEETING ROOM - CITY HALL MARCH 22, 2011 - 9:00 AM

CASE NO: CE10020694

CASE ADDR: 1400 NE 56 ST # 113

OWNER: ISLES AT CORAL RIDGE DEVELOPMENT

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REOUIRED PERMITS:

- 1. WOODEN FENCES HAVE BEEN INSTALLED.
- 2. THE DOCK HAS BEEN REBUILT.
- 3. EXTERIOR DOORS HAVE BEEN REPLACED.
- 4. THE POOL BATHROOMS HAVE BEEN REMODELED.
- 5. THE PARKING LOT HAS BEEN REPAVED AND RESTRIPED.
- 6. RAILINGS HAVE BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PIPING AND FIXTURES HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELINGS, INCLUDING THE BATHS LOCATED AT THE COMMUNITY POOL.
- 2. AN EXTERIOR SHOWER WAS INSTALLED/REPLACED ON THE WALL OF THE POOL BATHROOM BUILDING.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING ALL OF THE KITCHEN AND BATH REMODELINGS, INCLUDING THE POOL BATHS.
- 2. MISCELLANEOUS EXTERIOR LIGHTING HAS BEEN INSTALLED.

FBC(2007) 109.10

WORK WAS COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

CITY COMMISSION MEETING ROOM - CITY HALL

MARCH 22, 2011 - 9:00 AM

CASE NO: CE10020695

CASE ADDR: 1400 NE 56 ST # 114

OWNER: ISLES AT CORAL RIDGE DEVELOPMENT

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REOUIRED PERMITS:

- 1. WOODEN FENCES HAVE BEEN INSTALLED.
- 2. THE DOCK HAS BEEN REBUILT.
- 3. EXTERIOR DOORS HAVE BEEN REPLACED.
- 4. THE POOL BATHROOMS HAVE BEEN REMODELED.
- 5. THE PARKING LOT HAS BEEN REPAVED AND RESTRIPED.
- 6. RAILINGS HAVE BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PIPING AND FIXTURES HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELINGS, INCLUDING THE BATHS LOCATED AT THE COMMUNITY POOL.
- 2. AN EXTERIOR SHOWER WAS INSTALLED/REPLACED ON THE WALL OF THE POOL BATHROOM BUILDING.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING ALL OF THE KITCHEN AND BATH REMODELINGS, INCLUDING THE POOL BATHS.
- 2. MISCELLANEOUS EXTERIOR LIGHTING HAS BEEN INSTALLED.

FBC(2007) 109.10

WORK WAS COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

CASE NO: CE10020700

CASE ADDR: 1400 NE 56 ST # 205

ISLES AT CORAL RIDGE DEVELOPMENT OWNER:

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. WOODEN FENCES HAVE BEEN INSTALLED.
- 2. THE DOCK HAS BEEN REBUILT.
- 3. EXTERIOR DOORS HAVE BEEN REPLACED.
- 4. THE POOL BATHROOMS HAVE BEEN REMODELED.
- 5. THE PARKING LOT HAS BEEN REPAVED AND RESTRIPED.
- 6. RAILINGS HAVE BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PIPING AND FIXTURES HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELINGS, INCLUDING THE BATHS LOCATED AT THE COMMUNITY POOT.
- 2. AN EXTERIOR SHOWER WAS INSTALLED/REPLACED ON THE WALL OF THE POOL BATHROOM BUILDING.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING ALL OF THE KITCHEN AND BATH REMODELINGS, INCLUDING THE POOL BATHS.
- 2. MISCELLANEOUS EXTERIOR LIGHTING HAS BEEN INSTALLED.

FBC(2007) 109.10

WORK WAS COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

CITY COMMISSION MEETING ROOM - CITY HALL

MARCH 22, 2011 - 9:00 AM

CASE NO: CE10020701

CASE ADDR: 1400 NE 56 ST # 206

OWNER: ISLES AT CORAL RIDGE DEVELOPMENT

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REOUIRED PERMITS:

- 1. WOODEN FENCES HAVE BEEN INSTALLED.
- 2. THE DOCK HAS BEEN REBUILT.
- 3. EXTERIOR DOORS HAVE BEEN REPLACED.
- 4. THE POOL BATHROOMS HAVE BEEN REMODELED.
- 5. THE PARKING LOT HAS BEEN REPAVED AND RESTRIPED.
- 6. RAILINGS HAVE BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PIPING AND FIXTURES HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELINGS, INCLUDING THE BATHS LOCATED AT THE COMMUNITY POOL.
- 2. AN EXTERIOR SHOWER WAS INSTALLED/REPLACED ON THE WALL OF THE POOL BATHROOM BUILDING.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING ALL OF THE KITCHEN AND BATH REMODELINGS, INCLUDING THE POOL BATHS.
- 2. MISCELLANEOUS EXTERIOR LIGHTING HAS BEEN INSTALLED.

FBC(2007) 109.10

WORK WAS COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

CITY COMMISSION MEETING ROOM - CITY HALL MARCH 22, 2011 - 9:00 AM

CASE NO: CE10020703

CASE ADDR: 1400 NE 56 ST # 208

OWNER: ISLES AT CORAL RIDGE DEVELOPMENT

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. WOODEN FENCES HAVE BEEN INSTALLED.
- 2. THE DOCK HAS BEEN REBUILT.
- 3. EXTERIOR DOORS HAVE BEEN REPLACED.
- 4. THE POOL BATHROOMS HAVE BEEN REMODELED.
- 5. THE PARKING LOT HAS BEEN REPAVED AND RESTRIPED.
- 6. RAILINGS HAVE BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PIPING AND FIXTURES HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELINGS, INCLUDING THE BATHS LOCATED AT THE COMMUNITY POOL.
- 2. AN EXTERIOR SHOWER WAS INSTALLED/REPLACED ON THE WALL OF THE POOL BATHROOM BUILDING.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING ALL OF THE KITCHEN AND BATH REMODELINGS, INCLUDING THE POOL BATHS.
- 2. MISCELLANEOUS EXTERIOR LIGHTING HAS BEEN INSTALLED.

FBC(2007) 109.10

WORK WAS COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

THE EXTERIOR DOORS, DOCK, WOOD FENCES, AND RAILINGS HAVE NOT BEEN PROVEN TO SUFFICIENTLY WITHSTAND ESTIMATED OR ACTUAL IMPOSED DEAD, LIVE, WIND, OR ANY OTHER LOADS THROUGH THE PERMIT AND INSPECTION PROCESS.

CASE NO: CE10020704

CASE ADDR: 1400 NE 56 ST # 209

ISLES AT CORAL RIDGE DEVELOPMENT OWNER:

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REOUIRED PERMITS:

- 1. WOODEN FENCES HAVE BEEN INSTALLED.
- 2. THE DOCK HAS BEEN REBUILT.
- 3. EXTERIOR DOORS HAVE BEEN REPLACED.
- 4. THE POOL BATHROOMS HAVE BEEN REMODELED.
- 5. THE PARKING LOT HAS BEEN REPAVED AND RESTRIPED.
- 6. RAILINGS HAVE BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PIPING AND FIXTURES HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELINGS, INCLUDING THE BATHS LOCATED AT THE COMMUNITY POOT.
- 2. AN EXTERIOR SHOWER WAS INSTALLED/REPLACED ON THE WALL OF THE POOL BATHROOM BUILDING.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING ALL OF THE KITCHEN AND BATH REMODELINGS, INCLUDING THE POOL BATHS.
- 2. MISCELLANEOUS EXTERIOR LIGHTING HAS BEEN INSTALLED.

FBC(2007) 109.10

WORK WAS COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

CITY COMMISSION MEETING ROOM - CITY HALL

MARCH 22, 2011 - 9:00 AM

CASE NO: CE10020705

CASE ADDR: 1400 NE 56 ST # 210

OWNER: ISLES AT CORAL RIDGE DEVELOPMENT

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. WOODEN FENCES HAVE BEEN INSTALLED.
- 2. THE DOCK HAS BEEN REBUILT.
- 3. EXTERIOR DOORS HAVE BEEN REPLACED.
- 4. THE POOL BATHROOMS HAVE BEEN REMODELED.
- 5. THE PARKING LOT HAS BEEN REPAVED AND RESTRIPED.
- 6. RAILINGS HAVE BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PIPING AND FIXTURES HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELINGS, INCLUDING THE BATHS LOCATED AT THE COMMUNITY POOL.
- 2. AN EXTERIOR SHOWER WAS INSTALLED/REPLACED ON THE WALL OF THE POOL BATHROOM BUILDING.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING ALL OF THE KITCHEN AND BATH REMODELINGS, INCLUDING THE POOL BATHS.
- 2. MISCELLANEOUS EXTERIOR LIGHTING HAS BEEN INSTALLED.

FBC(2007) 109.10

WORK WAS COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

CITY COMMISSION MEETING ROOM - CITY HALL MARCH 22, 2011 - 9:00 AM

CASE NO: CE10020706

CASE ADDR: 1400 NE 56 ST # 211

OWNER: ISLES AT CORAL RIDGE DEVELOPMENT

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. WOODEN FENCES HAVE BEEN INSTALLED.
- 2. THE DOCK HAS BEEN REBUILT.
- 3. EXTERIOR DOORS HAVE BEEN REPLACED.
- 4. THE POOL BATHROOMS HAVE BEEN REMODELED.
- 5. THE PARKING LOT HAS BEEN REPAVED AND RESTRIPED.
- 6. RAILINGS HAVE BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PIPING AND FIXTURES HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELINGS, INCLUDING THE BATHS LOCATED AT THE COMMUNITY POOL.
- 2. AN EXTERIOR SHOWER WAS INSTALLED/REPLACED ON THE WALL OF THE POOL BATHROOM BUILDING.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING ALL OF THE KITCHEN AND BATH REMODELINGS, INCLUDING THE POOL BATHS.
- 2. MISCELLANEOUS EXTERIOR LIGHTING HAS BEEN INSTALLED.

FBC(2007) 109.10

WORK WAS COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

THE EXTERIOR DOORS, DOCK, WOOD FENCES, AND RAILINGS HAVE NOT BEEN PROVEN TO SUFFICIENTLY WITHSTAND ESTIMATED OR ACTUAL IMPOSED DEAD, LIVE, WIND, OR ANY OTHER LOADS THROUGH THE PERMIT AND INSPECTION PROCESS.

56

MARCH 22, 2011 - 9:00 AM

CASE NO: CE08071578

CASE ADDR: 1731 NE 3 AV

OWNER: VOLPE, TODD D

INSPECTOR: BURT FORD

VIOLATIONS: FBC 708.3

THE FIRE SEPARATION HAS NOT BEEN MAINTAINED BETWEEN APARTMENT B AND THE EFFICIENCY.

FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. THE FRONT BEDROOM IN APARTMENT B HAS BEEN CONVERTED INTO AN EFFICIENCY.
- 2. TWO DECKS WERE REPLACED IN THE REAR YARD.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

1. CIRCUITS HAVE BEEN ADDED/ALTERED AND THE ELECTRICAL LOADS IMPOSED EXCEED THE ORIGINAL DESIGN CALCULATIONS IN THE EFFICIENCY.

FBC(2007) 110.1.1

THE USE OF THE PROPERTY HAS BEEN CHANGED FROM A DUPLEX TO A TRIPLEX WITHOUT OBTAINING A CERTIFICATE OF OCCUPANCY THROUGH THE PERMITTING AND INSPECTION PROCESS.

FBC(2007) 1604.1

THE DECK STRUCTURES HAVE NOT DEMONSTRATED TO BE ABLE TO COMPLY WITH THE STRENGTH REQUIREMENTS FOR THE LOADS IMPOSED THROUGH THE PERMIT AND INSPECTION PROCESS.

CITY COMMISSION MEETING ROOM - CITY HALL MARCH 22, 2011 - 9:00 AM

CASE NO: CE08080683

CASE ADDR: 1538 NE 3 AVE

OWNER: TUCHOW, TYLER

INSPECTOR: BURT FORD

VIOLATIONS: 9-281(a)

RUBBISH AND TRASH ARE LITTERING THE PREMISES.

REMOVE TRASH AND DEBRIS.

FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. WINDOWS WERE INSTALLED.
- 2. DOORS WERE INSTALLED.
- 3. A FENCE WAS INSTALLED.
- 4. VINYL SIDING WAS INSTALLED.
- 5. INTERIOR ALTERATIONS AND DRYWALL WERE DONE.
- 6. KITCHEN AND BATH REMODELING HAVE BEEN DONE.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. A WASHER WAS INSTALLED.
- 2. PIPING AND FIXTURES HAVE BEEN INSTALLED FOR THE KITCHEN AND BATH REMODELING.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. CIRCUITS HAVE BEEN ADDED/ALTERED FOR WINDOW AND WALL A/C UNITS.
- 2. CIRCUITS HAVE BEEN ADDED/ALTERED FOR WASHER AND DRYER THAT WERE INSTALLED.
- 3. CIRCUITS HAVE BEEN ADDED/ALTERED FOR THE KITCHEN AND BATH REMODELING.
- 4. CIRCUITS HAVE BEEN ADDED/ALTERED IN THE GENERAL INTERIOR WORK BEING DONE.

FBC(2007) 105.4.11

THE MECHANICAL SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

1. WALL AND WINDOW UNITS HAVE BEEN INSTALLED.

58

FBC(2007) 109.10

WORK HAS BEEN COVERED UP WITHOUT FIRST HAVING OBTAINED THE REQUIRED INSPECTION APPROVALS.

CASE NO: CE09020070

CASE ADDR: 2000 N OCEAN BLVD # HOTEL OWNER: URBANA PELICAN GRAND I LLC

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

1. A TENT ON THE BEACH SIDE OF THE PROPERTY AT THE SOUTH END HAS BEEN INSTALLED WITHOUT A PERMIT.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1.CIRCUITS HAVE BEEN INSTALLED TO POWER THE LIGHTING AND OUTLETS INSIDE THE TENT.

FBC(2007) 1612.1.2

THE TENT HAS NOT BEEN PROVEN TO SUFFICIENTLY WITHSTAND ESTIMATED OR ACTUAL IMPOSED DEAD, LIVE, WIND, OR ANY OTHER LOADS THROUGH THE PERMIT AND INSPECTION PROCESS.

HEARING TO IMPOSE FINES

CHAPTER 11, FORT LAUDEERDALE, CODE OF ORDINANCES

CASE NO: CE07031444

CASE ADDR: 2491 STATE ROAD 84
OWNER: BILL RICHARDSON TR

RICHARDSON, BILL

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC 1012.1

SAFEGUARDS HAVE BEEN INSTALLED ON THE TOP OF THE CBS OFFICE BUILDING AND ON THE BALCONY OVERLOOKING THE SOUTH OVERWATER BAY. THE STRENGTH REQUIREMENT FOR THE SAFEGUARDS HAS NOT BEEN DEMONSTRATED THROUGH THE PERMITTING PROCESS.

FBC 1012.3

THE SAFEGUARDS INSTALLED ON THE UPPER DECK OF THE CBS OFFICE BUILDING AND ON THE BALCONY OVERLOOKING THE SOUTH OVERWATER BOAT SLIP DO NOT HAVE THE REQUIRED BALUSTERS OR PATTERN TO PREVENT AN OBJECT OF FOUR INCH DIAMETER TO PASS THOUGH AND FALL FROM THE DECK.

FBC 105.1

THE FACILITY HAS BEEN EXPANDED BY CONSTRUCTION OF BUILDINGS. EXISTING FACILITIES HAVE BEEN ALTERED AND/OR EXPANDED IN SIZE. THE REQUIRED PERMITS FOR THIS WORK WERE NOT OBTAINED. THE CONSTRUCTION, ALTERATIONS, AND EXPANSIONS INCLUDE THE FOLLOWING:

- 1. CONSTRUCTION OF A LARGE WOOD FRAMED ENCLOSURE INSIDE THE YACHT REPAIR BUILDING.
- 2. CONSTRUCTION OF A SHADE PAVILION WITH A RED STREET SIGN ON IT. THE SIGN READS "DALE EARNHART JR DR."
- 3. REMOVAL OF LARGE SECTIONS OF BLOCK WALL FROM THE WEST EXPOSURE OF THE COVERED BOAT DOCKS.
- 4. INSTALLATION OF SEVERAL SMALL ACCESSORY BUILDINGS ADJOINING THE WEST EXPOSURE OF THE COVERED BOAT DOCKS.

THIS AREA HAS BEEN APPROVED AS A PARKING AREA.

5. CONSTRUCTION OF A CARPENTRY SHOP BUILDING ON THE WEST SIDE OF THE PROPERTY. THIS BUILDING IS ATTACHED TO THE SOUTH END OF AN ORIGINAL MASONRY BUILDING NOW USED AS A TOOL ROOM.

- 6. CONSTRUCTION OF A DUST COLLECTION TOWER ON THE WEST EDGE OF THE PROPERTY.
- 7. THE PLACEMENT OF FREIGHT CONTAINERS UTILIZED AS ACCESSORY BUILDINGS COMPLETE WITH ELECTRICAL POWER AND AIR CONDITIONING EQUIPMENT.
- 8. ENTRANCE GATES INSTALLED.
- 9. SAFEGUARDS INSTALLED ON THE ROOF OF THE OFFICE BUILDING.
- 10. OFFICE TRAILER INSTALLED AS A PERMANENT FACILITY COMPLETE WITH HANDICAP RAMP. THE NORTH SIDE IS AN OFFICE AND THE SOUTH SIDE IS A RESTROOM. IT IS CONSTRUCTED IN THE AREA APPROVED FOR OVERFLOW PARKING.
- 11. A ROOF STRUCTURE CONNECTING TWO MASONRY STRUCTURES ON THE WEST SIDE OF THE PROPERTY. THE BATTERY SHOP AND THE ORIGINAL SHOP ARE CONNECTED BY THIS ROOF.
- 12. A TUBE AND MEMBRANE STRUCTURE BEING USED FOR SPRAY PAINTING.
- 13. A BALCONY HAS BEEN CONSTRUCTED OVERLOOKING THE SOUTH BAY OF THE COVERED DOCKS. THE BALCONY FACES NORTH.
- 14. A DOOR HAS BEEN INSTALLED HIGH IN THE MASONRY WALL WHICH ALLOWS ACCESS TO THE BALCONY NOTED IN ITEM 13 ABOVE.
- 15. A STEEL SUPPORT SYSTEM HAS BEEN DEVISED TO SUPPORT A FREE AIR WIRING METHOD.

FBC 105.2.11

AIR CONDITIONING EQUIPMENT HAS BEEN INSTALLED THROUGHOUT THE FACILITY WITHOUT OBTAINING THE REQUIRED PERMIT. THE LOCATIONS INCLUDE, BUT ARE NOT LIMITED TO: THE MAIN OFFICE BUILDING, IN FREIGHT CONTAINERS USED AS ACCESSORY STRUCTURES, ACCESSORY SHEDS, THE OFFICE TRAILER AND THE ENCLOSURE INSIDE THE YACHT REPAIR BUILDING.

FBC 105.2.4

PLUMBING INSTALLATIONS HAVE BEEN DONE WITHOUT PERMITS. THE WORK INCLUDES:

- 1. THE PLUMBING CONNECTIONS FOR THE OFFICE TRAILER
- 2. A MISTING SYSTEM FOR THE PAVILION.
- 3. A COMPRESSED AIR DELIVERY SYSTEM.

FBC 105.2.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN EXPANDED, ALTERED AND OR REPAIRED REPEATEDLY WITHOUT OBTAINING THE REOUIRED PERMITS. THE WORK THAT HAS NOT BEEN PERMITTED AND NOT INSPECTED AS REQUIRED INCLUDES THE FOLLOWING:

- 1. THE OPEN WIRING SYSTEM HAS BEEN REPAIRED/REPLACED.
- 2. THE CARPENTER SHOP PREMISE WIRING.
- 3. ALL WIRING, FIXTURES AND OUTLETS INSTALLED IN SHEDS AND FREIGHT CONTAINERS.
- 4. ALL WIRING, FIXTURES AND OUTLETS INSTALLED IN THE LARGE FRAMED ENCLOSURE INSIDE THE YACHT REPAIR BUILDING.
- 5. ALL ELECTRICAL CONNECTIONS TO THE OFFICE TRAILER.
- 6. ALL ELECTRICAL ALTERATIONS CONNECTED TO THE INSTALLATION OF AIR CONDITIONING INSTALLED IN THE ORIGINAL CBS OFFICE.

FBC 1612.1.2

ALL THE CONSTRUCTION DONE WITHOUT PERMITS (SEE LIST SPECIFIED FOR F.B.C. 105.1) THAT IS SUBJECT TO WIND LOADING, GRAVITY LOADING AND ANY OTHER LOADING HAS NOT DEMONSTRATED THE REQUIRED STRENGTH OF MATERIAL AND DESIGN THROUGH THE PERMITTING PROCESS.

FBC-P 303.2

THE COMPRESSED AIR DELIVERY SYSTEM THAT HAS BEEN INSTALLED DOES NOT UTILIZE APPROVED PIPE. THE SYSTEM IS MADE FROM P.V.C. PIPE.

NEC 110-12(a)

ELECTRICAL EQUIPMENT IS NOT PROPERLY CONNECTED TO THE SYSTEM. MANY UNUSED OPENINGS IN THIS EQUIPMENT ARE NOT PROPERLY COVERED.

NEC 225.19(D)(1)

THE REQUIRED CLEARANCE FROM THE CONDUCTORS FASTENED TO THE WALL IS NOT PROVIDED WHERE THE DOORWAY PROVIDES ACCESS TO THE BALCONY WHICH OVERLOOKS THE COVERED BOAT SLIP ON THE SOUTH.

NEC 240.21(B)(1)(1)

THE TAP CONDUCTORS UTILIZED FOR THE OPEN FREE AIR WIRING SYSTEM ARE NOT FUSED ACCORDING TO APPROVED METHODS. THE OVER FUSING CONDITON DOES NOT PROVIDE THE DEGREE OF SAFETY REQUIRED BY THE CODE.

NEC 310.8(D)(2)

THE CONDUCTORS USED FOR THE OPEN FREE AIR WIRING SYSTEM ARE NOT APPROVED FOR THIS USE. THE CONDUCTORS ARE NOT RESISTANT TO U.V. LIGHT AS REQUIRED.

NEC 90.1 (A)

THE ELECTRICAL SYSTEM OF THE BUILDING IS NOT BEING MAINTAINED ACCORDING TO THE MINIMUM SAFTEY STANDARD OF THE NATIONAL ELECTRICAL CODE. DEFICIENCIES PERVADE THE ENTIRE SYSTEM.

NEC 90.1 (B)

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN EXPANDED REPEATEDLY WITHOUT PROPER PLANNING. WIRING SYSTEMS HAVE BEEN OVERLOADED BY METHODS AND USAGE NOT IN CONFORMITY TO THE NATIONAL ELECTRICAL CODE. THIS HAS OCCURRED BECAUSE THE INITIAL WIRING DID NOT PROVIDE ADEOUATELY FOR FUTURE INCREASES OF ELECTRICAL USE.

NFPA 101:39.2.4.1

TWO EXITS ARE NOT PROVIDED FROM THE 2ND FLOOR OFFICE AREA.

NFPA 1:18.2.2.5.8

FIRE LANE SIGNS ARE NOT PROVIDED CONSISTENT WITH THE CODE.

NFPA 303:2.1

NO SMOKING SIGNS ARE NOT PROVIDED IN ACCORDANCE WITH THE CODE.

NFPA 303:4.10.2

FIRE DETECTORS ARE NOT PROVIDED IN ACCORDANCE WITH THE CODE.

NFPA 303:4.3.2

AN APPROVED FIRE SPRINKLER SYSTEM IS NOT PROVIDED FOR ALL MARINA AND BOATYARD BUILDINGS IN EXCESS OF 5000 SQUARE FT.

NFPA 303:4.4.1

DOCK FIRE LINE IS NOT PROVIDED.

NFPA 303:4.5

FIRE HYDRANTS ARE NOT PROVIDED IN ACCORDANCE WITH THE CODE.

NFPA 33:5.1

TARPS, PLASTIC SHEETING AND OTHER COMBUSTIBLE MATERIALS ARE BEING USED IN THE PLACE OF A SPRAY BOOTH.

NFPA 33:6.3.1

DISPENSING, TRANSFER, MIXING AND FILLING CONTAINERS WITH FLAMMABLE LIQUIDS IS BEING DONE OUTSIDE OF MIXING ROOMS OR SPRAY AREAS.

NFPA 33:7.1

SPRAY AREAS ARE NOT PROTECTED BY AN APPROVED FIRE PROTECTION SYSTEM.

CASE NO: CE08010523

CASE ADDR: 2251 SW 27 LANE

BRIGHT, RICKEY DEAN OWNER:

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

- 1. THERE IS TOTAL INTERIOR REMODELING WORK: NEW KITCHEN, BATHROOMS, CABINETS AND FIXTURES.
- 2. COLUMNS SUPPORTING THE TIE BEAM IN REAR OF BUILDING HAVE BEEN REMOVED.
- 3. PARTITIONS WERE REMOVED AND NEW ONES ARE BEING BUILT. GLASS BLOCK UNITS WERE INSTALLED AT THE ENTRANCE.
- 4. ROOF WORK IS BEING DONE. AN ALUMINUM ROOF COVER IS ON TOP OF A CONCRETE SLAB IN THE REAR OF THE DWELLING.
- 5. WINDOWS AND DOORS ARE BEING REPLACED.

FBC 105.2.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. THE PLUMBING FIXTURES FOR THE KITCHEN AND BATHROOMS ARE BEING REPLACED.

FBC 105.2.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. ELECTRICAL LOAD DEMAND WAS INCREASED BY ADDING ADDITIONAL LIGHTS AND WALL OUTLETS THAT HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED AMPERAGE LOADING THROUGH THE PERMITTING PROCESS.

FBC 105.2.11

THE MECHANICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. THE CENTRAL A/C UNITS ARE BEING REPLACED.
- 2. THE DUCT WORK IS BEING REPLACED.
- 3. VENTILATION FOR THE BATHROOMS AND KITCHEN ARE BEING REPLACED.

FBC 109.6

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS THROUGH THE PERMITTING AND INSPECTION PROCESS.

FBC 1604.1

THE STRUCTURE FOR THE ROOF DOES NOT MEET THE STANDARD FOR GRAVITY LOADING AND HAS NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS.

CASE NO: CE08020178 CASE ADDR: 3621 SW 22 ST OWNER: MARTIN, IDANIA INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS: 1. KITCHEN WAS REMODELED, NEW FIXTURES WERE ADDED.

- 2. NEW CABINETS WERE INSTALLED.
- 3. SHED WAS INSTALLED IN THE REAR OF THE PROPERTY.

FBC 105.2.11

THE MECHANICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO: 1. THE EXHAUST FAN WITH THE VENTILATION DUCT WAS REPLACED.

FBC 105.2.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO: 1. SINK AND FAUCET WERE REPLACED IN THE KITCHEN.

FBC 105.2.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO: 1. ELECTRICAL LOAD DEMAND WAS INCREASED BY ADDING ADDITIONAL LIGHTS, WALL OUTLETS AND HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED LOADING THROUGH THE PERMITTING PROCESS.

FBC 109.6

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS THROUGH THE PERMITTING PROCESS.

66

CODE ENFORCEMENT BOARD AGENDA CITY COMMISSION MEETING ROOM - CITY HALL

MARCH 22, 2011 - 9:00 AM

CASE NO: CE10071965 CASE ADDR: 2308 NW 14 CT

OWNER: AMSTAR ACQUISTIONS LLC

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

- 1. INTERIOR REMODELING WORK IN THE KITCHEN AND BATHROOM.
- 2. NEW CABINETS WERE INSTALLED
- 3. ALL THE FIXTURES WERE REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. PLUMBING FIXTURES WERE REPLACED - SINK, FAUCETS, LAVATORY IN THE BATHROOM AND KITCHEN AREAS.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. ELECTRICAL LOAD DEMAND WAS INCREASED BY ADDING ADDITIONAL LIGHTS AND WALL OUTLETS THAT HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED AMPERAGE LOADING THROUGH THE PERMITTING PROCESS.

FBC(2007) 109.10

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS THROUGH THE PERMITTING AND INSPECTION PROCESS.

67

MARCH 22, 2011 - 9:00 AM

CASE NO: CE10081013 CASE ADDR: 3340 SW 18 ST

OWNER: FEDERAL NATIONAL MORTGAGE ASSN

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

- 1. THE CARPORT WAS ENCLOSED AND CONVERTED INTO LIVING SPACE.
- 2. THE REAR PORCH WAS ENCLOSED AND CONVERTED INTO LIVING SPACE WITH AN ILLEGAL ADDITION ADDED TO THE REAR ENCLOSURE.
- 3. THE KITCHEN AND BATHROOMS WERE REMODELED WITH NEW FIXTURES AND CABINETS.
- 4. SKYLIGHTS WERE INSTALLED ON TOP OF THE ROOF OVER THE KITCHEN AREA.
- 5. WINDOWS AND DOORS WERE REPLACED.
- 6. A SHED WAS BUILT OUT OF PLYWOOD AND 2X4 AT THE REAR OF THE PROPERTY AND IS OVER THE SETBACK LINE.
- 7. INTERIOR STRUCTURAL ALTERATIONS WERE DONE TO CONVERT THE DWELLING INTO A ROOMING HOUSE.
- 8. A CENTRAL A/C WAS INSTALLED WITH CENTRAL HEAT AND A WALL UNIT WAS PLACED IN THE ENCLOSED CARPORT.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. THE KITCHEN AND BATHROOMS WERE REMODELED WITH NEW FIXTURES.
- 2. THE LAUNDRY ROOM BEHIND THE CARPORT WAS CONVERTED INTO ANOTHER BATHROOM.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. THE ELECTRICAL LOAD DEMAND WAS INCREASED BY ADDING ADDITIONAL LIGHTS AND WALL OUTLETS IN THE ENCLOSED CARPORT, REAR PORCH AND THE ILLEGAL ADDITION. THEY HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED AMPERAGE LOADING THROUGH THE PERMITTING PROCESS.

CODE ENFORCEMENT BOARD AGENDA
CITY COMMISSION MEETING ROOM - CITY HALL
MARCH 22, 2011 - 9:00 AM

FBC(2007) 105.4.11

THE MECHANICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. A CENTRAL A/C WITH DUCT WORK AND AN ELECTRICAL HEATER WAS INSTALLED IN THE MAIN HOUSE.
- 2. A WALL A/C UNIT WAS PLACED IN THE WALL OF THE ILLEGALLY ENCLOSED CARPORT.

FBC(2007) 1604.1

THE STRUCTURES FOR THE CARPORT, REAR PORCH WITH THE ADDITION ENCLOSURES, AND THE SHED DO NOT MEET THE STANDARD FOR GRAVITY LOADING AND HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS. ALL THE STRUCTURES THAT WERE DONE ILLEGALLY ARE DEEMED TO BE UNSAFE AND THE CONSTRUCTION IS UNDERDESIGNED. IT WOULD NOT PROVIDE THE REQUIRED RESISTANCE TO UPLIFT WHICH THE CODE PROTECTS NEIGHBORS FROM FLYING DEBRIS IN A STORM AND WHICH THIS STRUCTURE MAY BECOME, SO THEY MUST BE REMOVED.

FBC(2007) 1612.1.2

ALL THE WINDOWS, DOORS AND SKYLIGHT INSTALLATIONS HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS.

FBC(2007) 1626.1

THE NEW WINDOWS, DOOR AND SKYLIGHTS WITH GLASS NEED TO BE IMPACT RESISTANT OR BE PROTECTED BY AN APPROVED HURRICANE PROTECTION SYSTEM.

CITY COMMISSION MEETING ROOM - CITY HALL

MARCH 22, 2011 - 9:00 AM

CASE NO: CE10081762 CASE ADDR: 2000 NW 13 AVE

OWNER: BAC HOME LOANS SERVICING LP

% MARSHALL C WATSON PA

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

- 1. A WOOD FENCE WAS INSTALLED WITH AN ISSUED PERMIT FROM DECEMBER 12, 1997 AND WAS VOIDED BY THE OWNER AFTER THE WORK WAS DONE WITHOUT INSPECTION.
- 2. DRIVEWAY PAVERS WORK WAS DONE WITH AN APPLIED PERMIT FROM JULY 25,2005.
- 3. THE ELECTRICAL SERVICE WAS UPGRADED WITH A PERMIT THAT WAS ISSUED MARCH 29, 2005 AND WAS ALLOWED TO EXPIRE WITHOUT INSPECTIONS.
- 4. A STORAGE SHED WAS PLACED AT THE REAR OF THE PROPERTY.
- 5. THE KITCHEN AREA WAS REMODELED WITH NEW CABINETS AND FIXTURES.

FBC(2007) 105.10.3.1

THERE IS A BUILDING PERMIT WHICH FAILED INSPECTION AND/OR WAS LEFT TO EXPIRE FOR THE ELECTRICAL UPGRADE:

1. PERMIT #05032883 ISSUED JULY 27,2005. NO INSPECTIONS.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. KITCHEN WAS REMODELED WITH NEW CABINETS. THE PLUMBING FIXTURES WERE REPLACED.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT OR FINAL INSPECTIONS IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. THE ELECTRICAL SERVICE AND BREAKERS PANEL WAS UPGRADED.

MARCH 22, 2011 - 9:00 AM

2. THE LOAD DEMAND WAS INCREASED BY ADDING ADDITIONAL LIGHTS AND WALL OUTLETS THAT HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED AMPERAGE LOADING THROUGH THE PERMITTING AND INSPECTION PROCESS.

FBC(2007) 109.10

ALL THE WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS THROUGH THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE10090682 CASE ADDR: 1937 NW 9 AVE

OWNER: CRP II-LAUDERDALE MANOR LLC

INSPECTOR: GEORGE OLIVA

VIOLATIONS: 5-26(b)

OPERATING A BUSINESS LOCATED WITHIN THREE HUNDRED FEET OF ANOTHER BUSINESS WITH A VENDOR LICENSE TO SELL ALCOHOLIC BEVERAGES FOR CONSUMPTION ON OR OFF THE PREMISES IS PROHIBITED AND REQUIRES A CONDITIONAL USE PERMIT PER SECTION 47-24-3.

1. 1951 NW 9 AVE - DIVINITY LOUNGE #720001 OPERATIONAL LICENSE GOOD TILL 9/30/11 - FOR NIGHT CLUB.

FBC 1019.11.5.1

AN ACCESSIBLE MEANS OF EGRESS IS ONE THAT COMPLIES WITH THIS CODE AND THE MINIMUM NUMBER OF EXITS REQUIRED SHALL BE PROVIDED AND HAVE ACCESS TO ALL THE OCCUPANT LOAD.

FBC(2007) 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

- 1. CABINETRY IS BEING DONE BY THE BAR AREA.
- 2. COUNTERTOP SINKS AND ELECTRICAL OUTLETS ARE BEING INSTALLED.
- 3. A NEW THREE TANK SINK IS BEING INSTALLED BY THE KITCHEN AREA.
- 4. WINDOWS AND DOORS ARE NOT MAINTAINED IN A SECURE MANNER. SOME OF THE GLASS PANES ARE BROKEN AND COVERED WITH PLYWOOD.

FBC(2007) 105.1.5

AS PER S. 500.12, FLORIDA STATUTES, A FOOD PERMIT FROM THE DEPARTMENT OF AGRICULTURE AND CONSUMER SERVICES IS REQUIRED OF ANY PERSON WHO OPERATES A FOOD ESTABLISHMENT.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. THERE IS A DRAIN AND RUNNING WATER SUPPLY PIPES BEING INSTALLED IN THE KITCHEN AND BAR AREAS.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. ELECTRICAL LOAD DEMAND WAS INCREASED BY ADDING ADDITIONAL LIGHTS AND WALL OUTLETS THAT HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED AMPERAGE LOADING THROUGH THE PERMITTING PROCESS.
- 2. THERE ARE EXPOSED WIRES IN WALL OUTLETS & LIGHTS
- 3. SOME OF THE PROTECTIVE COVERS IN THE ELECTRIC BOXES ARE MISSING.

FBC(2007) 105.4.11

THE MECHANICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. MECHANICAL VENTILATION AND THE EXAUST SYSTEM FROM THE KITCHEN AREA MUST COMPLY WITH THE FBC(2007)MECHANICAL.
- 2. A PERMIT IS REQUIRED TO INSTALL A WALL UNIT IN THE KITCHEN WALL AND CENTRAL A/C DUCT WORK.

FBC(2007) 105.4.15

A PERMIT IS NEEDED TO REPAIR OR REPLACE ANY REQUIRED IMPACT-RESISTANT OR TEMPERED GLASS FOR EXTERIOR WINDOWS AND GLASS DOORS IN A NEW OR EXISTING BUILDING.

FBC(2007) 110.1.1

MUST OBTAIN THE REQUIRED CERTIFICATE OF OCCUPANCY BEFORE OPENING FOR BUSINESS.

CITY OF FORT LAUDERDALE Page 72 CODE ENFORCEMENT BOARD AGENDA

CITY COMMISSION MEETING ROOM - CITY HALL

MARCH 22, 2011 - 9:00 AM

CASE NO: CE05110901 CASE ADDR: 1629 NE 12 ST

MCDERMOTT DEVELOPMENT LLC OWNER:

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REOUIRED PERMITS: 1. A FENCE WAS INSTALLED WITHOUT FIRST OBTAINING A PERMIT. PERMIT APPLICATION 06033358 WAS APPLIED FOR BUT NEVER PICKED UP.

FBC(2007) 109.10

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

THE WOOD FENCE HAS NOT BEEN PROVEN TO SUFFICIENTLY WITHSTAND ESTIMATED OR ACTUAL IMPOSED DEAD, LIVE, WIND, OR ANY OTHER LOADS THROUGH THE PERMIT AND

INSPECTION PROCESS.

CASE NO: CE07080634

CASE ADDR: 430 ARIZONA AVE

OWNER: GRANT, CLAUDETTE B H/E

GRANT, DONALD

INSPECTOR: BURT FORD

VIOLATIONS: FBC 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. NEW WINDOWS HAVE BEEN INSTALLED.
- 2. NEW DOORS HAVE BEEN INSTALLED.
- 3. STUCCO WORK IS BEING DONE.
- 4. THERE ARE REPAIRS BEING DONE TO THE SOFFIT.
- 5. THERE IS INTERIOR REMODELING BEING DONE.
- 6. THERE HAS BEEN BLOCK INSTALLED WHERE WALL A/C'S HAVE BEEN REMOVED.

FBC 105.2.11

THE MECHANICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO: 1. WALL AIR CONDITIONERS HAVE BEEN INSTALLED.

CITY COMMISSION MEETING ROOM - CITY HALL MARCH 22, 2011 - 9:00 AM

FBC 105.2.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. PLUMBING FIXTURES HAVE BEEN REPLACED WHILE PERFORMING INTERIOR REMODELING.

FBC 105.2.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. NEW ELECTRICAL WIRING IS BEING RUN ALONG THE SOFFIT AND INTO THE ROOF AREA.
- 2. A SERVICE UPGRADE HAS BEEN DONE.

FBC 109.6

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC 1604.1

THE WINDOWS AND DOOR(S) HAVE NOT BEEN DEMONSTRATED TO BE ABLE TO WITHSTAND WIND LOAD REQUIREMENTS THROUGH THE PERMIT AND INSPECTION PROCESS.

FBC 1626.1

THE NEW WINDOWS NEED TO BE IMPACT GLASS OR HAVE AN APPROVED METHOD OF HURRICANE PROTECTION.

CITY COMMISSION MEETING ROOM - CITY HALL

MARCH 22, 2011 - 9:00 AM

CASE NO: CE08021545 CASE ADDR: 900 NE 26 AV

OWNER: SUNRISE INTRACOASTAL DENTAL CTR

INSPECTOR: BURT FORD

VIOLATIONS: FBC 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

1. THE ENTIRE FIRST FLOOR IS BEING REMODELED.

- 2. INTERIOR WALLS HAVE BEEN FRAMED.
- 3. DRYWALL HAS BEEN INSTALLED AND TAPED.
- 4. NEW EXTERIOR DOORS HAVE BEEN INSTALLED.

FBC 105.2.11

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. WORK HAS BEEN DONE ON THE A/C SYSTEM.

FBC 105.2.4

THE PLUMBING SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. NEW PIPING AND FIXTURES ARE BEING REPLACED IN THE REMODELED BATHROOMS AND KITCHEN.

FBC 105.2.5

THE ELECTRICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. CIRCUITS HAVE BEEN ADDED/ALTERED DURING THE FIRST FLOOR REMODELING.

FBC 106.10.3.1

THE FOLLOWING PERMITS HAVE EXPIRED:

- 1. 00021729 DEMO 800SF OF EXTERIOR WALL.
- 2. 05050161 ELECTRICAL WORK AFTER FIRE.

FBC 109.6

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC 1612.1.2

THE EXTERIOR DOORS HAVE NOT BEEN PROVEN TO SUFFICIENTLY WITHSTAND ESTIMATED OR ACTUAL IMPOSED DEAD, LIVE, WIND, OR ANY OTHER LOADS THROUGH THE PERMIT AND INSPECTION PROCESS.

CITY OF FORT LAUDERDALE Page

75

CODE ENFORCEMENT BOARD AGENDA

CITY COMMISSION MEETING ROOM - CITY HALL

MARCH 22, 2011 - 9:00 AM

CASE NO: CE08110858 CASE ADDR: 1000 NW 52 ST

OWNER: US PAVERS & SUPPLIERS INC

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

1. A CHAIN LINK FENCE HAS BEEN INSTALLED.

2. PAVERS HAVE BEEN INSTALLED.

FBC(2007) 109.10

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING

THE REQUIRED APPROVALS.

CASE NO: CE10061265

CASE ADDR: 536 W MELROSE CIR

OWNER: FEDERAL NATIONAL MORTGAGE ASSN

% MARSHALL C WATSON PA

INSPECTOR: BURT FORD

VIOLATIONS: 9-280(g)

THERE ARE EXPOSED WIRES IN A JUNCTION BOX ON THE EXTERIOR WALL IN THE BACK OF THE BUILDING.

FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. THE PORCH, IN THE REAR OF THE BUILDING, HAS BEEN ENCLOSED. IT APPEARS TO BE 2X4 FRAMING AND CONVERTED INTO AN EXTRA BEDROOM.
- 2. NEW DOOR(S) HAVE BEEN INSTALLED IN THE PORCH CONVERSION.
- 3. NEW WINDOWS HAVE BEEN INSTALLED IN THE PORCH CONVERSION.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

- 1. THE BATHROOM IN THE MAIN HOUSE HAS A NEW TOILET, NEW SINK, AND NEW FIXTURES.
- 2. A SINK AND FIXTURES HAS BEEN INSTALLED IN THE PORCH CONVERSION.

MARCH 22, 2011 - 9:00 AM

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. ELECTRICAL CIRCUITS WERE ADDED TO THE PORCH CONVERSION.

FBC(2007) 105.4.11

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. A WALL AIR CONDITIONER HAVE BEEN INSTALLED IN THE PORCH CONVERSION.

FBC(2007) 109.10

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

CASE NO: CE10120236

CASE ADDR: 1717 SW 17 ST

OWNER: HOUCK, STEVE

INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC(2007) 3304.1

THE OPEN FOOTERS EXCAVATED FOR A MASONRY WALL ARE

NOT PROTECTED AND ARE ENDANGERING LIFE AND

PROPERTY.

FBC(2007) 3306.1

PEDESTRIANS AND THE COMMUNITY ARE NOT PROTECTED DURING THE CONSTRUCTION OF THE MASONRY WALL.

CASE NO: CE09060554

CASE ADDR: 1121 GUAVA ISLE
OWNER: YOHAM, JEFFREY
INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC 105.1

A BOAT LIFT HAS BEEN INSTALLED WITHOUT OBTAINING

THE REQUIRED PERMITS.
