NEW BUSINESS				
OWNER:	CE06120242 420 SE 13 ST JOHNSON, ALEXANDER P WAYNE STRAWN			
VIOLATIONS:	47-21.3. THE PARCEL OF LAND HAS BEEN CHANGED IN USE FROM A SINGLE FAMILY DWELLING TO AN OFFICE AND THE REAR YARD PAVED OVER WITHOUT PROVIDING THE REQUIRED LANDSCAPING.			
	47-24.1.B. THE USE OF THE SITE HAS BEEN CHANGED WITHOUT FIRST OBTAINING A DEVELOPMENT PERMIT FROM THE CITY.			
	FBC 105.1 THE FOLLOWING ALTERATIONS AND CONSTRUCTION PROJECTS HAVE BEEN ACCOMPLISHED WITHOUT OBTAINING THE REQUIRED PERMITS:			
	 THE BUILDING HAS BEEN CHANGED IN OCCUPANCY. THE REAR YARD HAS BEEN PAVED OVER. THE GARAGE HAS BEEN CONVERTED INTO LIVING AREA WITH THE GARAGE DOORS REMOVED AND A WINDOW INSTALLED. A RAMP HAS BEEN CONSTRUCTED TO PROVIDE ACCESS FROM THE PARKING LOT TO THE BUILDING. THE REAR SCREEN PORCH HAS BEEN ALTERED. THE SCREENING HAS BEEN REMOVED AND WINDOWS INSTALLED. 			
	FBC 105.2.11 A CENTRAL AIR-CONDITIONING SYSTEM HAS BEEN INSTALLED WITHOUT OBTAINING A PERMIT.			
	FBC 11-1.2 THE BUILDING AND PROPERTY FORMERLY APPROVED FOR A RESIDENCE HAS BEEN ALTERED TO ACCOMMODATE A LAW OFFICE. THE REQUIRED ACCESSIBILITY FOR THE DISABLED HAS NOT BEEN PROVIDED.			

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

FBC 110.1.1 THE BUILDING IS BEING UTILIZED AS AN OFFICE BUILDING WITHOUT OBTAINING A CERTIFICATE OF OCCUPANCY FOR USE AS AN OFFICE BUILDING. THE BUILDING WAS PREVIOUSLY APPROVED FOR USE AS A SINGLE FAMILY DWELLING.

CASE NO:	CE06110858					
CASE ADDR:	1640 NW 12 CT					
OWNER:	HEZRECO LLC					

OWNER.	REAKECO DDC				
INSPECTOR:	WAYNE	STRAWN			

VIOLATIONS: FBC 105.1 THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. NEW WINDOWS WERE INSTALLED.
- 2. THE KITCHEN WAS REMODELED.
- 3. THE CARPORT WAS ENCLOSED.
- 4. AN UN-PERMITTED BATHROOM WAS INSTALLED IN THE ILLEGAL CARPORT CONVERSION.
- 5. EXTERIOR DOORS WERE INSTALLED/REPLACED.
- 6. THE SCREEN PORCH AT THE REAR OF THE BUILDING HAS BEEN ALTERED BY THE REMOVAL OF THE SUPPORT SYSTEM. WOODEN RAFTERS AND VERTICAL WOOD FRAMING NOW SUPPORT THE ORIGINAL METAL ROOF OF THE SCREENED PORCH.
- 7. A CONCRETE DRIVEWAY HAS BEEN INSTALLED.

FBC 105.2.11

THE MECHANICAL SYSTEM 1 OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

A CENTRAL A/C UNIT HAS BEEN INSTALLED.

FBC 105.2.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. BATHROOM WAS INSTALLED IN THE ILLEGAL CARPORT CONVERSION.
- 2. KITCHEN SINKS WERE REPLACED.
- 3. A DISHWASHER AND DISPOSAL WERE INSTALLED.
- 4. A TANKLESS WATER HEATER WAS INSTALLED.

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

FBC 105.2.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. KITCHEN WAS REMODELED AND OUTLETS WERE MOVED AND OR ADDED.
- 2. AN ILLEGAL BATHROOM WAS INSTALLED AND OUTLETS WERE ADDED.
- 3. CIRCUITS FOR CARPORT CONVERSION WERE ADDED.
- 4. CIRCUITS FOR THE CENTRAL A/C WERE ADDED.
- FBC 109.6

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS AND PERMITS.

FBC 1604.1

THE SCREEN PORCH ENCLOSURE WAS NOT CONSTRUCTED IN ACCORDANCE WITH STRENGTH REQUIREMENTS FOR THE LOADS IMPOSED.

FBC 1626.1

EVERY NEW WINDOW INSTALLED MUST NOW BE PROTECTED WITH APPROVED HURRICANE SHUTTERS AND INSTALLED BY A LICENSED CONTRACTOR.

FBC-M 402.3.1
THE ADDED BATHROOM DOES NOT HAVE A MEANS OF
VENTILATION.

CASE NO:	CE06030553	
CASE ADDR:	3901 SW 16 ST	
OWNER:	3901 DAVIE ASSOCIATES LLC	
INSPECTOR:	JORG HRUSCHKA	

VIOLATIONS: 47-19.4.D.1. BULK CONTAINER PLACEMENT AND ENCLOSURE IS NOT PROVIDED.

> 47-20.20.H. THE PARKING LOT IS IN DISREPAIR. IT HAS POTHOLES.

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

47-21.9.G.1.

A LANDSCAPE PLAN IS REQUIRED TO BE ON FILE WITH THE CITY OF FORT LAUDERDALE. THIS PLAN MUST DEMONSTRATE COMPLIANCE WITH THE 50% RETROACTIVE REQUIREMENT FOR LANDSCAPING. THIS LANDSCAPE PLAN IS NOT ON FILE WITH THE CITY OF FORT LAUDERDALE. THE PROPERTY DOES NOT HAVE THE REQUIRED RETROACTIVE LANDSCAPING.

47-21.9.G.2.

A LANDSCAPE PLAN IS REQUIRED TO BE ON FILE WITH THE CITY OF FORT LAUDERDALE. THIS PLAN MUST DEMONSTRATE COMPLIANCE WITH THE 50% RETROACTIVE REQUIREMENT FOR LANDSCAPING. THIS LANDSCAPE PLAN IS NOT ON FILE WITH THE CITY OF FORT LAUDERDALE. THE PROPERTY DOES NOT HAVE THE REQUIRED RETROACTIVE LANDSCAPING.

47-22.9

OUTSIDE SIGN INSTALLED WITHOUT A PERMIT.

9-280(b)

THE WALLS ARE IN DISREPAIR AND HAVE HOLES, INCLUDING BUT NOT LIMITED TO THE REAR OF THE BUILDING.

9-280(g)

THERE ARE EXPOSED WIRES AND MISSING LIGHTS.

9-281(b)

THERE ARE TRASH, RUBBISH AND DEBRIS ON THE PROPERTY.

9-305

THIS BUILDING IS NOT MAINTAINED IN A SECURE AND ATTRACTIVE MANNER.

- 1. SAGGING AND DETERIORATED OVERHANG SECTIONS ARE NOT STRUCTURALLY SOUND.
- 2. A ROLL UP SHUTTER AT 3911 IS NOT ATTACHED TO THE WALL PROPERLY AND IS LEANING PRECARIOUSLY.
- 3. WALLS IN THE REAR ARE MISSING PAINT.
- 4. THERE ARE HOLES IN THE WALL.
- 5. THE BOTTOM OF A DOOR WAS COVERED WITH CONCRETE, BLOCKING EGRESS FROM THE BUILDING.

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

9-306

THIS BUILDING IS NOT MAINTAINED IN A SECURE AND ATTRACTIVE MANNER.

- 1. SAGGING AND DETERIORATED OVERHANG SECTIONS ARE NOT STRUCTURALLY SOUND.
- 2. A ROLL UP SHUTTER AT 3911 IS NOT ATTACHED TO THE WALL PROPERLY AND IS LEANING PRECARIOUSLY.
- 3. WALLS IN THE REAR ARE MISSING PAINT.
- 4. THERE ARE HOLES IN THE WALL.
- 5. THE BOTTOM OF A DOOR WAS COVERED WITH CONCRETE, BLOCKING EGRESS FROM THE BUILDING.
- 9-308(a)

THE ROOF IS NOT MAINTAINED IN A SAFE, CLEAN AND WATERTIGHT CONDITION.

FBC 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. STRUCTURAL REPAIRS WERE DONE TO OVERHANG SECTION AT UNIT 3903.
- 2. A SLIDING DOOR WAS REMOVED AND REPLACED WITH A WALL AT UNIT 3901.
- 3. THE PARKING LOT WAS RE-STRIPED (PERMIT APPLICATION 04090544 WAS SUBMITTED, BUT WAS NEVER ISSUED)
- 4. WINDOW OPENINGS WERE BLOCKED OFF.
- 5. EXTERIOR STEEL DOORS WERE REPLACED.
- 6. SEVERAL APPROXIMATELY 3X3 ENTRY AREA PADS WERE POURED AT REAR OF THE BUILDING, ESPECIALLY UNITS 3913-3927.
- 7. THE BARBERSHOP AT 3912 AND UNIT 3919 WERE FIRE-DAMAGED IN 2000 AND WERE REBUILT.
- 8. THE BOTTOM OF THE REAR EXIT DOOR OF UNIT 3911 HAS BEEN COVERED WITH CONCRETE AND CANNOT BE OPENED FROM THE INSIDE. THIS DEPRIVES THE TENANT OF A SECONDARY MEANS OF EGRESS IN CASE OF FIRE.

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

FBC 105.2.11

THE MECHANICAL SYSTEMS OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

CENTRAL A/C UNITS AND OTHER MECHANICAL SYSTEMS HAVE BEEN INSTALLED, RELOCATED AND OR REPLACED IN MULTIPLE UNITS.

FBC 105.2.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

PERMIT 06062347 WAS ISSUED, BUT NEVER CLOSED OUT.

FBC 105.2.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

EXTERIOR AND INTERIOR OUTLETS, INCLUDING BUT NOT LIMITED TO UNITS 3913-3921.

FBC 109.6

WORK WAS DONE AND COVERED UP WITHOUT HAVING PASSED THE REQUIRED INSPECTIONS.

FBC 1522.2

ROOF TOP MOUNTED EQUIPMENT AND SUPPORT IS NOT SECURED TO THE STRUCTURE IN COMPLIANCE WITH THE LOAD REQUIREMENTS FOR HIGH VELOCITY HURRICANES ZONES.

FBC 1604.1

THE REPAIR OF THE ROOF OVERHANG IS NOT DESIGNED AND CONSTRUCTED ACCORDING TO THE STRENGTH REQUIREMENTS FOR THE LOADS IMPOSED. THE WALL INSTALLATION AT 3901 IS NOT DESIGNED AND CONSTRUCTED ACCORDING TO THE STRENGTH REQUIREMENTS FOR THE LOADS IMPOSED.

INSPECTOR:	CE07120414 2880 SW 16 ST APOSTOLIC ALLIANCE CHURCH OF THE LORD JESUS CHRIST, INC THOMAS CLEMENTS NFPA 1 1.7.5.1
	UNABLE TO GAIN ENTRY TO PERFORM A FIRE SAFETY INSPECTION.
OWNER:	CE07120386 3128 SW 12 PL CELESTIN, OLINCE THOMAS CLEMENTS
	NFPA 101 31.3.4.5.1 HARDWIRED SMOKE DETECTORS NOT INSTALLED.
CASE NO: CASE ADDR: OWNER:	
VIOLATIONS:	NFPA 1 1.12.1 INTERIOR RENOVATIONS WERE PERFORMED WITHOUT OBTAINING A PERMIT.
OWNER:	CE07120387 3400 SW 12 PL AMERICAN ONE RENTALS INC THOMAS CLEMENTS
VIOLATIONS:	NFPA 101 31.3.4.5.1 HARDWIRED SMOKE DETECTORS NOT INSTALLED.
CASE NO: CASE ADDR: OWNER: INSPECTOR:	CE07120415 3408 W BROWARD BLVD WILLIAMS, LORETTA & WILLIAMS, RUPERT THOMAS CLEMENTS
VIOLATIONS:	NFPA 1 1.7.5.1 UNABLE TO GAIN ENTRY TO PERFORM A FIRE SAFETY INSPECTION.

OWNER: INSPECTOR:	CE07091105 3412 W BROWARD BLVD WILLIAMS, LORETTA & WILLIAMS, RUPERT THOMAS CLEMENTS NFPA 1 1.7.5.1
	UNABLE TO GAIN ENTRY TO PERFORM A FIRE SAFETY INSPECTION.
OWNER:	CE07120395 3709 SW 12 PL HOWARD, CHARLENE THOMAS CLEMENTS
VIOLATIONS:	NFPA 101 31.3.4.5.1 HARDWIRED SMOKE DETECTORS NOT INSTALLED.
OWNER:	CE07120397 3711 SW 12 PL HOWARD, CHARLENE THOMAS CLEMENTS
	NFPA 101 31.3.4.5.1 HARDWIRED SMOKE DETECTORS NOT INSTALLED.
OWNER:	CE07120380 3760 SW 1 ST LEVY, CHERYL & LEVY, JOSEPH
	THOMAS CLEMENTS NFPA 101 31.3.4.5.1 HARDWIRED SMOKE DETECTORS NOT INSTALLED
CASE NO: CASE ADDR: OWNER: INSPECTOR:	CE07120382 3811 SW 12 CT RAHIM, DIRK THOMAS CLEMENTS
VIOLATIONS:	NFPA 101 31.3.4.5.1 HARDWIRED SMOKE DETECTORS NOT INSTALLED.

CASE NO:	CE07120383
CASE ADDR:	3827 SW 12 CT KELLERMAN, JOY J
OWNER: INSPECTOR:	KELLERMAN, JOY J THOMAS CLEMENTS
INSPECION.	THOMAS CHEMENIS
VIOLATIONS:	NFPA 101 31.3.4.5.1
	HARDWIRED SMOKE DETECTORS NOT INSTALLED.
CASE NO:	
CASE ADDR:	3831 SW 12 PL
OWNER:	THOMAS, MICHAEL
INSPECTOR:	THOMAS CLEMENTS
VIOLATIONS:	NFPA 101 31.3.4.5.1
	HARDWIRED SMOKE DETECTORS NOT INSTALLED.
CASE NO:	CE07120384
	3906 SW 12 CT
OWNER:	THIRD D B INVESTMENTS LLC
INSPECTOR:	THOMAS CLEMENTS
VIOLATIONS:	NFPA 101 31.3.4.5.1
11011110110	HARDWIRED SMOKE DETECTORS NOT INSTALLED.
CASE NO:	ረፑበ7120385
	3910 SW 12 CT
	FLORES, BENJAMIN &
	HARGROVE, DARRELL
INSPECTOR:	THOMAS CLEMENTS
VIOLATIONS:	NFPA 101 31.3.4.5.1
VIOLINIIOND	HARDWIRED SMOKE DETECTORS NOT INSTALLED.
CASE NO:	
	3971 SW 12 PL
OWNER:	THE 3981 TRUST
	KINNEY, NANCY TRSTEE
INSPECTOR:	THOMAS CLEMENTS
VIOLATIONS:	NFPA 101 31.3.4.5.1
	HARDWIRED SMOKE DETECTORS NOT INSTALLED.

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

CASE NO:	CE07120408
CASE ADDR:	3981 SW 12 PL
OWNER:	THE 3981 TRUST
	KINNEY, NANCY TRSTEE
INSPECTOR:	THOMAS CLEMENTS
VIOLATIONS:	NFPA 101 31.3.4.5.1

VIOLATIONS: NFPA 101 31.3.4.5.1 HARDWIRED SMOKE DETECTORS NOT INSTALLED.

	RETURN HEARING (OLD BUSINESS)
CASE NO: CASE ADDR: OWNER:	CE05092124 720 NE 13 CT VILLA SUN RAY CONDO ASSN INC JORG HRUSCHKA
VIOLATIONS:	FBC 2121.2.2.2 DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOWS OR DOOR OPENINGS.
	FBC 104.2.11 INSTALLED MECHANICAL SYSTEMS, INCLUDING, BUT NOT LIMITED TO:
	INSTALLED NEW AIR-CONDITIONING UNITS: DUCTS WIRING PLUMBING EXHAUST SYSTEMS
	FBC 104.9.3.1 PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS.
	FBC 704.3 TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.
	FBC 104.2.4 ALTERED THE PLUMBING TO INCLUDE, BUT NOT LIMITED TO:
	INSTALLED: NEW PLUMBING FIXTURES TUBS TOILETS SINKS WATER HEATERS

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

FBC 105.4

THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT, WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS, AND WITHOUT INSPECTIONS, DRYWALL INSTALLED WITHOUT INSPECTIONS, FENCING INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR-CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS, ELECTRICAL WIRING INSTALLED WITHOUT INSPECTIONS, PLUMBING INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPARTMENT OF THE CITY OF FORT LAUDERDALE.

FBC 104.1

ALTERED THIS FOUR (4) UNIT BUILDING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED: FENCING DOORS WINDOWS BRICK PAVERS CABINETS

FBC 104.2.5

ALTERED THE ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED: NEW ELECTRICAL WIRING FIXTURES SWITCHES RECEPTACLES BREAKER PANELS NEW SERVICE

47-20.13 E.

INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRE A FRENCH DRAIN STORM WATER SYSTEM TO BE INSTALLED IN THE SWALE.

ULDR 47-21.9.A.1.

THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

CASE NO:	CE05092015					
CASE ADDR:	720 NE 13 CT # 1					
OWNER:	BLAND, MICHAEL					
INSPECTOR:	JORG HRUSCHKA					

VIOLATIONS: 47-20.13 E. INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRE A FRENCH DRAIN STORM WATER SYSTEM TO BE INSTALLED IN THE SWALE.

FBC 104.1

ALTERED THIS FOUR (4) UNIT BUILDING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED: FENCING DOORS WINDOWS BRICK PAVERS CABINETS

FBC 104.2.11

INSTALLED MECHANICAL SYSTEMS, INCLUDING, BUT NOT LIMITED TO:

INSTALLED NEW AIR-CONDITIONING UNITS: DUCTS WIRING PLUMBING EXHAUST SYSTEMS

FBC 104.2.4 ALTERED THE PLUMBING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED: NEW PLUMBING FIXTURES TUBS TOILETS SINKS WATER HEATERS

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

FBC 104.2.5

ALTERED THE ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED: NEW ELECTRICAL WIRING FIXTURES SWITCHES RECEPTACLES BREAKER PANELS NEW SERVICE

FBC 104.9.3.1

PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS.

FBC 105.4

THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT, WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS, AND WITHOUT INSPECTIONS, DRYWALL INSTALLED WITHOUT INSPECTIONS, FENCING INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR-CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS, ELECTRICAL WIRING INSTALLED WITHOUT INSPECTIONS, PLUMBING INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPARTMENT OF THE CITY OF FORT LAUDERDALE.

FBC 2121.2.2.2

DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOWS OR DOOR OPENINGS.

FBC 704.3

TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.

ULDR 47-21.9.A.1.

THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.

Page 14

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

CASE NO:	CE05092038				
CASE ADDR:	720 NE 13 CT # 2				
OWNER: MARTIN, PABLO R					
INSPECTOR:	JORG HRUSCHKA				

VIOLATIONS: 47-20.13 E. INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRE A FRENCH DRAIN STORM WATER SYSTEM TO BE INSTALLED IN THE SWALE.

FBC 104.1

ALTERED THIS FOUR (4) UNIT BUILDING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED: FENCING DOORS WINDOWS BRICK PAVERS CABINETS

FBC 104.2.11

INSTALLED MECHANICAL SYSTEMS, INCLUDING, BUT NOT LIMITED TO:

INSTALLED NEW AIR-CONDITIONING UNITS: DUCTS WIRING PLUMBING EXHAUST SYSTEMS

FBC 104.2.4 ALTERED THE PLUMBING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED: NEW PLUMBING FIXTURES TUBS TOILETS SINKS WATER HEATERS

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

FBC 104.2.5

ALTERED THE ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED: NEW ELECTRICAL WIRING FIXTURES SWITCHES RECEPTACLES BREAKER PANELS NEW SERVICE

FBC 104.9.3.1

PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS.

FBC 105.4

THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT, WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS, AND WITHOUT INSPECTIONS, DRYWALL INSTALLED WITHOUT INSPECTIONS, FENCING INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR-CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS, ELECTRICAL WIRING INSTALLED WITHOUT INSPECTIONS, PLUMBING INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPARTMENT OF THE CITY OF FORT LAUDERDALE.

FBC 2121.2.2.2

DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOWS OR DOOR OPENINGS.

FBC 704.3

TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.

ULDR 47-21.9.A.1.

THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

CASE	NO:	CE05092046					
CASE	ADDR:	720	NE	13	CT	#	3
OWNER:		SCHETTER, JAMIE					
INSPE	JOR	G HF	RUS	CHKA	ł		

VIOLATIONS: 47-20.13 E. INSTALLED MORE THAN THE REQUURED 50% BRICK PAVERS ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRE A FRENCH DRAIN STORM WATER SYSTEM TO BE INSTALLED IN THE SWALE.

FBC 104.1

ALTERED THIS FOUR (4) UNIT BUILDING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED: FENCING DOORS WINDOWS BRICK PAVERS CABINETS

FBC 104.2.11

INSTALLED MECHANICAL SYSTEMS, INCLUDING, BUT NOT LIMITED TO:

INSTALLED NEW AIR-CONDITIONING UNITS: DUCTS WIRING PLUMBING EXHAUST SYSTEMS

FBC 104.2.4 ALTERED THE PLUMBING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED: NEW PLUMBING FIXTURES TUBS TOILETS SINKS WATER HEATERS

FBC 104.2.5 ALTERED THE ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED: NEW ELECTRICAL WIRING FIXTURES SWITCHES RECEPTACLES BREAKER PANELS NEW SERVICE

FBC 104.9.3.1

PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS.

FBC 105.4

THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT, WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS, AND WITHOUT INSPECTIONS, DRYWALL INSTALLED WITHOUT INSPECTIONS, FENCING INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR-CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS, ELECTRICAL WIRING INSTALLED WITHOUT INSPECTIONS, PLUMBING INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPARTMENT OF THE CITY OF FORT LAUDERDALE.

DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOWS OR DOOR OPENINGS.

FBC 704.3

TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.

ULDR 47-21.9.A.1.

THERE IS LITTLE OR NO REQUIRED LANSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.

FBC 2121.2.2.2

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

CASE NO:	CE05092051
CASE ADDR:	720 NE 13 CT # 4
OWNER:	VON KARASCHAN, ERIC
INSPECTOR:	JORG HRUSCHKA

VIOLATIONS: 47-20.13 E. INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRE A FRENCH DRAIN STORM WATER SYSTEM TO BE INSTALLED IN THE SWALE.

FBC 104.1

ALTERED THIS FOUR (4) UNIT BUILDING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED: FENCING DOORS WINDOWS BRICK PAVERS CABINETS

FBC 104.2.11 INSTALLED MECHANICAL SYSTEMS, INCLUDING, BUT NOT LIMITED TO:

INSTALLED NEW AIR-CONDITIONING UNITS: DUCTS WIRING PLUMBING EXHAUST SYSTEMS

FBC 104.2.4 ALTERED THE PLUMBING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED: NEW PLUMBING FIXTURES TUBS TOILETS SINKS WATER HEATERS

FBC 104.2.5

ALTERED THE ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED: NEW ELECTRICAL WIRING FIXTURES SWITCHES RECEPTACLES BREAKER PANELS NEW SERVICE

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

FBC 104.9.3.1

PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS.

FBC 105.4

THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT, WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS, AND WITHOUT INSPECTIONS, DRYWALL INSTALLED WITHOUT INSPECTIONS, FENCING INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR-CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS, ELECTRICAL WIRING INSTALLED WITHOUT INSPECTIONS, PLUMBING INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPARTMENT OF THE CITY OF FORT LAUDERDALE.

FBC 2121.2.2.2

DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOWS OR DOOR OPENINGS.

FBC 704.3

TENANT FIRE SEPARATIONS BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.

ULDR 47-21.9.A.1.

THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.

CASE NO:	CE05092093
CASE ADDR:	720 NE 13 CT # 5
OWNER:	KANTOR, MARC A
INSPECTOR:	JORG HRUSCHKA

VIOLATIONS: 47-20.13 E.

INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRE A FRENCH DRAIN STORM WATER SYSTEM TO BE INSTALLED IN THE SWALE.

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

FBC 104.1
ALTERED THIS FOUR (4) UNIT BUILDING TO INCLUDE, BUT NOT
LIMITED TO:

INSTALLED: FENCING DOORS WINDOWS BRICK PAVERS CABINETS

FBC 104.2.11

INSTALLED MECHANICAL SYSTEMS, INCLUDING, BUT NOT LIMITED TO:

INSTALLED: NEW AIR-CONDITIONING UNITS DUCTS WIRING PLUMBING EXHAUST SYSTEMS

FBC 104.2.4

ALTERED THE PLUMBING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED: NEW PLMBING FIXTURES TUBS TOILETS SINKS WATER HEATERS

FBC 104.2.5

ALTERED THE ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED: NEW ELECTRICAL WIRING FIXTURES SWITCHES RECEPTACLES BREAKER PANELS NEW SERVICE

FBC 104.9.3.1

PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS.

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

FBC 105.4

THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT, WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS, AND WITHOUT INSPECTIONS, DRYWALL INSTALLED WITHOUT INSPECTIONS, FENCING INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR-CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS, ELECTRICAL WIRING INSTALLED WITHOUT INSPECTIONS, PLUIMBING INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPARTMENT OF THE CITY OF FORT LAUDERDALE.

FBC 2121.2.2.2

DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOWS OR DOOR OPENINGS.

FBC 704.3

TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.

ULDR 47-21.9.A.1.

THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.

CASE NO:	CE05100037
CASE ADDR:	728 NE 13 CT
OWNER:	VILLA SUN RAY
	CONDO ASSN INC
INSPECTOR:	JORG HRUSCHKA

VIOLATIONS: FBC 104.1 ALTERED THIS BUILDING TO INCLUDE, BUT NOT LIMITED TO:

> INSTALLED: FENCING DOORS WINDOWS BRICK PAVERS CABINETS

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

FBC 104.2.11 INSTALLED MECHANICAL SYSTEMS INCLUDING, BUT NOT LIMITED TO:

INSTALLED NEW: AIR-CONDITIONING UNITS DUCTS WIRING PLUMBING EXHAUST SYSTEMS

FBC 104.2.4

ALTERED THE PLUMBING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED NEW: PLUMBING FIXTURES TUBS TOILETS SINKS WATER HEATERS

FBC 104.2.5

ALTERED THE ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED NEW: ELECTRICAL WIRING FIXTURES SWITCHES RECEPTACLES BREAKER PANELS NEW SERVICE

FBC 104.9.3.1

PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS.

INTERIOR REMODELING #04100456 PLUMBING - - - - #04100457

APPLICATION #04100462 HAS FAILED PLAN REVIEW AND IS THUS NULL AND VOID.

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

FBC 105.4

THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS AND WITHOUT INSPECTIONS. DRYWALL WAS INSTALLED WITHOUT INSPECTIONS, FENCING INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR-CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS, ELECTRICAL WIRING INSTALLED WITHOUT INSPECTIONS. PLUMBING INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPARTMENT OF THE CITY OF FORT LAUDERDALE.

FBC 2121.2.2.2

DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS.

FBC 704.3

TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.

ULDR 47-20.13.E

INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS, ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRES A FRENCH DRAIN STORM WATER SYSTEM TO BE INSTALLED IN THE SWALE.

ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.

CASE NO:	CE05092144
CASE ADDR:	728 NE 13 CT # 6
OWNER:	DARCY, BRUCE C
INSPECTOR:	JORG HRUSCHKA

VIOLATIONS: FBC 704.3

TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.

ULDR 47-20.13.E

INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS, ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRES A FRENCH DRAIN STORM WATER SYSTEM TO BE INSTALLED IN THE SWALE.

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.

FBC 104.1

ALTERED THIS BUILDING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED: FENCING DOORS WINDOWS BRICK PAVERS CABINETS

FBC 104.2.11 INSTALLED MECHANICAL SYSTEMS INCLUDING, BUT NOT LIMITED TO:

INSTALLED NEW: AIR-CONDITIONING UNITS DUCTS WIRING PLUMBING EXHAUST SYSTEMS

FBC 104.2.4

ALTERED THE PLUMBING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED NEW: PLUMBING FIXTURES TUBS TOILETS SINKS WATER HEATERS

FBC 104.2.5

ALTERED THE ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED NEW: ELECTRICAL WIRING FIXTURES SWITCHES RECEPTACLES BREAKER PANELS NEW SERVICE

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

FBC 104.9.3.1

PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS.

INTERIOR REMODELING #04100456 PLUMBING - - - - #04100457

APPLICATION #04100462 has failed plan review and is thus null and void.

FBC 105.4

THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS AND WITHOUT INSPECTIONS. DRYWALL WAS INSTALLED WITHOUT INSPECTIONS, FENCING INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR-CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS, ELECTRICAL WIRING INSTALLED WITHOUT INSPECTIONS. PLUMBING INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPT. OF THE CITY OF FORT LAUDERDALE.

FBC 2121.2.2.2

DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS.

CASE NO: CE05100033

				_
	LO)BAR,	MARK	
OWNER:	WI	EISS,	JOHN I	M &
CASE ADD	R: 72	28 NE	13 CT	# 7
CIIDE NO	01	CHOSTOCOSS		

INSPECTOR: JORG HRUSCHKA

VIOLATIONS: FBC 104.1

ALTERED THIS BUILDING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED: FENCING DOORS WINDOWS BRICK PAVERS CABINETS

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

FBC 104.2.11 INSTALLED MECHANICAL SYSTEMS INCLUDING, BUT NOT LIMITED TO:

INSTALLED NEW: AIR-CONDITIONING UNITS DUCTS WIRING PLUMBING EXHAUST SYSTEMS

FBC 104.2.4

ALTERED THE PLUMBING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED NEW: PLUMBING FIXTURES TUBS TOILETS SINKS WATER HEATERS

FBC 104.2.5

ALTERED THE ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED NEW: ELECTRICAL WIRING FIXTURES SWITCHES RECEPTACLES BREAKER PANELS NEW SERVICE

FBC 104.9.3.1

PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS.

INTERIOR REMODELING #04100456 PLUMBING - - - - #04100457

APPLICATION #04100462 HAS FAILED PLAN REVIEW AND IS THUS NULL AND VOID.

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

FBC 105.4

THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNMS AND WITHOUT INSPECTIONS. DRYWALL WAS INSTALLED WITHOUT INSPECTIONS, FENCING INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR-CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS, ELECTRICAL WIRING INSTALLED WITHOUT INSPECTIONS. PLUMBING INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPARTMENT OF THE CITY OF FORT LAUDERDALE.

FBC 2121.2.2.2

DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS.

FBC 704.3

TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.

ULDR 47-20.13.E

INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS, ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRED A FRENCH DRAIN STORM WATER SYSTEM TO BE INSTALLED IN THE SWALE.

ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.

CASE NO:	CE05100048
CASE ADDR:	728 NE 13 CT # 8
OWNER:	RUBINO, FRANK
INSPECTOR:	JORG HRUSCHKA

VIOLATIONS: FBC 104.1

ALTERED THIS BUILDING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED: FENCING DOORS WINDOWS BRICK PAVERS CABINETS

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

FBC 104.2.11 INSTALLED MECHANICAL SYSTEMS INCLUDING, BUT NOT LIMITED TO:

INSTALLED NEW: AIR-CONDITIONING UNITS DUCTS WIRING PLUMBING EXHAUST SYSTEMS

FBC 104.2.4

ALTERED THE PLUMBING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED NEW: PLUMBING FIXTURES TUBS TOILETS SINKS WATER HEATERS

FBC 104.2.5

ALTERED THE ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED NEW: ELECTRICAL WIRING FIXTURES SWITCHES RECEPTACLES BREAKER PANELS NEW SERVICE

FBC 104.9.3.1.

PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS:

INTERIOR REMODELING #04100456 PLUMBING - - - - #04100457

APPLICATION #04100462 HAS FAILED PLAN REVIEW AND IS THUS NULL AND VOID.

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

FBC 105.4

THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS AND WITHOUT INSPECTIONS. DRYWALL WAS INSTALLED WITHOUT INSPECTIONS, FENCING INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR-CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS, ELECTRICAL WIRING INSTALLED WITHOUT INSPECTIONS. PLUMBING INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPARTMENT OF THE CITY OF FORT LAUDERDALE.

FBC 2121.2.2.2

DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS.

FBC 704.3

TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.

ULDR 47-20.13.E

INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS, ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRES A FRENCH DRAIN STORM WATER SYSTEM TO BE INSTALLED IN THE SWALE.

ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.

```
_____
```

CASE NO: CE05100074

CASE ADDR:	728 NE 13 CT # 9
OWNER:	GOODWIN, KENNETH &
	MARGARINOS, JESUS A
THOPHOP .	TODA UDUAQUUN

INSPECTOR: JORG HRUSCHKA

VIOLATIONS: FBC 104.1

ALTERED THIS BUILDING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED: FENCING DOORS WINDOWS BRICK PAVERS CABINETS

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

FBC 104.2.11 INSTALLED MECHANICAL SYSTEMS INCLUDING, BUT NOT LIMITED TO:

INSTALLED NEW: AIR-CONDITIONING UNITS DUCTS WIRING PLUMBING EXHAUST SYSTEMS

FBC 104.2.4

ALTERED THE PLUMBING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED NEW: PLUMBING FIXTUIRES TUBS TOILETS SINKS WATER HEATERS

FBC 104.2.5

ALTERED THE ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED NEW: ELECTRICAL WIRING FIXTURES SWITCHES RECEPTACLES BREAKER PANELS NEW SERVICE

FBC 104.9.3.1.

PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS.

INTERIOR REMODELING #04100456 PLUMBING - - - - #04100457

APPLICATION #04100457 HAS FAILED PLAN REVIEW AND IS THUS NULL AND VOID.

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

FBC 105.4

THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS AND WITHOUT INSPECTIONS. DRYWALL WAS INSTALLED WITHOUT INSPECTIONS, FENCING INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR-CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS, ELECTRICAL WIRING INSTALLED WITHOUT INSPECTIONS. PLUMBING INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPARTMENT OF THE CITY OF FORT LAUDERDALE.

FBC 2121.2.2.2

DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS.

FBC 704.3

TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.

ULDR 47-20.13.E

INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS, ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRES A FRENCH DRAIN STORM WATER SYSTEM TO BE INSTALLED IN THE SWALE.

ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.

CASE NO:	CE05100097
CASE ADDR:	728 NE 13 CT # 10
OWNER:	BERNARD, TONY
INSPECTOR:	JORG HRUSCHKA

VIOLATIONS: FBC 104.1

ALTERED THIS BUILDING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED: FENCING DOORS WINDOWS BRICK PAVERS CABINETS

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

FBC 104.2.11 INSTALLED MECHANICAL SYSTEMS INCLUDING, BUT NOT LIMITED TO:

INSTALLED NEW: AIR-CONDITIONING UNITS DUCTS WIRING PLUMBING EXHAUST SYSTEMS

FBC 104.2.4

ALTERED THE PLUMBING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED NEW: PLUMBING FIXTURES TUBS TOILETS SINKS WATER HEATERS

FBC 104.2.5

ALTERED THE ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED NEW: ELECTRICAL WIRING FIXTURES SWITCHES RECEPTACLES BREAKER PANELS NEW SERVICE

FBC 104.9.3.1

PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS:

INTERIOR REMODELING #04100456 PLUMBING - - - - # 04100457

APPLICATION #04100462 HAS FAILED PLAN REVIEW AND IS THUS NULL AND VOID.

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

FBC 105.4

THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS AND WITHOUT INSPECTIONS. DRYWALL WAS INSTALLED WITHOUT INSPECTIONS, FENCING INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR-CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS, ELECTRICAL WIRING INSTALLED WITHOUT INSPECTIONS. PLUMBING INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON AN PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPARTMENT OF THE CITY OF FORT LAUDERDALE.

FBC 2121.2.2.2

DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS.

FBC 704.3

TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.

ULDR 47-20.13.E

INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS, ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRES A FRENCH DRAIN STORM WATER SYSTEM TO BE INSTALLED IN THE SWALE.

ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.

CASE NO:	CE05100374
CASE ADDR:	728 NE 13 CT # 11
OWNER:	SULLIVAN, SANDRA
INSPECTOR:	JORG HRUSCHKA

VIOLATIONS: FBC 104.1

ALTERED THIS BUILDING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED: FENCING DOORS WINDOWS BRICK PAVERS CABINETS

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

FBC 104.2.11 INSTALLED MECHANICAL SYSTEMS INCLUDING, BUT NOT LIMITED TO:

INSTALLED NEW: AIR-CONDITIONING UNITS DUCTS WIRING PLUMBING EXHAUST SYSTEMS

FBC 104.2.4

ALTERED THE PLUMBING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED NEW: PLUMBING FIXTURES TUBS TOILETS SINKS WATER HEATERS

FBC 104.2.5

ALTERED THE ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED NEW: ELECTRICAL WIRING FIXTURES SWITCHES RECEPTACLES BREAKER PANELS NEW SERVICE

FBC 104.9.3.1

PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS.

INTERIOR REMODELING #04100456 PLUMBING - - - - #04100457

APPLICATION #04100462 HAS FAILED PLAN REVIEW AND IS THUS NULL AND VOID.

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

FBC 105.4

THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS AND WITHOUT INSPECTIONS. DRYWALL WAS INSTALLED WITHOUT INSPECTIONS, FENCING INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR-CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS, ELECTRICAL WIRING INSTALLED WITHOUT INSPECTIONS. PLUMBING INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPARTMENT OF THE CITY OF FORT LAUDERDALE.

FBC 2121.2.2.2

DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS.

FBC 704.3

TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.

ULDR 47-20.13.E

INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS, ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRES A FRENCH DRAIN STORM WATER SYSTEM TO BE INSTALLED IN THE SWALE.

ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.

CASE	NO:	CE05100380				
CASE	ADDR:	728 NE 13 CT # 12				

OWNER:	IRISH,	KEVIN	D &	
	MCCLURI	E, MICH	HAEL	W

INSPECTOR: JORG HRUSCHKA

VIOLATIONS: FBC 104.1

ALTERED THIS BUILDING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED: FENCING DOORS WINDOWS BRICK PAVERS CABINETS

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

FBC 104.2.11 INSTALLED MECHANICAL SYSTEMS INCLUDING, BUT NOT LIMITED TO:

INSTALLED NEW: AIR-CONDITIONING UNITS DUCTS WIRING PLUMBING EXHAUST SYSTEMS

FBC 104.2.4

ALTERED THE PLUMBING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED NEW: PLUMBING FIXTURES TUBS TOILETS SINKS WATER HEATERS

FBC 104.2.5

ALTERED THE ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED NEW: ELECTRICAL WIRING FIXTURES SWITCHES RECEPTACLES BREAKER PANELS NEW SERVICE

FBC 104.9.3.1

PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS.

INTERIOR REMODELING #04100456 PLUMBING - - - - #04100457

APPLICATION #04100462 HAS FAILED PLAN REVIEW AND IS THUS NULL AND VOID.

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

FBC 105.4

THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS AND WITHOUT INSPECTIONS. DRYWALL WAS INSTALLED WITHOUT INSPECTIONS, FENCING INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR-CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS, ELECTRICAL WIRING INSTALLED WITHOUT INSPECTIONS. PLUMBING INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPARTMENT OF THE CITY OF FORT LAUDERDALE.

FBC 2121.2.2.2

DOOR AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS.

FBC 704.3

TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.

ULDR 47-20.13.E

INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS, ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRES A FRENCH DRAIN STORM SYSTEM TO BE INSTALLED IN THE SWALE.

ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.

CASE NO:	CE05100382
CASE ADDR:	728 NE 13 CT # 13
OWNER:	IRISH, KEVIN D
INSPECTOR:	JORG HRUSCHKA

VIOLATIONS: FBC 104.1

ALTERED THIS BUILDING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED: FENCING DOORS WINDOWS BRICK PAVERS CABINETS

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

FBC 104.2.11 INSTALLED MECHANICAL SYSTEMS INCLUDING, BUT NOT LIMITED TO:

INSTALLED NEW: AIR-CONDITIONING UNITS DUCTS WIRING PLUMBING EXHAUST SYSTEMS

FBC 104.2.4

ALTERED THE PLUMBING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED NEW: PLUMBING FIXTURES TUBS TOILETS SINKS WATER HEATERS

FBC 104.2.5 ALTERED ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO:

> INSTALLED NEW ELECTRICAL WIRING FIXTURES SWITCHES RECEPTACLES BREAKER PANELS

FBC 104.9.3.1

PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS.

NEW SERVICE

INTERIOR REMODELING #04100456 PLUMBING - - - - - #04100457

APPLICATION #04100462 HAS FAILED PLAN REVIEW AND IS THUS NULL AND VOID.

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

FBC 105.4

THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOPR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS AND WITHOUT INSPECTIONS. DRYWALL WAS INSTALLED WITHOUT INSPECTIONS, FENCING INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR-CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS, ELECTRICAL WIRING INSTALLED WITHOUT INSPECTIONS. PLUMBING INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPARTMENT OF THE CITY OF FORT LAUDERDALE.

FBC 2121.2.2.2

DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OF DOOR OPENINGS.

FBC 704.3

TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.

ULDR 47-20.13.E

INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS, ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRES A FRENCH DRAIN STORM WATER SYSTEM TO BE INSTALLED IN THE SWALE.

ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.

```
_____
```

CASE NO:	CE05100391
CASE ADDR:	728 NE 13 CT # 14
OWNER:	BASTIDAS, CARLOS
INSPECTOR:	JORG HRUSCHKA

VIOLATIONS: FBC 104.1

ALTERED THIS BUILDING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED: FENCING DOORS WINDOWS BRICK PAVERS CABINETS

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

FBC 104.2.11 INSTALLED MECHANICAL SYSTEMS INCLUDING, BUT NOT LIMITED TO:

INSTALLED NEW: AIR-CONDITIONING UNITS DUCTS WIRING PLUMBING EXHAUST SYSTEMS

FBC 104.2.4 ALTERED THE PLUMBING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED NEW: PLUMBING FIXTURES TUBS TOILETS SINKS WATER HEATERS

FBC 104.2.5

ALTERED THE ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED NEW: ELECTRICAL WIRING FIXTURES SWITCHES RECEPTACLES BREAKER PANELS NEW SERVICE

FBC 104.9.3.1

PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS.

INTERIOR REMODELING #04100456 PLUMBING - - - - - - #04100457

APPLICATION #04100462 HAS FAILED PLAN REVIEW AND IS THUS NULL AND VOID.

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

FBC 105.4

THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS AND WITHOUT INSPECTIONS. DRYWALL WAS INSTALLED WITHOUT INSPECTIONS, FENCING INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR-CONDITINING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS, ELECTRICAL WIRING INSTALLED WITHOUT INSPECTIONS. PLUMBING INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPARTMENT OF THE CITY OF FORT LAUDERDALE.

FBC 2121.2.2.2

DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS.

FBC 704.3

TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.

ULDR 47-20.13.E

INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS, ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRES A FRENCH DRAIN STORM WATER SYSTEM TO BE INSTALLED IN THE SWALE.

ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.

CASE NO: CE05100446 CASE ADDR: 736 NE 13 CT

CHOL HDDIC	,50 MH 15 CI
OWNER:	VILLA SUN RAY CONDO ASSN INC
INSPECTOR:	JORG HRUSCHKA

VIOLATIONS: FBC 104.1 ALTERED THIS EIGHT (8) UNIT BUILDING TO INCLUDE, BUT NOT LIMITED TO:

> INSTALLED: FENCING DOORS WINDOWS BRICK PAVERS CABINETS

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

FBC 104.2.11 INSTALLED MECHANICAL SYSTEMS INCLUDING, BUT NOT LIMITED TO:

INSTALLED NEW: AIR-CONDITIONING UNITS DUCTS WIRING PLUMBING EXHAUST SYSTEMS

FBC 104.2.4

ALTERED THIS PLUMBING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED NEW: PLUMBING FIXTURES TUBS TOILETS SINKS WATER HEATERS

FBC 104.2.5

ALTERED THE ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED NEW: ELECTRICAL WIRING FIXTURESS SWITCHES RECEPTACLES BREAKER PANELS NEW SERVICE

FBC 104.9.3.1

PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS. APPLICATIONS #04100464, #04100466, #04100467, AND #04100469 HAVE FAILED PLAN REVIEW AND THUS ARE NULL AND VOID.

FBC 105.4

THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS AND WITHOUT INSPECTIONS. DRYWALL WAS INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR-CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS. ELECTRICAL WIRING WAS INSTALLED WITHOUT INSPECTIONS. PLUMBING WAS INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPARTMENT OF THE CITY OF FORT LAUDERDALE.

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

FBC 2121.2.2.2

DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS.

FBC 704.3

TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.

ULDR 47-20.13.E INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH

REQUIRES A FRENCH DRAIN STORMWATER SYSTEM TO BE INSTALLED IN THE SWALE.

ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.

CASE NO:	CE05100394
CASE ADDR:	736 NE 13 CT # 15
OWNER:	JAMILA, SIDNEY
INSPECTOR:	JORG HRUSCHKA

VIOLATIONS: FBC 104.1 ALTERED THIS EIGHT (8) UNIT BUILDING TO INCLUDE, BUT NOT LIMITED TO:

> INSTALLED: FENCING DOORS WINDOWS BRICK PAVERS CABINETS

FBC 104.2.11

INSTALLED MECHANICAL SYSTEMS INCLUDING, BUT NOT LIMITED TO:

INSTALLED NEW: AIR-CONDITIONING UNITS DUCTS WIRING PLUMBING EXHAUST SYSTEMS

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

FBC 104.2.4 ALTERED THE PLUMBING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED NEW: PLUMBING FIXTURES TUBS TOILETS SINKS WATER HEATERS

FBC 104.2.5

ALTERED THE ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED NEW: ELECTRICAL WIRING FIXTURES SWITCHES RECEPTACLES BREAKER PANELS NEW SERVICE

FBC 104.9.3.1

PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS. APPLICATIONS #04100464, #04100466, #04100467 AND #04100469 HAVE FAILED PLAN REVIEW AND THUS ARE NULL AND VOID

FBC 105.4

THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS AND WITHOUT INSPECTIONS. DRYWALL WAS INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR-CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS ELECTRICAL WIRING WAS INSTALLED WITHOUT INSPECTIONS. PLUMBING WAS INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPARTMENT OF THE CITY OF FORT LAUDERDALE.

FBC 2121.2.2.2

DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS.

FBC 704.3

TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am ULDR 47-20.13.E INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRES A FRENCH DRAIN STORMWATER SYSTEM TO BE INSTALLED IN THE SWALE. ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING. _____ CASE NO: CE05100462 CASE ADDR: 736 NE 13 CT # 16 OWNER: KANTOR, MARC A INSPECTOR: JORG HRUSCHKA VIOLATIONS: FBC 104.1 ALTERED THIS EIGHT (8) UNIT BUILDING TO INCLUDE, BUT NOT LIMITED TO: INSTALLED: FENCING

DOORS WINDOWS BRICK PAVERS CABINETS

FBC 104.2.11 INSTALLED MECHANICAL SYSTEMS INCLUDING, BUT NOT LIMITED TO:

> INSTALLED NEW: AIR-CONDITIONING UNITS DUCTS WIRING PLUMBING EXHAUST SYSTEMS

FBC 104.2.4 ALTERED THE PLUMBING TO INCLUDE, BUT NOT LIMITED TO:

> INSTALLED NEW: PLUMBING FIXTURES TUBS TOILETS SINKS WATER HEATERS

FBC 104.2.5

ALTERED THE ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED NEW: ELECTRICAL WIRING FIXTURES SWITCHES RECEPTACLES BREAKER PANELS NEW SERVICE

FBC 104.9.3.1

PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS. APPLICATIONS # 04100464, #04100466, #04100467 AND #04100469 HAVE FAILED PLAN REVIEW AND THUS ARE NULL AND VOID.

FBC 105.4

THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS AND WITHOUT INSPECTIONS. DRYWALL WAS INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR-CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS. ELECTRICAL WIRING WAS INSTALLED WITHOUT INSPECTIONS. PLUMBING WAS INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPARTMENT OF THE CITY OF FORT LAUDERDALE.

FBC 2121.2.2.2

DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS.

FBC 704.3

TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.

ULDR 47-20.13.E

INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRES A FRENCH DRAIN STORMWATER SYSTEM TO BE INSTALLED IN THE SWALE.

ULDR 47-21.9.A.1.

THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.

_____ CASE NO: CE05100465 CASE ADDR: 736 NE 13 CT # 17 OWNER: MATO-CAMACHO, MIGUEL A INSPECTOR: JORG HRUSCHKA VIOLATIONS: FBC 104.1 ALTERED THIS EIGHT (8) UNIT BUILDING TO INCLUDE, BUT NOT LIMITED TO: INSTALLED: FENCING DOORS WINDOWS BRICK PAVERS CABINETS FBC 104.2.11 INSTALLED MECHANICAL SYSTEMS INCLUDING, BUT NOT LIMITED TO: INSTALLED NEW: AIR-CONDITIONING UNITS DUCTS WIRING PLUMBING EXHAUST SYSTEMS FBC 104.2.4 ALTERED THIS PLUMBING TO INCLUDE, BUT NOT LIMITED TO: INSTALLED NEW: PLUMBING FIXTURES TUBS TOILETS SINKS WATER HEATERS FBC 104.2.5 ALTERED THE ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO: INSTALLED NEW: ELECTRICAL WIRING FIXTURES SWITCHES RECEPTACLES BREAKER PANELS NEW SERVICE

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

FBC 104.9.3.1

PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS. APPLICATIONS # 04100464, #04100466, #04100467 AND #04100469 HAVE FAILED PLAN REVIEW AND THUS ARE NULL AND VOID.

FBC 105.4

THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS AND WITHOUT INSPECTIONS. DRYWALL WAS INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR-CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS. ELECTRICAL WIRING WAS INSTALLED WITHOUT INSPECTIONS. PLUMBING WAS INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPARTMENT OF THE CITY OF FORT LAUDERDALE.

FBC 2121.2.2.2

DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS.

FBC 704.3

TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.

ULDR 47-20.13.E

INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRES A FRENCH DRAIN STORMWATER SYSTEM TO BE INSTALLED IN THE SWALE.

ULDR 47-21.9.A.1.

THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

CASE NO:	CE05100467
CASE ADDR:	736 NE 13 CT # 18
OWNER:	ROBINSON, MICHAEL
INSPECTOR:	JORG HRUSCHKA

VIOLATIONS: FBC 104.1 ALTERED THIS EIGHT (8) UNIT BUILDING TO INCLUDE, BUT NOT LIMITED TO:

> INSTALLED: FENCING DOORS WINDOWS BRICK PAVERS CABINETS

FBC 104.2.11 INSTALLED MECHANICAL SYSTEMS INCLUDING, BUT NOT LIMITED TO:

> INSTALLED NEW: AIR-CONDITIONING UNITS DUCTS WIRING PLUMBING EXHAUST SYSTEMS

FBC 104.2.4

ALTERED THIS PLUMBING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED NEW: PLUMBING FIXTURES TUBS TOILETS SINKS WATER HEATERS

FBC 104.2.5

ALTERED THE ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED NEW: ELECTRICAL WIRING FIXTURES SWITCHES RECEPTACLES BREAKER PANELS NEW SERVICE

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

FBC 104.9.3.1

PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS. APPLICATIONS # 04100464, #04100466, #04100467 AND #04100469 HAVE FAILED PLAN REVIEW AND THUS ARE NULL AND VOID.

FBC 105.4

THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS AND WITHOUT INSPECTIONS. DRYWALL WAS INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR-CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS. ELECTRICAL WIRING WAS INSTALLED WITHOUT INSPECTIONS. PLUMBING WAS INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPARTMENT OF THE CITY OF FORT LAUDERDALE.

FBC 2121.2.2.2

DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS.

FBC 704.3

TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.

ULDR 47-20.13.E

INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRES A FRENCH DRAIN STORMWATER SYSTEM TO BE INSTALLED IN THE SWALE.

ULDR 47-21.9.A.1.

THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

CASE NO:	CE05100471
CASE ADDR:	736 NE 13 CT # 19
OWNER:	JOINER, JEREMY SCOTT &
	MEJIA, CARLOS ARIEL
INSPECTOR:	JORG HRUSCHKA

VIOLATIONS: FBC 104.1 ALTERED THIS EIGHT (8) UNIT BUILDING TO INCLUDE, BUT NOT LIMITED TO:

> INSTALLED: FENCING DOORS WINDOWS BRICK PAVERS CABINETS

FBC 104.2.11 INSTALLED MECHANICAL SYSTEMS INCLUDING, BUT NOT LIMITED TO:

> INSTALLED NEW: AIR-CONDITIONING UNITS DUCTS WIRING PLUMBING EXHAUST SYSTEMS

FBC 104.2.4

ALTERED THIS PLUMBING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED NEW: PLUMBING FIXTURES TUBS TOILETS SINKS WATER HEATERS

FBC 104.2.5 ALTERED THE ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO:

> INSTALLED NEW: ELECTRICAL WIRING FIXTURES SWITCHES RECEPTACLES BREAKER PANELS NEW SERVICE

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

FBC 104.9.3.1

PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS. APPLICATIONS # 04100464, #04100466, #04100467 AND #04100469 HAVE FAILED PLAN REVIEW AND THUS ARE NULL AND VOID.

FBC 105.4

THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS AND WITHOUT INSPECTIONS. DRYWALL WAS INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR-CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS. ELECTRICAL WIRING WAS INSTALLED WITHOUT INSPECTIONS. PLUMBING WAS INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPARTMENT OF THE CITY OF FORT LAUDERDALE.

FBC 2121.2.2.2

DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS.

FBC 704.3

TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.

ULDR 47-20.13.E

INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRES A FRENCH DRAIN STORMWATER SYSTEM TO BE INSTALLED IN THE SWALE.

ULDR 47-21.9.A.1.

THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

CASE NO:	CE05100474
CASE ADDR:	736 NE 13 CT # 20
OWNER:	SCHIAFFINO, MIGUEL A &
	AUBRY, ANA T
INSPECTOR:	JORG HRUSCHKA

VIOLATIONS: FBC 104.1 ALTERED THIS EIGHT (8) UNIT BUILDING TO INCLUDE, BUT NOT LIMITED TO:

> INSTALLED: FENCING DOORS WINDOWS BRICK PAVERS CABINETS

FBC 104.2.11 INSTALLED MECHANICAL SYSTEMS INCLUDING, BUT NOT LIMITED TO:

> INSTALLED NEW: AIR-CONDITIONING UNITS DUCTS WIRING PLUMBING EXHAUST SYSTEMS

FBC 104.2.4 ALTERED THIS PLUMBING TO INCLUDE, BUT NOT LIMITED TO:

> INSTALLED NEW PLUMBING FIXTURES TUBS TOILETS SINKS WATER HEATERS

FBC 104.2.5 ALTERED THE ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO:

> INSTALLED NEW: ELECTRICAL WIRING FIXTURES SWITCHES RECEPTACLES BREAKER PANELS NEW SERVICE

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

FBC 104.9.3.1

PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS. APPLICATIONS # 04100464, #04100466, #04100467 AND #04100469 HAVE FAILED PLAN REVIEW AND THUS ARE NULL AND VOID.

FBC 105.4

THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS AND WITHOUT INSPECTIONS. DRYWALL WAS INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR-CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS. ELECTRICAL WIRING WAS INSTALLED WITHOUT INSPECTIONS. PLUMBING WAS INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPARTMENT OF THE CITY OF FORT LAUDERDALE.

FBC 2121.2.2.2

DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS.

FBC 704.3

TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.

ULDR 47-20.13.E

INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRES A FRENCH DRAIN STORMWATER SYSTEM TO BE INSTALLED IN THE SWALE.

ULDR 47-21.9.A.1.

THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

CASE NO:	CE05100479
CASE ADDR:	736 NE 13 CT # 21
OWNER:	LACKEY, WILLIAM &
	SCHINDLER, RAY J
INSPECTOR:	JORG HRUSCHKA

VIOLATIONS: FBC 104.1 ALTERED THIS EIGHT (8) UNIT BUILDING TO INCLUDE, BUT NOT LIMITED TO:

> INSTALLED: FENCING DOORS WINDOWS BRICK PAVERS CABINETS

FBC 104.2.11 INSTALLED MECHANICAL SYSTEMS INCLUDING, BUT NOT LIMITED TO:

> INSTALLED NEW: AIR-CONDITIONING UNITS DUCTS WIRING PLUMBING EXHAUST SYSTEMS

FBC 104.2.4 ALTERED THIS PLUMBING TO INCLUDE, BUT NOT LIMITED TO:

> INSTALLED NEW: PLUMBING FIXTURES TUBS TOILETS SINKS WATER HEATERS

FBC 104.2.5 ALTERED THE ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO:

> INSTALLED NEW: ELECTRICAL WIRING FIXTURES SWITCHES RECEPTACLES BREAKER PANELS NEW SERVICE

Page 56

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

FBC 104.9.3.1

PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS. APPLICATIONS # 04100464, #04100466, #04100467 AND #04100469 HAVE FAILED PLAN REVIEW AND THUS ARE NULL AND VOID.

FBC 105.4

THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS AND WITHOUT INSPECTIONS. DRYWALL WAS INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR-CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS. ELECTRICAL WIRING WAS INSTALLED WITHOUT INSPECTIONS. PLUMBING WAS INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPARTMENT OF THE CITY OF FORT LAUDERDALE.

FBC 2121.2.2.2

DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS.

FBC 704.3

TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.

ULDR 47-20.13.E

INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRES A FRENCH DRAIN STORMWATER SYSTEM TO BE INSTALLED IN THE SWALE.

ULDR 47-21.9.A.1.

THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

CASE NO:	CE05100483	
CASE ADDR:	736 NE 13 CT #	22
OWNER:	WALKER, RONALD	Е
INSPECTOR:	JORG HRUSCHKA	

VIOLATIONS: FBC 104.1 ALTERED THIS EIGHT (8) UNIT BUILDING TO INCLUDE, BUT NOT LIMITED TO:

> INSTALLED: FENCING DOORS WINDOWS BRICK PAVERS CABINETS

FBC 104.2.11

INSTALLED MECHANICAL SYSTEMS INCLUDING, BUT NOT LIMITED TO:

INSTALLED NEW: AIR-CONDITIONING UNITS DUCTS WIRING PLUMBING EXHAUST SYSTEMS

FBC 104.2.4

ALTERED THIS PLUMBING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED NEW: PLUMBING FIXTURES TUBS TOILETS SINKS WATER HEATERS

FBC 104.2.5

ALTERED THE ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED NEW: ELECTRICAL WIRING FIXTURES SWITCHES RECEPTACLES BREAKER PANELS NEW SERVICE

FBC 104.9.3.1

PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS. APPLICATIONS # 04100464, #04100466, #04100467 AND #04100469 HAVE FAILED PLAN REVIEW AND THUS ARE NULL AND VOID.

Page 58

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

FBC 105.4

THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS AND WITHOUT INSPECTIONS. DRYWALL WAS INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR-CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS. ELECTRICAL WIRING WAS INSTALLED WITHOUT INSPECTIONS. PLUMBING WAS INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPARTMENT OF THE CITY OF FORT LAUDERDALE.

FBC 2121.2.2.2

DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS.

FBC 704.3

TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.

ULDR 47-20.13.E

ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.

CASE 1	NO:	CE05	5100)484	1		
CASE .	ADDR:	736	NE	13	СТ	#	23
OWNER	:	JAMI	LLA,	, SI	DNE	ΞY	

INSPECTOR: JORG HRUSCHKA

VIOLATIONS: FBC 104.1 ALTERED THIS EIGHT (8) UNIT BUILDING TO INCLUDE, BUT NOT LIMITED TO:

> INSTALLED: FENCING DOORS WINDOWS BRICK PAVERS CABINETS

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

FBC 104.2.11 INSTALLED MECHANICAL SYSTEMS INCLUDING, BUT NOT LIMITED TO:

> INSTALLED NEW: AIR-CONDITIONING UNITS DUCTS WIRING PLUMBING EXHAUST SYSTEMS

FBC 104.2.4

ALTERED THIS PLUMBING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED NEW: PLUMBING FIXTURES TUBS TOILETS SINKS WATER HEATERS

FBC 104.2.5

ALTERED THE ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED NEW: ELECTRICAL WIRING FIXTURES SWITCHES RECEPTACLES BREAKER PANELS NEW SERVICE

FBC 104.9.3.1

PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS. APPLICATIONS # 04100464, #04100466, #04100467 AND #04100469 HAVE FAILED PLAN REVIEW AND THUS ARE NULL AND VOID.

FBC 105.4

THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS AND WITHOUT INSPECTIONS. DRYWALL WAS INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR-CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS. ELECTRICAL WIRING WAS INSTALLED WITHOUT INSPECTIONS. PLUMBING WAS INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPARTMENT OF THE CITY OF FORT LAUDERDALE.

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

FBC 2121.2.2.2

DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS.

FBC 704.3

TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.

ULDR 47-20.13.E INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRES A FRENCH DRAIN STORMWATER SYSTEM TO BE INSTALLED IN THE SWALE.

ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.

CASE NO:	CE04051739
CASE ADDR:	1424 HOLLY HEIGHTS DR
OWNER:	OASIS FALLS CONDO ASSN INC
INSPECTOR:	JORG HRUSCHKA

VIOLATIONS: FBC 104.1 ALTERED THIS SIX (6) UNIT BUILDING TO INCLUDE, BUT NOT LIMITED TO:

> INSTALLED: FENCING DOORS WINDOWS BRICK PAVERS CABINETS

FBC 104.2.4

ALTERED THE PLUMBING TO INCLUDE, BUT NOT LIMITED TO:

INSTALLED NEW: PLUMBING FIXTURES TUBS TOILETS SINKS WATER HEATERS

FBC 104.2.5 ALTERED THE ELECTRICAL TO INCLUDE, BUT NOT LIMITED TO:

> INSTALLED NEW: ELECTRICAL WIRING FIXTURES SWITCHES RECEPTACLES BREAKER PANELS NEW SERVICE

FBC 104.9.3.1.

PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS:

SHUTTER - - - - - - #05062503 INTERIOR REMODELING - #05050076

FBC 105.4

THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT WINDOWS INSTALLED WITHOUT BUCKS, DOORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS AND WITHOUT INSPECTIONS. DRYWALL WAS INSTALLED WITHOUT INSPECTIONS, FENCING INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR-CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS, ELECTRICAL WIRING INSTALLED WITHOUT INSPECTIONS, PLUMBING INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPARTMENT OF THE CITY OF FORT LAUDERDALE.

FBC 2121.2.2.2

DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS.

FBC 704.3

TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.

ULDR 47-20.13.E

INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS, WHICH REQUIRES A FRENCH DRAIN STORMWATER SYSTEM TO BE INSTALLED IN THE SWALE.

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.

CASE NO:	CE04051740
CASE ADDR:	1430 HOLLY HEIGHTS DR
OWNER:	OASIS FALLS CONDO ASSN INC
INSPECTOR:	JORG HRUSCHKA

VIOLATIONS: FBC 104.1 ALTERED THIS SIX (6) UNIT BUILDING TO INCLUDE, BUT NOT LIMITED TO:

> BRICK PAVERS CABINETS

FBC 104.9.3.1.

PERMITS ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE THAN NINETY (90) DAYS SINCE AN INSPECTION HAS PASSED ON THESE PERMITS:

POOL - - - #04090799 DOORS - - #04092026 PLUMBING - #04090800

FBC 105.4

THERE HAS BEEN FRAMING REMOVED, FRAMING REBUILT, WINDOWS INSTALLED WITHOUT BUCKS, DORS INSTALLED INTO EXTERIOR WALLS WITHOUT THE REQUIRED FILLED CELLS OR COLUMNS AND WITHOUT INSPECTIONS. DRYWALL WAS INSTALLED WITHOUT INSPECTIONS, FENCING INSTALLED WITHOUT INSPECTIONS AND NOT PER PLAN OR PER CODE. WALL AIR-CONDITIONING UNITS WERE REMOVED AND THE HOLES WERE BLOCKED UP WITHOUT INSPECTIONS, ELECTRICAL WIRING AND PLUMBING WERE INSTALLED WITHOUT INSPECTIONS AND ALL THIS IS NOT ON ANY PLAN SUBMITTED AND APPROVED BY THE BUILDING DEPARTMENT OF THE CITY OF FORT LAUDERDALE.

FBC 2121.2.2.2

DOORS AND WINDOWS HAVE BEEN INSTALLED IN THE EXTERIOR OF THE BUILDING WITHOUT THE REQUIRED VERTICAL REINFORCING BARS PLACED IN CONCRETE FILLED CELLS ON EACH SIDE OF WINDOW OR DOOR OPENINGS.

FBC 704.3

TENANT FIRE SEPARATION BETWEEN APARTMENTS ARE REQUIRED DUE TO THE AMOUNT OF WORK BEING DONE ON THIS BUILDING.

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

ULDR 47-20.13.E INSTALLED MORE THAN THE REQUIRED 50% BRICK PAVERS ACCORDING TO THE U.L.D.R. IN THE FRONT PARKING AND SWALE AREAS WHICH REQUIRES A FRENCH DRAIN STORMWATER SYSTEM TO BE INSTALLED IN THE SWALE.

ULDR 47-21.9.A.1. THERE IS LITTLE OR NO REQUIRED LANDSCAPING IN THE FRONT INCLUDING VUA LANDSCAPING.

CASE NO:	CE03120005
CASE ADDR:	219 SW 21 TER
OWNER:	BRIA, JOHN & GEORGIANN
INSPECTOR:	JORG HRUSCHKA

- VIOLATIONS: FBC 104.1 THE FOLLOWING WORK WAS DONE WITHOUT FIRST OBTAINING A BUILDING PERMIT:
 - 1. INSTALLED AN OVERHEAD RAILTRACK SYSTEM.
 - 2. INSTALLED OVENS/KILNS.
 - 3. ALUMINUM ROOF ADDED TO THE REAR OF THE BUILDING.
 - 4. ADDED ON OVERHEAD GARAGE DOOR TO THE REAR WALL WITH UNSUPPORTED CONCRETE BLOCK AT THE TOP OF THE OPENING.

FBC 104.2.5 ELECTRICAL CIRCUITS HAVE BEEN ADDED TO THE REAR ALUMINUM ROOF WITHOUT FIRST OBTAINING AN ELECTRICAL PERMIT.

CASE NO: CE06101576 CASE ADDR: 808 NE 16 AVE OWNER: PIERSON, CRAIG & URBINA, VALESKA INSPECTOR: JORG HRUSCHKA VIOLATIONS: FBC 105.1 INSTALLED WOOD FENCE WITHOUT A PERMIT. FBC 106.10.3.1 THERE ARE TWO (2) EXPIRED PERMITS AT THIS SINGLE FAMILY HOUSE, 01031941 FOR SHUTTERS ON FRENCH DOORS ISSUED ON 5/9/01 WITH NO INSPECTION, 02071922 FOR IRRIGATION WATER METER ISSUED ON 7/26/02 WITH NO INSPECTION.

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

- CASE NO: CE07030221
- CASE ADDR: 1111 SW 4 ST
- OWNER: VILLAS SANTA FE CORP
- INSPECTOR: JORG HRUSCHKA
- VIOLATIONS: 25-13

THE SWALE AREA OF THE RIGHT-OF-WAY HAS BEEN PAVED OVER WITHOUT OBTAINING A PERMIT FROM THE CITY'S ENGINEERING DEPARTMENT.

47-21.9 G.1.

A LANDSCAPE PLAN WHICH DEMONSTRATES THE RETROACTIVE REQUIREMENTS HAS NOT BEEN SUBMITTED TO THE LANDSCAPE DEPARTMENT.

FBC 105.1

ONE TWO STORY CONDOMINIUM HAS BEEN ALTERED WITHOUT A PERMIT, INCLUDING BUT NOT LIMITED TO:

- 1) BATHROOMS HAVE BEEN ALTERED.
- 2) KITCHEN CABINETS AND COUNTERS HAVE BEEN INSTALLED.
- 3) WALLS HAVE BEEN OPENED BETWEEN KITCHEN AND LIVING ROOM.
- 4) RAILINGS HAVE BEEN INSTALLED ON SECOND FLOOR LANDING.
- 5) CONCRETE WALKS HAVE BEEN INSTALLED.
- 6) THE DRIVEWAY AND PARKING LOT HAVE BEEN RESURFACED.
- 7) A FOUNTAIN HAS BEEN INSTALLED.
- 8) A FENCE HAS BEEN INSTALLED.

FBC 105.2.11

THE A/C UNITS HAVE BEEN REPLACED WITHOUT OBTAINING A PERMIT.

FBC 105.2.18

A SITE FENCE HAS BEEN INSTALLED WITHOUT A PERMIT.

FBC 105.2.4

THE PLUMBING SYSTEMS HAS BEEN ALTERED WITHOUT A PERMIT, INCLUDING BUT NOT LIMITED TO:

- 1) KITCHEN SINKS HAVE BEEN INSTALLED.
- 2) BATHROOM FIXTURES HAVE BEEN REPLACED.
- 3) THE LAUNDRY FACILITIES HAVE BEEN ALTERED.
- 4) A FOUNTAIN HAS BEEN INSTALLED.

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

FBC 105.2.5
THE ELECTRICAL SYSTEM HAS BEEN ALTERED WITHOUT A
PERMIT, INCLUDING BUT NOT LIMITED TO:
1) GENERAL PREMISE WIRING
2) CIRCUIT TO POWER FOUNTAIN

3) WIRING IN LAUNDRY AREA

CASE NO: CE05120448 CASE ADDR: 1224 NE 7 AVE OWNER: PROGRESSO HOLDING GROUP

INSPECTOR: JORG HRUSCHKA

VIOLATIONS: 9-313(b) THE NUMBERS ON THIS WAREHOUSE ARE NOT VISIBLE FROM THE ROAD.

FBC 105.1
ALTERED THIS WAREHOUSE TO INCLUDE BUT NOT LIMITED
TO:

INSTALLED A NEW ROOF ON THIS WAREHOUSE WITHOUT A PERMIT.

CASE NO:	CE07022152
CASE ADDR:	1306 SE 13 TER
OWNER:	HAYES, PATRICIA S
INSPECTOR:	JORG HRUSCHKA

VIOLATIONS: FBC 105.1

- 1) AN EXTERIOR DOOR HAS BEEN INSTALLED IN THE KITCHEN
- 2) THE KITCHEN HAS BEEN ALTERED
- 3) THE CEILINGS AND SEVERAL WALLS HAVE BEEN REPLACED WITH NEW DRYWALL
- 4) A BATHROOM HAS BEEN ALTERED
- 5) STRUCTURAL REPAIRS AND ALTERATIONS TO THE EXTERIOR FRAME HAVE BEEN MADE IN THE FAMILY ROOM AND THE STORAGE ROOM
- 6) THE BUILDING HAS BEEN ALTERED AND A PEDESTAL HAS BEEN CONSTRUCTED TO ACCOMMODATE THE INSTALLATION OF NEW DUCT WORK AND A FUTURE A/C UNIT
- 7) EXPANSION FOAM INSULATION HAS BEEN SPRAYED ON THE ROOF TRUSS SYSTEM
- 8) STUCCO REPAIRS HAVE BEEN MADE

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

FBC 105.2.11

NEW DUCT WORK HAS BEEN INSTALLED. A PEDESTAL TO SUPPORT A FUTURE A/C UNIT HAS BEEN BUILT. THE ELECTRIC TO POWER FUTURE UNIT HAS BEEN INSTALLED.

FBC 105.2.4

KITCHEN AND BATHROOM FIXTURES HAVE BEEN REMOVED. NEW SHOWER HANDLES AND SHUT OFF VALVES HAVE BEEN INSTALLED. THE WATER HEATER HAS BEEN REPLACED. ALTERATIONS TO THE WATER SUPPLY AND SEWER LINES HAVE BEEN MADE.

FBC 105.2.5

- THE FOLLOWING ALTERATIONS HAVE BEEN MADE
- 1) NEW CIRCUIT TO POWER WATER HEATER
- 2) NEW CUICUIT TO POWER A/C UNITS
- 3) GENERAL PREMISE WIRING, INCLUDING EXTENSIVE REWIRING OF KITCHEN, BATHROOMS AND BEDROOMS
- 4) NEW ELECTRICAL PANELS AND BREAKERS
- 5) TELEPHONE AND COAXIAL CABLES HAVE BEEN INSTALLED
- 6) HI-HAT LIGHTING HAS BEEN INSTALLED

FBC 1604.1

THE REPAIRS TO THE STRUCTURAL FRAME MEMBERS IN THE GARAGE AND FLORIDA ROOM, INCLUDING ANCHORAGE AND CONNECTION, ARE NOT DESIGNED OR CONSTRUCTED IN ACCORDANCE WITH THE STRENGTH REQUIREMENTS FOR THE LOADS IMPOSED.

CASE NO: CE06051992

```
CASE ADDR: 3341 SW 20 ST
```

```
OWNER: RAMIREZ, LUIS &
RAMIREZ, ALEIDY
```

```
INSPECTOR: JORG HRUSCHKA
```

VIOLATIONS: FBC 105.1 ALTERED THIS PROPERTY TO INCLUDE, BUT NOT LIMITED TO: WOOD FENCE, DOOR, WINDOWS, AND PAVERS.

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

CASE NO:	CE07	0214	49	
CASE ADDF	4836	NE	23	AVE
OWNED .	DIICK	TAT T	ттт	глм т

OWNER:	BUCK,	WILLIAM	ΙL	&
	BUCK,	MARY L		
INSPECTOR:	JORG I	HRUSCHKA		

VIOLATIONS: FBC 105.1 INSTALLED KITCHEN CABINETS WITHOUT A PERMIT.

25

CASE NO: CE05120450

CASE ADDR:	400 NE 13 ST
OWNER:	D & D RESOURCES LLC

INSPECTOR:	MOHAMMED MALIK
VIOLATIONS:	FBC 105.1
	THERE HAVE BEEN PHYSICAL ALTERATIONS AND
	IMDROVEMENTS TO THE BUILDING WITHOUT FIRS

IMPROVEMENTS TO THE BUILDING WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMIT. SUCH ITEMS INCLUDE, BUT ARE NOT LIMITED TO THE FOLLOWING:

- 1. INSTALLED NEW SIGNS
- 2. REPOURED AIR-CONDITIONING CONCRETE PAD AND INSTALLED/REPLACED NEW AIR-CONDITIONING UNIT.
- 3. REPAVED PARKING LOT.
- 4. PLACED THREE (3) NEW CONTAINERS IN PARKING LOT, WHICH ARE BEING USED FOR TIRE STORAGE AND INSTALLATION.
- 5. INSTALLED NEW CANOPY.
- 6. INSTALLED NEW FENCE AND GATE.
- 7. ELECTRICAL WORK IN CONTAINERS.

FBC 105.2.11

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE BUILDING WITHOUT FIRST OBTAINING THE REQUIRED MECHANICAL PERMIT. SUCH ITEMS INCLUDE, BUT ARE NOT LIMITED TO THE FOLLOWING:

1. INSTALLED/REPLACED NEW AIR-CONDITIONING UNITS.

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

FBC 105.2.5

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE BUILDING WITHOUT FIRST OBTAINING THE REQUIRED ELECTRICAL PERMIT. SUCH ITEMS INCLUDE, BUT ARE NOT LIMITED TO THE FOLLOWING:

1. INSTALLED NEW ELECTRICAL BREAKERS, FIXTURES AT THE NEW CONTAINERS AND ALL REQUIRED WIRING TO ENERGIZE THE TIRE INSTALLATION MACHINES.

CASE NO:	CE06111420
CASE ADDR:	320 SW 31 AVE
OWNER:	ROWE, ANTOINETTE
INSPECTOR:	WAYNE STRAWN

VIOLATIONS: FBC 105.2.4 THE PLUMBING SYSTEM HAS BEEN ALTERED BY THE INSTALLATION OF PIPING TO DISPOSE OF THE GREY-WATER GENERATED BY THE LAUNDRY FACILITY.

FBC 105.1

THE FIRE DAMAGED CARPORT HAS BEEN DEMOLISHED WITHOUT OBTAINING A PERMIT. THE FIRE DAMAGE TO THE UTILITY ROOM AND CONNECTING ROOF HAVE BEEN REPAIRED WITHOUT OBTAINING A PERMIT.

FBC 1612.1.2

THE FIRE DAMAGED RAFTERS THAT HAVE BEEN UTILIZED IN THE REPAIR ATTEMPT WILL NOT MEET THE DESIGN STRENGTH REQUIREMENTS TO WITHSTAND ALL LOADS IMPOSED WITH SAFETY.

CASE NO: CE07030857

- CASE ADDR: 519 NW 23 AVE
- OWNER: MICHEL & TANIA OUAKNINE INC.

INSPECTOR: WAYNE STRAWN

VIOLATIONS: 47-20.20.H. THE PARKING LOT STRIPING HAS FADED TO A LARGE EXTENT.

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

9-278(e)

THE VENTILATION OF EACH MOTEL ROOM HAS BEEN COMPROMISED BY THE REMOVAL AND REPLACEMENT OF THE ORIGINAL WINDOWS. THE REPLACEMENTS ARE FIXED PANES THAT DO NOT OPEN.

9-279(g)

WATER HEATER NOT MAINTAINED SAFE AS REQUIRED. THE INSTALLATION WAS NOT INSPECTED AND APPROVED.

9-280(b)

1) WINDOWS ARE INOPERABLE OR MISSING GLASS.

- 2) BATHROOM WALLS HAVE HOLES AND MISSING PLASTER.
- 3) SOFFIT IN DISREPAIR.
- 4) STEEL SUPPORT POST FOR FRONT ROOF PROJECTION IS RUSTED OFF AT THE BASE.
- 9-280(c)

THE FRONT PORCH ROOF PROJECTION IS NOT SUPPORTED PROPERLY. THE STEEL COLUMN IS RUSTED OFF.

9-280(g)

THE ELECTRICAL SYSTEM IS NOT BEING MAINTAINED SAFE.

FBC 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1) WINDOWS AND DOORS HAVE BEEN REPLACED THROUGHOUT BUILDING.
- 2) KITCHEN CABINETS AND COUNTERS INSTALLED.
- 3) A WOODEN POST (4 X 4) HAS BEEN INSTALLED TO SUPPORT THE PORCH ROOF PROJECTION IN FRONT. THIS IS A STRUCTURAL REPAIR ATTEMPT. THE ORIGINAL STEEL COLUMN HAS RUSTED OFF AT THE BASE.
- 4) NEW VANITIES INSTALLED IN EVERY ROOM.
- 5) RAFTER REPLACEMENT IN THE LAUNDRY ROOM.
- 6) AWNINGS INSTALLED OVER ALL WINDOWS.

FBC 105.2.11

AIR-CONDITIONING UNITS HAVE BEEN REPLACED IN ALL THE ROOMS WITHOUT OBTAINING THE REQUIRED PERMITS.

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

FBC 105.2.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1) ALL LAVATORIES IN THE RENTAL ROOMS HAVE BEEN REPLACED.
- 2) LARGE ELECTRIC WATER HEATER WAS INSTALLED IN LAUNDRY ROOM.
- 3) KITCHEN SINK INSTALLED IN THE FRONT APARTMENT.
- 4) BATHROOM FIXTURES CHANGED OUT.
- 5) SOLAR WATER HEATING SYSTEM INSTALLED WITH PANELS ON ROOF.
- 6) SOIL PIPE REPAIR/REPLACEMENT ON THE SOUTH EXPOSURE OF THE BUILDING.

FBC 105.2.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1) NEW CIRCUITS FOR MOTEL ROOM LIGHTING (WIREMOLD APPLICATION) INCLUDING NEW SWITCHES AND FIXTURES.
- 2) NEW CIRCUITS AND RECEPTACLES IN FRONT ROOM (M.C.CABLE INSTALLATION).
- 3) NEW CIRCUIT FOR LARGE ELECTRIC WATER HEATER INSTALLED IN LAUNDRY ROOM.
- 4) NEW CIRCUITS FOR A CAMERA SYSTEM INSTALLED THROUGHOUT THE BUILDING. (LOW VOLTAGE SYSTEM)

FBC-M 402.3.1

THE MEN'S ROOM DOES NOT HAVE MECHANICAL VENTILATION AND THE WINDOW DOES NOT OPEN.

NEC 90.1 (A)

FEEDER CONDUIT AND WIRING TO LAUNDRY IS SEVERELY DETERIORATED.

NEC 90.1 (B)

WIRING AND CONDUIT FOUND BROKEN, HANGING AND NOT SECURED PROPERLY.

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

CASE	NO:	CE06030776

CASE ADDR: 812 NW 15 TER

OWNER: CAPITAL INNOVATIONS INC

INSPECTOR: WAYNE STRAWN

VIOLATIONS: 47-20.20.H

THE PARKING LOT IS NOT BEING MAINTAINED IN GOOD OPERATING CONDITION. THE LOT NEEDS TO BE RE-STRIPED AND PROPER PARKING WHEELSTOPS INSTALLED.

47-21.9 G.1.

THE PROPERTY DOES NOT COMPLY WITH THE RETROACTIVE LANDSCAPING REQUIREMENT OF A MINIMUM OF 50% OF TODAY'S REQUIREMENT. A LANDSCAPING PLAN WHICH PROVIDES COMPLIANCE WITH THE REQUIREMENT HAS NOT BEEN PROVIDED TO THE DEPARTMENT.

FBC 105.1

WINDOWS AND DOORS HAVE BEEN REPLACED WITHOUT VALID PERMITS. PERMIT #96011872 FOR THE REPLACEMENT OF ALL DOORS AND WINDOWS EXPIRED AFTER FAILING ALL FIELD INSPECTIONS. PERMIT #04032779 FOR THE SAME JOB HAS ALSO EXPIRED BECAUSE NO FIELD INSPECTIONS WERE SCHEDULED. IN ADDITION THE BUILDING HAS BEEN RESTUCCO-ED WITHOUT OBTAINING A PERMIT.

FBC 105.2.11

WINDOW AIR-CONDITIONING UNITS HAVE BEEN INSTALLED IN THE BUILDING WITHOUT OBTAINING PERMITS.

FBC 105.2.4

PERMIT #99051937 TO INSTALL A KITCHEN SINK IN APT #4 HAS EXPIRED WITHOUT INSPECTION. THE WORK EXISTS NOW AS WORK WITHOUT A PERMIT.

FBC 1612.1.2

THE EXTERIOR WALLS HAVE CRACKED AND SHOWN SIGNS OF INSTABILITY BECAUSE THE FOOTINGS ARE INADEQUATE. THE STAIR STEP OPENING OF THE MORTAR JOINTS HAS BEEN CONCEALED BY THE RECENT STUCCO JOB. THE SPLICE OF A SUPPORT BEAM ON THE PORCH ROOF IS ALSO INADEQUATE TO PROVIDE THE REQUIRED SUPPORT FOR ALL LOADS IMPOSED.

Page 72

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

FBC 1626.1 THE WINDOWS INSTALLED WITHOUT A VALID PERMIT DO NOT MEET THE IMPACT TEST CRITERIA AND ARE NOT PROTECTED BY ANY PROTECTIVE DEVICE (SHUTTERS) THAT MEET THE IMPACT CRITERIA.

FBC 2319.4 THE SUPPORT BEAM FOR THE PORCH ROOF IS SPLICED BETWEEN SUPPORTS WHICH IS PROHIBITED.

FBC R403.1

THE BUILDING IS NOT SUPPORTED PROPERLY WITH EXTERIOR WALLS SUPPORTED ON A SLAB ONLY. THE APPROVED PLANS SHOW A 10" X 20" FOOTING FOR A STEM WALL BUT THERE IS NO EVIDENCE THAT THIS FOOTING EXISTS.

CASE NO:	CE07030177
CASE ADDR:	915 CORDOVA RD
OWNER:	MOLINET, TAMMI L
INSPECTOR:	WAYNE STRAWN

VIOLATIONS: FBC 105.1

A REPLACEMENT DOCK WAS BUILT WITH NEW PILES AND ADDITIONAL DOLPHIN PILES WERE INSTALLED WITHOUT OBTAINING THE NECESSARY APPROVALS AND BUILDING PERMITS.

8-144.

THE DOCK WAS REPLACED AND PILINGS WERE ADDED WITHOUT OBTAINING PERMISSION FROM THE COMMISSION OR THE REQUIRED BUILDING PERMITS FORM THE CITY.

CASE NO:	CE06070690
CASE ADDR:	1114 - 1116 SW 4 ST
OWNER:	VILLAS FLORENCE INC
INSPECTOR:	WAYNE STRAWN

VIOLATIONS: 25-13 THE SWALE AREA OF THE RIGHT OF WAY HAS BEEN PAVED OVER WITHOUT OBTAINING A PERMIT FROM THE CITY ENGINEERING DEPARTMENT.

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

47-21.9 G.1.

A LANDSCAPE PLAN WHICH DEMONSTRATES THE REQUIRED RETROACTIVE REQUIREMENTS HAS NOT BEEN SUBMITTED TO THE LANDSCAPE DEPARTMENT.

FBC 105.1

TWO ONE STORY, (FOUR) UNIT BUILDINGS HAVE BEEN ALTERED WITHOUT PERMITS. THE ALTERATIONS INCLUDE BUT MAY NOT BE LIMITED TO:

- 1. THE LAUNDRY ROOM WALL IN BUILDING 1114 HAS BEEN REPAIRED (THE REPAIR IS IMPROPERLY DONE AND LEAVES THE REQUIRED FIRE SEPARATION FOR THE METER ROOM COMPROMISED).
- 2. EXTERIOR DOORS AND WINDOWS INSTALLED.
- 3. BATHROOM VANITIES INSTALLED.
- 4. KITCHEN CABINETS AND COUNTERS HAVE BEEN INSTALLED.
- 5. PARKING AREA HAS BEEN RESURFACED
- 6. THE STUCCO ON BOTH BUILDINGS HAS BEEN COMPLETELY REDONE.

FBC 105.2.11

THE VENTILATION SYSTEM HAS BEEN ALTERED IN THE LAUNDRY ROOM. THE DRYER EXHAUST PIPE HAS BEEN INSTALLED WITHOUT A PERMIT.

FBC 105.2.18

A PERIMETER FENCE WAS INSTALLED WITHOUT A PERMIT.

FBC 105.2.4

THE PLUMBING SYSTEMS WERE ALTERED WITHOUT A PERMIT, INCLUDING, BUT NOT LIMITED TO:

- 1) WATER HEATERS WERE REPLACED.
- 2) A SPRINKLER SYSTEM WAS INSTALLED.
- 3) BATHROOM FIXTURES AND VANITIES WERE REPLACED.
- 4) KITCHEN SINKS AND FAUCETS WERE REPLACED.
- 5) LAUNDRY ROOM PLUMBING SYSTEM ALTERED IN BLDG 1114.

FBC 105.2.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED WITHOUT A PERMIT, INCLUDING BUT NOT LIMITED TO:

1) PREMISE WIRING.

- 2) CIRCUIT TO POWER SPRINKLER SYSTEM.
- 3) CIRCUIT TO POWER LAUNDRY ROOM.
- 4) CIRCUIT TO POWER WATER HEATER.

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

FBC 1626.1
THE WINDOWS AND DOORS INSTALLED WITHOUT A VALID
PERMIT DO NOT MEET THE IMPACT TEST CRITERIA AND
ARE NOT PROTECTED BY ANY PROTECTIVE DEVICE
(SHUTTERS) THAT MEET THE IMPACT CRITERIA.

CASE NO: CE06021206

CASE ADDR:	1406 NW 13 AVE
OWNER:	BAGICALLUPPI, PHILLIP
INSPECTOR:	WAYNE STRAWN

VIOLATIONS: FBC 105.2.11 ALTERED THE MECHANICAL SYSTEMS INCLUDING, BUT NOT LIMITED TO INSTALLED NEW AIR-CONDITIONING UNITS:

> DUCTS WIRING PLUMBING EXHAUST SYSTEMS

FBC 105.2.5
ALTERED THE ELECTRICAL TO INCLUDE, BUT NOT LIMITED
TO INSTALLED NEW ELECTRICAL REMOVED ELECTRICAL
WIRING:

FIXTURES SWITCHES RECEPTACLES BREAKER PANELS NEW SERVICE

FBC 106.10.3.4
PERMIT #05041498 FOR WOOD FENCE ISSUED ON 4/19/05
HAS FAILED A FINAL INSPECTION ON 6/17/05. PERMITS
ARE NULL AND VOID DUE TO THE FACT IT HAS BEEN MORE
THAN 90 DAYS SINCE AN INSPECTION HAS PASSED ON
THIS PERMIT.

FBC 105.1

ALTERED THIS SINGLE FAMILY HOUSE TO INCLUDE, BUT LIMITED TO:

REMOVED INTERIOR WALLS, CEILINGS AND INSTALLED NEW FRAMING, ALL WITHOUT PERMITS OR INSPECTIONS.

Page 75

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

- CASE NO: CE06121030
- CASE ADDR: 1460 SW 28 ST
- OWNER: NBT HOLDINGS COMPANY
- INSPECTOR: WAYNE STRAWN
- VIOLATIONS: 9-280(b)
 - 1) EXTERIOR DOOR IS NOT MAINTAINED AND NOT WATERTIGHT.
 - 2) THE FRONT SCREEN DOOR IS IN DISREPAIR.
 - 3) THE CARPORT ROOF IS NOT MAINTAINED. THE RAFTERS AND DECKING ARE TERMITE AND WOOD ROT DAMAGED.
 - 9-281(b)

TRASH, AND DEBRIS OF VARIOUS DESCRIPTIONS INCLUDING, BUT NOT LIMITED TO: A SHOPPING CART AND A BICYCLE HAVE BEEN DEPOSITED IN THE SIDE AND REAR YARD.

FBC 105.1

THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING THE REQUIRED PERMITS. THE WORK INCLUDES, BUT MAY NOT BE LIMITED TO:

- 1) WINDOWS REPLACED ON THE EAST SIDE.
- 2) A SHELTER HOUSING THE WATER HEATER HAS BEEN ATTACHED TO THE WEST EXPOSURE OF THE BUILDING.
- 3) AN ALUMINUM SCREEN ENCLOSURE HAS BEEN INSTALLED IN THE OPENINGS OF THE FRONT PORCH AREA.
- 4) ENTRY DOOR AT WEST SIDE WAS REPLACED.
- 5) NEW KITCHEN CABINETS AND COUNTER INSTALLED.

FBC 105.2.11

A CENTRAL AIR-CONDITIONING SYSTEM HAS BEEN INSTALLED WITHOUT OBTAINING THE PREQUIRED PERMIT.

FBC 105.2.4

THE PLUMBING SYSTEMS WERE ALTERED WITHOUT OBTAINING THE REQUIRED PERMITS, INCLUDING BUT NOT LIMITED TO:

- 1) CLEAN OUT COVERS FOR SEWER LINES ARE MISSING.
- 2) A GAS FIRED HOT WATER HEATER HAS BEEN INSTALLED OUTSIDE OF THE BUILDING AND A NEW KITCHEN SINK INSTALLED.

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

FBC 105.2.5
THE ELECTRICAL SYSTEMS WERE ALTERED WITHOUT
OBTAINING THE REQUIRED PERMITS, INCLUDING BUT NOT
LIMITED TO:

GENERAL PREMISE WIRING, INCLUDING BUT NOT LIMITED TO:

THE CARPORT LIGHTING.

CASE NO: CE051	21982

CASE ADDR:	1708 NW 6 ST
OWNER:	LUCY'S MEAT MARKET CORP
INSPECTOR:	WAYNE STRAWN

VIOLATIONS: 47-20.20.H. THE PARKING LOT IS NOT BEING MAINTAINED IN GOOD OPERATION CONDITION. THE LOT NEEDS TO BE RE-STRIPED AND THE PARKING WHEELSTOPS ARE BROKEN OR LOOSE.

> 47-20.4.D.3. THE SIGN FOR THE ACCESSIBLE PARKING SPACE DOES NOT SPECIFY THE FINE AS REQUIRED.

- 47-21.11 A.9. THE BUFFERYARD AREA DOES NOT HAVE TREES AS REQUIRED.
- 47-21.8.A.

REFUSE AND DEBRIS INCLUDING, BUT NOT LIMITED TO DISCARDED BEER BOTTLES, PAPERS AND OTHER DEBRIS EXIST IN THE PLANTER AREAS.

47-21.8.E.

THE TREES IN THE PARKING AREA ARE MISSING.

47-25.3 A.3.d.iv.

THE REQUIRED MASONRY BUFFER WALL BETWEEN RESIDENTIAL AND COMMERCIAL PROPERTIES HAS NOT BEEN PROVIDED.

9-280(g)

ELECTRICAL FIXTURES FOR EXTERIOR LIGHTING ARE MISSING, LOOSE OR IN DISREPAIR. CONDUIT IS LOOSE AND NOT FASTENED PROPERLY.

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

9-280(h)(1)

THE CHAIN LINK FENCE ON THE EAST SIDE OF THE PROPERTY IS IN DISREPAIR. VERTICAL SUPPORTS HAVE BEEN BENT OVER AND DISCONNECTED FROM THE HORIZONTAL RAIL.

9-304(b)

THE PARKING AREA HAS LARGE HOLES IN THE SURFACE.

9-308(c)

THE BUILDING FACADE HAS NOT BEEN MAINTAINED IN GOOD CONDITION. SECTIONS ARE MISSING AND UNSIGHTLY.

9-309

MECHANICAL EQUIPMENT INSTALLED ON THE ROOF AND ON THE WEST EXPOSURE OF THE BUILDING ARE MISSING THE EQUIPMENT SHROUDS AND COVERS.

FBC 105.1

THE FOLLOWING BUILDING ALTERATIONS, REPAIRS AND IMPROVEMENTS HAVE BEEN COMPLETED WITHOUT OBTAINING THE REQUIRED BUILDING PERMITS:

- 1. THE FLOOR-PLAN TO THE FIRST FLOOR HAS BEEN ALTERED BY THE REMOVAL OF A WALL.
- 2. WINDOWS AND DOORS ON THE SECOND FLOOR HAVE BEEN REPLACED.
- 3. SECURITY BARS HAVE BEEN INSTALLED ON THE SECOND FLOOR WINDOWS.
- 4. TWO ROLL UP SECURITY DOORS HAVE BEEN INSTALLED ON THE EAST EXPOSURE OF THE FIRST FLOOR. A WINDOW AND DOOR ARE PROTECTED IN THIS MANNER.
- 5. THE BUILDING HAS BEEN RE-ROOFED.
- MAKE-SHIFT SHELTERS HAVE BEEN CONSTRUCTED TO HOUSE REFRIGERATION/MECHANICAL EQUIPMENT ON THE WEST EXPOSURE OF THE BUILDING.

FBC 105.2.11

AIR-CONDITIONING AND REFRIGERATION SYSTEMS HAVE BEEN INSTALLED AND/OR ALTERED FOR THE OPERATION OF THE MEAT MARKET WITHOUT OBTAINING PERMITS. ELEMENTS OF THESE SYSTEMS ARE NOTED BY THE EQUIPMENT MOUNTED ON THE ROOF ABOVE THE STORE AND AT GROUND LEVEL ON THE WEST EXPOSURE OF THE BUILDING.

FBC 105.2.4

A WATER HEATER HAS BEEN INSTALLED WITHOUT OBTAINING THE REQUIRED PERMIT.

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

FBC 105.2.5

ELECTRICAL ALTERATONS AND CIRCUIT EXTENSIONS HAVE BEEN DONE ON THE BUILDING WITHOUT OBTAINING THE REQUIRED PERMITS. THE WORK INCLUDES, BUT MAY NOT BE LIMITED TO:

- 1. EXTENSIVE CIRCUIT EXTENSIONS OVER THE ROOF OF THE STORE TO POWER AIR-CONDITIONING EQUIPMENT AND EXTERIOR LIGHTING. MOST OF THIS WORK IS WIRED THROUGH CONDUIT. THE CONDUIT HAS BEEN INSTALLED DIRECTLY UPON THE SURFACE OF THE FLAT ROOF AND IS NOW IN POOR CONDITION.
- 2. NEW PREMISE WIRING HAS BEEN INSTALLED IN CONDUIT INSIDE THE BUILDING.
- 3. A CIRCUIT HAS BEEN ADDED TO POWER A COFFEE MACHINE BY MEANS OF A LONG EXTENSION CORD STRUNG OVER THE FREEZER DOOR.
- 4. LIGHTING HAS BEEN INSTALLED ON THE ROOF TO ILLUMINATE THE PARKING AREA. IT IS NOW IN DISREPAIR.

FBC 11-4.6.2

THE DISABLED ACCESSIBLE PARKING SPACE PROVIDED IS NOT THE REQUIRED 12 FEET IN WIDTH.

FBC 11-4.6.6

THE REQUIRED 60 INCH LOADING ZONE FOR THE ACCESSIBLE PARKING SPACE HAS NOT BEEN PROVIDED.

CASE NO:	CE06061015
CASE ADDR:	2051 NW 28 AVE
OWNER:	WILLIAMS, TOCCARA
INSPECTOR:	WAYNE STRAWN

VIOLATIONS: FBC 105.1
THE FOLOWING WORK HAS BEEN DONE WITHOUT OBTAINING
THE REQUIRED PERMITS.
1. ALL THE WINDOWS AND DOORS HAVE BEEN CHANGED OUT.
2. THE CARPORT ROOF HAS BEEN REBUILT. NEW RAFTERS
AND DECKING HAVE BEEN INSTALLED.

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

OWNER:	CE07040525 4750 NW 15 AVE FIRST INDUSTRIAL L P IVETT SPENCE-BROWN
VIOLATIONS:	FBC 105.1 FIREWALL WAS OPENED WITHOUT A PERMIT.
OWNER:	CE07040542 6245 NW 9 AVE VICTORIA'S CORPORATE PLAZA LLC IVETT SPENCE-BROWN
VIOLATIONS:	NFPA 101 13.3.1 2ND FLOOR SOUTH AND EAST HAS UNENCLOSED UNPROTECTED VERTICAL OPENING.
	NFPA 101 40.3.4.1 FIRE ALARM REQUIRED WITH A PERMIT.
VIOLATIONS:	FBC 105.1 INTERIOR ALTERATION WAS DONE WITHOUT FIRST OBTAINING A PERMIT.
CASE NO: CASE ADDR: OWNER:	CE06110989 6795 NW 17 AVE CABO 6795 LLC IVETT SPENCE-BROWN
VIOLATIONS:	NFPA 1 4.5.8.1 SPRAY BOOTH IS MISSING ANNUAL SERVICE TAG.
	NFPA 101 7.10.1.2 EXIT SIGN IS MISSING.
	NFPA 101 7.10.5.1 EXIT SIGN DOES NOT ILLUMINATE

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

CASE NO:	CE07082001
CASE ADDR:	445 SW 27 AVE
OWNER:	WESTWOOD APARTMENTS LLC
INSPECTOR:	THOMAS CLEMENTS

VIOLATIONS: NFPA 101 31.3.4.1.1 A FIRE ALARM IS NOT PROVIDED.

> NFPA 101 31.3.4.5.1 A HARDWIRED SMOKE DETECTOR HAS TO BE OUTSIDE EVERY SLEEPING UNIT.

CASE	NO:	CE070	061	L043	
CASE	ADDR:	3220	W	BROWARD	BLVD

- OWNER: A&M INVESTMENTS OF AMERICA LLC
- INSPECTOR: THOMAS CLEMENTS
- VIOLATIONS: NFPA 1 1.12.1 ALTERATIONS DONE WITHOUT OBTAINING A PERMIT.
 - NFPA 1 1.7.6 THE ELECTRICAL BREAKER THAT SERVICES THE EXIT AND EMERGENCY LIGHTS IS NOT MARKED.
 - NFPA 1 10.13.1.1 ADDRESS IS NOT PROVIDED ON THE ADDRESS SIDE OF THE STRUCTURE CONSISTENT WITH THE CODE.
 - NFPA 1 13.6.3.10 FIRE EXTINGUISHERS ARE NOT MOUNTED CONSISTENT WITH THE CODE.
 - NFPA 1 13.6.6.1.1 FIRE EXTINGUISHERS ARE NOT PROVIDED WITHIN 75 FOOT TRAVEL DISTANCE.

NFPA 10 6.3.1 THE FIRE EXTINGUISHERS HAVE NOT BEEN SERVICED AND TAGGED BY A STATE LICENSED COMPANY WITHIN THE PAST 12 MONTHS.

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

	CE07061040 3224 W BROWARD BLVD A & M INVESTMENTS OF AMERICA LLC THOMAS CLEMENTS
VIOLATIONS:	NFPA 1 1.12.1 ALTERATIONS DONE WITHOUT A PERMIT.
	NFPA 1 11.1.5 EXTENSION CORDS ARE BEING USED AS A SUBSTITUTE FOR PERMANENT WIRING.
	NFPA 1 13.6.6.1.1 FIRE EXTINGUISHERS ARE NOT PROVIDED WITHIN 50 FOOT TRAVEL DISTANCE.

Page 82

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

	F.S.S. 162.09 HEARING TO IMPOSE FINES		
OWNER:	CE01100240 631 NE 18 AVE STORELLI, JOHN & SUSAN MOHAMMED MALIK		
VIOLATIONS:	FBC 104.1 ENCLOSED CARPORT WITHOUT OBTAINING REQUIRED PERMITS.		
	NOTE: BOARD OF ADJUSTMENT CASE NO 01-47 APPEAL DENIED PERMIT APPLICATION A-0105283 FAILED ZONING.		
OWNER:	1145 NE 5 TER VILLAVICENCIO, GINA L MOHAMMED MALIK FBC 105.1 THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE BUILDING WITHOUT FIRST		
	OBTAINING THE REQUIRED BUILDING PERMIT. SUCH ITEMS INCLUDE, BUT ARE NOT LIMITED TO THE FOLLOWING:		
	1. INSTALLED NEW WINDOWS		
	2. INSTALLED NEW FENCE		
	FBC 105.2.18 INSTALLED NEW FENCE WITHOUT PERMITS.		
CASE NO: CASE ADDR: OWNER:	CE06080836 1121 NE 2 AVE SOUTH POINT INC C/O WILSHIRE CREDIT CORP		
INSPECTOR:	WAYNE STRAWN		
VIOLATIONS:	47-34.1.A.3. THE OPERATION OF FOUR RENTAL/LIVING UNITS EXCEEDS THE DENSITY LIMITS FOR AN RD-15 ZONING DISTRICT.		

Page 83

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

FBC 105.1

THE FOLLOWING ALTERATIONS, CONVERSIONS, AND ADDITIONS HAVE BEEN DONE WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. THE FLORIDA ROOM ON THE MAIN HOUSE HAS BEEN ENCLOSED.
- 2. THE CARPORT OF THE REAR BUILDING (GUEST HOUSE) HAS BEEN ENCLOSED AND CONVERTED INTO AN APARTMENT.
- 3. A ROOF STRUCTURE HAS BEEN CONSTRUCTED ON THE NORTH EXPOSURE OF THE MAIN HOUSE.
- 4. A SMALL ADDITION HAS BEEN BUILT ON THE SOUTH SIDE OF THE WEST PROJECTION OF THE MAIN HOUSE.
- 5. CONVERSION OF THE MAIN HOUSE TO A DUPLEX.
- 6. CONCRETE DRIVEWAY INSTALLED.
- 7. WOODEN FENCING INSTALLED.
- 8. AN ENCLOSURE CONSTRUCTED TO HOUSE A WATER HEATER CONNECTED TO THE WEST EXPOSURE OF THE ORIGINAL DWELLING.

FBC 105.2.11

AIR-CONDITIONING UNITS HAVE BEEN INSTALLED WITHOUT OBTAINING THE REQUIRED PERMITS.

FBC 105.2.4

PLUMBING ALTERATIONS, REPAIRS AND ADDITONS HAVE BEEN DONE WITHOUT OBTAINING PERMITS. THE WORK INCLUDES, BUT MAY NOT BE LIMITED TO, PVC PIPING ON THE WEST WALL OF THE ORIGINAL HOUSE, THE INSTALLATION OF A WATER HEATER OUTSIDE THE FOOTPRINT OF THE HOUSE ON THE WEST EXPOSURE AND PLUMBING ALTERATIONS ASSOCIATED WITH THE CONVERSION OF THE CARPORT INTO AN APARTMENT.

FBC 105.2.5

THE ELECTRICAL SYSTEMS OF THE BUILDINGS ON THE PROPERTY HAVE BEEN ALTERED BY THE ADDITION OF CIRCUITS TO POWER A JACUZZI, EXTERIOR LIGHTING AND THE CARPORT CONVERTED INTO AN APARTMENT.

FBC 110.1.1

THE MAIN HOUSE AND THE GUEST HOUSE WITH THE CONNECTED CARPORT HAVE BOTH BEEN CONVERTED AND OCCUPIED CONTRARY TO THE APPROVED USE AND CERTIFICATE OF OCCUPANCY. THE MAIN HOUSE IS A SINGLE FAMILY DWELLING AND IS BEING USED AS A DUPLEX AND THE CARPORT ATTACHED TO THE REAR GUEST HOUSE ON THE NORTH HAS BEEN ENCLOSED AND UTILIZED AS AN APARTMENT.

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

OWNER:	CE05121203 2902 NW 69 CT DEMUTH, AUDREY LYNN WAYNE STRAWN
VIOLATIONS:	105.1 FENCING HAS BEEN INSTALLED ON THE EAST AND WEST SIDES OF THE PROPERTY WITHOUT OBTAINING THE REQUIRED PERMITS.
	47-19.5.E.3. THE GATES INSTALLED IN THE FENCING ON THE EAST SIDE OF THE PROPERTY SWING OVER THE PUBLIC RIGHT OF WAY.
	47-19.5.E.5. THE FENCING INSTALLED ON THE EAST SIDE OF THE PROPERTY HAS NO PROVISION TO BREAK UP THE LINEAR ASPECT AND MONOTONOUS APPEARANCE OF THIS CONTINUOUS FENCING.
	47-34.1.A.1. THE FENCING ON THE EAST SIDE OF THE PROPERTY DOES NOT HAVE THE REQUIRED SETBACK FROM THE PUBLIC RIGHT OF WAY AS REQUIRED BY TABLE 1, SECTION 47-19.5.B. U.L.D.R.
	CE06091348 3733 SW 12 CT GOLDSTEIN, DONALD JORG HRUSCHKA
VIOLATIONS:	FBC 105.1 ALTERED THIS SINGLE FAMILY RENTAL HOUSE TO INCLUDE, BUT NOT LIMITED TO:
	1. INSTALLED WINDOWS IN THIS HOUSE WITHOUT A PERMIT.
	FBC 105.2.11 ALTERED THE MECHANICAL SYSTEMS INCLUDING, BUT NOT LIMITED TO:
	1 INSTALLED & NEW CENTRAL AIR-CONDITIONING UNIT

1. INSTALLED A NEW CENTRAL AIR-CONDITIONING UNIT.

AGENDA CODE ENFORCEMENT BOARD City Commission Meeting Room - City Hall JANUARY 22, 2008 10:00am

FBC 106.10.3.1

- 1. PERMIT #99100582 ISSUED ON 10/12/99 WITH A PASSED ROUGH ELECTRICAL INSPECTION ON 2/7/00 IS THUS NULL AND VOID.
- 2. APPLICATION #00051559 APPLIED ON 5/19/00 WAS NEVER REVIEWED BY PLAN REVIEW, THUS IS NULL AND VOID.

- CASE NO: CE07071620
- CASE ADDR: 21 KENTUCKY AVE
- OWNER: D R K OF BROWARD COUNTY INC. INSPECTOR: THOMAS CLEMENTS
- VIOLATIONS: NFPA 101 31.3.4.1.1 FIRE ALARM SYSTEM NOT PRESENT.
 - NFPA 101 31.3.4.5.1 HARDWIRE SMOKE DETECTORS NEED TO BE INSTALLED IN EACH APARTMENT.

- CASE NO: CE07040546 CASE ADDR: 4710 NW 15 AVE #C OWNER: FIRST INDUSTRIAL L P
- INSPECTOR: IVETT SPENCE-BROWN
- VIOLATIONS: NFPA 1 4.5.8.1 SECOND FLOOR OFFICE DOES NOT HAVE A LEGAL EXIT.