

FORT LAUDERDALE

Denice of America

# CODE ENFORCEMENT BOARD HEARING AGENDA

# OCTOBER 27, 2009 9:00 AM

CITY COMMISSION MEETING ROOM - CITY HALL 100 N ANDREWS AVENUE FT LAUDERDALE, FL 33301

CODE ENFORCEMENT BOARD Code of Ordinances: Sec. 11-3.

PURPOSE: Hear and decide cases in which violations are alleged of any provision of the Florida Building Code, Broward County Addition and violations of the Code of Ordinances of the City of Fort Lauderdale when alleged together with a violation of the Florida Building Code.

**Note:** If any person decides to appeal any decision made with respect to any matter considered at this public meeting or hearing he/she will need a record of the proceedings and for such purpose, he/she may need to ensure that a verbatim record of the proceedings is made, which record includes the testimony and evidence upon which the appeal is to be based.

**Board Members:** Sam Mitchell, **Chair** • Genia Ellis, **Vice Chair** • Ronald Perkins • Jan Sheppard • Joan Hinton • Howard Nelson • Howard Elfman • Chad Thilborger (alternate) • **Board Attorney:** Bruce Jolly

TWO OR MORE FORT LAUDERDALE CITY COMMISSIONERS OR MEMBERS OF A CITY OF FORT LAUDERDALE ADVISORY BOARD MAY BE IN ATTENDANCE AT THIS MEETING.

COMMUNICATION TO THE CITY COMMISSION WILL BE ADDRESSED AT THE END OF THE HEARING.

CITY OF FORT LAUDERDALE Page 1

AGENDA

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL

OCTOBER 27, 2009 9:00 AM

\_\_\_\_\_ NEW BUSINESS \_\_\_\_\_ CASE NO: CE07080650 CASE ADDR: 3580 SW 16 ST OWNER: ERLICK, JANET L INSPECTOR: GERRY SMILEN VIOLATIONS: FBC(2007) 105.4.1 REMODELING HAS STARTED ON THE SINGLE FAMILY DWELLING DUE TO WATER DAMAGE IN THE FOLLOWING MANNER WITHOUT A PERMIT: 1. INTERIOR DEMOLITION. 2. INTERIOR WALLS RELOCATED. 3. WATER DAMAGED DRYWALL WAS REPLACED. \_\_\_\_\_ CASE NO: CE08092060 CASE ADDR: 1533 NE 16 AV OWNER: STEVENSON, KENNETH J INSPECTOR: GERRY SMILEN VIOLATIONS: FBC(2007) 105.4.1 A WOOD TRELLIS STRUCTURE HAS BEEN CONSTRUCTED ON THE FRONT OF THE SINGLE FAMILY DWELLING WITHOUT OBTAINING A PERMIT. \_\_\_\_\_ CASE NO: CE08101135 CASE ADDR: 1826 SW 29 ST OWNER: PROVENZALE, ANTHONY PROVENZALE, DOMINIC INSPECTOR: GERRY SMILEN VIOLATIONS: FBC 105.1 AN ADDITION AND RENOVATION WORK HAVE BEEN DONE WITHOUT PERMITS. FBC(2007) 105.4.11 THE AIR CONDITIONING SYSTEM HAS BEEN ALTERED TO ACCOMODATE THE ADDITIONS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO: 1. A NEW CONDENSING UNIT HAS BEEN INSTALLED. 2. A NEW AIR HANDLER HAS BEEN INSTALLED. 3. A WALL A/C UNIT HAS BEEN INSTALLED.

## AMENDED CITY OF FORT LAUDERDALE Page 2 AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 27, 2009 9:00 AM

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED WITHOUT PERMITS IN THE FOLLOWING MANNER TO ACCOMODATE THE ADDITION TO THE EXISTING HOUSE INCLUDING BUT NOT LIMITED TO:

- 1. PREMISE WIRING FOR THE ADDITION.
- 2. ADDITIONAL CIRCUITRY AND CONNECTION FOR A HOT WATER HEATER.
- 3. ADDITIONAL CIRCUITRY AND CONNECTIONS FOR THE A/C SYSTEM.
- 4. ADDITIONAL CIRCUITRY AND CONNECTIONS FOR A WASHER AND DRYER.
- 5. WIRING FOR SECURITY LIGHTING.
- 6. WIRING FOR A NEW KITCHEN.

FBC(2007) 105.4.4

THE PLUMBING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO:

- 1. INSTALLATION OF NEW BATHROOM FIXTURES.
- 2. RELOCATION OF A HOT WATER HEATER.
- 3. RELOCATION OF A WASHING MACHINE.
- 4. PLUMBING FOR A NEW KITCHEN.

\_\_\_\_\_

## CASE NO: CE08111292

CASE ADDR:	1611 S ANDREWS AVE
OWNER:	C E V KIRKILES INC
INSPECTOR:	GERRY SMILEN

VIOLATIONS: 9-280(b)

THE PLANTER WALLS IN FRONT OF THE COMMERCIAL BUILDING WERE DAMAGED BY A VEHICULAR COLLISION AND WERE NEVER REBUILT.

FBC 1626.1

THE COMMERCIAL BUILDING SUFFERED STRUCTURAL DAMAGE AS THE RESULT OF A VEHICULAR COLLISION. THE WALL REPAIR WAS COMPLETED WITHOUT THE CERTIFICATION OF A LICENSED DESIGN PROFESSIONAL. THE WALL AREA HAS NOT BEEN PROVEN TO WITHSTAND THE STRENGTH AND LOADS REQUIRED BY THE FLORIDA BUILLDING CODE.

CITY OF FORT LAUDERDALE Page 3

#### AGENDA

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL

## OCTOBER 27, 2009

9:00 AM

CASE	NO:	CE0	710	1002	2
CASE	ADDR:	500	SW	11	ST
OWNEI	ર:	LENT	ΓZ,	RIC	CK
INSPE	ECTOR:	GERI	RY	SMII	LEN

VIOLATIONS: FBC(2007) 105.4.11 A NEW A/C CONDENSING UNIT HAS BEEN INSTALLED WITHOUT A PERMIT.

\_\_\_\_\_

ASE NO:	CE04011959
CASE ADDR:	3000 STATE ROAD 84
OWNER:	VYCD 1 NEW RIVER LLC
INSPECTOR:	GEORGE OLIVA

- VIOLATIONS: FBC(2007) 105.10.3.1
  - THERE ARE FIVE EXPIRED PERMITS:
  - 1. ATF CODE VIOLATIONS P#99051499.
  - 2. ATF PLUMBING P#0210119.
  - 3. ELECTRIC P#02100185.
  - 4. REPLACE 25 WINDOWS P#02091349.
  - 5. ATF REMODEL 1 AND 2 FLOOR OFFICES P#02052127.

FBC(2007) 109.10

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS THROUGH THE PERMITTING AND INSPECTION PROCESS.

FBC(2007) 1604.1

THE STRUCTURE FOR THE OFFICES REMODELING WORK DOES NOT MEET THE STANDARD FOR GRAVITY LOADING AND HAS NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS.

FBC(2007) 1612.1.2 ALL THE WINDOWS, SHUTTERS AND DOOR INSTALLATIONS HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WINDLOADING THROUGH THE PERMITTING PROCESS.

\_\_\_\_\_

## CITY OF FORT LAUDERDALE Page 4

#### AGENDA

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL

## OCTOBER 27, 2009

9:00 AM

OWNER:	CE09010728 621 SW 28 WY CHARLES, JEAN F GEORGE OLIVA
VIOLATIONS:	FBC 105.1 THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS: 1. THE WINDOWS WERE REPLACED ON THE PROPERTY.
	FBC 1612.1.2 ALL THE WINDOWS, SHUTTERS AND DOOR INSTALLATIONS HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WINDLOADING THROUGH THE PERMITTING PROCESS
	FBC 1626.1 THE NEW WINDOWS AND DOOR WITH GLASS NEED TO BE IMPACT RESISTANT OR BE PROTECTED BY AN APPROVED HURRICANE PROTECTION SYSTEM.
OWNER:	CE08060235 2210 SW 36 AV HEMPSTEAD, THOMAS DOUGLAS & BOBBY GEORGE OLIVA
VIOLATIONS:	<ul> <li>FBC(2007) 105.1</li> <li>THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:</li> <li>1. FIRE DAMAGED THE REAR OF THE PROPERTY. REPAIRS WERE DONE IN THE UTILITY ROOM AND FAMILY ROOM.</li> <li>2. THE BREEZEWAY WAS REMOVED DUE TO FIRE DAMAGES.</li> <li>3. THE SLIDING GLASS DOORS WERE REPLACED DUE TO FIRE DAMAGE.</li> </ul>
	<pre>FBC(2007) 105.4.5 THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN DAMAGED DUE TO THE FIRE; PERMIT IS NEEDED IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO: 1. ALL ELECTRICAL SUPPLY AND RUNS BETWEEN ELECTRICAL PANELS AND SUPPLY OUTLETS MUST BE</pre>

CHECKED FOR FIRE DAMAGES AND REPAIR AS NEEDED.

## AMENDED CITY OF FORT LAUDERDALE Page 5 AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 27, 2009 9:00 AM

FBC(2007) 109.10

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS THROUGH THE PERMITTING AND INSPECTION PROCESS.

FBC(2007) 1604.1

THE STRUCTURE FOR THE STORAGE ROOM AND THE ROOF AT THE REAR OF THE PROPERTY THAT WAS DAMAGED BY FIRE DOES NOT MEET THE STANDARD FOR GRAVITY LOADING AND HAS NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WINDLOADING THROUGH THE PERMITTING PROCESS. ALL THE STRUCTURES THAT WERE DONE ILLEGALLY ARE UNSAFE AND THEY MUST BE REMOVED.

FBC(2007) 1612.1.2

THE DOOR INSTALLATIONS HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WINDLOADING THROUGH THE PERMITTING PROCESS.

- CASE NO: CE08121039 CASE ADDR: 2488 SW 6 CT OWNER: SCHMALHAUS, DAGOBERT & BEAULAC, ANDREE
- INSPECTOR: GEORGE OLIVA
- VIOLATIONS: FBC 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

- 1. THE SCREEN PORCH HAS BEEN ENCLOSED INTO AN ILLEGAL CONVERSION APARTMENT WITH A BEDROOM AND BATHROOM ON THE SOUTHWEST CORNER.
- 2. SUPPORT COLUMNS AT THE FRONT ENTRANCE ARE NOT PROPERLY ATTACHED TO THE STRUCTURE AND ARE NOT PROPERLY ANCHORED TO THE OVERHANG STRUCTURE. AT THE FRONT ENTRANCE IT IS UNSTABLE AND THE ROOF IS LEANING.
- 3. THERE IS A SEPARATE STRUCTURE IN THE REAR WHICH HAS UNPERMITTED PLUMBING AND ELECTRICAL HOOK-UPS. THE DOOR ON THE REAR STRUCTURE IS IN DISREPAIR AND IS NOT PROPERLY INSTALLED. IT DOES NOT APPEAR WATER TIGHT.
- 4. CHAIN LINK FENCE WITHOUT PERMIT.

FBC 105.2.11

THE MECHANICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO: 1. EXHAUST DUCT ILLEGALLY INSTALLED FROM ORIGINAL

- STRUCTURE INTO AN ILLEGAL CONVERTED BEDROOM.
- 2. NEW AIR CONDITIONER INSTALLED.

## FBC 105.2.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. COLD AND HOT WATER WAS SUPPLIED TO THE ILLEGAL ENCLOSURE. THE RISERS WERE REDONE OR REPOSITIONED FOR THE ADDITIONAL BATHROOM.

## FBC 105.2.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. ELECTRICAL LOAD DEMAND WAS INCREASED BY ADDING ADDITIONAL LIGHTS AND WALL OUTLETS THAT HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED AMPERAGE LOADING THROUGH THE PERMITTING PROCESS.

## FBC 109.6

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS THROUGH THE PERMITTING AND INSPECTION PROCESS.

## FBC 1604.1

THE STRUCTURE FOR THE SCREEN PORCH CONVERSION AND FRONT PORCH DOES NOT MEET THE STANDARD FOR GRAVITY LOADING AND HAS NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS.

## FBC 1612.1.2

ALL THE WINDOWS, SHUTTERS AND DOOR INSTALLATIONS ON THE ENCLOSED SCREEN PORCH HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS.

\_\_\_\_\_

#### AGENDA

## CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL

## OCTOBER 27, 2009

## 9:00 AM

CASE	NO:	CE09020950
C A C F	• תתת	

CASE ADDR:	210 SW 29 AV
OWNER:	PAUL, OMINIGUE
INSPECTOR:	GEORGE OLIVA

VIOLATIONS: FBC 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

- 1. WINDOWS AND FRONT DOOR WERE REPLACED.
- 2. THERE IS STUCCO WORK BEING DONE.

## FBC 105.2.11

THE MECHANICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO: 1. A CENTRAL A/C WAS INSTALLED WITH DUCT WORK AND ELECTRIC HEATERS.

FBC 105.2.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

 ELECTRICAL LOAD DEMAND WAS INCREASED BY ADDING A CENTRAL A/C WITH ELECTRIC HEATERS, ADDITIONAL LIGHTS AND WALL OUTLETS THAT HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED AMPERAGE LOADING THROUGH THE PERMITTING PROCESS.

FBC 109.6

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS THROUGH THE PERMITTING AND INSPECTION PROCESS.

FBC 1612.1.2

ALL THE WINDOWS, SHUTTERS AND DOOR INSTALLATIONS HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WINDLOADING THROUGH THE PERMITTING PROCESS.

FBC 1626.1 THE NEW WINDOWS AND DOOR WITH GLASS NEED TO BE IMPACT RESISTANT OR BE PROTECTED BY AN APPROVED HURRICANE PROTECTION SYSTEM.

#### AGENDA

CODE ENFORCEMENT BOARD

## CITY COMMISSION MEETING ROOM - CITY HALL

## OCTOBER 27, 2009

## 9:00 AM

- CASE NO: CE08071795
- CASE ADDR: 3512 RIVERLAND RD
- OWNER: DEUTSCHE BANK NATL TR CO TRSTEE
- % FLORIDA DEFAULT LAW GROUP PL
- INSPECTOR: GEORGE OLIVA

## VIOLATIONS: FBC 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

- 1. WINDOWS AND FRONT DOOR WERE REPLACED.
- 2. A GLASS SLIDING DOOR WAS INSTALLED FACING THE SOUTH END OF THE PROPERTY.
- 3. KITCHEN AND BATHROOMS WERE REMODELED.

FBC 105.2.11

THE MECHANICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. A CENTRAL A/C SYSTEM WITH DUCT WORK AND AN ELECTRIC HEATER WERE INSTALLED.

## FBC 105.2.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. KITCHEN AND BATHROOMS WERE REMODELED AND NEW FIXTURES WERE INSTALLED.
- FBC 105.2.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO: 1. ELECTRICAL LOAD DEMAND WAS INCREASED BY ADDING A CENTRAL A/C WITH AN ELECTRICAL HEATER,

ADDITIONAL KITCHEN LIGHTS AND WALL OUTLETS THAT HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED AMPERAGE LOADING THROUGH THE PERMITTING PROCESS.

FBC 109.6

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS THROUGH THE PERMITTING AND INSPECTION PROCESS.

## AMENDED CITY OF FORT LAUDERDALE Page 9 AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 27, 2009 9:00 AM

FBC 1604.1

THE STRUCTURAL SUPPORT AROUND THE SLIDING GLASS DOOR DOES NOT MEET THE STANDARD FOR GRAVITY LOADING AND HAS NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WINDLOADING THROUGH THE PERMITTING PROCESS.

FBC 1612.1.2

ALL THE WINDOWS AND DOOR INSTALLATIONS HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WINDLOADING THROUGH THE PERMITTING PROCESS.

FBC 1626.1

THE NEW WINDOWS AND DOOR WITH GLASS NEED TO BE IMPACT RESISTANT OR BE PROTECTED BY AN APPROVED HURRICANE PROTECTION SYSTEM.

\_\_\_\_\_

CASE NO:	CE06110950
CASE ADDR:	1611 N FEDERAL HWY
OWNER:	FRAM FED FIVE INC
INSPECTOR:	BURT FORD

VIOLATIONS: FBC 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

1. THE PARKING LOT HAS BEEN BLACK TOPPED AND RESTRIPED.

FBC 105.2.5

THE ELECTRICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. LIGHTS HAVE BEEN INSTALLED TO ILLUMINATE THE NON-ELECTRIC SIGN AT THE FRONT OF THE PROPERTY.

FBC 106.10.3.1

THE FOLLOWING PERMITS HAVE EXPIRED:

- 1. 98102299 -- COMMERCIAL DEMO OF CARPORT, NO FINAL INSPECTION WAS DONE.
- 2. 99020285 -- INSTALL BRICK PAVER 200 SF., FAILED THE FINAL INSPECTION ON 7/27/1999.
- 3. 99020649 -- ERECT NON-ELECTRIC GROUND SIGN, NO FINAL INSPECTION WAS DONE.
- 4. 06120717 -- SHUTTER PERMIT, FAILED FRAMING 10/13/2008.

AGENDA

CODE ENFORCEMENT BOARD

## CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 27, 2009

9:00 AM

2 00 121

FBC 109.6
WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING
THE REQUIRED APPROVALS.

\_\_\_\_\_

CASE NO:	CE08080683
CASE ADDR:	1538 NE 3 AVE
OWNER:	TUCHOW, TYLER
INSPECTOR:	BURT FORD

VIOLATIONS: 9-281(a)

RUBBISH AND TRASH ARE LITTERING THE PREMISES. REMOVE TRASH AND DEBRIS.

FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. WINDOWS WERE INSTALLED.
- 2. DOORS WERE INSTALLED.
- 3. A FENCE WAS INSTALLED.
- 4. VINYL SIDING WAS INSTALLED.
- 5. INTERIOR ALTERATIONS AND DRYWALL WERE DONE.
- 6. KITCHEN AND BATH REMODELING HAVE BEEN DONE.

FBC(2007) 105.4.11

THE MECHANICAL SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

1. WALL AND WINDOW UNITS HAVE BEEN INSTALLED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. A WASHER WAS INSTALLED.
- 2. PIPING AND FIXTURES HAVE BEEN INSTALLED FOR THE KITCHEN AND BATH REMODELING.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. CIRCUITS HAVE BEEN ADDED/ALTERED FOR WINDOW AND WALL A/C UNITS.
- 2. CIRCUITS HAVE BEEN ADDED/ALTERED FOR WASHER AND DRYER THAT WERE INSTALLED.

## AMENDED CITY OF FORT LAUDERDALE Page 11 AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 27, 2009 9:00 AM

- 3. CIRCUITS HAVE BEEN ADDED/ALTERED FOR THE KITCHEN AND BATH REMODELING.
- 4. CIRCUITS HAVE BEEN ADDED/ALTERED IN THE GENERAL INTERIOR WORK BEING DONE.

FBC(2007) 109.10
WORK HAS BEEN COVERED UP WITHOUT FIRST HAVING
OBTAINED THE REQUIRED INSPECTION APPROVALS.

\_\_\_\_\_

- CASE NO: CE09100512 CASE ADDR: 561 BAYSHORE DR #2 OWNER: BRUNNER, WILLIAM F & BOSCARINO, JOHN
- INSPECTOR: BURT FORD
- VIOLATIONS: FBC(2007) 105.1
  THE BUILDING/PROPERTY HAS BEEN ALTERED IN THE
  FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED
  PERMITS:
  1.REPAIRED, SEALED, AND RESTRIPED PARKING AREA IN
  THE FRONT OF THE BUILDING.

FBC(2007) 109.10 WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

-----

CASE NO:	CE08081197
CASE ADDR:	561 BAYSHORE DR #3
OWNER:	BOSCARINO, JOHN A 1/2 INT
	BRUNNER, WILLIAM F
TNODDOD.	

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1 THE BUILDING/PROPERTY HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS: 1. REPAIRED, SEALED, AND RESTRIPED PARKING AREA IN

THE FRONT OF THE BUILDING.

FBC(2007) 109.10
WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING
THE REQUIRED APPROVALS.

\_\_\_\_\_

AGENDA

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL

## OCTOBER 27, 2009

9:00 AM

CASE NO: CE09100513 CASE ADDR: 561 BAYSHORE DR #7 OWNER: BELIVEAU, DOROTHY ZENDER INSPECTOR: BURT FORD VIOLATIONS: FBC(2007) 105.1 THE BUILDING/PROPERTY HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS: 1. REPAIRED, SEALED, AND RESTRIPED PARKING AREA IN THE FRONT OF THE BUILDING. FBC(2007) 109.10 WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS. \_\_\_\_\_ CASE NO: CE09100510 CASE ADDR: 561 BAYSHORE DR #9 OWNER: PRICE, GREGORY R INSPECTOR: BURT FORD VIOLATIONS: FBC(2007) 105.1 THE BUILDING/PROPERTY HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS: 1. REPAIRED, SEALED, AND RESTRIPED PARKING AREA IN THE FRONT OF THE BUILDING. FBC(2007) 109.10 WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REOUIRED APPROVALS. \_\_\_\_\_ CASE NO: CE08120690 CASE ADDR: 17 S FT LAUD BEACH BLVD # 216 THOR GALLERY AT BEACH PLACE LLC OWNER: THOMSON % K FAHEY INSPECTOR: BURT FORD VIOLATIONS: FBC 105.1 THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REOUIRED PERMITS: 1. INTERIOR REMODELING HAS BEEN DONE.

FBC 105.2.5 THE ELECTRICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER: 1. ELECTRICAL CIRCUITS HAVE BEEN ADDED/ALTERED DURING THE INTERIOR REMODELING. FBC 109.6 WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS. \_\_\_\_\_ CASE NO: CE09011019 CASE ADDR: 3711 N OCEAN BLVD OWNER: MV MANAGEMENT CORP INSPECTOR: BURT FORD VIOLATIONS: FBC(2007) 105.1 THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS: 1. A BARBECUE HUT HAS BEEN BUILT FOR THE OUTSIDE BAR AREA. FBC(2007) 105.10.3.1 THE FOLLOWING PERMITS HAVE EXPIRED: 1. 04051613 FOR THE ACCESSORY STRUCTURE, A BBQ HUT. PASSED A FOUNDATION INSPECTION ON 11/3/2004. FBC(2007) 109.10 WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REOUIRED APPROVALS. FBC(2007) 1612.1.2 THE BARBECUE HUT HAS NOT BEEN PROVEN TO SUFFICIENTLY WITHSTAND ESTIMATED OR ACTUAL IMPOSED DEAD, LIVE, WIND, OR ANY OTHER LOADS THROUGH THE PERMIT AND INSPECTION PROCESS.

## AMENDED CITY OF FORT LAUDERDALE Page 14 AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 27, 2009 9:00 AM

CASE NO: CE09050536 CASE ADDR: 3220 BAYVIEW DR # 215 OWNER: BALSAMO, ROSE % MARIE GREGOV INSPECTOR: TAMMY ARANA VIOLATIONS: NFPA 1:4.4.5 There is an unprotected vertical opening. \_\_\_\_\_ CASE NO: CE09050539 CASE ADDR: 3220 BAYVIEW DR # 301 OWNER: WACKELL, ROBERT V & JANE L INSPECTOR: TAMMY ARANA VIOLATIONS: NFPA 1:4.4.5 There is an unprotected vertical opening. \_\_\_\_\_ CASE NO: CE09050541 CASE ADDR: 3220 BAYVIEW DR # 302 OWNER: BAZAN, OSCAR ENRIQUE ZAYAS INSPECTOR: TAMMY ARANA VIOLATIONS: NFPA 1:4.4.5 There is an unprotected vertical opening. \_\_\_\_\_ CASE NO: CE09050543 CASE ADDR: 3220 BAYVIEW DR # 303 OWNER: ALVARADO-STADLER, NATALIA STADLER, KAI INSPECTOR: TAMMY ARANA VIOLATIONS: NFPA 1:4.4.5 There is an unprotected vertical opening. \_\_\_\_\_ CASE NO: CE09050550 CASE ADDR: 3220 BAYVIEW DR # 304 OWNER: MATYSEK, KRZYSZTOF & TINA E INSPECTOR: TAMMY ARANA VIOLATIONS: NFPA 1:4.4.5 There is an unprotected vertical opening. \_\_\_\_\_

AGENDA

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL

OCTOBER 27, 2009

9:00 AM

\_\_\_\_\_ RETURN HEARING (OLD BUSINESS) \_\_\_\_\_ CASE NO: CE06030884 CASE ADDR: 817 NW 15 TER OWNER: HARMON, JAMES & SYLVIA INSPECTOR: GEORGE OLIVA VIOLATIONS: FBC 105.1 THE BUILDING HAS BEEN REPAIRED, ALTERED AND IMPROVEMENTS ATTEMPTED WITHOUT OBTAINING THE REQUIRED PERMITS. THE ALTERATIONS INCLUDE THE FOLLOWING: 1. RE-ROOF OF THE BUILDING. 2. REMOVAL AND REPLACEMENT OF WINDOWS AND DOORS. 3. INSTALLATION OF AIR CONDITIONING UNITS. 4. REPLACEMENT OF THE SUPPORT SYSTEM FOR THE ROOF PROJECTION ON THE FRONT OF THE BUILDING. 5. ALTERATON OF THE ROOF STRUCTURE OF THE SHED IN THE REAR YARD. 6. INSTALLATION OF A SHUTTER SYSTEM. 7. INSTALLATION OF CHAIN LINK FENCING. FBC 105.2.4 THE PLUMBING SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING THE REQUIRED PERMIT. THE ALTERATIONS INCLUDE THE INSTALLATION OF PVC VENT PIPING AND SUPPLY PIPING. FBC 105.2.5 THE ELECTRICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMIT. 1. THE INSTALLATION/EXPANSION OF CIRCUITRY TO POWER A LIGHT ATTACHED TO THE REAR SHED. 2. REMOVAL AND REPLACEMENT OF THE SERVICE EQUIPMENT. FBC 109.6 THE REOUIRED INSPECTIONS FOR THE UNPERMITTED WORK CITED IN THIS DOCUMENT HAVE BEEN MISSED. THE METHODS AND MATERIALS UTILIZED ARE NOW CONCEALED.

CITY OF FORT LAUDERDALE Page 16 AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 27, 2009 9:00 AM

FBC 1612.1.2

THE REQUIRED RESISTANCE TO WIND AND GRAVITY LOADING AS SPECIFIED BY THE FLORIDA BUILDING CODE IN A HIGH VELOCITY WIND ZONE HAS NOT BEEN DEMONSTRATED FOR THE FOLLOWING BUILDING ALTERATIONS:

- 1. THE REMOVAL AND REPLACEMENT OF THE WINDOWS AND DOORS.
- 2. THE REPLACEMENT OF THE FRONT ROOF PROJECTION SUPPORT SYSTEM.
- 3. THE REBUILD OF THE SHED ROOF. THE PRODUCTS AND MATERIALS USED AS WELL AS THE ATTACHMENT METHODS HAVE NOT BEEN APPROVED AND INSPECTED TO ASSURE COMPLIANCE.

FBC 1626.1

THE WINDOWS AND DOORS INSTALLED HAVE NOT DEMONSTRATED THE RESISTANCE TO THE IMPACT OF WINDBORNE DEBRIS REQUIRED BY THE FLORIDA BUILDING CODE IN A HIGH VELCITY HURRICANE ZONE. THE REOUIRED RESISTANCE IS USUALLY ASSURED THROUGH THE PERMITTING PROCESS BY THE APPROVAL OF THE MATERIALS/PRODUCTS AND ATTACHMENT SYSTEM UTILIZED.

\_\_\_\_\_

CASE NO:	CE07021312
CASE ADDR:	1320 NW 7 TER
OWNER:	SILIEN, CONCEPTIA 1/2 INT EA
	NOEL, LEON VEL
INSPECTOR:	GEORGE OLIVA

VIOLATIONS: FBC 109.6

EXTENSIVE ALTERATIONS AND EXPANSIONS OF THE BUILDING HAVE BEEN DONE WITHOUT ANY FIELD INSPECTIONS AS REQUIRED BY THE FLORIDA BUILDING CODE. THE ALTERATIONS WERE COMPLETED AND MUCH OF THE WORK COVERED OVER SO THAT IT CANNOT BE INSPECTED.

FBC 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS.

1. THE BUILDING FOOTPRINT HAS BEEN EXPANDED ON THE WEST EXPOSURE AND ON THE NORTH EXPOSURE BEHIND THE CARPORT.

## AMENDED CITY OF FORT LAUDERDALE Page 17 AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 27, 2009 9:00 AM

- 2. THE CARPORT HAS BEEN ENCLOSED AND CONVERTED FOR LIVING SPACE.
- 3. THE LIVING SPACE HAS BEEN EXPANDED BY AN ADDITION BEHIND THE ORIGINAL CARPORT AND AN ADDITION ON THE FRONT OF THE BUILDING.
- 4. WINDOWS AND DOORS HAVE BEEN INSTALLED.

FBC 105.2.11

AIR CONDITIONING EQUIPMENT HAS BEEN INSTALLED WITHOUT OBTAINING THE REQUIRED PERMIT.

FBC 105.2.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED WITHOUT OBTAINING THE REQUIRED PERMITS. THE ALTERATIONS AND EXPANSION OF THE SYSTEM ARE AS FOLLOWS:

- 1. THE INSTALLATION OF CIRCUITS TO POWER AIR CONDITIONING EQUIPMENT.
- 2. PREMISE WIRING INSTALLED IN THE ADDITIONS ON THE FRONT AND REAR OF THE BUILDING.
- 3. CIRCUITS INSTALLED TO POWER EXTERIOR LIGHTING.

FBC 1612.1.2

EXTENSIVE ALTERATIONS/EXPANSIONS AND INSTALLATIONS HAVE BEEN DONE COMPROMISING THE BUILDING ENVELOPE. THE ALTERATIONS DO NOT DEMONSTRATE COMPLIANCE WITH THE WIND LOADING REQUIREMENTS OF THE FLORIDA BUILDING CODE. THIS COMPLIANCE MUST BE DEMONSTRATED THROUGH THE PERMITING PROCESS.

FBC 1626.1

EXTENSIVE ALTERATIONS/EXPANSIONS AND INSTALLATIONS HAVE BEEN DONE WITHOUT DEMONSTRATING COMPLIANCE WITH THE REQUIREMENTS OF THE FLORIDA BUILDING CODE REGARDING RESISTANCE TO THE IMPACT OF WINDBORNE DEBRIS. THIS RESISTANCE SHOULD HAVE BEEN DEMONSTRATED THROUGH THE PERMITTING PROCESS.

#### AGENDA

## CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL

## OCTOBER 27, 2009

## 9:00 AM

- CASE NO: CE07060475
- CASE ADDR: 1380 SW 34 AV
- OWNER: RODRIGUEZ, BERNARDO &
- MOREIRA, MARENA
- INSPECTOR: GEORGE OLIVA

## VIOLATIONS: FBC 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

- 1. THERE ARE TWO ROOM ADDITIONS THAT WERE DONE ILLEGALLY, ONE BETWEEN 2005 AND 2007 AND THE OTHER BETWEEN 2007 AND 2009.
- 2. THE FRONT PORCH AND CARPORT JOIST WERE REPLACED AND COVERED WITH DRYWALL. WORK WAS BETWEEN 2007 AND 2009.
- 3. WINDOWS AND DOORS WERE INSTALLED ON THE ADDITIONS.
- FBC 105.2.11

THE MECHANICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. THERE IS A CENTRAL A/C WITH DUCT WORK AND ELECTRIC HEATER.
- 2. KITCHEN AND BATHROOM(S) VENTILATIONS.
- FBC 105.2.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO: 1. KITCHEN AND BATHROOM(S) FIXTURES WERE REPLACED,

AND PLUMBING LINES WERE ADDED TO THE ADDITIONS.

## FBC 105.2.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. ELECTRICAL LOAD DEMAND WAS INCREASED BY ADDING ADDITIONAL LIGHTS AND WALL OUTLETS IN THE ADDITIONS THAT HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED AMPERAGE LOADING THROUGH THE PERMITTING PROCESS.
- 2. ELECTRICAL SUPPLY TO THE A/C WITH ELECTRIC HEATER.

## AMENDED CITY OF FORT LAUDERDALE Page 19 AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 27, 2009 9:00 AM

FBC 109.6

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS THROUGH THE PERMITTING AND INSPECTION PROCESS.

FBC 1604.1

THE STRUCTURES FOR THE TWO ADDITIONS, FRONT PORCH AND CARPORT DO NOT MEET THE STANDARD FOR GRAVITY LOADING AND HAS NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS.

FBC 1612.1.2

ALL THE WINDOWS AND DOOR INSTALLATIONS HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS

CASE NO:	CE07120173
CASE ADDR:	301 W SUNRISE BLVD
OWNER:	GY-RICH INC
INSPECTOR:	GEORGE OLIVA

VIOLATIONS: 47-19.4 D.7.

THE DUMPSTER ENCLOSURE THAT HAS BEEN INSTALLED DOES NOT HAVE THE APPROVED SANITATION FACILITIES WHICH ARE REQUIRED FOR A BUSINESS THAT SERVES FOOD. A WATER SUPPLY AND AN APPROVED DRAIN ARE REQUIRED.

47-20.20.H.

THE PARKING LOT IS NOT BEING MAINTAINED. THE STRIPES ARE NOT VISIBLE AND MANY PARKING BUMPERS FOR LANDSCAPE PROTECTION ARE BROKEN.

47-21.8.A.

THE LANDSCAPING HAS NOT BEEN MAINTAINED. PLANTING AREAS HAVE BEEN ELIMINATED AND TREES HAVE BEEN REMOVED WITHOUT REPLACEMENT.

47-25.3 A.3.d.iv. THE REQUIRED BUFFER WALL HAS NOT BEEN MAINTAINED. THE POSTS LEAN AND MANY CONCRETE PANELS ARE MISSING.

## CITY OF FORT LAUDERDALE Page 20 AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 27, 2009 9:00 AM

FBC 105.1

THE BUILDING AND PROPERTY HAVE BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. A KITCHEN HAS BEEN INSTALLED WITHOUT OBTAINING A PERMIT FOR THE FLOOR PLAN ALTERATION.
- 2. A DUMPSTER ENCLOSURE HAS BEEN INSTALLED ON THE NORTHEAST CORNER OF THE PROPERTY WHERE A LANDSCAPE AREA WAS.
- 3. SECURITY BARS HAVE BEEN INSTALLED ON THE BUILDING.
- 4. CHAIN LINK SECURITY ENCLOSURES HAVE BEEN INSTALLED TO PROTECT EOUIPMENT ON THE NORTH AND WEST EXPOSURES OF THE BUILDING.

FBC 105.2.4

THE FOLLOWING INSTALLATIONS OF PLUMBING FACILITIES HAVE BEEN DONE WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. LAVATORIES FOR THE KITCHEN AREA.
- 2. A GREASE TRAP NEXT TO THE BUILDING ON THE EAST.
- 3. WATER SUPPLY AND DRAIN FOR THE DUMPSTER ON THE NORTHEAST CORNER OF THE PROPERTY.
- 4. WASTE AND SUPPLY PIPING FOR ALL THE INSTALLATIONS CITED.

FBC 11-4.1.2(5)(a)

NO PROVISION HAS BEEN MADE TO PROVIDE THE REQUIRED SPECIAL PARKING FOR DISABLED CUSTOMERS.

\_\_\_\_\_

CASE NO:	CE08040779
CASE ADDR:	1028 NW 7 TER
OWNER:	WATKINS, JAKE JR
INSPECTOR:	GEORGE OLIVA

VIOLATIONS: FBC 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. NEW DOORS, ONE IN WEST ELEVATION AND ONE IN NORTH ELEVATION.
- 2. ENCLOSED THE SCREEN PORCH INTO AN APARTMENT OR LIVING AREA.
- 3. INSTALLED WINDOWS AND A DOOR IN THE ILLEGAL ENCLOSEMENT.

FBC 105.2.11

THE MECHANICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO: 1. WALL A/C WAS INSTALLED IN THE ILLEGAL ENCLOSEMENT.

FBC 105.2.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. ELECTRICAL LOAD DEMAND WAS INCREASED BY ADDING A CENTRAL A/C IN THE MAIN HOUSE, LIGHTS, WALL OUTLETS WERE ADDED, WALL A/C WAS INSTALLED IN THE SCREEN PORCH ENCLOSEMENT AND HAS NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED LOADING THROUGH THE PERMITTING PROCESS.

## FBC 109.6

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC 117.1.2

STRUCTURES COMMENCED WITHOUT A PERMIT OR THE PERMIT FOR WHICH HAS EXPIRED PRIOR TO COMPLETION AND NO CERTIFICATE OF OCCUPANCY HAS BEEN ISSUED, SHALL BE PRESUMED AND DEEMED UNSAFE.

## FBC 1604.1

THE STRUCTURE FOR THE SCREEN PORCH CONVERSION DOES NOT MEET THE STANDARD FOR GRAVITY LOADING.

FBC 1612.1.2

ALL THE WINDOW AND DOOR INSTALLATIONS HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS.

\_\_\_\_\_\_

AGENDA

.

## CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL

## OCTOBER 27, 2009

## 9:00 AM

- CASE NO: CE08072324
- CASE ADDR: 1036 NW 9 AVE
- OWNER: HAYLING, ROBERT B & ATHEA W &
- CARTER, JEREMIAH
- INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC 105.1 THE PARKING LOT HAS BEEN RE-STRIPED WITHOUT OBTAINING THE REQUIRED PERMIT.

## FBC 105.2.4

PLUMBING WORK HAS BEEN DONE WITHOUT OBTAINING THE REQUIRED PERMIT. THE WORK INCLUDES:

- 1. THE INSTALLATION OF HEAD WASH SINKS FOR THE BEAUTY SHOP.
- 2. PLUMBING REPAIRS OF THE WASTE LINE AT THE REAR OF THE BUILDING.

## FBC 11-4.6.2

THE ACCESSIBLE PARKING SPACE PROVIDED DOES NOT PROVIDE THE TWELVE FEET IN WIDTH AS REQUIRED.

FBC 11-4.6.3 A FIVE FOOT WIDE ACCESS AISLE FOR THE ACCESSIBLE PARKING SPACE HAS NOT BEEN PROVIDED AS REQUIRED.

\_\_\_\_\_

CASE NO:	CE08082310			
CASE ADDR:	3030 SW 22 ST			
OWNER:	WALL, MICHAEL D & JANE I			
INSPECTOR:	GEORGE OLIVA			

## VIOLATIONS: FBC 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

1. THERE IS A POOL ON THE SOUTH SIDE OF THE PROPERTY THAT WAS FINISHED WITHOUT OBTAINING THE FINAL INSPECTION.

## AMENDED CITY OF FORT LAUDERDALE Page 23 AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 27, 2009 9:00 AM

FBC 106.10.3.1

THERE IS AN EXPIRED BUILDING PERMIT FOR THE POOL #02091266 WHICH FAILED FINAL INSPECTION ON AUGUST 13,2003. THE STEEL INSPECTION FAILED ON DECEMBER 13, 2003 BECAUSE THE CONCRETE POURING WAS DONE COVERING THE STEEL WITHOUT PASSING THE STEEL INSPECTION.

FBC 109.6

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS THROUGH THE PERMITTING AND INSPECTION PROCESS.

FBC 1604.2

THE STRUCTURE FOR THE POOL AND DECK DOES NOT MEET THE STANDARD FOR GRAVITY LOADING AND HAS NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS.

-----

CASE NO:	CE08090676				
CASE ADDR:	1341 SW 24 AV				
OWNER:	ROQUE, RIGOBERTO & MIRIAM E				
INSPECTOR:	GEORGE OLIVA				

VIOLATIONS: FBC 1612.1.2 ALL THE WINDOW, SHUTTER, AND DOOR INSTALLATIONS HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS.

FBC 1626.1

THE NEW WINDOWS AND DOOR WITH GLASS NEED TO BE IMPACT RESISTANT OR BE PROTECTED BY AN APPROVED HURRICANE PROTECTION SYSTEM.

FBC 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

1. WINDOWS AND FRONT DOOR WERE REPLACED. A DOUBLE GLASS FRENCH DOOR WAS INSTALLED ON THE SOUTH SIDE OF THE PROPERTY.

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 27, 2009

9:00 AM

FBC 109.6

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS THROUGH THE PERMITTING AND INSPECTION PROCESS.

\_\_\_\_\_

CASE NO:	CE08010621				
CASE ADDR:	1023 NW 7 TER				
OWNER:	BROWN, MINNIE				
INSPECTOR:	GEORGE OLIVA				

- VIOLATIONS: FBC 105.1
  - THE FOLLOWING IMPROVEMENTS AND ALTERATIONS HAVE BEEN DONE WITHOUT OBTAINING THE REQUIRED PERMITS:
  - 1. THE RESIDENCE ON THE PROPERTY HAS BEEN ALTERED/IMPROVED BY THE REMOVAL AND REPLACEMENT OF THE WINDOWS.
  - 2. A METAL SHED HAS BEEN CONSTRUCTED IN THE REAR YARD.
  - 3. A ROOF STRUCTURE AND DOG PENS HAVE BEEN CONSTRUCTED IN THE REAR YARD.

FBC 1612.1.2

THE ACCESSORY STRUCTURES IN THE REAR YARD AND THE WINDOWS THAT HAVE BEEN INSTALLED HAVE NOT DEMONSTRATED THE STRENGTH REQUIRED BY THE FLORIDA BUILDING CODE TO COMPLY WITH THE MINIMUM WIND LOADING IN A HIGH VELOCITY HURRICANE ZONE. THE STRENGTH REQUIREMENT IS ASSURED ONLY IF THE INSTALLATIONS WERE INSTALLED THROUGH THE PERMITTING PROCESS.

FBC 1626.1

THE WINDOWS INSTALLED HAVE NOT DEMONSTRATED COMPLIANCE WITH THE MINIMUM RESISTANCE TO THE IMPACT OF WINDBORNE DEBRIS AS REQUIRED BY THE FLORIDA BUILDING CODE IN A HIGH VELOCITY HURRICANE ZONE.

## 9:00 AM

- CASE NO: CE08030272
- CASE ADDR: 3521 RIVERLAND RD OWNER: LAKHA, ZULFIQAR
- INSPECTOR: GEORGE OLIVA

#### VIOLATIONS: FBC 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

- 1. THE GARAGE DOOR WAS ENCLOSED FROM INSIDE AND THE GAME ROOM SPACE WAS ADDED TO THE GARAGE MAKING A RENTAL APARTMENT.
- 2. A KITCHEN WAS BUILT AND CABINETS AND PLUMBING WITH FIXTURES WERE INSTALLED.
- 3. A BATHROOM WAS BUILT WITH ALL THE PLUMBING FIXTURES.
- 4. A ROOF OVERHANG WAS BUILT ALL THE WAY TO THE PROPERTY SETBACK ON THE EAST SIDE.

FBC 105.2.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO: 1. A KITCHEN AND BATHROOM WAS ADDED.

## FBC 105.2.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. ELECTRICAL LOAD DEMAND WAS INCREASED BY ADDING AN ADDITIONAL KITCHEN AREA WITH THE APPLIANCES, LIGHTS, WALL A/C, OUTLETS THAT HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED AMPERAGE LOADING THROUGH THE PERMITTING PROCESS.

## FBC 109.6

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS THROUGH THE PERMITTING AND INSPECTION PROCESS.

\_\_\_\_\_

## CITY OF FORT LAUDERDALE Page 26 AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 27, 2009 9:00 AM

CASE	NO:	CE08031427

- CASE ADDR: 2900 NE 30 ST # M-4 OWNER: HOLTZ, HEATHER &
- SIMPKINS, SCOTT M
- INSPECTOR: BURT FORD

VIOLATIONS: FBC 105.1 INTERIOR ALTERATIONS WERE DONE WITHOUT FIRST OBTAINING A PERMIT, INCLUDING BUT NOT LIMITED TO KITCHEN AND BATH REMODELING.

FBC 105.2.4
KITCHEN AND BATH FIXTURES WERE REMOVED AND
REPLACED WITHOUT A PERMIT.

CASE NU: CEUDUOIDI/	CASE	NO:	CE06081617
---------------------	------	-----	------------

CASE ADDR:	9 FORT ROYAL ISLE
OWNER:	FRIEDBERG, SHELDON
INSPECTOR:	BURT FORD

VIOLATIONS: FBC 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- REPAIRS TO THE FRONT ENTRANCE SLAB AND ROOF WERE DONE AND AFTER THE FACT PERMIT, 06120880, WAS APPLIED FOR BUT NEVER ISSUED.
- 2. A CHICKEE HUT WAS INSTALLED IN THE BACKYARD BY THE POOL.
- 3. PAVERS WERE INSTALLED IN THE DRIVEWAY.
- 4. AN ALUMINUM FENCE WAS INSTALLED ON THE POOL DECK IN THE BACKYARD.
- 5. NEW WINDOWS AND DOORS HAVE BEEN INSTALLED.

FBC 105.2.5

THE ELECTRICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO: 1. ELECTRICAL CONDUIT, CIRCUITS, AND FIXTURES HAVE BEEN INSTALLED IN THE CHICKEE HUT.

FBC 109.6

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 27, 2009 9:00 AM

FBC 1604.1

THE WINDOWS, DOORS, FENCE, AND REPAIRS TO THE FRONT PORCH HAVE NOT BEEN DEMONSTRATED TO BE ABLE TO WITHSTAND WIND LOAD REQUIREMENTS THROUGH THE PERMIT AND INSPECTION PROCESS.

FBC 1626.1

THE NEW WINDOWS AND NEW DOORS WITH GLASS NEED TO BE IMPACT RESISTANT OR BE PROTECTED BY AN APPROVED HURRICANE PROTECTION SYSTEM.

CASE NO:	CE08031925			
CASE ADDR:	1640 NW 25 AV			
OWNER:	BANKS, ROBERTA			
INSPECTOR:	BURT FORD			

VIOLATIONS: FBC 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. THE KITCHEN IS BEING REMODELED.
- 2. NEW DRYWALL WAS INSTALLED ON THE KITCHEN CEILING.
- 3. THE MASTER BATHROOM HAS BEEN REMODELED AND THE SECOND BATHROOM IS IN THE PROCESS OF BEING DONE.
- 4. NEW DOORS HAVE BEEN INSTALLED.

FBC 105.2.4

THE PLUMBING SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. PLUMBING FIXTURES AND PIPING HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATH REMODELS.

FBC 105.2.5

THE ELECTRICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATH REMODELS.
- 2. RECESSED LIGHTING WAS INSTALLED IN THE LIVING ROOM AND KITCHEN CEILINGS.
- 3. AN OUTLET WAS ADDED TO POWER THE WALL MOUNTED TELEVISION.

FBC 109.6
WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING
THE REQUIRED APPROVALS.

CASE NO: CE08101015 CASE ADDR: 1522 DAVIE BLVD OWNER: WASHINGTON MUTUAL BANK INSPECTOR: GERRY SMILEN VIOLATIONS: 18-27(a) THERE IS PLANT OVERGROWTH, RUBBISH, TRASH, AND DEBRIS ON THE PROPERTY.

47-34.1.A.1.

THE SINGLE FAMILY HOME WAS CONVERTED INTO A DUPLEX, WHICH IS A PROHIBITED LAND USE IN THIS RS 8 ZONING DISTRICT.

9-280(b) BUILDING IS NOT STRUCTURALLY SOUND AND MAINTAINED IN A SECURE AND ATTRACTIVE MANNER. THE ROOF SURFACES SHALL BE WATERTIGHT.

9-280(d)

THE EXTERIOR WALLS ARE SUBJECT TO DETERIORATION AND ARE NOT PROTECTED FROM THE ELEMENTS. PAINT IS PEELING, CRACKING AND FADING. CAULKING IS MISSING. STRUCTURAL CRACKS ALLOW WATER PENETRATION.

9-280(h) THE FENCE IS IN DISREPAIR.

FBC 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. NEW WINDOWS WERE INSTALLED.
- 2. THE CARPORT WAS ENCLOSED, AND CONVERTED INTO AN APARTMENT.
- 3. A SECOND KITCHEN WAS INSTALLED IN THE CARPORT CONVERSION.
- 4. THE PORCH WAS ENCLOSED.
- 5. EXTERIOR DOORS WERE INSTALLED/REPLACED.
- 6. BATHROOMS WERE ADDED IN THE MAIN HOUSE & CARPORT.

- 7. INTERIOR WALLS WERE CONSTRUCTED TO CREATE A BEDROOM AND A BATHROOM.
- 8. THE FENCE WAS PARTIALLY DAMAGED AND REPLACED.
- 9. THE WINDOW ON THE SW CORNER WAS COVERED.
- 10. A LOAD BEARING WALL WAS PARTIALLY REMOVED BETWEEN THE HALLWAY AND THE LIVING ROOM.

## FBC 105.2.11

THE MECHANICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO: 1. WALL AND WINDOW UNITS WERE INSTALLED.

2. A CENTRAL A/C UNIT WAS INSTALLED.

## FBC 105.2.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO: 1. BATHROOM SINKS AND TOILETS WERE REPLACED.

2. GENERAL ALTERATIONS TO THE PLUMBING SYSTEMS.

## FBC 105.2.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. EXTERIOR AND INTERIOR OUTLETS WERE MOVED AND/OR ADDED.
- 2. CIRCUITS FOR CARPORT AREA WERE ADDED.
- 3. SERVICE WAS UPGRADED TO 200 AMPS.
- 4. GENERAL PREMISE WIRING WAS ALTERED.
- 5. A CIRCUIT TO POWER THE CENTRAL A/C UNIT WAS ADDED.
- 6. THE ELECTRICAL LOADS IMPOSED ON THE CIRCUITS INCLUDING BUT NOT LIMITED TO THE PORCH, BEDROOM, LIVING ROOM AND CARPORT, EXCEEDS THE CAPACITY OF THE EXISTING CIRCUITRY.

## FBC 109.6

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS THROUGH THE PERMITTING AND INSPECTION PROCESS.

FBC 1604.1

THE ENCLOSURES WERE NOT CONSTRUCTED IN ACCORDANCE WITH STRENGTH REQUIREMENTS FOR THE LOADS IMPOSED.

## CITY COMMISSION MEETING ROOM - CITY HALL

# OCTOBER 27, 2009

9:00 AM

OWNER:	CE09050128 3000 SW 15 AVE EILER, DAVID & STEVENS, DON GERRY SMILEN
VIOLATIONS:	105.1 A FENCE HAS BEEN INSTALLED ON THE PROPERTY WITHOUT OBTAINING THE REQUIRED PERMITS.
CASE ADDR: OWNER:	CE04120647 2325 S FEDERAL HWY MEDINA, CONNIE REV TR MEDINA, ARAEL SR TRSTEE GERRY SMILEN
VIOLATIONS:	<pre>FBC(2007) 11-4.6.3 THE PROPERTY DOES NOT HAVE ANY HANDICAP PARKING SPACES. FBC(2007) 11-4.6.4 THE PROPERTY DOES NOT HAVE ANY SIGNAGE DISPLAYED FOR HANDICAP PARKING OR MARKINGS.</pre>
CASE ADDR: OWNER:	CE09050449 3220 BAYVIEW DR # 101 ANDRESS, RICHARD YOUNG, PETER TAMMY ARANA
VIOLATIONS:	<pre>MO 13-64   KNOX Box is not provided with at least one (1) set   of firefighter service keys for the elevator(s). NFPA 1:4.4.5   There is an unprotected vertical opening.</pre>

CITY OF FORT LAUDERDALE Page 31

#### AGENDA

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 27, 2009

## 9:00 AM

CASE NO: CE09050456 CASE ADDR: 3220 BAYVIEW DR # 103 OWNER: GROSS, DONALD INSPECTOR: TAMMY ARANA VIOLATIONS NFPA 1:4.4.5 There is an unprotected vertical opening. MO 13-64 KNOX Box is not provided with at least one (1) set of firefighter service keys for the elevator(s) \_\_\_\_\_ CE09050460 CASE NO: CASE ADDR: 3220 BAYVIEW DR # 104 OWNER: CALDERON, JUAN G INSPECTOR: TAMMY ARANA VIOLATIONS: NFPA 1:4.4.5 There is an unprotected vertical opening. MO 13-64 KNOX Box is not provided with at least one (1) set of firefighter service keys for the elevator(s). \_\_\_\_\_ CASE NO: CE09050462 CASE ADDR: 3220 BAYVIEW DR # 111 OWNER: ESNO, ANDREA INSPECTOR: TAMMY ARANA VIOLATIONS: NFPA 1:4.4.5 There is an unprotected vertical opening. MO 13-64 KNOX Box is not provided with at least one (1) set of firefighter service keys for the elevator(s)

\_\_\_\_\_

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 27, 2009 9:00 AM

CITY OF FORT LAUDERDALE Page 32

AGENDA

CASE NO: CE09050467 CASE ADDR: 3220 BAYVIEW DR # 112 OWNER: ROBERTS, YRSA RINCONES INSPECTOR: TAMMY ARANA VIOLATIONS: NFPA 1:4.4.5 There is an unprotected vertical opening. -----CE09050469 CASE NO: CASE ADDR: 3220 BAYVIEW DR # 114 OWNER: RANNER, STEVEN L & DONNA J INSPECTOR: TAMMY ARANA VIOLATIONS: NFPA 1:4.4.5 There is an unprotected vertical opening. \_\_\_\_\_ CASE NO: CE09050475 CASE ADDR: 3220 BAYVIEW DR # 115 OWNER: PROTO, JOSEPH R INSPECTOR: TAMMY ARANA VIOLATIONS: NFPA 1:4.4.5 There is an unprotected vertical opening. \_\_\_\_\_ CASE NO: CE09050525 CASE ADDR: 3220 BAYVIEW DR # 201 OWNER: CORSARO, ANA R & MICHAEL J INSPECTOR: TAMMY ARANA VIOLATIONS: NFPA 1:4.4.5 There is an unprotected vertical opening. \_\_\_\_\_ CASE NO: CE09050527 CASE ADDR: 3220 BAYVIEW DR # 202 OWNER: ALVARADO, ALFREDO & AURA M INSPECTOR: TAMMY ARANA VIOLATIONS: NFPA 1:4.4.5 There is an unprotected vertical opening.

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 27, 2009 9:00 AM

CASE NO: CE09050529

INSPECTOR: TAMMY ARANA

VIOLATIONS: NFPA 1:4.4.5

CASE NO: CE09050530

OWNER: PEEL, CHARLES F INSPECTOR: TAMMY ARANA

CASE ADDR: 3220 BAYVIEW DR # 203 OWNER: DE BIASE, IVAN &

CASE ADDR: 3220 BAYVIEW DR # 204

MONICA TRUJILLO

CITY OF FORT LAUDERDALE Page 33

AGENDA

There is an unprotected vertical opening.

\_\_\_\_\_

VIOLATIONS: NFPA 1:4.4.5 There is an unprotected vertical opening. \_\_\_\_\_ CASE NO: CE09050531 CASE ADDR: 3220 BAYVIEW DR # 211 OWNER: CAPPONI, ANDREA & ROSSI, ROSSANA INSPECTOR: TAMMY ARANA VIOLATIONS: NFPA 1:4.4.5 There is an unprotected vertical opening. \_\_\_\_\_ CASE NO: CE09050533 CASE ADDR: 3220 BAYVIEW DR # 212 OWNER: FLORA, ALAN INSPECTOR: TAMMY ARANA VIOLATIONS: NFPA 1:4.4.5 There is an unprotected vertical opening. \_\_\_\_\_ CASE NO: CE09050535 CASE ADDR: 3220 BAYVIEW DR # 214 OWNER: LIGITORI, ANGELA INSPECTOR: TAMMY ARANA

VIOLATIONS: NFPA 1:4.4.5 There is an unprotected vertical opening.

AGENDA

CODE ENFORCEMENT BOARD

CITY COMMISSION MEETING ROOM - CITY HALL

OCTOBER 27, 2009

9:00 AM

CASE NO: CE07120458 CASE ADDR: 1548 SW 5 PL OWNER: RIVERSIDE CONDO ASSOCIATION OF BROWARD, INC INSPECTOR: THOMAS CLEMENTS PRESENTED BY TAMMY ARANA

VIOLATIONS: NFPA 101 31.3.4.5.1 HARDWIRED SMOKE DETECTORS NOT INSTALLED.

\_\_\_\_\_

CASE	NO:	CE08091566				
CASE	ADDR:	1029	NW	1	AV	
OWNEF	र:	FOJTI	ΓK,	ME	LISSA	
INSPECTOR:		GEOR	GE C	ЪI	VA	

VIOLATIONS: FBC 105.1

THE FOLLOWING ALTERATIONS, EXPANSIONS, IMPROVEMENTS AND CONSTRUCTION HAVE BEEN DONE ON THE BUILDING AND PROPERTY WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. THE LIVING AREA OF THE BUILDING HAS BEEN EXPANDED BY THE ENCLOSURE OF THE FRONT AND REAR PORCH.
- 2. THE FOOTPRINT OF THE BUILDING HAS BEEN EXPANDED BY THE CONSTRUCTION OF ROOF STRUCTURES ON THE FRONT OF THE BUILDING.
- 3. THE FOOTPRINT OF THE BUILDING HAS BEEN EXPANDED BY THE CONSTRUCTION OF A ROOF STRUCTURE ON THE REAR OF THE BUILDING.
- 4. THE FOOTPRINT OF THE BUILDING HAS BEEN EXPANDED BY AN ADDITION ON THE NORTH WEST CORNER OF THE BUILDING.
- 5. A LARGE IN-GROUND SWIMMING POOL HAS BEEN CONSTRUCTED IN THE REAR YARD.
- 6. A LARGE AREA OF THE REAR YARD HAS BEEN PAVED WITH CONCRETE.
- 7. A CONCRETE DRIVEWAY HAS BEEN CONSTRUCTED IN THE FRONT YARD.
- 8. NEW DOORS AND WINDOWS HAVE BEEN INSTALLED.

FBC 105.2.11

AN AIR CONDITIONING SYSTEM HAS BEEN INSTALLED WITHOUT OBTAINING THE REQUIRED PERMIT.

FBC 105.2.4

PLUMBING WORK HAS BEEN DONE WITHOUT OBTAINING THE REQUIRED PLUMBING PERMIT. THE WORK INCLUDES, BUT MAY NOT BE LIMITED TO:

1. THE INSTALLATION OF A SWIMMING POOL AND THE PIPING FOR SUCH.

FBC 105.2.5

CIRCUITS HAVE BEEN ADDED TO POWER AIR CONDITIONING EQUIPMENT, OUTLETS IN THE AREAS OF THE BUILDING THAT HAVE BEEN ADDED WITHOUT PERMITS AND TO POWER CIRCULATION EQUIPMENT FOR THE POOL. THE ELECTRICAL SERVICE TO THE BUILDING HAS BEEN UPGRADED. NO PERMITS WERE OBTAINED FOR THE CITED ALTERATIONS AND IMPROVEMENTS.

## FBC 1612.1.2

THE ROOF STRUCTURES AT THE FRONT OF THE BUILDING ARE NOT DESIGNED TO PROVIDE THE REQUIRED STRENGTH TO RESIST THE WIND LOADING IN A HIGH VELOCITY HURRICANE ZONE. THE CONSTRUCTION METHODS EMPLOYED DO NOT PROVIDE THE REQUIRED STRENGTH FOR GRAVITY LOADING IN ANY ZONE. ALL THE ADDITIONS, ENCLOSURES AND IMPROVEMENTS, INCLUDING WINDOWS AND DOORS, HAVE NOT DEMONSTRATED COMPLIANCE WITH THE STRENGTH REQUIREMENTS THROUGH THE PERMITTING PROCESS. THE FLORIDA BUILDING CODE (SEE FBC 117.1.2 ) DEEMS ALL WORK DONE WITHOUT A PERMIT TO BE UNSAFE.

\_\_\_\_\_

# AMENDED CITY OF FORT LAUDERDALE Page 36 AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 27, 2009 9:00 AM

\_\_\_\_\_ HEARING TO IMPOSE FINES CHAPTER 11, FORT LAUDERDALE CODE OF ORDINANCES \_\_\_\_\_ CASE NO: CE08100091 CASE ADDR: 414 SE 12 CT OWNER: OLSEN, JONATHAN & FRAMPTON, SEAN INSPECTOR: BURT FORD VIOLATIONS: FBC(2007) 105.1 THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS: 1. NEW WINDOWS HAVE BEEN INSTALLED. 2. WINDOW OPENINGS HAVE BEEN FRAMED IN. FBC(2007) 105.4.11 THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER: 1. WINDOW A/C UNITS HAVE BEEN INSTALLED. 2. WALL A/C UNITS HAVE BEEN INSTALLED. 3. DUCT WORK FOR THE GAS WATER HEATER HAS BEEN INSTALLED. FBC(2007) 105.4.4 THE PLUMBING SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER: 1. A GAS WATER HEATER HAS BEEN INSTALLED ON THE OUTSIDE OF THE BUILDING. FBC(2007) 109.10 WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REOUIRED APPROVALS. FBC(2007) 1612.1.2 THE WINDOW/WALL AIR CONDITIONING UNITS AND THE WATER HEATER HAVE NOT BEEN PROVEN TO SUFFICIENTLY WITHSTAND ESTIMATED OR ACTUAL IMPOSED DEAD, LIVE, WIND, OR ANY OTHER LOADS THROUGH THE PERMIT AND INSPECTION PROCESS.

#### AGENDA

#### CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL

# OCTOBER 27, 2009

9:00 AM

CASE	NO:	CE053	1115	570	
CASE	ADDR:	3051	NE	32	AVE
OWNER	र:	ANNI	EOPA	A LI	LC

INSPECTOR: BURT FORD

VIOLATIONS: 47-21 G.1.

A LANDSCAPE PLAN IS REQUIRED TO BE ON FILE WITH THE CITY OF FORT LAUDERDALE. THIS PLAN MUST DEMONSTRATE COMPLIANCE WITH THE 50% RETROACTIVE REQUIREMENT FOR LANDSCAPING. THIS LANDSCAPE PLAN IS NOT ON FILE WITH THE CITY OF FORT LAUDERDALE. THE PROPERTY DOES NOT HAVE THE REQUIRED RETROACTIVE LANDSCAPING.

FBC 105.1

- 1. ROOF STRUCTURES WERE BUILT ON THE SOUTH SIDE OF PROPERTY.
- 2. CANVAS AWNINGS WERE ERECTED.
- 3. AN AWNING STRUCTURE WAS CONVERTED INTO A STORAGE ROOM, INCLUDING, BUT NOT LIMITED TO AN ASPHALT SHINGLE ROOF, WOOD FRAME WALLS AND ROOF STRUCTURE, SEVERAL DOORS, CONCRETE FLOORS, AND INTERIOR BUILD OUT.
- 4. A WALK-IN COOLER WAS INSTALLED.
- 5. A FENCE WAS CONSTRUCTED.
- 6. A TRELLIS WAS ERECTED OVER FRONT ENTRANCE.
- 7. AN A/C SUPPORT STRUCTURE WAS ERECTED.
- 8. THE FIRE SPRINKLER SYSTEM WAS ALTERED, SPRINKLER HEADS WERE ADDED.

FBC 105.2.11

1. CENTRAL A/C UNITS AND OTHER MECHANICAL SYSTEMS HAVE BEEN INSTALLED, RELOCATED AND/OR REPLACED.

FBC 105.2.4

- 1. A SINK WAS INSTALLED.
- 2. A WATER HEATER WAS INSTALLED.
- 3. THE FIRE SPRINKLER SYSTEM WAS ALTERED AND ENLARGED.

FBC 105.2.5

- 1. EXTERIOR AND INTERIOR LIGHTING AND GENERAL POWER OUTLETS.
- 2. CIRCUITS TO A/C UNITS.
- 3. CIRCUITS TO ICE MACHINES AND WALK-IN COOLERS.
- 4. CIRCUIT TO WATER HEATER.

CITY OF FORT LAUDERDALE Page 38 AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 27, 2009 9:00 AM

FBC 109.6

WORK WAS DONE AND COVERED UP WITHOUT HAVING PASSED THE REQUIRED INSPECTIONS.

FBC 1604.1

THE ROOF STRUCTURES, STORAGE AND THE A/C SUPPORT STRUCTURE ARE NOT DESIGNED AND CONSTRUCTED ACCORDING TO THE STRENGTH REQUIREMENTS FOR THE LOADS IMPOSED AND DO NO CONFORM WITH ANY BUILDING CODES PAST OR PRESENT.

\_\_\_\_\_

- CASE NO: CE07032115 CASE ADDR: 2153 NE 62 ST OWNER: FIERMONTE, MICHAEL MORTON, E DANIEL
- INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REOUIRED PERMITS: 1. NEW EXTERIOR DOORS HAVE BEEN INSTALLED.

- 2. NEW WINDOWS HAVE BEEN INSTALLED.
- 3. THE KITCHEN HAS BEEN REMODELED.

FBC(2007) 105.10.3.1

THE FOLLOWING PERMITS HAVE EXPIRED:

- 1. REMODEL PERMIT 05041695.
- 2. PLUMBING PERMIT 0605194.
- 3. ELECTRICAL PERMIT 05060024 WAS VOIDED, BUT HAD BEEN APPROVED TO BE ISSUED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. PIPING AND FIXTURES HAVE BEEN REPLACED DURING THE KITCHEN REMODELING.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING THE KITCHEN REMODELING.
- 2. NEW ELECTRICAL SERVICE HAS BEEN INSTALLED.

AGENDA

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL

#### OCTOBER 27, 2009 9:00 AM

.. ..

FBC(2007) 109.10
WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING
THE REQUIRED APPROVALS.

CASE NO: CE08032088

CASE ADDR:	2900 NE 30 ST # L-6
OWNER:	WEISS, MAX
INSPECTOR:	BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS: 1. A BATHROOM WAS REMODELED.

2. DRYWALL HAS BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. PIPING AND FIXTURES HAVE BEEN ALTERED/REPLACED DURING THE BATHROOM REMODELING.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. CIRCUITS WERE ADDED/ALTERED DURING THE BATHROOM REMODELING.

FBC(2007) 109.10
WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING
THE REQUIRED APPROVALS.

\_\_\_\_\_

CASE NO:	CE04090141
CASE ADDR:	1434 NW 9 ST
OWNER:	PATSIMAS, CONSTANTINE
INSPECTOR:	GEORGE OLIVA

VIOLATIONS: 9-280(b)

THE BUILDING IS NOT BEING MAINTAINED IN REASONABLY GOOD REPAIR. FACIA AND SOFFIT ARE LOOSE AND THE FRONT DOOR DOES NOT FIT PROPERLY.

9-280(g)

ELECTRICAL CONDUIT IS LOOSE AND BROKEN. THIS CONDITION IS FOUND MOST NOTABLE WHERE THE A/C COMPRESSOR AND SPRINKLER SYSTEM ARE CONNECTED TO THE SYSTEM.

9-280(h)(1)

CHAIN LINK FENCING IS IN DISREPAIR.

FBC(2007) 1026.1

THE WEST BUILDING HAS A SECURITY BAR INSTALLED OVER THE CENTER WINDOW OF THE EAST EXPOSURE. THIS WINDOW IS THE ONLY MEANS FOR EMERGENCY ESCAPE AND RESCUE FOR THE BEDROOM IT SERVES. THE SECURITY INSTALLATION IS PERMANENTLY FIXED WITH NO PROVISION TO BE OPERATIONAL FROM THE INSIDE.

#### FBC(2007) 105.1

THE TWO RESIDENTIAL STRUCTURES HAVE BEEN ALTERED WITHOUT OBTAINING THE REQUIRED PERMIT OR THE PERMITS WERE ISSUED AND ALLOWED TO EXPIRE WITHOUT PASSING THE REQUIRED FIELD INSPECTIONS. THE WORK NOW EXISTS AS NON-PERMITTED WORK.

- 1. SECURITY BAR INSTALLATION PERMITS 97092340 AND 97092341 HAVE EXPIRED WITHOUT PASSING FIELD INSPECTIONS.
- 2. RE-ROOF PERMIT 96080012 HAS EXPIRED WITHOUT PASSING FIELD INSPECTION.
- 3. A NEW DOOR AND JAMB HAVE BEEN INSTALLED ON THE WEST SIDE OF THE EAST BUILDING.
- 4. CHAIN LINK FENCING HAS BEEN INSTALLED ABUTTING THE STREET AND THE AVENUE.
- 5. PAYPHONE INSTALLATION ON SOUTHEAST CORNER OF THE PROPERTY.

FBC(2007) 105.10.3.1

THE FOLLOWING PERMITS HAVE EXPIRED WITHOUT PASSING FIELD INSPECTION. THEY HAVE BECOME NULL AND VOID.

- SECURITY BAR INSTALLATION PERMIT #97092340 FOR 1434 NW 9 STREET.
- 2. SECURITY BAR INSTALLATION PERMIT #97092341 FOR 1436 NW 9 STREET.
- 3. RE-ROOF PERMIT #96080012.

CITY OF FORT LAUDERDALE Page 41 AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 27, 2009 9:00 AM

FBC(2007) 105.4.11 A CENTRAL AIR CONDITIONING SYSTEM HAS BEEN

INSTALLED FOR THE EAST BUILDING (1434) WITHOUT OBTAINING THE REQUIRED PERMIT.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE WEST BUILDING (1436) HAS BEEN ALTERED, EXPANDED OR REPAIRED WITHOUT OBTAINING THE REQUIRED PLUMBING PERMIT. THE WORK INCLUDES THE INSTALLATION OF SUPPLY AND WASTE PIPING ALONG WITH THE FIXTURES THEY SERVE. THIS PIPING IS NOTED ON THE SOUTH WALL OF THE BUILDING.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE BUILDINGS ON THE PROPERTY HAS BEEN REMODELED, EXPANDED, AND REPAIRED WITHOUT OBTAINING THE REQUIRED PERMITS. THE WORK INCLUDES THE FOLLOWING:

- 1. CIRCUIT TO PROVIDE POWER TO THE AIR CONDITIONING SYSTEM OF 1434.
- 2. CIRCUIT TO POWER SPRINKLER SYSTEM.
- 3. CIRCUITS ROUTED TO THE OUTSIDE OF THE EXTERIOR WALLS TO EXPAND OR REPLACE ORIGINAL CIRCUITRY.
- 4. CIRCUIT TO POWER EXTERIOR LIGHT.

\_\_\_\_\_

CASE NO:	CE08051178
CASE ADDR:	735 NW 17 ST
OWNER:	SAINTUS, FRITZ JR
INSPECTOR:	GEORGE OLIVA

VIOLATIONS: 47-34.1.A.1.

THE SHED CONSTRUCTED ON THE WEST EDGE OF THE PROPERTY HAS BEEN BUILT WITHIN THE SET-BACK THAT IS REQUIRED IN AN RDS ZONING DISTRICT.

9-313(a) THE BUILDING IS NOT PROPERLY NUMBERED WITH NUMERALS THAT CLEARLY CONTRAST WITH THE BACKGROUND AND ARE CLEARLY VISIBLE FROM THE STREET.

# FBC 105.1

THE BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS. THESE ALTERATIONS AND CONSTRUCTION INCLUDE THE FOLLOWING:

- 1. CONSTRUCTION OF AN ADDITION ON THE REAR OF THE BUILDING.
- 2. REMOVAL AND REPLACEMENT OF THE DOORS AND WINDOWS.
- 3. THE FRONT PORCH ROOF HAS BEEN EXTENDED TO THE EAST.
- 4. THE BUILDING HAS BEEN RE-ROOFED.
- 5. THE KITCHEN AND BATHROOM HAVE BEEN REMODELED.
- 6. A SHED HAS BEEN CONSTRUCTED IN THE REAR YARD.
- 7. THE FRONT PORCH HAS BEEN ENCLOSED WITH LATTICE.
- 8. THE DRIVEWAY PAVING HAS BEEN EXTENDED TO THE EAST.
- 9. A CONCRETE DRIVEWAY HAS BEEN INSTALLED ON THE WEST SIDE OF THE BUILDING.
- 10. A LARGE CONCRETE PATIO DECK HAS BEEN INSTALLED IN THE REAR YARD.

#### FBC 105.2.11

AIR CONDITIONING EQUIPMENT HAS BEEN INSTALLED IN WINDOWS AND WALLS WITHOUT OBTAINING THE REQUIRED PERMIT.

#### FBC 105.2.4

THE PLUMBING SYSTEM OF THE BUILDING HAS BEEN ALTERED IN THE REMODELING AND IMPROVEMENT PROCESS. PERMITS FOR THE IMPROVEMENTS/ALTERATIONS HAS NOT BEEN ISSUED. THE WORK INCLUDES THE FOLLOWING: 1. REPLACEMENT OF THE WATER CLOSET, LAVATORY AND

- BATHTUB.
- 2. REPLACEMENT OF THE KITCHEN SINK.

#### FBC 105.2.5

THE ELECTRICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED AND EXPANDED WITHOUT OBTAINING THE REQUIRED PERMITS. THE ALTERATIONS INCLUDE THE FOLLOWING:

1. CIRCUITS ADDED TO THE ADDITION ON THE REAR OF THE BUILDING TO POWER OUTLETS, LIGHTS AND THE AIR CONDITIONER.

# AMENDED CITY OF FORT LAUDERDALE Page 43 AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 27, 2009 9:00 AM

- 2. THE RELOCATION OF THE RANGE AND REFRIGERATOR OUTLETS FOR THE KITCHEN REMODEL.
- 3. THE ADDITION OF A RANGE HOOD CIRCUIT AND UPGRADE OF THE BATHROOM CIRCUITRY.

#### FBC 1612.1.2

THE WINDOWS AND DOORS ALONG WITH THE ADDITION ON THE REAR OF THE BUILDING HAVE NOT DEMONSTRATED COMPLIANCE WITH THE STRENGTH REQUIREMENTS OF THE HIGH VELOCITY HURRICANE ZONE THROUGH THE PERMITTING PROCESS.

#### FBC 1626.1

THE WINDOWS AND DOORS ALONG WITH THE ADDITION ATTACHED TO THE REAR OF THE BUILDING HAVE NOT DEMONSTRATED THE REQUIRED RESISTANCE TO IMPACT FROM WINDBORNE DEBRIS THROUGH THE PERMITTING PROCESS.

# GAGE NO: GE00020221

CASE NO.	CE09020331
CASE ADDR:	361 DELAWARE AVE
OWNER:	WRIGHT, JAMES R
INSPECTOR:	GEORGE OLIVA

VIOLATIONS: FBC 1612.1.2 ALL THE WINDOWS, SHUTTERS, AND DOOR INSTALLATIONS HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS.

FBC 1626.1

THE NEW WINDOWS AND DOOR WITH GLASS NEED TO BE IMPACT RESISTANT OR BE PROTECTED BY AN APPROVED HURRICANE PROTECTION SYSTEM.

### FBC 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

1. WINDOWS AND THE FRONT DOOR HAVE BEEN REPLACED. HURRICANE SHUTTERS WERE INSTALLED IN SOME OF THE OPENINGS.

# AMENDED CITY OF FORT LAUDERDALE Page 44 AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 27, 2009 9:00 AM

- 2. NEW CENTRAL A/C WAS INSTALLED WITH DUCT WORK AND AN ELECTRICAL HEATER.
- 3. INTERIOR REMODELLING WORK IN KITCHEN AND BATHROOM AREA.

#### FBC 105.2.11

THE MECHANICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO: 1. CENTRAL A/C WAS INSTALLED WITH DUCT WORK AND AN ELECTRICAL HEATER.

#### FBC 105.2.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO: 1. KITCHEN AND BATHROOM FIXTURES HAVE BEEN REPLACED.

FBC 105.2.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. ELECTRICAL LOAD DEMAND WAS INCREASED BY REPLACING OR ADDING ADDITIONAL LIGHTS AND WALL OUTLETS THAT HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED AMPERAGE LOADING THROUGH THE PERMITTING PROCESS.
- 2. POWER SUPPLIED TO THE A/C WITH A ELECTRIC HEATER.

FBC 109.6

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS THROUGH THE PERMITTING AND INSPECTION PROCESS.

\_\_\_\_\_

#### AGENDA

#### CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL

# OCTOBER 27, 2009

#### 9:00 AM

- CASE NO: CE08060101
- CASE ADDR: 1210 NW 1 AV
- OWNER: CRUZ, JOSE 1/2 INT
- CRUZ, MARIA
- INSPECTOR: GEORGE OLIVA

#### VIOLATIONS: FBC 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

- 1. THE PROPERTY WINDOWS WERE REPLACED, AND THE FRONT DOOR TOO.
- 2. LAUNDRY AREA, AND WATER HEATER ON THE BACK OF THE PROPERTY WITHOUT ANY COVER OR PROTECTION FROM THE ELEMENTS FOR THE ELECTRICAL CONNECTIONS.
- FBC 105.2.11

THE MECHANICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO: 1. A CENTRAL A/C WAS INSTALLED WITH ELECTRICAL HEATERS AND DUCT WORK.

FBC 105.2.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO: 1. WATER LINES FOR THE ELECTRIC WATER HEATER AND

WASHER MACHINES.

FBC 105.2.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. ELECTRICAL LOAD DEMAND WAS INCREASED BY ADDING A CENTRAL A/C WITH ELECTRIC HEATERS THAT HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED AMPERAGE LOADING THROUGH THE PERMITTING PROCESS.

#### FBC 109.6

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS THROUGH THE PERMITTING AND INSPECTION PROCESS.

# AMENDED CITY OF FORT LAUDERDALE Page 46 AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 27, 2009 9:00 AM

FBC 1612.1.2 ALL THE WINDOW, SHUTTER, AND DOOR INSTALLATIONS HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS.

FBC 1626.1 THE NEW WINDOWS AND DOOR WITH GLASS NEED TO BE IMPACT RESISTANT OR BE PROTECTED BY AN APPROVED HURRICANE PROTECTION SYSTEM.

CASE NO:	CE08072176
CASE ADDR:	1221 NE 1 AV
OWNER:	PAWLIK, WALTRAUD
INSPECTOR:	GERRY SMILEN

VIOLATIONS: FBC(2007) 105.1 AN OPEN CARPORT HAS BEEN ENCLOSED ON THE SINGLE FAMILY DWELLING WITHOUT OBTAINING THE REQUIRED PERMITS.

FBC(2007) 105.4.17
AN OVERHEAD GARAGE DOOR HAS BEEN INSTALLED IN AN
ILLEGALLY ENCLOSED CARPORT WITHOUT A PERMIT.

\_\_\_\_\_

CASE NO:	CE08021649
CASE ADDR:	900 NE 18 AV # 706
OWNER:	FIERMONTE, MICHAEL &
	MORTON, ELLETT D
INSPECTOR:	GERRY SMILEN

VIOLATIONS: FBC 105.1 THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS, INCLUDING BUT NOT LIMITED TO: 1. BATHROOMS WERE REMODELED.

- 2. THE KITCHEN WAS REMODELED.
- 3. THE INTERIOR FLOOR PLAN LAYOUT WAS ALTERED. THE KITCHEN WAS OPENED TO THE LIVING AREA.

# AMENDED CITY OF FORT LAUDERDALE Page 47 AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 27, 2009 9:00 AM

FBC 105.2.4

RELOCATION.

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS, INCLUDING BUT NOT LIMITED TO: 1. BATH AND KITCHEN FIXTURES WERE REPLACED. 2. A JACUZZI TUB WAS INSTALLED. FBC 105.2.5 THE ELECTRICAL SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS, INCLUDING BUT NOT LIMITED TO: 1. ELECTRICAL CIRCUITS WERE MOVED, ALTERED AND ADDED IN THE KITCHEN AND BATHROOMS. 2. AN ELECTRICAL CIRCUIT WAS ADDED FOR A JACUZZI TUB. \_\_\_\_\_ CASE NO: CE08121112 CASE ADDR: 410 SW 7 ST OWNER: DONALDSON, STEWART INSPECTOR: GERRY SMILEN VIOLATIONS: FBC(2007) 105.4.10 A NEW FLAT ROOF HAS BEEN INSTALLED WITHOUT A PERMIT. \_\_\_\_\_ CASE NO: CE09011033 CASE ADDR: 1001 SW 4 ST OWNER: FRANCAVILLA, JOHN INSPECTOR: GERRY SMILEN VIOLATIONS: FBC(2007) 105.10.3.1 THE PERMITS ON THE BUILDINGS THAT WERE TRANSPORTED TO THE PROPERTY HAVE EXPIRED. FBC(2007) 105.4.1 THE WOOD FRAME SINGLE FAMILY HOMES HAVE BEEN SIGNIFICANTLY ALTERED WITH ATTEMPTS AT REPAIR AND

FBC(2007) 105.4.2
THE BUILDINGS HAVE BEEN RELOCATED WITH AN EXPIRED
PERMIT.

# AMENDED CITY OF FORT LAUDERDALE Page 48 AGENDA CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 27, 2009 9:00 AM

FBC(2007) 105.4.5 THE ELECTRICAL SYSTEMS OF THE BUILDINGS HAVE BEEN DISCONNECTED AND ALTERED WITHOUT A VALID PERMIT.

CASE NO: CE09031279 CASE ADDR: 721 SW 8 TER OWNER: G 4 A HOLDINGS CORP INSPECTOR: GERRY SMILEN VIOLATIONS: FBC(2007) 105.10.3.5 THE TWO STORY DUPLEX REMAINS INCOMPLETE WITH THE FOLLOWING PERMITS THAT HAVE EXPIRED: 1. 07052447.

- 2. 07052514.
- 3. 07052515.
- 4. 07052517.
- 5. 07052518.
- FBC(2007) 3306.4
  THE PROPERTY IS NOT SUFFICIENTLY PROTECTED FROM
  PEDESTRIAN TRAFFIC AND POSES A LIFE SAFETY ISSUE.