FORT LAUDERDALE

CODE ENFORCEMENT BOARD HEARING AGENDA

OCTOBER 25, 2011 9:00 AM

CITY COMMISSION MEETING ROOM - CITY HALL 100 N ANDREWS AVENUE FT. LAUDERDALE, FL 33301

CODE ENFORCEMENT BOARD

Code of Ordinances: Sec. 11-3.

PURPOSE: Hear and decide cases in which violations are alleged of any provision of the Florida Building Code, Broward County Amendments and violations of the Code of Ordinances of the City of Fort Lauderdale when alleged together with a violation of the Florida Building Code.

Note: If any person decides to appeal any decision made with respect to any matter considered at this public meeting or hearing he/she will need a record of the proceedings and for such purpose, he/she may need to ensure that a verbatim record of the proceedings is made, which record includes the testimony and evidence upon which the appeal is to be based.

Board Members: Jan Sheppard, Chair • Howard Nelson, Vice Chair • Genia Ellis

- Joan Hinton Howard Elfman Chad Thilborger Paul Dooley
- Joshua Miron (alternate) P J Espinal (alternate) Robert Smith (alternate)
- Board Attorney: Bruce Jolly

TWO OR MORE FORT LAUDERDALE CITY COMMISSIONERS OR MEMBERS OF A CITY OF FORT LAUDERDALE ADVISORY BOARD MAY BE IN ATTENDANCE AT THIS MEETING.

COMMUNICATION TO THE CITY COMMISSION WILL BE ADDRESSED AT THE END OF THE HEARING.

CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 25, 2011 - 9:00 AM

HEARING BUSINESS

CASE NO: CE05110587 CASE ADDR: 2710 SW 12 TER PONSARD, JONATHAN OWNER: INSPECTOR: JORG HRUSCHKA

VIOLATIONS: FBC 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED BUILDING PERMITS:

- 1. THE CARPORT WAS ENCLOSED.
- 2. THE KITCHEN WAS REMODELED.
- 3. A FENCE WAS INSTALLED. PERMIT 98090702 DID NOT PASS FINAL INSPECTIONS.

FBC 105.2.5

ELECTRICAL CIRCUITS WERE ADDED TO THE CARPORT AREA WITHOUT FIRST OBTAINING A PERMIT. THE KITCHEN CIRCUITRY WAS ALTERED. OUTLETS WERE MOVED AND ADDED.

FBC(2007) 105.10.3.1

1. FENCE PERMIT 98090702 DID NOT PASS FINAL INSPCTIONS.

FBC(2007) 1604.1

- 1. THE FRAMED WALL SECTIONS, INCLUDING WINDOWS AND DOORS, HAVE NOT BEEN DEMONSTRATED TO BE ABLE TO WITHSTAND WIND LOAD REQUIREMENTS THROUGH THE PERMIT AND INSPECTION PROCESS.
- 2. THE BUILDING MATERIALS USED DO NOT COMPLY WITH THE FBC.

CASE NO: CE11051192 CASE ADDR: 2227 SW 5 ST OWNER: BURCE, MELISSA INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

1. A WOOD DECK WITH A ROOF WAS BUILT AT THE REAR OF THE DWELLING.

CITY OF FORT LAUDERDALE Page CODE ENFORCEMENT BOARD AGENDA CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 25, 2011 - 9:00 AM

FBC(2007) 1604.1

THE STRUCTURES FOR THE WOOD DECK AND THE ROOF
COVER DO NOT MEET THE STANDARD FOR GRAVITY LOADING
AND HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE
REQUIRED WIND LOADING THROUGH THE PERMITTING
PROCESS. ALL THE STRUCTURES THAT WERE DONE
ILLEGALLY ARE DEEMED TO BE UNSAFE AND THE
CONSTRUCTION IS UNDERDESIGNED. THEY WOULD NOT
PROVIDE THE REQUIRED RESISTANCE TO UPLIFT. THE
CODE PROTECTS NEIGHBORS FROM FLYING DEBRIS IN A
STORM, WHICH THIS STRUCTURE MAY BECOME. THEY MUST
BE REMOVED.

._____

CASE NO: CE10042353 CASE ADDR: 1760 SW 25 AV

OWNER: PETERSON, CYNTHIA L H/E

FORMAN, JENNIFER PEARLIN

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

1. A 10X10 STORAGE SHED WAS INSTALLED AT THE SOUTH SIDE OF THE LOT.

FBC(2007) 1604.1

THE STRUCTURES FOR THE STORAGE SHED DO NOT MEET THE STANDARD FOR GRAVITY LOADING AND HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS. ALL THE STRUCTURES THAT WERE DONE ILLEGALLY ARE DEEMED TO BE UNSAFE AND THE CONSTRUCTION IS UNDERDESIGNED. THEY WOULD NOT PROVIDE THE REQUIRED RESISTANCE TO UPLIFT. THE CODE PROTECTS NEIGHBORS FROM FLYING DEBRIS IN A STORM, WHICH THIS STRUCTURE MAY BECOME. THEY MUST BE REMOVED.

CITY COMMISSION MEETING ROOM - CITY HALL

OCTOBER 25, 2011 - 9:00 AM

CASE NO: CE10100487 CASE ADDR: 845 NW 13 AVE US BANK NA TRSTEE OWNER:

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC 105.1

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE

FOLLOWING MANNER:

1. THE SEWER LINE COMING FROM THE PROPERTY WAS HOOKED UP TO THE CITY SEWER LINES. PLUMBING INSPECTOR J. J. SLOANE ISSUED A STOP WORK ORDER ON 6/2/10 FOR INSTALLATION OF A SEWER LINE WITHOUT A PERMIT. SO FAR THERE IS NO EFFORT FROM THE OWNERS TO CORRECT THE VIOLATION.

CASE NO: CE11010418 CASE ADDR: 1340 NW 45 ST OWNER: COPILAH, LEONORA INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR

INSPECTIONS:

1. FLORIDA ROOM WINDOWS FACING SOUTH WERE REPLACED.

FBC(2007) 1612.1.2

ALL THE NEW WINDOW INSTALLATIONS HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS.

CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 25, 2011 - 9:00 AM

CASE NO: CE11020851 CASE ADDR: 2300 NW 15 CT

OWNER: WELLS FARGO BANK NA TRSTEE

% GLADSTONE LAW GROUP PA

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR

INSPECTIONS:

1. THE WINDOWS WERE REPLACED. SOME OPENINGS WERE ENCLOSED TO FIT THE NEW WINDOWS WITHOUT A

PERMIT AT THE DWELLING.

FBC(2007) 1612.1.2

ALL THE WINDOWS INSTALLATIONS HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS.

FBC(2007) 1626.1

THE NEW WINDOWS WITH GLASS NEED TO BE IMPACT

RESISTANT OR BE PROTECTED BY AN APPROVED HURRICANE

PROTECTION SYSTEM.

CASE NO: CE11030105 CASE ADDR: 3680 SW 12 PL

OWNER: PNMAC MORTGAGE OPPORTUNITY FUND

INVESTORS LLC

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

- 1. CARPORT AND FRONT PORCH WERE ENCLOSED INTO LIVING SPACE. PART OF THE CARPORT WAS TURNED INTO A RENTAL APARTMENT.
- 2. THE MAIN ENTRANCE TO THE PROPERTY WAS MOVED FROM ITS ORIGINAL LOCATION TO THE FRONT OF THE ENCLOSED PORCH.
- 3. SOME OF THE WINDOWS WERE REPLACED ON THE PROPERTY.
- 4. ENTRANCE DOORS WERE REPLACED ON THE BACK AND WEST SIDE OF THE PROPERTY.

CITY OF FORT LAUDERDALE P
CODE ENFORCEMENT BOARD AGENDA
CITY COMMISSION MEETING ROOM - CITY HALL
OCTOBER 25, 2011 - 9:00 AM

- 5 THERE ARE TWO SHEDS THAT WERE BUILT ON THE PROPERTY; ONE ON THE WEST SIDE AND THE OTHER ON THE SOUTH SIDE.
- 6. A CENTRAL A/C WITH DUCTS AND HEATER WAS INSTALLED.
- 7. MECHANICAL VENTILATIONS FOR THE BATHROOMS AND EXTRA KITCHEN AREAS.
- 8. PLUMBING ALTERATIONS FOR THE NEW KITCHEN AND BATHROOMS WITH NEW FIXTURES.
- 9. THE ELECTRICAL LOAD HAS BEEN CHANGED BY ADDING A CENTRAL A/C WITH A 7.5 KW HEATER AND ADDITIONAL ELECTRICAL CIRCUITS WERE CREATED INSIDE THE ILLEGAL APARTMENTS.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. THE PLUMBING ALTERATIONS WERE DONE TO BUILD THE NEW BATHROOMS AND KITCHEN AREAS WITH DRAINAGE PIPES AND HOT AND COLD WATER SUPPLY LINES TO THE NEW FIXTURES.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. THE ELECTRICAL OUTLETS, SWITCHES AND LAMPS THAT WERE INSTALLED IN THE NEW RENTAL APARTMENT MUST MEET THE NEC 210 REQUIREMENTS.
- 2. THE POWER SUPPLY TO THE CENTRAL A/C WITH THE ELECTRICAL 7.5 KW HEATER AND THE ADDITIONAL COOKING AREAS HAS INCREASED THE ELECTRICAL LOAD OVER THE APPROVED LOAD DEMAND.

FBC(2007) 105.4.11

THE MECHANICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. A CENTRAL A/C WITH DUCT WORK AND ELECTRIC HEATER WAS INSTALLED.
- 2. THE MECHANICAL VENTILATION FOR THE BATHROOMS AND KITCHEN AREAS WAS CREATED.

CITY OF FORT LAUDERDALE Page CODE ENFORCEMENT BOARD AGENDA CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 25, 2011 - 9:00 AM

FBC(2007) 110.1.1

THE USE AND THE OCCUPANCY OF THE BUILDING HAS CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION RS-8 TO MULTI-FAMILY WITHOUT OBTAINING THE REQUIRED CERTIFICATE OF OCCUPANCY.

FBC(2007) 1604.1

THE STRUCTURES FOR THE CARPORT EXTENSION AND THE ENCLOSED FRONT PORCH DO NOT MEET THE STANDARD FOR GRAVITY LOADING AND HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS. ALL THE STRUCTURES THAT WERE DONE ILLEGALLY ARE DEEMED TO BE UNSAFE AND THE CONSTRUCTION IS UNDERDESIGNED. THEY WOULD NOT PROVIDE THE REQUIRED RESISTANCE TO UPLIFT. THE CODE PROTECTS NEIGHBORS FROM FLYING DEBRIS IN A STORM, WHICH THIS STRUCTURE MAY BECOME. THEY MUST BE REMOVED.

FBC(2007) 1612.1.2

ALL THE NEW WINDOWS AND DOOR INSTALLATIONS HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS.

FBC(2007) 1626.1

THE NEW WINDOWS WITH GLASS NEED TO BE IMPACT RESISTANT OR BE PROTECTED BY AN APPROVED HURRICANE PROTECTION SYSTEM.

CASE NO: CE11051850 CASE ADDR: 2471 NW 16 ST

BEARD, MELVIN C III & OWNER:

BEARD, UNDREA

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMIT OR INSPECTIONS.

- 1. THE GARAGE HAS BEEN CONVERTED INTO LIVING SPACE WITHOUT A PERMIT.
- 2. THE WATER HEATER HAS BEEN REPLACED WITHOUT A PERMIT (MFG. DATE 3/11).
- 3. THE A/C CONDENSING UNIT HAS BEEN REPLACED WITHOUT A PERMIT.

FBC(2007) 105.10.3.1

THERE IS ONE BUILDING PERMIT #06043445 FOR THE GARAGE DOOR REPLACEMENT, WHICH FAILED FINAL INSPECTIONS NOV. 5, 2007 AND WAS LEFT TO EXPIRE.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO: 1. THE ELECTRIC WATER HEATER HAS BEEN REPLACED.

FBC(2007) 105.4.11

THE MECHANICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. THE CENTRAL A/C CONDENSING UNIT HAS BEEN REPLACED.

FBC(2007) 110.1.1

THE USE AND THE OCCUPANCY OF THE BUILDING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF A SINGLE FAMILY DWELLING WITH A GARAGE, BY CONVERTING THE GARAGE INTO LIVING SPACE WITHOUT OBTAINING THE REQUIRED CERTIFICATE OF OCCUPANCY AND PERMITS.

CASE NO: CE11060179
CASE ADDR: 3134 SW 14 ST

OWNER: MK ASSOCIATES LLC

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

- 1. INTERIOR RENOVATIONS ARE IN PROGRESS.
- 2. BATHROOMS AND KITCHEN WERE UPGRADED WITH NEW CABINETS AND FIXTURES.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. PLUMBING ALTERATIONS WERE DONE TO REMODEL THE BATHROOMS AND KITCHEN AREAS WITH DRAINAGE PIPES AND HOT AND COOL WATER SUPPLY LINES TO THE NEW FIXTURES.

CITY OF FORT LAUDERDALE Pag
CODE ENFORCEMENT BOARD AGENDA
CITY COMMISSION MEETING ROOM - CITY HALL
OCTOBER 25, 2011 - 9:00 AM

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. THE ELECTRICAL OUTLETS, SWITCHES AND LAMPS WERE REMOVED AND ARE BEING REPLACED THROUGHOUT THE DWELLING. THE ONES INSIDE THE KITCHEN AND BATHROOMS MUST MEET THE NEC 210.8 REQUIREMENTS.

FBC(2007) 109.10

THE WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS THROUGH THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE10051428 CASE ADDR: 3013 SE 5 ST

OWNER: STEELE OCEANSIDE PROPERTY INC

% SOPHIA ENTERPRISES INC

INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC(2007) 105.1

THE COMMERCIAL STORE SPACE HAS BEEN ALTERED WITH A DOORWAY CUT OUT IN THE TENANT SEPARATION WALL WITHOUT OBTAINING THE REQUIRED PERMITS.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED WITH THE INSTALLATION OF A SINK WITHOUT OBTAINING THE REQUIRED PERMITS.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED WITH THE ADDITION OF ELECTRICAL WIRING FOR LIGHTING, GENERAL PREMISE WIRING AND CONNECTIONS FOR NEW A/C EQUIPMENT WITHOUT OBTAINING THE REQUIRED PERMITS.

FBC(2007) 105.4.7

SIGNAGE FOR THE TATTOO PARLOR HAS BEEN INSTALLED WITHOUT A PERMIT.

FBC(2007) 105.4.11

NEW A/C EQUIPMENT AND DUCT WORK HAVE BEEN INSTALLED WITHOUT A PERMIT.

CITY COMMISSION MEETING ROOM - CITY HALL

OCTOBER 25, 2011 - 9:00 AM

CASE NO: CE11051528 CASE ADDR: 221 SE 12 AVE

OWNER: LAS OLAS YACHT CLUB LLC

INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC(2007) 105.4.18

A WOOD FENCE INSTALLATION HAS COMMENCED WITHOUT

OBTAINING THE REQUIRED PERMITS.

CASE NO: CE10101072

CASE ADDR: 1401 SEABREEZE BLVD KANE, BRADLEY & OWNER:

ENGEN, MARIA

INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC(2007) 105.1

THE SINGLE FAMILY RESIDENCE HAS BEEN ALTERED WITH THE INSTALLATION OF A PAVER DRIVEWAY WITHOUT A

PERMIT.

FBC(2007) 105.4.5

ELECTRIC MOTORS WERE INSTALLED ON THE FRONT GATE

WITHOUT A PERMIT.

FBC(2007) 105.4.18

A ROLLING GATE WAS INSTALLED ON THE FRONT OF THE

PROPERTY WITHOUT A PERMIT.

CASE NO: CE11052398

CASE ADDR: 711 W BROWARD BLVD RONALD CUTLER TR OWNER:

CUTLER, RONALD TRSTEE % A RAVITCH

INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC(2007) 105.1

THE COMMERCIAL BUILDING HAS BEEN ALTERED WITH AN OPENING CUT THROUGH THE MASONRY TENANT SEPARATION

WALL WITHOUT A PERMIT.

FBC(2007) 1604.1

THE DOOR OPENING CUT IN THE LOAD BEARING MASONRY WALL HAS NOT BEEN DEMONSTRATED TO WITHSTAND ALL LOADS BEARING ON THE WALL THROUGH THE PERMITTING

AND INSPECTION PROCESS.

CODE ENFORCEMENT BOARD AGENDA

CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 25, 2011 - 9:00 AM

CASE NO: CE11020582
CASE ADDR: 1615 NE 3 CT
OWNER: HUNTER, SUSANA
INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC(2007) 105.1

THE SINGLE FAMILY DWELLING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. NEW WINDOWS ARE INSTALLED.
- 2. NEW DOORS ARE INSTALLED.
- 3. A CARPORT IS ENCLOSED AND CONVERTED INTO AN EFFICIENCY UNIT.
- 4. THE FRONT OF THE PROPERTY HAS BEEN COVERED IN ASPHALT.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED WITHOUT A PERMIT BY ADDING A BATHROOM TO THE ENCLOSED CARPORT.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PREMISE WIRING WAS ADDED FOR THE ENCLOSED CARPORT.
- 2. A POST LIGHT HAS BEEN INSTALLED.
- 3. EXTERIOR OUTLETS HAVE BEEN INSTALLED.

FBC(2007) 105.4.8

AWNINGS HAVE BEEN INSTALLED ON THE BUILDING WITHOUT OBTAINING THE REQUIRED PERMITS.

FBC(2007) 105.4.18

A WOOD FENCE HAS BEEN INSTALLED ON THE PROPERTY WITHOUT A PERMIT.

FBC(2007) 109.10

THE CARPORT STRUCTURE HAS BEEN ENCLOSED AND ALL OF THE WORK HAS BEEN COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS THROUGH THE PERMITTING AND INSPECTION PROCESS.

CODE ENFORCEMENT BOARD AGENDA CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 25, 2011 - 9:00 AM

CITY OF FORT LAUDERDALE

FBC(2007) 110.1.1

THE USE AND OCCUPANCY OF THE SINGLE FAMILY RESIDENCE HAS CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION WITHOUT

OBTAINING THE REQUIRED CERTIFICATE OF OCCUPANCY.

CASE NO: CE11032747

CASE ADDR: 1525 SE 15 ST # 22

OWNER: ROSSE, ANNIE INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC(2007) 105.4.11

A WALL A/C UNIT HAS BEEN INSTALLED IN AN EXTERIOR WALL OF AN APARTMENT COMPLEX WITHOUT OBTAINING THE

REOUIRED PERMIT.

CASE NO: CE11041400 CASE ADDR: 205 NE 14 AVE OWNER: SECOR, DIANE INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC(2007) 105.1

THE TWO STORY DUPLEX HAS BEEN ALTERED WITH THE REPAIR OF TERMITE DAMAGED FLOOR JOISTS THAT

SEPARATE TWO RESIDENTIAL UNITS WITHOUT OBTAINING A

PERMIT.

FBC(2007) 1604.1

THE FLOOR JOIST REPAIR THAT SEPARATES TWO

INDIVIDUAL FAMILY UNITS HAVE NOT BEEN PROVEN TO WITHSTAND REQUIRED LIVE AND DEAD LOADS THROUGH THE

PERMITTING AND INSPECTION PROCESS.

CASE NO: CE11041536

CASE ADDR: 2109 S MIAMI RD DAVIES, HEATHER OWNER: INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC(2007) 105.4.11

WALL A/C UNITS HAVE BEEN INSTALLED IN THE MULTI-FAMILY SINGLE STORY BUILDING WITHOUT

PERMITS.

CITY COMMISSION MEETING ROOM - CITY HALL

OCTOBER 25, 2011 - 9:00 AM

CASE NO: CE11041539

CASE ADDR: 2113 S MIAMI RD

OWNER: DAVIES' ANCHORAGE LLC

INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC(2007) 105.4.11

WALL A/C UNITS HAVE BEEN INSTALLED WITHOUT PERMITS

ON THE MULTI-FAMILY SINGLE STORY BUILDING.

CASE NO: CE11050309 CASE ADDR: 1026 NW 7 AV OWNER: NAIDU, SANJEEVAI INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC(2007) 105.1

A PORCH HAS BEEN ENCLOSED IN THE REAR OF THE SINGLE FAMILY DWELLING WITHOUT OBTAINING THE

REOUIRED PERMITS.

FBC(2007) 1604.1

THE WALLS FOR THE PORCH ENCLOSURE DO NOT MEET THE STANDARD FOR GRAVITY LOADING AND HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS.

CASE NO: CE10070297

CASE ADDR: 3038 N FEDERAL HWY # E

OWNER: 3038 PARTNERS LLC

INSPECTOR: BURT FORD

VIOLATIONS: FBC 105.1

DURING A BUSINESS TAX INSPECTION ON 6/22/10, I FOUND INTERIOR PARTITIONS HAD BEEN INSTALLED IN THIS SPACE. A NEW CIRCUIT BREAKER PANEL HAS BEEN INSTALLED AND THE OLD PANEL TURNED INTO A J BOX WITH NO COVER AND WIRES EXPOSED IN THE AIR HANDLER CLOSET. I WAS NOT ABLE TO FIND PERMITS FOR THIS

WORK IN PERMIT RECORDS. THE AIR HANDLER WAS

RELOCATED TO THIS CLOSET AND INSTALLED IN SUCH A

MANNER THAT IT CANNOT BE SERVICED.

CODE ENFORCEMENT BOARD AGENDA

CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 25, 2011 - 9:00 AM

CASE NO: CE10080162

CASE ADDR: 1330 SE 4 AVE # H
OWNER: KERR-DOVE, CLAUDETTE

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REOUIRED PERMITS:

- 1. CABINETS AND COUNTERTOPS HAVE BEEN INSTALLED IN THE RECEPTION AREA.
- 2. CABINETS AND COUNTERTOPS HAVE BEEN INSTALLED IN THE LUNCH AREA.
- 3. CABINETS HAVE BEEN INSTALLED IN EACH OF THE PATIENT EXAMINATION ROOMS.
- 4. MISCELLANOUS DRYWALL REPAIR HAS BEEN COMPLETED.
- 5. A ROOM HAS BEEN BUILT TO HOUSE THE PHARMACY AREA.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. PIPING AND FIXTURES HAVE BEEN INSTALLED IN ALL AREAS WHERE NEW CABINETS HAVE BEEN INSTALLED.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

- 1. MISCELLANEOUS OUTLETS, SWITCHES, AND FIXTURES WERE REPLACED.
- 2. CIRCUITS INSTALLED AT ALL CABINET AREA INSTALLATIONS.
- 3. AN ALARM SYSTEM HAS BEEN INSTALLED.
- 4. A CLOSED CIRCUIT TELEVISION SYSTEM HAS BEEN INSTALLED WITH CIRCUITS TO POWER THE EQUIPMENT.

FBC(2007) 105.4.11

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. A NEW A/C AIR HANDLER, CONDENSING UNIT, AND PLENUM HAVE BEEN INSTALLED.

CITY OF FORT LAUDERDALE CODE ENFORCEMENT BOARD AGENDA CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 25, 2011 - 9:00 AM

FBC(2007) 109.10

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

THE AIR CONDITIONING CONDENSING UNIT HAS NOT BEEN PROVEN TO SUFFICIENTLY WITHSTAND ESTIMATED OR ACTUAL IMPOSED DEAD, LIVE, WIND, OR ANY OTHER LOADS THROUGH THE PERMIT AND INSPECTION PROCESS.

CASE NO: CE10091199 CASE ADDR: 844 NW 10 TER OWNER: MAKHOUL, GEORGE

INSPECTOR: BURT FORD

VIOLATIONS: 9-313(a)

THERE IS NO ADDRESS OR BAY IDENTIFICATION ON THE BUILDING.

FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS: 1. AN INTERIOR OFFICE OR ROOM HAS BEEN BUILT INSIDE THE STORAGE BAY.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. MISC ELECTRICAL FIXTURES AND OUTLETS HAVE BEEN ADDED.

FBC(2007) 105.4.11

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. A WALL A/C UNIT HAS BEEN INSTALLED IN THE OFFICE INSIDE THE STORAGE BAY.

FBC(2007) 1612.1.2

THE WALL AIR CONDITIONING UNITS HAVE NOT BEEN PROVEN TO SUFFICIENTLY WITHSTAND ESTIMATED OR ACTUAL IMPOSED DEAD, LIVE, WIND, OR ANY OTHER LOADS THROUGH THE PERMIT AND INSPECTION PROCESS.

CODE ENFORCEMENT BOARD AGENDA

CITY COMMISSION MEETING ROOM - CITY HALL

OCTOBER 25, 2011 - 9:00 AM

CASE NO: CE11031086 CASE ADDR: 725 N BIRCH RD

OWNER: BLUE DOLPHIN VILLAS LLC

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

1. REPLACED A WOOD FENCE, PERMIT 94006787, WITH A MASONARY WALL IN THE FRONT OF THE BUILDING AND ALONG THE NORTH SIDE.

FBC(2007) 109.10

WORK WAS PERFORMED AND/OR COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

THE MASONARY WALL HAS NOT BEEN PROVEN TO SUFFICIENTLY WITHSTAND ESTIMATED OR ACTUAL IMPOSED DEAD, LIVE, WIND, OR ANY OTHER LOADS THROUGH THE PERMIT AND INSPECTION PROCESS.

CASE NO: CE11031983
CASE ADDR: 2741 NE 25 PL
OWNER: AVERY, MICHAEL R

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

1. A SHED HAS BEEN INSTALLED ON THE EAST SIDE OF THE PROPERTY.

FBC(2007) 1612.1.2

THE SHED HAS NOT BEEN PROVEN TO SUFFICIENTLY WITHSTAND ESTIMATED OR ACTUAL IMPOSED DEAD, LIVE, WIND, OR ANY OTHER LOADS THROUGH THE PERMIT AND INSPECTION PROCESS.

CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 25, 2011 - 9:00 AM

CASE NO: CE11041294
CASE ADDR: 3216 NE 42 CT
OWNER: TESOLIN, BRUNO &

AULENSI, JERI LYNN

INSPECTOR: BURT FORD

VIOLATIONS: 9-280(b)

1. SOME OF THE WINDOWS ARE LEAKING.

2. THE PAVERS ALONG THE DOCK AREA AND THE STEPS FROM THE POOL TO THE DOCK ARE SINKING. THEY ARE UNEVEN AND POSE A TRIPPING HAZARD.

9-308(a)

THE ROOF TILE ON THE WEST AND SOUTH FACES ARE SLIDING. MANY OF THE TILES ARE BROKEN OR MISSING.

FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. THE GARAGE HAS BEEN CONVERTED INTO A BEDROOM.
 INTERIOR WALLS HAVE BEEN FRAMED AND DRYWALL
 INSTALLED AND FINISHED. A WOODEN BASE, TO RAISE
 THE FLOOR ABOVE THE CONCRETE GARAGE SLAB, HAS
 BEEN INSTALLED.
- 2. THE FLORIDA ROOM HAS BEEN CONVERTED INTO LIVING SPACE. DOORS AND WINDOWS HAVE BEEN INSTALLED. THE ORIGINAL EXTERIOR WINDOWS AND DOORS HAVE BEEN REMOVED.
- 3. A BOAT LIFT HAS BEEN INSTALLED ON THE DOCK.
- 4. THE KITCHEN HAS BEEN REMODELED. NEW CABINETS, COUNTERTOPS AND APPLIANCES HAVE BEEN INSTALLED.
- 5. ALL OF THE BATHROOMS HAVE BEEN REMODELED.

 VANITY CABINETS AND TOPS HAVE BEEN INSTALLED.

 DRYWALL OR CONCRETE BOARDS HAVE BEEN INSTALLED
 IN THE SHOWERS AND TILED.
- 6. CABINETS AND COUNTERTOPS HAVE BEEN INSTALLED TO CREATE A BAR AREA.
- 7. THE ROOF ON THE SOUTH SIDE HAS BEEN REPAIRED, TRUSSES AND SHEETING.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. PIPING AND FIXTURES HAVE BEEN ADDED/REPLACED DURING THE KITCHEN REMODELING.

CITY OF FORT LAUDERDALE CODE ENFORCEMENT BOARD AGENDA CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 25, 2011 - 9:00 AM

- 2. PIPING AND FIXTURES HAVE BEEN ADDED/REPLACED DURING THE BATHROOM REMODELINGS.
- 3. THE WATER HEATER HAS BEEN CHANGED OUT.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

- 1. CIRCUITS HAVE BEEN ADDED/ALTERED DURING THE KITCHEN REMODELING.
- 2. CIRCUITS HAVE BEEN ADDED/ALTERED DURING THE BATHROOM REMODELINGS.
- 3. CIRCUITS HAVE BEEN ADDED/ALTERED DURING THE CONVERSION OF THE GARAGE TO A BEDROOM, LIGHTING, OUTLETS, SWITCHES.
- 4. CIRCUITS HAVE BEEN ADDED/ALTERED DURING THE CONVERSION OF THE FLORIDA ROOM TO LIVING SPACE, LIGHTING, OUTLETS, SWITCHES, ETC.
- 5. CIRCUITS HAVE BEEN ADDED TO POWER THE BOATLIFT.
- 6. CIRCUITS HAVE BEEN ADDED/ALTERED FOR THE BAR AREA AND FOR THE GENERAL LIGHTING ABOVE.
- 7. MISC RECESSED LIGHTING, OUTLETS AND SWITCHES HAVE BEEN INSTALLED THROUGHOUT THE HOUSE.

FBC(2007) 105.4.11

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

- 1. THE AIR HANDLER AND CONDENSING UNIT HAVE BEEN REPLACED.
- 2. A/C DUCT HAS BEEN INSTALLED IN THE CONVERTED BEDROOM FROM A NON-AIR CONDITIONED GARAGE.
- 3. THE FLORIDA ROOM CONVERTED TO LIVING SPACE HAS INCREASED THE AIR CONDITIONED SQUARE FOOTAGE OF THE BUILDING.

FBC(2007) 109.10

WORK WAS PERFORMED AND/OR COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

THE AIR CONDENSING UNIT, THE BOAT LIFT, THE TRUSS AND ROOF REPAIRS, INSTALLED WINDOWS AND DOORS HAVE NOT BEEN PROVEN TO SUFFICIENTLY WITHSTAND ESTIMATED OR ACTUAL IMPOSED DEAD, LIVE, WIND, OR ANY OTHER LOADS THROUGH THE PERMIT AND INSPECTION PROCESS.

CODE ENFORCEMENT BOARD AGENDA

CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 25, 2011 - 9:00 AM

CASE NO: CE11052218
CASE ADDR: 2730 NE 30 PL
OWNER: PETRUCCI, PETER D

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. AN ALUMINUM AWNING HAS BEEN INSTALLED AT THE FRONT ENTRANCE OF THE MIDDLE APARTMENT.
- 2. A WOOD HOMEBUILT SHUTTER HAS BEEN INSTALLED ON THE BACK EXTERIOR SLIDING GLASS DOOR ON THE WEST APARTMENT, 2726.
- 3. THE KITCHEN IS BEING REMODELED IN UNIT 2730.
- 4. A KITCHENETTE HAS BEEN INSTALLED IN UNIT 2730 IN THE BACK BEDROOM.
- 5. DRYWALL REPAIR IS BEING DONE IN UNIT 2730.
- 6. A WOOD FENCE HAS BEEN INSTALLED.
- 7. EXTERIOR DOORS HAVE BEEN INSTALLED IN THE LAUNDRY IN THE BACK OF THE PROPERTY AND IN THE BACK ROOM OF UNIT 2730.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

- 1. PLUMBING HAS BEEN INSTALLED IN THE BACK ROOM OF UNIT 2730 TO SUPPLY THE WASHER.
- 2. WASTE PIPE HAS BEEN INSTALLED AND IS RUNNING ALONG THE BASEBOARD.
- 3. A GAS WATER HEATER HAS BEEN INSTALLED AND HAS A SERIAL NUMBER FOR BEING MANUFACTURED IN 2002.
- 4. PLUMBING HAS BEEN INSTALLED TO SUPPLY THE LAUNDRY THAT IS LOCATED IN THE SAME ROOM AS THE WATER HEATER IN THE BACK OF THE BUILDING.
- 5. PIPING AND FIXTURES ARE BEING ADDED/REPLACED DURING THE KITCHEN REMODELING IN UNIT 2730.
- 6. PIPING AND FIXTURES WERE INSTALLED IN THE KITCHENETTE INSTALLED IN THE BACK BEDROOM OF UNIT 2730.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. CIRCUITS ARE BEING ADDED/ALTERED DURING THE KITCHEN REMODELING IN UNIT 2730.

Page 19

CODE ENFORCEMENT BOARD AGENDA

CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 25, 2011 - 9:00 AM

- 2. THERE IS MISC ROMEX RUNNING THROUGHOUT UNIT 2730.
- 3. CIRCUITS WERE ADDED TO POWER THE WASHER AND DRYER IN UNIT 2730.

FBC(2007) 109.10

WORK WAS PERFORMED AND/OR COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 708.1 1.

THERE IS AN INTERIOR HOLLOW CORE DOOR THAT SEPARATES UNIT 2730 AND THE MIDDLE APARTMENT, 2728, LOCATED IN THE KITCHEN OF UNIT 2730.

CASE NO: CASE ADDR: 5360 NW 35 AVE

CE11081874

OWNER: FRANK M RUFF REV TR

ANITA RUFF REV TR

INSPECTOR: RON TETREAULT

VIOLATIONS: FSS 633.082

THE FIRE CONTROL SYSTEMS, FIRE HYDRANTS, YARD HYDRANTS, AND FIRE PROTECTION SYSTEMS HAVE/HAS NOT BEEN INSPECTED IN ACCORDANCE WITH THE CODE.

NFPA 1:11.1.2 (Covers)

THERE IS A COVER MISSING ON AN ELECTRICAL BOX CAUSING ELECTRICAL WIRING TO BE EXPOSED.

NFPA 1:13.3.1.1 (SERVICE)

THE FIRE SPRINKLER SYSTEMS IS IN NEED OF SERVICE.

NFPA 101:7.2.1.5.2

LOCKS PROVIDED IN THE MEANS OF EGRESS REQUIRE A KEY, TOOL OR SPECIAL KNOWLEDGE OR EFFORT FOR OPERATION FROM THE EGRESS SIDE.

NFPA 101:7.9.2.1

THE EMERGENCY LIGHT DOES NOT ILLUMINATE AS DESIGNED.

NFPA 1962:4.3.2

OCCUPANT-USE HOSE HAVE NOT BEEN INSPECTED IN ACCORDANCE WITH NFPA 1962 SECTION 4.6.

CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 25, 2011 - 9:00 AM

NFPA 1:1.12.1

WORK REQUIRES A PERMIT.

NFPA 1:14.4.1

THE PATH OF EGRESS IS OBSTRUCTED/BLOCKED.

CASE NO: CE11091330

CASE ADDR: 229 S FT LAUD BEACH BLVD

OWNER: EL-AD FL BEACH LLC

INSPECTOR: RON TETREAULT

VIOLATIONS: FSS 633.082

THE FIRE CONTROL SYSTEMS, FIRE HYDRANTS, YARD HYDRANTS, AND FIRE PROTECTION SYSTEMS HAVE/HAS NOT

BEEN INSPECTED IN ACCORDANCE WITH THE CODE.

NFPA 25:12.7.1

THE FIRE DEPARTMENT CONNECTION (FDC)

CAP(S)/PLUG(S) IS(ARE) MISSING.

CASE NO: CE11091331

CASE ADDR: 3220 BAYVIEW DR # 102

PIER 41 CONDOMINIUM ASSN INC OWNER:

% ROYAL PROPERTY MGMT GROUP INC

INSPECTOR: RON TETREAULT

VIOLATIONS: FSS 633.082

THE FIRE CONTROL SYSTEMS, FIRE HYDRANTS, YARD HYDRANTS, AND FIRE PROTECTION SYSTEMS HAVE/HAS NOT

BEEN INSPECTED IN ACCORDANCE WITH THE CODE.

NFPA 101:31.3.6.2.1

DOORS THAT OPEN ONTO EXIT ACCESS CORRIDORS, OTHER THAN THOSE COMPLYING WITH 8.3.4 OR IN BUILDINGS MEETING 31.3.6.2.2, SHALL HAVE NOT LESS THAN A 20-MINUTE FIRE PROTECTION RATING IN ACCORDANCE WITH

SECTION 8.3.

CODE ENFORCEMENT BOARD AGENDA

CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 25, 2011 - 9:00 AM

RETURN HEARING (OLD BUSINESS)

CASE NO: CE04061463
CASE ADDR: 3081 HARBOR DR
OWNER: RAJ HOTELS LLC
INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC(2007) 105.1

1. THE PARKING LOT HAS BEEN RESURFACED AND RESTRIPED WITHOUT A PERMIT.

2. THE DESIGNATED HANDICAPPED SPACE DOES NOT CONFORM TO THE REQUIREMENTS OF CHAPTER 11 OF THE FLORIDA BUILDING CODE.

FBC(2007) 105.4.7

A REQUIRED HANDICAP PARKING SIGN HAS BEEN REMOVED.

FBC(2007) 11-4.6.4

THE HANDICAP SIGN HAS BEEN REMOVED FROM THE DESIGNATED HANDICAPPED PARKING SPACE ALLOWING COMMON PARKING TO OCCUR.

CASE NO: CE11011965
CASE ADDR: 1729 SW 14 ST
OWNER: YAKOV HOLDING INC

INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC(2007) 105.1

THE SINGLE FAMILY DWELLING HAS BEEN ALTERED IN THE FOLLOWING WAY WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. THE HOUSE HAS BEEN LATHED AND STUCCOED.
- 2. A NEW FRONT DOOR HAS BEEN INSTALLED.
- 3. NEW WINDOWS HAVE BEEN INSTALLED.
- 4. A REAR PORCH HAS BEEN ENCLOSED.

Page 22

CITY OF FORT LAUDERDALE CODE ENFORCEMENT BOARD AGENDA

CITY COMMISSION MEETING ROOM - CITY HALL

OCTOBER 25, 2011 - 9:00 AM

CASE NO: CE08101015

CASE ADDR: 1522 DAVIE BLVD

OWNER: WASHINGTON MUTUAL BANK

INSPECTOR: GERRY SMILEN

VIOLATIONS: 18-27(a)

THERE IS PLANT OVERGROWTH, RUBBISH, TRASH, AND

DEBRIS ON THE

PROPERTY.

47-34.1.A.1.

THE SINGLE FAMILY HOME WAS CONVERTED INTO A DUPLEX, WHICH IS A PROHIBITED LAND USE IN THIS RS

8 ZONING DISTRICT.

9-280(b)

BUILDING IS NOT STRUCTURALLY SOUND AND MAINTAINED IN A SECURE AND ATTRACTIVE MANNER. THE ROOF SURFACES SHALL BE WATERTIGHT.

9-280(d)

THE EXTERIOR WALLS ARE SUBJECT TO DETERIORATION AND ARE NOT PROTECTED FROM THE ELEMENTS. PAINT IS PEELING, CRACKING AND FADING. CAULKING IS MISSING. STRUCTURAL CRACKS ALLOW WATER PENETRATION.

9-280(h)

THE FENCE IS IN DISREPAIR.

FBC 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. NEW WINDOWS WERE INSTALLED.
- 2. THE CARPORT WAS ENCLOSED, AND CONVERTED INTO AN APARTMENT.
- 3. A SECOND KITCHEN WAS INSTALLED IN THE CARPORT CONVERSION.
- 4. THE PORCH WAS ENCLOSED.
- 5. EXTERIOR DOORS WERE INSTALLED/REPLACED.
- 6. BATHROOMS WERE ADDED IN THE MAIN HOUSE & CARPORT.
- 7. INTERIOR WALLS WERE CONSTRUCTED TO CREATE A BEDROOM AND A BATHROOM.
- 8. THE FENCE WAS PARTIALLY DAMAGED AND REPLACED.
- 9. THE WINDOW ON THE SW CORNER WAS COVERED.
- 10. A LOAD BEARING WALL WAS PARTIALLY REMOVED BETWEEN THE HALLWAY AND THE LIVING ROOM.

CITY OF FORT LAUDERDALE CODE ENFORCEMENT BOARD AGENDA CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 25, 2011 - 9:00 AM

FBC 105.2.11

THE MECHANICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER,

INCLUDING BUT NOT LIMITED TO:

- 1. WALL AND WINDOW UNITS WERE INSTALLED.
- 2. A CENTRAL A/C UNIT WAS INSTALLED.

FBC 105.2.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. BATHROOM SINKS AND TOILETS WERE REPLACED.
- 2. GENERAL ALTERATIONS TO THE PLUMBING SYSTEMS.

FBC 105.2.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. EXTERIOR AND INTERIOR OUTLETS WERE MOVED AND/OR ADDED.
- 2. CIRCUITS FOR CARPORT AREA WERE ADDED.
- 3. SERVICE WAS UPGRADED TO 200 AMPS.
- 4. GENERAL PREMISE WIRING WAS ALTERED.
- 5. A CIRCUIT TO POWER THE CENTRAL A/C UNIT WAS ADDED.
- 6. THE ELECTRICAL LOADS IMPOSED ON THE CIRCUITS INCLUDING BUT NOT LIMITED TO THE PORCH, BEDROOM, LIVING ROOM AND CARPORT, EXCEEDS THE CAPACITY OF THE EXISTING CIRCUITRY.

FBC 109.6

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REOUIRED APPROVALS THROUGH THE PERMITTING AND INSPECTION PROCESS.

FBC 1604.1

THE ENCLOSURES WERE NOT CONSTRUCTED IN ACCORDANCE WITH STRENGTH REQUIREMENTS FOR THE LOADS IMPOSED.

CODE ENFORCEMENT BOARD AGENDA

CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 25, 2011 - 9:00 AM

CASE NO: CE10111974 CASE ADDR: 410 SE 14 CT

OWNER: VACA, MARIA ELENA

INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC(2007) 105.1

THE FOLLOWING WORK HAS BEEN COMPLETED ON THE SINGLE FAMILY DWELLING WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. A LARGE WOOD ANIMAL CAGE HAS BEEN INSTALLED IN THE BACKYARD.
- 2. THE FRONT PORCH HAS BEEN PARTIALLY ENCLOSED.
- 3. STRUCTURAL MEMBERS OF THE FRONT PORCH HAVE BEEN REPLACED.
- 4. FRONT PORCH ROOF HAS BEEN REPLACED WITH UNAPPROVED MATERIALS.
- 5. CEILINGS HAVE BEEN REPLACED WITH UNAPPROVED MATERIALS.
- 6. EXTERIOR DOORS HAVE BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. A NEW WATER HEATER HAS BEEN INSTALLED.
- 2. WASTE LINES FOR THE WASHING MACHINE HAVE BEEN INSTALLED.
- 3. WATER SUPPLY LINES HAVE BEEN INSTALLED FOR THE WASHING MACHINE.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. A HOT WATER HEATER HAS A NEW ELECTRICAL CONNECTION.
- 2. PREMISE WIRING WITH OUTLETS HAS BEEN INSTALLED.

FBC(2007) 105.4.11

THE FOLLOWING MECHANICAL WORK REQUIRES A PERMIT AND APPROVALS FROM THE PLAN REVIEW PROCESS:

1. HOOD FAN HAS BEEN REMOVED FROM THE KITCHEN LEAVING A CRUMPLED ALUMINUM DUCT EXPOSED IN THE KITCHEN.

CITY OF FORT LAUDERDALE CODE ENFORCEMENT BOARD AGENDA CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 25, 2011 - 9:00 AM

FBC(2007) 109.10

THE FOLLOWING WORK HAS BEEN COMPLETED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS THROUGH THE PERMITTING AND INSPECTION PROCESS:

- 1. CEILINGS HAVE BEEN REPLACED.
- 2. THE FRONT PORCH ROOF STRUCTURE AND ROOFING.
- 3. THE FRONT PORCH WALLS.

4. EXTERIOR DOOR REPLACEMENTS.

CASE NO: CE10120909

CASE ADDR: 1631 N ANDREWS SQ OWNER: PERKINS, DEBRA J INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC(2007) 105.1

THE FOLLOWING WORK HAS BEEN COMPLETED WITHOUT

OBTAINING THE REQUIRED PERMITS:

1. A KITCHEN HAS BEEN ADDED.

2. AN EFFICIENCY UNIT HAS BEEN PROVIDED.

FBC(2007) 105.4.4

PLUMBING FOR A KITCHEN IN THE EFFICIENCY UNIT HAS BEEN INSTALLED WITHOUT A PERMIT.

FBC(2007) 110.1.1

THE USE AND OCCUPANCY OF THE SINGLE FAMILY DWELLING HAS CHANGED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 708.3

1 HOUR FIRE RATED TENANT SEPARATION WALLS HAVE NOT BEEN PROVEN THROUGH THE PERMIT AND INSPECTION PROCESS.

CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 25, 2011 - 9:00 AM

CASE NO: CE10122048

CASE ADDR: 924 W LAS OLAS BLVD BRIGHT ASSETS LLC OWNER:

INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC(2007) 105.1

THE FOLLOWING WORK HAS BEEN PERFORMED ON THE FOUR UNIT MULTI-FAMILY BUILDING WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. NEW KITCHENS HAVE BEEN INSTALLED.
- 2. BATHROOMS HAVE BEEN REMODELED.
- 3. EXTERIOR STAIRWAYS AND LANDINGS HAVE BEEN CONSTRUCTED.
- 4. EXTERIOR OVERHANGS HAVE BEEN INSTALLED.
- 5. NEW WINDOWS HAVE BEEN INSTALLED.
- 6. NEW EXTERIOR DOORS HAVE BEEN INSTALLED.
- 7. AREAS OF THE BUILDING HAVE BEEN RESTUCCOED.
- 8. A SHED HAS BEEN PLACED IN THE REAR OF THE PROPERTY.
- 9. DRYWALL HAS BEEN REPLACED ON EXTERIOR WALLS.
- 10. SUPPORT COLUMNS HAVE BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. BATHROOM FIXTURES HAVE BEEN REPLACED.
- 2. WATER HEATERS HAVE BEEN INSTALLED.
- 3. KITCHENS HAVE BEEN REPLACED.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PREMISE WIRING.
- 2. ELECTRICAL CONNECTIONS FOR WATER HEATERS.
- 3. 220 VOLT OUTLETS FOR KITCHEN RANGES.
- 4. GFI OUTLETS FOR KITCHENS AND BATHROOMS.

FBC-P 502.1

THE INSTALLATIONS OF THE WATER HEATERS DOES NOT MEET THE REQUIREMENTS OF THE FLORIDA BUILDING CODE.

CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 25, 2011 - 9:00 AM

FBC(2007) 1009.3

THE STAIR TREADS AND RISERS ON THE EXTERIOR STAIRWAY DO NOT MEET THE REQUIREMENTS OF THE FLORIDA BUILDING CODE.

FBC(2007) 1009.10

THE HANDRAILS ON THE EXTERIOR STAIRWAY DO NOT CONFORM WITH THE FLORIDA BUILDING CODE.

CASE NO: CE11032316 CASE ADDR: 307 SW 11 AVE

OWNER: COMMUNITY 8 PROPERTIES LLC

INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC(2007) 105.1

THE MULTI-FAMILY BUILDING HAS BEEN ALTERED IN THE FOLLOWING WAY WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. NEW EXTERIOR DOORS HAVE BEEN INSTALLED.
- 2. A WOOD SHED HAS BEEN ERECTED IN THE REAR OF THE PROPERTY.
- 3. A NEW VANITY HAS BEEN INSTALLED.

FBC(2007) 105.4.4

THE FOLLOWING PLUMBING WORK HAS BEEN COMPLETED WITHOUT A PERMIT:

- 1. PLUMBING FOR A NEW VANITY SINK.
- 2. WASTE LINES HAVE BEEN INSTALLED IN THE SHED.
- 3. A NEW COMMODE HAS BEEN INSTALLED.

FBC(2007) 105.4.5

ELECTRICAL OUTLETS AND POWER HAVE BEEN PROVIDED IN THE SHED WITHOUT A PERMIT.

CASE NO: CE11032908

CASE ADDR: 845 N FT LAUD BEACH BLVD 845 NORTH ATLANTIC BLVD LLC OWNER:

INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC(2007) 105.4.5

THE INTERIOR ELECTRICAL PANEL IN THE COMMERCIAL BUILDING HAS BEEN REPLACED WITHOUT A PERMIT.

CITY COMMISSION MEETING ROOM - CITY HALL

OCTOBER 25, 2011 - 9:00 AM

CASE NO: CE11041498 CASE ADDR: 1609 NW 8 AVE

SPENCE, JERMAINE & ANGELA OWNER:

INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC(2007) 105.1

THE FOLLOWING WORK HAS BEEN COMPLETED WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. A PORCH OVERHANG, DECK AND WALLS WERE ADDED TO THE REAR OF THE BUILDING.
- 2. NEW WINDOWS WERE INSTALLED.
- 3. THE LIVING ROOM ON THE NORTH SIDE OF THE DUPLEX WAS CONVERTED TO A ROOM.
- 4. THE SEPARATION WALL OF THE DUPLEX WAS OPENED
- 5. THE KITCHEN ON THE NORTH SIDE WAS REMOVED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED WITH THE REMOVAL OF THE NORTH SIDE KITCHEN.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED WITH THE CONVERSION OF THE KITCHEN TO AN OFFICE AND THE LIVING ROOM TO A BEDROOM.

FBC(2007) 109.10

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS THROUGH THE PERMITTING AND INSPECTION PROCESS.

FBC(2007) 110.1.1

THE USE AND OCCUPANCY OF THE DUPLEX HAS CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION WITHOUT OBTAINING THE REQUIRED CERTIFICATE OF OCCUPANCY.

FBC 708.3

THE FIRE SEPARATION WALL BETWEEN RESIDENTIAL UNITS HAS BEEN COMPROMISED WITH A DOUBLE DOOR WIDTH OPENING CUT OUT OF THE WALL.

CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 25, 2011 - 9:00 AM

CASE NO: CE09011970 CASE ADDR: 1133 SW 5 PL OWNER: ACREE, BARBARA INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC(2007) 105.4.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT PERMITS INCLUDING BUT NOT LIMITED TO:

- 1. A CARPORT HAS BEEN ENCLOSED.
- 2. NEW DOORS HAVE BEEN INSTALLED.
- 3. NEW WINDOWS HAVE BEEN INSTALLED.

FBC(2007) 105.4.4

PLUMBING FOR A BATHROOM AND KITCHEN HAS BEEN COMPLETED WITHOUT A PERMIT.

FBC(2007) 105.4.5

ELECTRICAL PREMISE WIRING WAS COMPLETED WITHOUT OBTAINING A PERMIT.

FBC(2007) 1612.1.2

THE WINDOW AIR CONDITIONING UNITS HAVE NOT BEEN PROVEN TO SUFFICIENTLY WITHSTAND ESTIMATED OR ACTUAL IMPOSED DEAD, LIVE, WIND, OR ANY OTHER LOADS THROUGH THE PERMIT AND INSPECTION PROCESS.

CASE NO: CE11012060

CASE ADDR: 2554 TORTUGAS LN OWNER: HICKMAN, WILLIAM INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

THE FOLLOWING WORK WAS DONE WITHOUT OBTAINING THE PROPER PERMITS OR INSPECTIONS:

- 1. TWO NEW CENTRAL A/C'S WERE INSTALLED OVER THE LAST 6 MONTHS.
- 2. A WOOD FENCE WAS INSTALLED FACING THE SOUTH.
- 3. SOME OF THE WINDOWS WERE REPLACED AND TWO SETS OF DOUBLE GLASS DOORS, FRENCH STYLE, WERE INSTALLED FACING EAST.
- 4. THE BLACKTOP DRIVEWAY WAS REPLACED WITH PAVERS IN 2004.
- 5. THERE IS A WOOD SHED FACING THE NORTH SIDE BUILD OUT OF 2X4 AND PLYWOOD AND IS SITTING OVER THE SETBACK OF THE PROPERTY.

CITY OF FORT LAUDERDALE PACTOR CODE ENFORCEMENT BOARD AGENDA
CITY COMMISSION MEETING ROOM - CITY HALL
OCTOBER 25, 2011 - 9:00 AM

FBC(2007) 105.4.11

THE MECHANICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. THERE ARE TWO NEW CENTRAL A/C'S THAT WERE INSTALLED OVER THE LAST 6 MONTHS.

FBC(2007) 109.10

THE WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS THROUGH THE PERMITTING AND INSPECTION PROCESS.

FBC(2007) 1604.1

THE STRUCTURES FOR THE SHED BEING BUILT AND THE WOOD FENCE DO NOT MEET THE STANDARD FOR GRAVITY LOADING AND HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS. ALL THE STRUCTURES THAT WERE DONE ILLEGALLY ARE DEEMED TO BE UNSAFE AND THE CONSTRUCTION IS UNDERDESIGNED. THEY WOULD NOT PROVIDE THE REQUIRED RESISTANCE TO UPLIFT WHICH THE CODE PROTECTS ITS NEIGHBORS FROM FLYING DEBRIS IN A STORM AND WHICH THESE STRUCTURES MAY BECOME. THEY MUST BE REMOVED.

FBC(2007) 1612.1.2

ALL THE WINDOWS AND DOOR INSTALLATIONS HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS.

FBC(2007) 1626.1

THE NEW WINDOWS AND DOORS WITH GLASS NEED TO BE IMPACT RESISTANT OR BE PROTECTED BY AN APPROVED HURRICANE PROTECTION SYSTEM.

CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 25, 2011 - 9:00 AM

CASE NO: CE11060149

CASE ADDR: 3310 AUBURN BLVD OWNER: A & A SOUTH FLORIDA

INVESTMENT LLC

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

A STOP WORK ORDER WAS ISSUED FOR:

- 1. THE ROOF WAS REPLACED FROM CEMENT TILE TO SHINGLES.
- 2. THE KITCHEN AND BATHROOMS ARE BEING UPGRADED WITH NEW CABINETS AND FIXTURES.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. PLUMBING ALTERATIONS WERE DONE TO REMODEL THE BATHROOM AND KITCHEN AREAS WITH DRAINAGE PIPES AND HOT AND COLD WATER SUPPLY LINES TO THE NEW FIXTURES.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. JULY 1,2011 I DID A SITE INSPECTION AND FOUND THE ELECTRIC METER WAS JUMPED WITH TWO WIRES BY WORKERS DOING WORK INSIDE THE PROPERTY AFTER MY STOP WORK ORDER WAS ISSUED ON JUNE 2, 2011. A REQUEST TO DISCONNECT THE POWER FROM THE POLE WAS GIVEN TO FPL. THIS IS A VIOLATION OF FBC(2007)111.3 ENERGIZING SYSTEMS: It shall be unlawful for any person, firm or corporation to energize any wiring system or portion thereof until the electrical work has been inspected and approved, and the responsible person, firm or corporation is authorized by the appropriate governmental jurisdiction to energize the system.

CITY OF FORT LAUDERDALE

CODE ENFORCEMENT BOARD AGENDA

CITY COMMISSION MEETING ROOM - CITY HALL

OCTOBER 25, 2011 - 9:00 AM

2. THE ELECTRICAL OUTLETS, SWITCHES AND LAMPS WERE REMOVED AND ARE BEING REPLACED THROUGHOUT THE DWELLING. THEY MUST MEET THE NEC 210.8 REQUIREMENTS INSIDE THE KITCHEN AND BATHROOM.

FBC(2007) 109.10

THE WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS THROUGH THE PERMITTING AND INSPECTION PROCESS.

FBC(2007) 1604.1

THE STRUCTURE OF THE ROOF DOES NOT MEET THE STANDARD FOR GRAVITY LOADING AND HAS NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS. ALL THE STRUCTURES THAT WERE DONE ILLEGALLY ARE DEEMED TO BE UNSAFE AND THE CONSTRUCTION IS UNDERDESIGNED. THEY WOULD NOT PROVIDE THE REQUIRED RESISTANCE TO UPLIFT.

CASE NO: CE11020641

CASE ADDR: 2741 DAVIE BLVD

OWNER:

M R MCTIGUE PARTNERS L L C

% EAST KELLOGG PLAZA ASSOCIATES

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

1. STOP WORK ORDER WAS ISSUED TO RADIO SHACK FOR REPLACING THE METAL EXTERIOR DOOR FACING THE EAST WITHOUT OBTAINING THE PROPER PERMITS.

CITY COMMISSION MEETING ROOM - CITY HALL

OCTOBER 25, 2011 - 9:00 AM

CASE NO: CE09071049

CASE ADDR: 666 W CAMPUS CIR RBA CAPITAL LP OWNER:

% BRUCE R JACOBS PA

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

- 1. THE WINDOWS AND DOORS ON THE DWELLING WERE REPLACED WITH AN APPLIED PERMIT FROM 2008.
- 2. THE ELECTRICAL WAS UPGRADED WITH A VOID PERMIT FROM 2007.
- 3. A CENTRAL A/C WAS INSTALLED WITH A VOID PERMIT FROM 2007.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. THE ELECTRICAL PANEL WAS UPGRADED IN 2007 WITH A VOID PERMIT.
- 2. A CENTRAL A/C WITH A 7.5 ELECTRIC HEATER WAS INSTALLED IN 2007 ALSO WITH A VOID PERMIT.

FBC(2007) 105.4.11

THE MECHANICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. A CENTRAL A/C WAS INSTALLED WITH DUCT WORK AND AN ELECTRIC HEATER.

FBC(2007) 109.10

THE WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS THROUGH THE PERMITTING AND INSPECTION PROCESS.

FBC(2007) 1612.1.2

ALL THE WINDOWS AND DOOR INSTALLATIONS HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS.

FBC(2007) 1626.1

THE NEW WINDOWS AND DOOR WITH GLASS NEED TO BE IMPACT RESISTANT OR BE PROTECTED BY AN APPROVED HURRICANE PROTECTION SYSTEM.

CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 25, 2011 - 9:00 AM

CASE NO: CE11011144 CASE ADDR: 1821 SW 23 TER

OWNER: GLOBAL DIRECT MANAGEMENT LLC

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

STOP WORK ORDER WAS ISSUED FOR

- 1. THE KITCHEN AND BATHROOMS ARE BEING REMODELED.
- 2. THE OUTSIDE DOORS AND WINDOWS ARE BEING REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. PLUMBING FIXTURES IN THE KITCHEN AND BATHROOMS WERE REPLACED.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. THE ELECTRICAL OUTLETS IN THE KITCHEN ARE BEING REPLACED.
- 2. LIGHT FIXTURES WERE REPLACED.
- 3. THE 220V POWER SUPPLIED TO THE CENTRAL A/C.

FBC(2007) 105.4.11

THE MECHANICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. THERE IS A CENTRAL A/C FROM APRIL 2000 WITH DUCT WORK VENTILATION FOR THE KITCHEN HOOD AND BATHROOMS.

FBC(2007) 1612.1.2

ALL THE WINDOWS AND DOOR INSTALLATIONS HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS.

CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 25, 2011 - 9:00 AM

CASE NO: CE06030553 CASE ADDR: 3901 SW 16 ST

OWNER: 3901 DAVIE ASSOCIATES LLC

INSPECTOR: GEORGE OLIVA

VIOLATIONS: 47-19.4.D.1.

BULK CONTAINER PLACEMENT AND ENCLOSURE IS NOT

PROVIDED.

47-20.20.H.

THE PARKING LOT IS IN DISREPAIR. IT HAS POTHOLES.

47-21.9.G.1.

A LANDSCAPE PLAN IS REQUIRED TO BE ON FILE WITH THE CITY OF FORT LAUDERDALE. THIS PLAN MUST DEMONSTRATE COMPLIANCE WITH THE 50% RETROACTIVE REQUIREMENT FOR LANDSCAPING. THIS LANDSCAPE PLAN IS NOT ON FILE WITH THE CITY OF FORT LAUDERDALE. THE PROPERTY DOES NOT HAVE THE REQUIRED

RETROACTIVE LANDSCAPING.

47-21.9.G.2.

A LANDSCAPE PLAN IS REQUIRED TO BE ON FILE WITH THE CITY OF FORT LAUDERDALE. THIS PLAN MUST DEMONSTRATE COMPLIANCE WITH THE 50% RETROACTIVE REQUIREMENT FOR LANDSCAPING. THIS LANDSCAPE PLAN IS NOT ON FILE WITH THE CITY OF FORT LAUDERDALE. THE PROPERTY DOES NOT HAVE THE REQUIRED RETROACTIVE LANDSCAPING.

47-22.9.

OUTSIDE SIGN INSTALLED WITHOUT A PERMIT.

9-280(b)

THE WALLS ARE IN DISREPAIR AND HAVE HOLES, INCLUDING BUT NOT LIMITED TO THE REAR OF THE BUILDING.

9-280(g)

THERE ARE EXPOSED WIRES AND MISSING LIGHTS.

9-281(b)

THERE ARE TRASH, RUBBISH AND DEBRIS ON THE PROPERTY.

CITY OF FORT LAUDERDALE FOR CODE ENFORCEMENT BOARD AGENDA
CITY COMMISSION MEETING ROOM - CITY HALL
OCTOBER 25, 2011 - 9:00 AM

9-305

THIS BUILDING IS NOT MAINTAINED IN A SECURE AND ATTRACTIVE MANNER.

- 1. SAGGING AND DETERIORATED OVERHANG SECTIONS ARE NOT STRUCTURALLY SOUND.
- 2. A ROLL UP SHUTTER AT 3911 IS NOT ATTACHED TO THE WALL PROPERLY AND IS LEANING PRECARIOUSLY.
- 3. WALLS IN THE REAR ARE MISSING PAINT.
- 4. THERE ARE HOLES IN THE WALL.
- 5. THE BOTTOM OF A DOOR WAS COVERED WITH CONCRETE, BLOCKING EGRESS FROM THE BUILDING.

9-306

THIS BUILDING IS NOT MAINTAINED IN A SECURE AND ATTRACTIVE MANNER.

- 1. SAGGING AND DETERIORATED OVERHANG SECTIONS ARE NOT STRUCTURALLY SOUND.
- 2. A ROLL UP SHUTTER AT 3911 IS NOT ATTACHED TO THE WALL PROPERLY AND IS LEANING PRECARIOUSLY.
- 3. WALLS IN THE REAR ARE MISSING PAINT.
- 4. THERE ARE HOLES IN THE WALL.
- 5. THE BOTTOM OF A DOOR WAS COVERED WITH CONCRETE, BLOCKING EGRESS FROM THE BUILDING.

9-308(a)

THE ROOF IS NOT MAINTAINED IN A SAFE, CLEAN AND WATERTIGHT CONDITION.

FBC 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. STRUCTURAL REPAIRS WERE DONE TO OVERHANG SECTION AT UNIT 3903.
- 2. A SLIDING DOOR WAS REMOVED AND REPLACED WITH A WALL AT UNIT 3901.
- 3. THE PARKING LOT WAS RE-STRIPED (PERMIT APPLICATION 04090544 WAS SUBMITTED, BUT WAS NEVER ISSUED).
- 4. WINDOW OPENINGS WERE BLOCKED OFF.
- 5. EXTERIOR STEEL DOORS WERE REPLACED.
- 6. SEVERAL APPROXIMATELY 3X3 ENTRY AREA PADS WERE POURED AT REAR OF THE BUILDING, ESPECIALLY UNITS 3913-3927.

CITY OF FORT LAUDERDALE PORT CODE ENFORCEMENT BOARD AGENDA
CITY COMMISSION MEETING ROOM - CITY HALL
OCTOBER 25, 2011 - 9:00 AM

- 7. THE BARBERSHOP AT 3912 AND UNIT 3919 WERE FIRE-DAMAGED IN 2000 AND WERE REBUILT.
- 8. THE BOTTOM OF THE REAR EXIT DOOR OF UNIT 3911 HAS BEEN COVERED WITH CONCRETE AND CANNOT BE OPENED FROM THE INSIDE. THIS DEPRIVES THE TENANT OF A SECONDARY MEANS OF EGRESS IN CASE OF FIRE.

FBC 105.2.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO: PERMIT 06062347 WAS ISSUED, BUT NEVER CLOSED OUT.

FBC 105.2.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO: EXTERIOR AND INTERIOR OUTLETS, INCLUDING BUT NOT LIMITED TO UNITS 3913-3921

FBC 105.2.11

THE MECHANICAL SYSTEMS OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO: CENTRAL A/C UNITS AND OTHER MECHANICAL SYSTEMS HAVE BEEN INSTALLED, RELOCATED AND OR REPLACED IN MULTIPLE UNITS.

FBC 109.6

WORK WAS DONE AND COVERED UP WITHOUT HAVING PASSED THE REQUIRED INSPECTIONS.

FBC 1522.2

ROOF TOP MOUNTED EQUIPMENT AND SUPPORT IS NOT SECURED TO THE STRUCTURE IN COMPLIANCE WITH THE LOAD REQUIREMENTS FOR HIGH VELOCITY HURRICANE ZONES.

FBC 1604.1

THE REPAIR OF THE ROOF OVERHANG IS NOT DESIGNED AND CONSTRUCTED ACCORDING TO THE STRENGTH REQUIREMENTS FOR THE LOADS IMPOSED.

THE WALL INSTALLATION AT 3901 IS NOT DESIGNED AND CONSTRUCTED ACCORDING TO THE STRENGTH REQUIREMENTS FOR THE LOADS IMPOSED.

CITY OF FORT LAUDERDALE CODE ENFORCEMENT BOARD AGENDA CITY COMMISSION MEETING ROOM - CITY HALL

OCTOBER 25, 2011 - 9:00 AM

CASE NO:

CE10062044

CASE ADDR:

3913 SW 16 ST

OWNER:

ZARTOLAS, ADA H &

ZARTOLAS, GEORGE

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

- 1. THE STORE SPACE WAS CONVERTED INTO A TAKE-OUT RESTAURANT.
- 2. RESTAURANT EQUIPMENT THAT WAS INSTALLED INCLUDED A HOOD, DEEP FRYER, COOLERS AND A THREE TANK COMMERCIAL SINK.
- 3. A PARTITION WAS BUILT TO SPLIT THE STOREROOM INTO TWO SPACES: ONE FOR THE COOKING AREA AND THE OTHER FOR A CUSTOMER AREA WITH A COUNTER TO PLACE THE TAKE-OUT ORDERS ON.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. PLUMBING ALTERATIONS WERE DONE TO INSTALL THE NEW THREE TANK SINK IN THE KITCHEN AREAS WITH DRAINAGE PIPES AND HOT AND COLD WATER SUPPLY LINES.
- 2. A GREASE TRAP MUST BE PROVIDED AND FLOOR DRAINS FOR CLEANING PURPOSES.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. THE ELECTRICAL OUTLETS, SWITCHES AND LAMPS THAT WERE REMOVED OR RELOCATED TO BUILD THE TAKE-OUT RESTAURANT MUST MEET THE NEC AND THE FBC 2007 REQUIREMENTS.

FBC(2007) 105.4.11

THE MECHANICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. A COMMERCIAL HOOD, GAS STOVE AND REFRIGERATION EQUIPMENT INSIDE THE COOKING AREA.

CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 25, 2011 - 9:00 AM

CASE NO: CE07080634

CASE ADDR: 430 ARIZONA AVE

OWNER: GRANT, CLAUDETTE B H/E

GRANT, DONALD

INSPECTOR: BURT FORD

VIOLATIONS: FBC 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. NEW WINDOWS HAVE BEEN INSTALLED.
- 2. NEW DOORS HAVE BEEN INSTALLED.
- 3. STUCCO WORK IS BEING DONE.
- 4. THERE ARE REPAIRS BEING DONE TO THE SOFFIT.
- 5. THERE IS INTERIOR REMODELING BEING DONE.
- 6. THERE HAS BEEN BLOCK INSTALLED WHERE WALL A/C'S HAVE BEEN REMOVED.

FBC 105.2.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO: 1. PLUMBING FIXTURE HAVE BEEN REPLACED WHILE

PERFORMING INTERIOR REMODELING.

FBC 105.2.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. NEW ELECTRICAL WIRING IS BEING RUN ALONG THE SOFFIT AND INTO THE ROOF AREA.
- 2. A SERVICE UPGRADE HAS BEEN DONE.

FBC 105.2.11

THE MECHANICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO: 1. WALL AIR CONDITIONERS HAVE BEEN INSTALLED.

FBC 109.6

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC 1604.1

THE WINDOWS AND DOOR(S) HAVE NOT BEEN DEMONSTRATED TO BE ABLE TO WITHSTAND WIND LOAD REQUIREMENTS THROUGH THE PERMIT AND INSPECTION PROCESS.

CITY OF FORT LAUDERDALE CODE ENFORCEMENT BOARD AGENDA CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 25, 2011 - 9:00 AM

FBC 1626.1

THE NEW WINDOWS NEED TO BE IMPACT GLASS OR HAVE AN APPROVED METHOD OF HURRICANE PROTECTION.

CASE NO: CE09030895 CASE ADDR: 1369 SE 14 ST

OWNER: CHAMBERLAIN, KENT T

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. INSTALLED NEW WINDOWS AND DOORS.
- 2. INSTALLED DRIVEWAY PAVERS.
- 3. INSTALLED A WOODEN TRELLIS.
- 4. INSTALLED A WOODEN DECK.

FBC(2007) 105.10.3.1

THE FOLLOWING PERMIT HAS EXPIRED:

1. FENCE PERMIT, 01021208, WAS ISSUED 2/15/2001. IT FAILED BOTH THE ZONING FINAL INSPECTION AND THE BUILDING FINAL INSPECTION. A RE-INSPECTION WAS NOT SCHEDULED.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. EXTERIOR LIGHTING HAS BEEN INSTALLED AT TRELLIS AREA.

FBC(2007) 109.10

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

THE WINDOWS, DOORS, DECKS, AND TRELLIS HAVE NOT BEEN PROVEN TO SUFFICIENTLY WITHSTAND ESTIMATED OR ACTUAL IMPOSED DEAD, LIVE, WIND, OR ANY OTHER LOADS THROUGH THE PERMIT AND INSPECTION PROCESS.

FBC(2007) 1626.1

THE NEW WINDOWS AND NEW DOORS WITH GLASS NEED TO BE IMPACT RESISTANT OR BE PROTECTED BY AN APPROVED HURRICANE PROTECTION SYSTEM.

CITY COMMISSION MEETING ROOM - CITY HALL

OCTOBER 25, 2011 - 9:00 AM

CASE NO: CE09050642 CASE ADDR: 1301 NE 17 AVE

OWNER: DOMINICIS, MARIA LE

DOMINICIS, LUIS & DOMINICIS, D

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. NEW DOORS HAVE BEEN INSTALLED.
- 2. NEW WINDOWS HAVE BEEN INSTALLED.
- 3. THE KITCHEN IN THE MAIN HOUSE HAS BEEN REMODELED.
- 4. ALL BATHROOMS HAVE BEEN REMODELED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

- 1. WATER HEATERS HAVE BEEN INSTALLED.
- 2. PIPING AND FIXTURES HAVE BEEN REPLACED IN THE:
 - A. MAIN KITCHEN REMODEL.
 - B. ILLEGAL KITCHEN IN THE BACK BEDROOM.
 - C. ALL BATHROOMS THAT HAVE BEEN REMODELED.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

- 1. MAIN KITCHEN REMODEL.
- 2. ILLEGAL KITCHEN IN THE BACK BEDROOM.
- 3. ALL BATHROOMS THAT HAVE BEEN REMODELED.
- 4. TO POWER THE NEW A/C SYSTEMS.

FBC(2007) 105.4.11

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. TWO COMPLETE SYSTEMS HAVE BEEN INSTALLED.

FBC(2007) 109.10

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

Page 42

CITY OF FORT LAUDERDALE CODE ENFORCEMENT BOARD AGENDA

CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 25, 2011 - 9:00 AM

FBC(2007) 1626.1

THE NEW WINDOWS AND NEW DOORS WITH GLASS NEED TO BE IMPACT RESISTANT OR BE PROTECTED BY AN APPROVED HURRICANE PROTECTION SYSTEM.

CASE NO: CE09051511

CASE ADDR: 2516 N ATLANTIC BLVD OWNER: MAVROOKAS, PETER &

NOTTE-MAVROOKAS, KIM J

INSPECTOR: BURT FORD

VIOLATIONS: FBC 105.1

1. PERMIT APPLICATION 06031041 WAS SUBMITTED TO CHANGE THE SIZE OF WINDOW/DOOR OPENINGS FOR NEW WINDOWS/DOORS.

2. PERMIT APPLICATION 06031039 WAS SUBMITTED FOR WINDOW & DOOR REPLACEMENT.

3. THE WORK WAS DONE WITHOUT PERMITS BEING ISSUED.

CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 25, 2011 - 9:00 AM

CASE NO: CE10020688

CASE ADDR: 1400 NE 56 ST # 105

ISLES AT CORAL RIDGE DEVELOPMENT OWNER:

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REOUIRED PERMITS:

- 1. WOODEN FENCES HAVE BEEN INSTALLED.
- 2. THE DOCK HAS BEEN REBUILT.
- 3. EXTERIOR DOORS HAVE BEEN REPLACED.
- 4. THE POOL BATHROOMS HAVE BEEN REMODELED.
- 5. THE PARKING LOT HAS BEEN REPAVED AND RESTRIPED.
- 6. RAILINGS HAVE BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PIPING AND FIXTURES HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELINGS, INCLUDING THE BATHS LOCATED AT THE COMMUNITY POOT.
- 2. AN EXTERIOR SHOWER WAS INSTALLED/REPLACED ON THE WALL OF THE POOL BATHROOM BUILDING.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING ALL OF THE KITCHEN AND BATH REMODELINGS, INCLUDING THE POOL BATHS.
- 2. MISCELLANEOUS EXTERIOR LIGHTING HAS BEEN INSTALLED.

FBC(2007) 109.10

WORK WAS COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 25, 2011 - 9:00 AM

CASE NO: CE10020689

CASE ADDR: 1400 NE 56 ST # 106

ISLES AT CORAL RIDGE DEVELOPMENT OWNER:

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REOUIRED PERMITS:

- 1. WOODEN FENCES HAVE BEEN INSTALLED.
- 2. THE DOCK HAS BEEN REBUILT.
- 3. EXTERIOR DOORS HAVE BEEN REPLACED.
- 4. THE POOL BATHROOMS HAVE BEEN REMODELED.
- 5. THE PARKING LOT HAS BEEN REPAVED AND RESTRIPED.
- 6. RAILINGS HAVE BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PIPING AND FIXTURES HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELINGS, INCLUDING THE BATHS LOCATED AT THE COMMUNITY POOT.
- 2. AN EXTERIOR SHOWER WAS INSTALLED/REPLACED ON THE WALL OF THE POOL BATHROOM BUILDING.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING ALL OF THE KITCHEN AND BATH REMODELINGS, INCLUDING THE POOL BATHS.
- 2. MISCELLANEOUS EXTERIOR LIGHTING HAS BEEN INSTALLED.

FBC(2007) 109.10

WORK WAS COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 25, 2011 - 9:00 AM

CASE NO: CE10020690

CASE ADDR: 1400 NE 56 ST # 109

OWNER: ISLES AT CORAL RIDGE DEVELOPMENT

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. WOODEN FENCES HAVE BEEN INSTALLED.
- 2. THE DOCK HAS BEEN REBUILT.
- 3. EXTERIOR DOORS HAVE BEEN REPLACED.
- 4. THE POOL BATHROOMS HAVE BEEN REMODELED.
- 5. THE PARKING LOT HAS BEEN REPAVED AND RESTRIPED.
- 6. RAILINGS HAVE BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PIPING AND FIXTURES HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELINGS, INCLUDING THE BATHS LOCATED AT THE COMMUNITY POOL.
- 2. AN EXTERIOR SHOWER WAS INSTALLED/REPLACED ON THE WALL OF THE POOL BATHROOM BUILDING.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING ALL OF THE KITCHEN AND BATH REMODELINGS, INCLUDING THE POOL BATHS.
- 2. MISCELLANEOUS EXTERIOR LIGHTING HAS BEEN INSTALLED.

FBC(2007) 109.10

WORK WAS COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

CITY OF FORT LAUDERDALE CODE ENFORCEMENT BOARD AGENDA CITY COMMISSION MEETING ROOM - CITY HALL

OCTOBER 25, 2011 - 9:00 AM

CASE NO: CE10020691

CASE ADDR: 1400 NE 56 ST # 110

ISLES AT CORAL RIDGE DEVELOPMENT OWNER:

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REOUIRED PERMITS:

- 1. WOODEN FENCES HAVE BEEN INSTALLED.
- 2. THE DOCK HAS BEEN REBUILT.
- 3. EXTERIOR DOORS HAVE BEEN REPLACED.
- 4. THE POOL BATHROOMS HAVE BEEN REMODELED.
- 5. THE PARKING LOT HAS BEEN REPAVED AND RESTRIPED.
- 6. RAILINGS HAVE BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PIPING AND FIXTURES HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELINGS, INCLUDING THE BATHS LOCATED AT THE COMMUNITY POOT.
- 2. AN EXTERIOR SHOWER WAS INSTALLED/REPLACED ON THE WALL OF THE POOL BATHROOM BUILDING.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING ALL OF THE KITCHEN AND BATH REMODELINGS, INCLUDING THE POOL BATHS.
- 2. MISCELLANEOUS EXTERIOR LIGHTING HAS BEEN INSTALLED.

FBC(2007) 109.10

WORK WAS COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 25, 2011 - 9:00 AM

CASE NO: CE10020692

CASE ADDR: 1400 NE 56 ST # 111

ISLES AT CORAL RIDGE DEVELOPMENT OWNER:

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REOUIRED PERMITS:

- 1. WOODEN FENCES HAVE BEEN INSTALLED.
- 2. THE DOCK HAS BEEN REBUILT.
- 3. EXTERIOR DOORS HAVE BEEN REPLACED.
- 4. THE POOL BATHROOMS HAVE BEEN REMODELED.
- 5. THE PARKING LOT HAS BEEN REPAVED AND RESTRIPED.
- 6. RAILINGS HAVE BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PIPING AND FIXTURES HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELINGS, INCLUDING THE BATHS LOCATED AT THE COMMUNITY POOT.
- 2. AN EXTERIOR SHOWER WAS INSTALLED/REPLACED ON THE WALL OF THE POOL BATHROOM BUILDING.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING ALL OF THE KITCHEN AND BATH REMODELINGS, INCLUDING THE POOL BATHS.
- 2. MISCELLANEOUS EXTERIOR LIGHTING HAS BEEN INSTALLED.

FBC(2007) 109.10

WORK WAS COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 25, 2011 - 9:00 AM

CASE NO: CE10020693

CASE ADDR: 1400 NE 56 ST # 112

ISLES AT CORAL RIDGE DEVELOPMENT OWNER:

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REOUIRED PERMITS:

- 1. WOODEN FENCES HAVE BEEN INSTALLED.
- 2. THE DOCK HAS BEEN REBUILT.
- 3. EXTERIOR DOORS HAVE BEEN REPLACED.
- 4. THE POOL BATHROOMS HAVE BEEN REMODELED.
- 5. THE PARKING LOT HAS BEEN REPAVED AND RESTRIPED.
- 6. RAILINGS HAVE BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PIPING AND FIXTURES HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELINGS, INCLUDING THE BATHS LOCATED AT THE COMMUNITY POOT.
- 2. AN EXTERIOR SHOWER WAS INSTALLED/REPLACED ON THE WALL OF THE POOL BATHROOM BUILDING.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING ALL OF THE KITCHEN AND BATH REMODELINGS, INCLUDING THE POOL BATHS.
- 2. MISCELLANEOUS EXTERIOR LIGHTING HAS BEEN INSTALLED.

FBC(2007) 109.10

WORK WAS COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 25, 2011 - 9:00 AM

CASE NO: CE10020694

CASE ADDR: 1400 NE 56 ST # 113

ISLES AT CORAL RIDGE DEVELOPMENT OWNER:

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REOUIRED PERMITS:

- 1. WOODEN FENCES HAVE BEEN INSTALLED.
- 2. THE DOCK HAS BEEN REBUILT.
- 3. EXTERIOR DOORS HAVE BEEN REPLACED.
- 4. THE POOL BATHROOMS HAVE BEEN REMODELED.
- 5. THE PARKING LOT HAS BEEN REPAVED AND RESTRIPED.
- 6. RAILINGS HAVE BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PIPING AND FIXTURES HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELINGS, INCLUDING THE BATHS LOCATED AT THE COMMUNITY POOT.
- 2. AN EXTERIOR SHOWER WAS INSTALLED/REPLACED ON THE WALL OF THE POOL BATHROOM BUILDING.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING ALL OF THE KITCHEN AND BATH REMODELINGS, INCLUDING THE POOL BATHS.
- 2. MISCELLANEOUS EXTERIOR LIGHTING HAS BEEN INSTALLED.

FBC(2007) 109.10

WORK WAS COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 25, 2011 - 9:00 AM

CASE NO: CE10020695

CASE ADDR: 1400 NE 56 ST # 114

OWNER: ISLES AT CORAL RIDGE DEVELOPMENT

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. WOODEN FENCES HAVE BEEN INSTALLED.
- 2. THE DOCK HAS BEEN REBUILT.
- 3. EXTERIOR DOORS HAVE BEEN REPLACED.
- 4. THE POOL BATHROOMS HAVE BEEN REMODELED.
- 5. THE PARKING LOT HAS BEEN REPAVED AND RESTRIPED.
- 6. RAILINGS HAVE BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PIPING AND FIXTURES HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELINGS, INCLUDING THE BATHS LOCATED AT THE COMMUNITY POOL.
- 2. AN EXTERIOR SHOWER WAS INSTALLED/REPLACED ON THE WALL OF THE POOL BATHROOM BUILDING.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING ALL OF THE KITCHEN AND BATH REMODELINGS, INCLUDING THE POOL BATHS.
- 2. MISCELLANEOUS EXTERIOR LIGHTING HAS BEEN INSTALLED.

FBC(2007) 109.10

WORK WAS COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 25, 2011 - 9:00 AM

CASE NO: CE10020700

CASE ADDR: 1400 NE 56 ST # 205

OWNER: ISLES AT CORAL RIDGE DEVELOPMENT

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. WOODEN FENCES HAVE BEEN INSTALLED.
- 2. THE DOCK HAS BEEN REBUILT.
- 3. EXTERIOR DOORS HAVE BEEN REPLACED.
- 4. THE POOL BATHROOMS HAVE BEEN REMODELED.
- 5. THE PARKING LOT HAS BEEN REPAVED AND RESTRIPED.
- 6. RAILINGS HAVE BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PIPING AND FIXTURES HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELINGS, INCLUDING THE BATHS LOCATED AT THE COMMUNITY POOL.
- 2. AN EXTERIOR SHOWER WAS INSTALLED/REPLACED ON THE WALL OF THE POOL BATHROOM BUILDING.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING ALL OF THE KITCHEN AND BATH REMODELINGS, INCLUDING THE POOL BATHS.
- 2. MISCELLANEOUS EXTERIOR LIGHTING HAS BEEN INSTALLED.

FBC(2007) 109.10

WORK WAS COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

THE EXTERIOR DOORS, DOCK, WOOD FENCES, AND RAILINGS HAVE NOT BEEN PROVEN TO SUFFICIENTLY WITHSTAND ESTIMATED OR ACTUAL IMPOSED DEAD, LIVE, WIND, OR ANY OTHER LOADS THROUGH THE PERMIT AND INSPECTION PROCESS.

CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 25, 2011 - 9:00 AM

CASE NO: CE10020701

CASE ADDR: 1400 NE 56 ST # 206

OWNER: ISLES AT CORAL RIDGE DEVELOPMENT

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REOUIRED PERMITS:

- 1. WOODEN FENCES HAVE BEEN INSTALLED.
- 2. THE DOCK HAS BEEN REBUILT.
- 3. EXTERIOR DOORS HAVE BEEN REPLACED.
- 4. THE POOL BATHROOMS HAVE BEEN REMODELED.
- 5. THE PARKING LOT HAS BEEN REPAVED AND RESTRIPED.
- 6. RAILINGS HAVE BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PIPING AND FIXTURES HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELINGS, INCLUDING THE BATHS LOCATED AT THE COMMUNITY POOL.
- 2. AN EXTERIOR SHOWER WAS INSTALLED/REPLACED ON THE WALL OF THE POOL BATHROOM BUILDING.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING ALL OF THE KITCHEN AND BATH REMODELINGS, INCLUDING THE POOL BATHS.
- 2. MISCELLANEOUS EXTERIOR LIGHTING HAS BEEN INSTALLED.

FBC(2007) 109.10

WORK WAS COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

THE EXTERIOR DOORS, DOCK, WOOD FENCES, AND RAILINGS HAVE NOT BEEN PROVEN TO SUFFICIENTLY WITHSTAND ESTIMATED OR ACTUAL IMPOSED DEAD, LIVE, WIND, OR ANY OTHER LOADS THROUGH THE PERMIT AND INSPECTION PROCESS.

CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 25, 2011 - 9:00 AM

CASE NO: CE10020703

CASE ADDR: 1400 NE 56 ST # 208

OWNER: ISLES AT CORAL RIDGE DEVELOPMENT

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. WOODEN FENCES HAVE BEEN INSTALLED.
- 2. THE DOCK HAS BEEN REBUILT.
- 3. EXTERIOR DOORS HAVE BEEN REPLACED.
- 4. THE POOL BATHROOMS HAVE BEEN REMODELED.
- 5. THE PARKING LOT HAS BEEN REPAVED AND RESTRIPED.
- 6. RAILINGS HAVE BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PIPING AND FIXTURES HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELINGS, INCLUDING THE BATHS LOCATED AT THE COMMUNITY POOL.
- 2. AN EXTERIOR SHOWER WAS INSTALLED/REPLACED ON THE WALL OF THE POOL BATHROOM BUILDING.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING ALL OF THE KITCHEN AND BATH REMODELINGS, INCLUDING THE POOL BATHS.
- 2. MISCELLANEOUS EXTERIOR LIGHTING HAS BEEN INSTALLED.

FBC(2007) 109.10

WORK WAS COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 25, 2011 - 9:00 AM

CASE NO: CE10020704

CASE ADDR: 1400 NE 56 ST # 209

OWNER: ISLES AT CORAL RIDGE DEVELOPMENT

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. WOODEN FENCES HAVE BEEN INSTALLED.
- 2. THE DOCK HAS BEEN REBUILT.
- 3. EXTERIOR DOORS HAVE BEEN REPLACED.
- 4. THE POOL BATHROOMS HAVE BEEN REMODELED.
- 5. THE PARKING LOT HAS BEEN REPAVED AND RESTRIPED.
- 6. RAILINGS HAVE BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PIPING AND FIXTURES HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELINGS, INCLUDING THE BATHS LOCATED AT THE COMMUNITY POOL.
- 2. AN EXTERIOR SHOWER WAS INSTALLED/REPLACED ON THE WALL OF THE POOL BATHROOM BUILDING.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING ALL OF THE KITCHEN AND BATH REMODELINGS, INCLUDING THE POOL BATHS.
- 2. MISCELLANEOUS EXTERIOR LIGHTING HAS BEEN INSTALLED.

FBC(2007) 109.10

WORK WAS COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 25, 2011 - 9:00 AM

CASE NO: CE10020705

CASE ADDR: 1400 NE 56 ST # 210

OWNER: ISLES AT CORAL RIDGE DEVELOPMENT

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REOUIRED PERMITS:

- 1. WOODEN FENCES HAVE BEEN INSTALLED.
- 2. THE DOCK HAS BEEN REBUILT.
- 3. EXTERIOR DOORS HAVE BEEN REPLACED.
- 4. THE POOL BATHROOMS HAVE BEEN REMODELED.
- 5. THE PARKING LOT HAS BEEN REPAVED AND RESTRIPED.
- 6. RAILINGS HAVE BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PIPING AND FIXTURES HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELINGS, INCLUDING THE BATHS LOCATED AT THE COMMUNITY POOL.
- 2. AN EXTERIOR SHOWER WAS INSTALLED/REPLACED ON THE WALL OF THE POOL BATHROOM BUILDING.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING ALL OF THE KITCHEN AND BATH REMODELINGS, INCLUDING THE POOL BATHS.
- 2. MISCELLANEOUS EXTERIOR LIGHTING HAS BEEN INSTALLED.

FBC(2007) 109.10

WORK WAS COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

THE EXTERIOR DOORS, DOCK, WOOD FENCES, AND RAILINGS HAVE NOT BEEN PROVEN TO SUFFICIENTLY WITHSTAND ESTIMATED OR ACTUAL IMPOSED DEAD, LIVE, WIND, OR ANY OTHER LOADS THROUGH THE PERMIT AND INSPECTION PROCESS.

CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 25, 2011 - 9:00 AM

CASE NO: CE10020706

CASE ADDR: 1400 NE 56 ST # 211

OWNER: ISLES AT CORAL RIDGE DEVELOPMENT

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. WOODEN FENCES HAVE BEEN INSTALLED.
- 2. THE DOCK HAS BEEN REBUILT.
- 3. EXTERIOR DOORS HAVE BEEN REPLACED.
- 4. THE POOL BATHROOMS HAVE BEEN REMODELED.
- 5. THE PARKING LOT HAS BEEN REPAVED AND RESTRIPED.
- 6. RAILINGS HAVE BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PIPING AND FIXTURES HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELINGS, INCLUDING THE BATHS LOCATED AT THE COMMUNITY POOL.
- 2. AN EXTERIOR SHOWER WAS INSTALLED/REPLACED ON THE WALL OF THE POOL BATHROOM BUILDING.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING ALL OF THE KITCHEN AND BATH REMODELINGS, INCLUDING THE POOL BATHS.
- 2. MISCELLANEOUS EXTERIOR LIGHTING HAS BEEN INSTALLED.

FBC(2007) 109.10

WORK WAS COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 25, 2011 - 9:00 AM

CASE NO: CE10020708

CASE ADDR: 1400 NE 56 ST # 213

OWNER: ISLES AT CORAL RIDGE DEVELOPMENT

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. WOODEN FENCES HAVE BEEN INSTALLED.
- 2. THE DOCK HAS BEEN REBUILT.
- 3. EXTERIOR DOORS HAVE BEEN REPLACED.
- 4. THE POOL BATHROOMS HAVE BEEN REMODELED.
- 5. THE PARKING LOT HAS BEEN REPAVED AND RESTRIPED.
- 6. RAILINGS HAVE BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PIPING AND FIXTURES HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELINGS INCLUDING THE BATHS LOCATED AT THE COMMUNITY POOL.
- 2. AN EXTERIOR SHOWER WAS INSTALLED/REPLACED ON THE WALL OF THE POOL BATHROOM BUILDING.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING ALL OF THE KITCHEN AND BATH REMODELINGS, INCLUDING THE POOL BATHS.
- 2. MISCELLANEOUS EXTERIOR LIGHTING HAVE BEEN INSTALLED.

FBC(2007) 109.10

WORK WAS COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 25, 2011 - 9:00 AM

CASE NO: CE10020709

CASE ADDR: 1400 NE 56 ST # 214

OWNER: ISLES AT CORAL RIDGE DEVELOPMENT

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REOUIRED PERMITS:

- 1. WOODEN FENCES HAVE BEEN INSTALLED.
- 2. THE DOCK HAS BEEN REBUILT.
- 3. EXTERIOR DOORS HAVE BEEN REPLACED.
- 4. THE POOL BATHROOMS HAVE BEEN REMODELED.
- 5. THE PARKING LOT HAS BEEN REPAVED AND RESTRIPED.
- 6. RAILINGS HAVE BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PIPING AND FIXTURES HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELINGS, INCLUDING THE BATHS LOCATED AT THE COMMUNITY POOL.
- 2. AN EXTERIOR SHOWER WAS INSTALLED/REPLACED ON THE WALL OF THE POOL BATHROOM BUILDING.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING ALL OF THE KITCHEN AND BATH REMODELINGS, INCLUDING THE POOL BATHS.
- 2. MISCELLANEOUS EXTERIOR LIGHTING HAVE BEEN INSTALLED.

FBC(2007) 109.10

WORK WAS COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 25, 2011 - 9:00 AM

CASE NO: CE10020711

CASE ADDR: 1400 NE 56 ST # 302

OWNER: ISLES AT CORAL RIDGE DEVELOPMENT

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. WOODEN FENCES HAVE BEEN INSTALLED.
- 2. THE DOCK HAS BEEN REBUILT.
- 3. EXTERIOR DOORS HAVE BEEN REPLACED.
- 4. THE POOL BATHROOMS HAVE BEEN REMODELED.
- 5. THE PARKING LOT HAS BEEN REPAVED AND RESTRIPED.
- 6. RAILINGS HAVE BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PIPING AND FIXTURES HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELINGS, INCLUDING THE BATHS LOCATED AT THE COMMUNITY POOL.
- 2. AN EXTERIOR SHOWER WAS INSTALLED/REPLACED ON THE WALL OF THE POOL BATHROOM BUILDING.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING ALL OF THE KITCHEN AND BATH REMODELINGS, INCLUDING THE POOL BATHS.
- 2. MISCELLANEOUS EXTERIOR LIGHTING HAVE BEEN INSTALLED.

FBC(2007) 109.10

WORK WAS COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 25, 2011 - 9:00 AM

CASE NO: CE10020712

CASE ADDR: 1400 NE 56 ST # 303

OWNER: ISLES AT CORAL RIDGE DEVELOPMENT

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. WOODEN FENCES HAVE BEEN INSTALLED.
- 2. THE DOCK HAS BEEN REBUILT.
- 3. EXTERIOR DOORS HAVE BEEN REPLACED.
- 4. THE POOL BATHROOMS HAVE BEEN REMODELED.
- 5. THE PARKING LOT HAS BEEN REPAVED AND RESTRIPED.
- 6. RAILINGS HAVE BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PIPING AND FIXTURES HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELINGS, INCLUDING THE BATHS LOCATED AT THE COMMUNITY POOL.
- 2. AN EXTERIOR SHOWER WAS INSTALLED/REPLACED ON THE WALL OF THE POOL BATHROOM BUILDING.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING ALL OF THE KITCHEN AND BATH REMODELINGS, INCLUDING THE POOL BATHS.
- 2. MISCELLANEOUS EXTERIOR LIGHTING HAVE BEEN INSTALLED.

FBC(2007) 109.10

WORK WAS COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

THE EXTERIOR DOORS, DOCK, WOOD FENCES, AND RAILINGS HAVE NOT BEEN PROVEN TO SUFFICIENTLY WITHSTAND ESTIMATED OR ACTUAL IMPOSED DEAD, LIVE, WIND, OR ANY OTHER LOADS THROUGH THE PERMIT AND INSPECTION PROCESS.

CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 25, 2011 - 9:00 AM

CASE NO: CE10020714

CASE ADDR: 1400 NE 56 ST # 305

OWNER: ISLES AT CORAL RIDGE DEVELOPMENT

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. WOODEN FENCES HAVE BEEN INSTALLED.
- 2. THE DOCK HAS BEEN REBUILT.
- 3. EXTERIOR DOORS HAVE BEEN REPLACED.
- 4. THE POOL BATHROOMS HAVE BEEN REMODELED.
- 5. THE PARKING LOT HAS BEEN REPAVED AND RESTRIPED.
- 6. RAILINGS HAVE BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PIPING AND FIXTURES HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELINGS, INCLUDING THE BATHS LOCATED AT THE COMMUNITY POOL.
- 2. AN EXTERIOR SHOWER WAS INSTALLED/REPLACED ON THE WALL OF THE POOL BATHROOM BUILDING.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING ALL OF THE KITCHEN AND BATH REMODELINGS, INCLUDING THE POOL BATHS.
- 2. MISCELLANEOUS EXTERIOR LIGHTING HAVE BEEN INSTALLED.

FBC(2007) 109.10

WORK WAS COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 25, 2011 - 9:00 AM

CASE NO: CE10020715

CASE ADDR: 1400 NE 56 ST # 306

ISLES AT CORAL RIDGE DEVELOPMENT OWNER:

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REOUIRED PERMITS:

- 1. WOODEN FENCES HAVE BEEN INSTALLED.
- 2. THE DOCK HAS BEEN REBUILT.
- 3. EXTERIOR DOORS HAVE BEEN REPLACED.
- 4. THE POOL BATHROOMS HAVE BEEN REMODELED.
- 5. THE PARKING LOT HAS BEEN REPAVED AND RESTRIPED.
- 6. RAILINGS HAVE BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PIPING AND FIXTURES HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELINGS, INCLUDING THE BATHS LOCATED AT THE COMMUNITY POOT.
- 2. AN EXTERIOR SHOWER WAS INSTALLED/REPLACED ON THE WALL OF THE POOL BATHROOM BUILDING.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING ALL OF THE KITCHEN AND BATH REMODELINGS, INCLUDING THE POOL BATHS.
- 2. MISCELLANEOUS EXTERIOR LIGHTING HAVE BEEN INSTALLED.

FBC(2007) 109.10

WORK WAS COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 25, 2011 - 9:00 AM

CASE NO: CE10020717

CASE ADDR: 1400 NE 56 ST # 308

ISLES AT CORAL RIDGE DEVELOPMENT OWNER:

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REOUIRED PERMITS:

- 1. WOODEN FENCES HAVE BEEN INSTALLED.
- 2. THE DOCK HAS BEEN REBUILT.
- 3. EXTERIOR DOORS HAVE BEEN REPLACED.
- 4. THE POOL BATHROOMS HAVE BEEN REMODELED.
- 5. THE PARKING LOT HAS BEEN REPAVED AND RESTRIPED.
- 6. RAILINGS HAVE BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PIPING AND FIXTURES HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELINGS, INCLUDING THE BATHS LOCATED AT THE COMMUNITY POOT.
- 2. AN EXTERIOR SHOWER WAS INSTALLED/REPLACED ON THE WALL OF THE POOL BATHROOM BUILDING.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING ALL OF THE KITCHEN AND BATH REMODELINGS, INCLUDING THE POOL BATHS.
- 2. MISCELLANEOUS EXTERIOR LIGHTING HAVE BEEN INSTALLED.

FBC(2007) 109.10

WORK WAS COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 25, 2011 - 9:00 AM

CASE NO: CE10020719

CASE ADDR: 1400 NE 56 ST # 310

ISLES AT CORAL RIDGE DEVELOPMENT OWNER:

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REOUIRED PERMITS:

- 1. WOODEN FENCES HAVE BEEN INSTALLED.
- 2. THE DOCK HAS BEEN REBUILT.
- 3. EXTERIOR DOORS HAVE BEEN REPLACED.
- 4. THE POOL BATHROOMS HAVE BEEN REMODELED.
- 5. THE PARKING LOT HAS BEEN REPAVED AND RESTRIPED.
- 6. RAILINGS HAVE BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PIPING AND FIXTURES HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELINGS, INCLUDING THE BATHS LOCATED AT THE COMMUNITY POOT.
- 2. AN EXTERIOR SHOWER WAS INSTALLED/REPLACED ON THE WALL OF THE POOL BATHROOM BUILDING.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING ALL OF THE KITCHEN AND BATH REMODELINGS, INCLUDING THE POOL BATHS.
- 2. MISCELLANEOUS EXTERIOR LIGHTING HAVE BEEN INSTALLED.

FBC(2007) 109.10

WORK WAS COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 25, 2011 - 9:00 AM

CASE NO: CE10020720

CASE ADDR: 1400 NE 56 ST # 311

ISLES AT CORAL RIDGE DEVELOPMENT OWNER:

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REOUIRED PERMITS:

- 1. WOODEN FENCES HAVE BEEN INSTALLED.
- 2. THE DOCK HAS BEEN REBUILT.
- 3. EXTERIOR DOORS HAVE BEEN REPLACED.
- 4. THE POOL BATHROOMS HAVE BEEN REMODELED.
- 5. THE PARKING LOT HAS BEEN REPAVED AND RESTRIPED.
- 6. RAILINGS HAVE BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PIPING AND FIXTURES HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELINGS, INCLUDING THE BATHS LOCATED AT THE COMMUNITY POOT.
- 2. AN EXTERIOR SHOWER WAS INSTALLED/REPLACED ON THE WALL OF THE POOL BATHROOM BUILDING.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING ALL OF THE KITCHEN AND BATH REMODELINGS, INCLUDING THE POOL BATHS.
- 2. MISCELLANEOUS EXTERIOR LIGHTING HAVE BEEN INSTALLED.

FBC(2007) 109.10

WORK WAS COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 25, 2011 - 9:00 AM

CASE NO: CE10020721

CASE ADDR: 1400 NE 56 ST # 312

ISLES AT CORAL RIDGE DEVELOPMENT OWNER:

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REOUIRED PERMITS:

- 1. WOODEN FENCES HAVE BEEN INSTALLED.
- 2. THE DOCK HAS BEEN REBUILT.
- 3. EXTERIOR DOORS HAVE BEEN REPLACED.
- 4. THE POOL BATHROOMS HAVE BEEN REMODELED.
- 5. THE PARKING LOT HAS BEEN REPAVED AND RESTRIPED.
- 6. RAILINGS HAVE BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PIPING AND FIXTURES HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELINGS, INCLUDING THE BATHS LOCATED AT THE COMMUNITY POOT.
- 2. AN EXTERIOR SHOWER WAS INSTALLED/REPLACED ON THE WALL OF THE POOL BATHROOM BUILDING.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING ALL OF THE KITCHEN AND BATH REMODELINGS, INCLUDING THE POOL BATHS.
- 2. MISCELLANEOUS EXTERIOR LIGHTING HAVE BEEN INSTALLED.

FBC(2007) 109.10

WORK WAS COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 25, 2011 - 9:00 AM

CASE NO: CE10020722

CASE ADDR: 1400 NE 56 ST # 313

ISLES AT CORAL RIDGE DEVELOPMENT OWNER:

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REOUIRED PERMITS:

- 1. WOODEN FENCES HAVE BEEN INSTALLED.
- 2. THE DOCK HAS BEEN REBUILT.
- 3. EXTERIOR DOORS HAVE BEEN REPLACED.
- 4. THE POOL BATHROOMS HAVE BEEN REMODELED.
- 5. THE PARKING LOT HAS BEEN REPAVED AND RESTRIPED.
- 6. RAILINGS HAVE BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PIPING AND FIXTURES HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELINGS, INCLUDING THE BATHS LOCATED AT THE COMMUNITY POOT.
- 2. AN EXTERIOR SHOWER WAS INSTALLED/REPLACED ON THE WALL OF THE POOL BATHROOM BUILDING.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING ALL OF THE KITCHEN AND BATH REMODELINGS, INCLUDING THE POOL BATHS.
- 2. MISCELLANEOUS EXTERIOR LIGHTING HAVE BEEN INSTALLED.

FBC(2007) 109.10

WORK WAS COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 25, 2011 - 9:00 AM

CASE NO: CE10020723

CASE ADDR: 1400 NE 56 ST # 314

ISLES AT CORAL RIDGE DEVELOPMENT OWNER:

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REOUIRED PERMITS:

- 1. WOODEN FENCES HAVE BEEN INSTALLED.
- 2. THE DOCK HAS BEEN REBUILT.
- 3. EXTERIOR DOORS HAVE BEEN REPLACED.
- 4. THE POOL BATHROOMS HAVE BEEN REMODELED.
- 5. THE PARKING LOT HAS BEEN REPAVED AND RESTRIPED.
- 6. RAILINGS HAVE BEEN REPLACED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. PIPING AND FIXTURES HAVE BEEN ALTERED/ADDED DURING THE KITCHEN AND BATHROOM REMODELINGS, INCLUDING THE BATHS LOCATED AT THE COMMUNITY POOT.
- 2. AN EXTERIOR SHOWER WAS INSTALLED/REPLACED ON THE WALL OF THE POOL BATHROOM BUILDING.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. CIRCUITS HAVE BEEN ALTERED/ADDED DURING ALL OF THE KITCHEN AND BATH REMODELINGS, INCLUDING THE POOL BATHS.
- 2. MISCELLANEOUS EXTERIOR LIGHTING HAVE BEEN INSTALLED.

FBC(2007) 109.10

WORK WAS COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 25, 2011 - 9:00 AM

CASE NO: CE10021271

CASE ADDR: 3100 NE 29 ST # 106 OWNER: ELLIS, KALEEL M III

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS: 1. INTERIOR STRUCTURAL DEMOLITION HAS BEEN COMPLETED. THE UNIT HAS BEEN STRIPPED CLEAN.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. PLUMBING DEMOLITION HAS BEEN COMPLETED.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. ELECTRICAL DEMOLITION HAS BEEN COMPLETED.

FBC(2007) 105.4.11

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. MECHANICAL DEMOLITION HAS BEEN COMPLETED.

CASE NO: CE10041015

CASE ADDR: 2030 N ATLANTIC BLVD

OWNER: SUN TOWER INVESTMENTS INC

% BRUSCO CONST

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS: 1. LANDSCAPING HAS BEEN REMOVED AND PAVERS FOR PARKING HAVE BEEN INSTALLED.

CITY OF FORT LAUDERDALE

CODE ENFORCEMENT BOARD AGENDA

CITY COMMISSION MEETING ROOM - CITY HALL

OCTOBER 25, 2011 - 9:00 AM

CASE NO: CE10051025

CASE ADDR: 3001 E COMMERCIAL BLVD

OWNER: ANTIMUCCI, F& ANTIMUCCI, LINDA &

DAVERIO, GIANPIERO

INSPECTOR: BURT FORD

VIOLATIONS: FBC 105.1

ON 3/15/10 I DID A BUSINESS TAX INSPECTION AT THIS

ADDRESS. THERE WAS NO SIGN ON FRONT OF THE

BUILDING AT THAT TIME. ON 5/13/10 WHILE PASSING THIS ADDRESS I NOTICED A NEW SIGN "TAIL GATORS". CHECKING PERMIT HISTORY I WAS NOT ABLE TO FIND A

PERMIT FOR A NEW SIGN.

CASE NO: CE10060988

CASE ADDR: 2900 RIOMAR ST

OWNER: TIFFANY HOUSE LLC

INSPECTOR: BURT FORD

VIOLATIONS: 9-306

THIS VACANT BUILDING IS IN A GENERAL STATE OF DISREPAIR AS FOLLOWS:

- 1. EXTERIOR WALLS ARE STAINED.
- 2. THERE ARE AREAS WHERE THE PAINT IS PEELING OR IS MISSING.
- 3. THERE ARE AREAS WHERE THE EXTERIOR STUCCO AND CONCRETE HAVE FALLEN OFF OR IS SPALLING AND HAS EXPOSED THE REINFORCING STEEL.

9-307(a)

MANY OF THE WINDOWS ARE BROKEN.

FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

1. THE INTERIOR HAS BEEN GUTTED DOWN TO THE EXTERIOR WALLS. ALL OF THE FRAMING HAS BEEN REMOVED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. ALL PLUMBING PIPE, FIXTURES AND EQUIPMENT HAVE BEEN REMOVED FROM ALL OF THE BUILDINGS. THE INTERIOR HAS BEEN DEMOLISHED DOWN TO THE EXTERIOR WALLS.

CITY OF FORT LAUDERDALE CODE ENFORCEMENT BOARD AGENDA CITY COMMISSION MEETING ROOM - CITY HALL

OCTOBER 25, 2011 - 9:00 AM

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. THE ELECTRICAL SYSTEM HAS BEEN REMOVED FROM ALL OF THE BUILDINGS. THE INTERIOR HAS BEEN DEMOLISHED DOWN TO THE EXTERIOR WALLS.

FBC(2007) 105.4.11

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. ALL MECHANICAL DUCT AND EQUIPMENT HAVE BEEN REMOVED FROM ALL OF THE BUILDINGS. THE INTERIOR HAS BEEN DEMOLISHED DOWN TO THE EXTERIOR WALLS.

FBC(2007) 109.10

WORK WAS PERFORMED AND/OR COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

CASE NO: CE10071162 CASE ADDR: 1223 NE 15 AV

OWNER: 1223 NE 15TH AVENUE LLC

% CASEY WILLIAM COUGHLIN PA

INSPECTOR: BURT FORD

VIOLATIONS: 9-280(b)

THE EXTERIOR DOORS AND WINDOWS HAVE NOT BEEN MAINTAINED.

9-280(q)

THE ELECTRICAL SYSTEM HAS NOT BEEN MAINTAINED. THERE ARE EXPOSED WIRES ON ELECTRICAL OUTLETS WITHOUT COVERS.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. A WATER HEATER HAS BEEN INSTALLED IN UNIT #3.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. CIRCUITS HAVE BEEN ADDED/ALTERED WITH THE INSTALLATION OF THE WATER HEATER.

FBC(2007) 105.4.11

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

- 1. WALL A/C UNITS HAVE BEEN INSTALLED.
- 2. WINDOW A/C UNITS HAVE BEEN INSTALLED.

CASE NO: CE10091722 CASE ADDR: 2011 NE 31 AV OWNER: MCDEVITT, MICHAEL

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

1. KITCHEN AND BATHS ARE BEING REMODELED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. PIPING, FIXTURES, AND APPLIANCES HAVE BEEN REPLACED DURING THE KITCHEN AND BATH REMODELING.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. CIRCUITS HAVE BEEN ADDED/ALTERED DURING THE KITCHEN AND BATH REMODELING.

FBC(2007) 109.10

WORK WAS PERFORMED AND/OR COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

CITY OF FORT LAUDERDALE CODE ENFORCEMENT BOARD AGENDA CITY COMMISSION MEETING ROOM - CITY HALL

OCTOBER 25, 2011 - 9:00 AM

HEARING TO IMPOSE FINES

CHAPTER 11, FORT LAUDERDALE CODE OF ORDINANCES

CASE NO: CE09020587

CASE ADDR: 1525 SE 15 ST # 4 MAFF, BENJAMIN I OWNER:

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

1. NEW WINDOWS HAVE BEEN INSTALLED.

FBC(2007) 109.10

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING

THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

THE WINDOWS HAVE NOT BEEN PROVEN TO SUFFICIENTLY WITHSTAND ESTIMATED OR ACTUAL IMPOSED DEAD, LIVE, WIND, OR ANY OTHER LOADS THROUGH THE PERMIT AND

INSPECTION PROCESS.

CASE NO: CE09110699

CASE ADDR: 3111 NE 51 ST # 105C OWNER: MCGLINCHEY, DWAYNE

INSPECTOR: BURT FORD

VIOLATIONS: FBC 105.1

THE ENTRANCE DOOR HAS BEEN REPLACED WITHOUT A

PERMIT.

CODE ENFORCEMENT BOARD AGENDA

CITY COMMISSION MEETING ROOM - CITY HALL

OCTOBER 25, 2011 - 9:00 AM

CASE NO: CE10100508

CASE ADDR: 1407 HOLLY HEIGHTS DR

OWNER: KEYSTONE DEVELOPER SERVICE LLC

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

1. A WOODEN FENCE HAS BEGUN TO BE INSTALLED.

FBC(2007) 1612.1.2

THE WOODEN FENCE HAS NOT BEEN PROVEN TO SUFFICIENTLY WITHSTAND ESTIMATED OR ACTUAL IMPOSED

DEAD, LIVE, WIND, OR ANY OTHER LOADS THROUGH THE PERMIT AND INSPECTION PROCESS.

CASE NO: CE10012098 CASE ADDR: 3300 NE 16 CT

OWNER: SNYDER, GARY S & JANE LE

SNYDER FAM TR

INSPECTOR: BURT FORD

VIOLATIONS: 47-34.1.A.1.

THE SINGLE FAMILY HOME ORIGINALLY HAD A SEPARATE MAID'S QUARTERS WITH A GARAGE ATTACHED. THE GARAGE HAS BEEN CONVERTED INTO LIVING SPACE AND IS BEING USED AS A RENTAL UNIT, WHICH IS A PROHIBITED LAND USE IN THIS RS-8 ZONING DISTRICT, AS INDICATED IN SECTION 47-5.11.

FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. THE GARAGE THAT IS ATTACHED TO THE ORIGINAL MAID'S QUARTERS HAS BEEN CONVERTED INTO LIVING SPACE.
- 2. A PVC FENCE HAS BEEN INSTALLED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. PIPING AND FIXTURES HAVE BEEN ADDED/ALTERED IN THE GARAGE CONVERSION.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. CIRCUITS HAVE BEEN ADDED DURING THE GARAGE CONVERSION.

FBC(2007) 105.4.11

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. THE GARAGE CONVERSION HAS A/C INSTALLED.

FBC(2007) 109.10

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

THE PVC FENCE HAS NOT BEEN PROVEN TO SUFFICIENTLY WITHSTAND ESTIMATED OR ACTUAL IMPOSED DEAD, LIVE, WIND, OR ANY OTHER LOADS THROUGH THE PERMIT AND INSPECTION PROCESS.

CASE NO: CE10042246

CASE ADDR: 3333 NE 36 ST # 2 DADDARIO, ANGELA OWNER:

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. A FENCE HAS BEEN INSTALLED ON THE ROOF SURROUNDING THE CUPOLA.
- 2. AN EXTERIOR DOOR TO THE LAUNDRY ROOM HAS BEEN INSTALLED.
- 3. PAVERS HAVE BEEN INSTALLED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

- 1. A SPRINKLER SYSTEM HAS BEEN INSTALLED.
- 2. A WATER HEATER HAS BEEN INSTALLED.

CODE ENFORCEMENT BOARD AGENDA

CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 25, 2011 - 9:00 AM

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

- 1. EXTERIOR LIGHTING HAS BEEN INSTALLED AND CIRCUITS HAVE BEEN ADDED/ALTERED TO POWER THEM.
- 2. CIRCUITS HAVE BEEN ADDED/ALTERED TO POWER THE NEW WATER HEATER INSTALLED.
- 3. CIRCUITS HAVE BEEN ADDED/ALTERED TO POWER THE NEW SPRINKLER SYSTEM INSTALLED.

FBC(2007) 109.10

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

THE FENCE AND THE EXTERIOR LAUNDRY ROOM DOOR HAVE NOT BEEN PROVEN TO SUFFICIENTLY WITHSTAND ESTIMATED OR ACTUAL IMPOSED DEAD, LIVE, WIND, OR ANY OTHER LOADS THROUGH THE PERMIT AND INSPECTION PROCESS.

CASE NO: CE10042248

CASE ADDR: 3333 NE 36 ST # 3 OWNER: BAILEY, MAUREEN

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. A FENCE HAS BEEN INSTALLED ON THE ROOF SURROUNDING THE CUPOLA.
- 2. AN EXTERIOR DOOR TO THE LAUNDRY ROOM HAS BEEN INSTALLED.
- 3. PAVERS HAVE BEEN INSTALLED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

- 1. A SPRINKLER SYSTEM HAS BEEN INSTALLED.
- 2. A WATER HEATER HAS BEEN INSTALLED.

CODE ENFORCEMENT BOARD AGENDA

CITY COMMISSION MEETING ROOM - CITY HALL OCTOBER 25, 2011 - 9:00 AM

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

- 1. EXTERIOR LIGHTING HAS BEEN INSTALLED AND CIRCUITS HAVE BEEN ADDED/ALTERED TO POWER THEM.
- 2. CIRCUITS HAVE BEEN ADDED/ALTERED TO POWER THE NEW WATER HEATER INSTALLED.
- 3. CIRCUITS HAVE BEEN ADDED/ALTERED TO POWER THE NEW SPRINKLER SYSTEM INSTALLED.

FBC(2007) 109.10

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

THE FENCE AND THE EXTERIOR LAUNDRY ROOM DOOR HAVE NOT BEEN PROVEN TO SUFFICIENTLY WITHSTAND ESTIMATED OR ACTUAL IMPOSED DEAD, LIVE, WIND, OR ANY OTHER LOADS THROUGH THE PERMIT AND INSPECTION PROCESS.

CASE NO: CE10042243

CASE ADDR: 3333 NE 36 ST # 4

OWNER: RICHARD D FELDMANN REV TR

FELDMANN, RICHARD D TRSTEE

INSPECTOR: BURT FORD

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. A FENCE HAS BEEN INSTALLED ON THE ROOF SURROUNDING THE CUPOLA.
- 2. AN EXTERIOR DOOR TO THE LAUNDRY ROOM HAS BEEN INSTALLED.
- 3. PAVERS HAVE BEEN INSTALLED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

- 1. A SPRINKLER SYSTEM HAS BEEN INSTALLED.
- 2. A WATER HEATER HAS BEEN INSTALLED.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

- 1. EXTERIOR LIGHTING HAS BEEN INSTALLED AND CIRCUITS HAVE BEEN ADDED/ALTERED TO POWER THEM.
- 2. CIRCUITS HAVE BEEN ADDED/ALTERED TO POWER THE NEW WATER HEATER INSTALLED.
- 3. CIRCUITS HAVE BEEN ADDED/ALTERED TO POWER THE NEW SPRINKLER SYSTEM INSTALLED.

FBC(2007) 109.10

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

THE FENCE AND THE EXTERIOR LAUNDRY ROOM DOOR HAVE NOT BEEN PROVEN TO SUFFICIENTLY WITHSTAND ESTIMATED OR ACTUAL IMPOSED DEAD, LIVE, WIND, OR ANY OTHER LOADS THROUGH THE PERMIT AND INSPECTION PROCESS.

CASE NO: CE10061995

CASE ADDR: 3025 DAVIE BLVD

OWNER: MARKATIA EQUITIES INC

INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED WITH THE

CONNECTION OF A NEW SPLIT A/C SYSTEM.

FBC(2007) 105.4.11

A NEW SPLIT A/C SYSTEM HAS BEEN INSTALLED WITHOUT

A PERMIT.

CASE NO: CE11021410 CASE ADDR: 1325 SW 30 ST

GAZZOLA, OLIVIER R J

INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC(2007) 105.1

A BARN-LIKE STRUCTURE HAS BEEN ERECTED ON THE REAR OF THE PROPERTY OF THE SINGLE FAMILY RESIDENCE

WITHOUT A PERMIT.

Page 79

CITY OF FORT LAUDERDALE CODE ENFORCEMENT BOARD AGENDA

CITY COMMISSION MEETING ROOM - CITY HALL

OCTOBER 25, 2011 - 9:00 AM

CASE NO: CE09060554

CASE ADDR: 1121 GUAVA ISLE
OWNER: YOHAM, JEFFREY
INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC 105.1

A BOAT LIFT HAS BEEN INSTALLED WITHOUT OBTAINING

THE REQUIRED PERMITS.

CASE NO: CE10082026
CASE ADDR: 1650 SW 27 AV
OWNER: ECHOLS, AARON
INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC(2007) 105.1

THE FOLLOWING WORK HAS BEEN COMPLETED WITHOUT

OBTAINING THE REQUIRED PERMITS:

1. SHUTTERS FOR THE FLORIDA ROOM HAVE BEEN INSTALLED.

- 2. A SHED HAS BEEN PLACED IN THE REAR.
- 3. AN ATTACHED STORAGE CLOSET HAS BEEN CONSTRUCTED.
- 4. THE OVERHANGS HAVE BEEN RESURFACED.
- 5. THE CARPORT CEILING HAS BEEN RESURFACED.
- 6. BOTH BATHS HAVE BEEN REMODELED.
- 7. AN ACOUSTICAL CEILING WAS INSTALLED IN THE GAME ROOM.

FBC(2007) 105.4.4

THE FOLLOWING PLUMBING WORK HAS BEEN COMPLETED WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. TWO BATHROOMS HAVE BEEN REMODELED.
- 2. AN IRRIGATION PUMP HAS BEEN INSTALLED.
- 3. NATURAL GAS PIPING HAS BEEN INSTALLED.
- 4. A WATER HEATER HAS BEEN INSTALLED.

FBC(2007) 105.4.5

THE FOLLOWING ELECTRICAL WORK HAS BEEN COMPLETED WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. A BURGLAR ALARM HAS BEEN INSTALLED.
- 2. AN IRRIGATION PUMP HAS BEEN CONNECTED.
- 3. AN AIR HANDLER AND CONDENSING UNIT HAVE BEEN CONNECTED.
- 4. AN OUTLET FOR A WALL A/C UNIT HAS BEEN INSTALLED.

- 5. A CEILING FAN IN THE GAME ROOM HAS BEEN CONNECTED.
- 6. EXTERIOR OUTLETS AND SWITCHES HAVE BEEN INSTALLED.
- 7. SECURITY LIGHTING HAS BEEN INSTALLED.
- 8. ELECTRICAL OUTLETS HAVE BEEN INSTALLED IN THE STORAGE CLOSET.

FBC(2007) 105.4.11

THE FOLLOWING MECHANICAL WORK HAS BEEN COMPLETED WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. A NEW CONDENSING UNIT HAS BEEN INSTALLED.
- 2. A NEW AIR HANDLER HAS BEEN INSTALLED.
- 3. A WALL A/C UNIT HAS BEEN INSTALLED IN THE GAME ROOM.

CASE NO: CE10071991 CASE ADDR: 2600 NW 20 CT OWNER: PIERCE, RICKY INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

- 1. THE ADDITION ON THE WEST SIDE OF THE DWELLING WAS DONE WITH A CANCELLED PERMIT FROM BROWARD COUNTY FOR THE FOLLOWING STRUCTURAL WORK:
- A. A NEW BATHROOM AND BEDROOM.
- B. INTERIOR REMODELING OF KITCHEN AND THE EXISTING BATHROOM.
- C. THE INSTALLATION OF A CENTRAL A/C WITH DUCT WORK.
- 2. WORK CONTINUED WITHOUT A PERMIT AS NEW WINDOWS WERE INSTALLED, STUCCOED THE OUTSIDE WALLS OF THE BUILDING, AND FINISHING THE INTERIOR REMODELING WORK.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. THE ADDITION OF AN EXTRA BATHROOM.
- 2. THE REMODELING OF THE EXISTING BATHROOM AND KITCHEN.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. ELECTRICAL LOAD DEMAND WAS INCREASED BY ADDING A CENTRAL A/C WITH ELECTRIC HEATER AND ADDITIONAL LIGHTS AND WALL OUTLETS FOR THE ILLEGAL ADDITION THAT HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED AMPERAGE LOADING THROUGH THE PERMITTING PROCESS.

FBC(2007) 105.10.3.1

THERE IS A BUILDING PERMIT WHICH FAILED INSPECTION AND/OR WAS LEFT TO EXPIRE:

1. CANCEL MASTER PERMIT 04-12587 FOR THE INTERIOR REMODELING WORK AND THE ADDITION ON THE WEST SIDE THAT FAILED REVIEW. THE JOB WAS FINISHED AS WORK WITHOUT PERMIT.

CASE NO: CE10080653
CASE ADDR: 2001 NW 28 AVE
OWNER: PIERCE, RICKY
INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

- 1. FRONT ENTRANCE DOOR WAS REPLACED.
- 2. EXTERIOR WALLS WERE STUCCOED.
- 3. INTERIOR REMODELING IN THE KITCHEN AND BATHROOM WITH NEW FIXTURES AND CABINETS.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. PLUMBING FIXTURES WERE REPLACED IN THE KITCHEN AND BATHROOM.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. ELECTRICAL LOAD DEMAND WAS INCREASED BY ADDING ADDITIONAL LIGHTS AND WALL OUTLETS IN THE KITCHEN AND BATHROOM AREAS THAT HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED AMPERAGE LOADING THROUGH THE PERMITTING PROCESS.

FBC(2007) 1626.1

THE NEW ENTRANCE DOOR WITH GLASS NEED TO BE IMPACT RESISTANT OR BE PROTECTED BY AN APPROVED HURRICANE PROTECTION SYSTEM.

._____

CASE NO: CE10120978 CASE ADDR: 2121 NW 6 PL

OWNER: KOHUTH, RUSSELL EST

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

1.A LARGE SHED WAS INSTALLED AT LOT.

FBC(2007) 1604.1

THE STRUCTURE FOR THE LARGE SHED DOES NOT MEET THE STANDARD FOR GRAVITY LOADING AND HAS NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS. ALL THE STRUCTURES THAT WERE DONE ILLEGALLY ARE DEEMED TO BE UNSAFE AND THAT THE CONSTRUCTION IS UNDER DESIGNED. IT WOULD NOT PROVIDE THE REQUIRED RESISTANCE TO UPLIFT WHICH THE CODE PROTECTS NEIGHBORS FROM FLYING DEBRIS IN A STORM AND WHICH THIS STRUCTURE MAY BECOME. THEY MUST BE REMOVED

CASE NO: CE10090377 CASE ADDR: 1025 NW 8 AV OWNER: CEA, JEANNITTE &

CEA, JOSUE

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

- 1. THE TRIPLEX APARTMENT BUILDING WAS CHANGED INTO A FOURPLEX WITH FOUR KITCHENS AND BATHROOMS.
- 2. ATF PERMITS WERE ISSUED TO COMPLY THE VIOLATIONS BUT THE PERMITS WERE LEFT TO EXPIRE AND THE MASTER WAS VOIDED BY THE G.C.
- 3. THE FLOOR PLAN IN APARTMENT #1 WAS CHANGED TO BUILD THE EXTRA APARTMENT. BY ENCLOSING THE FIRST BEDROOM DOOR AND BUILDING NEW PARTITIONS, THIS CREATED THE MASTER BEDROOM, KITCHEN AND BATHROOM AREA WHERE THE STORAGE AREA USE TO BE.
- 4. AN EXTERIOR DOOR OPENING WAS ENCLOSED AND A WINDOW WAS SET IN THAT PLACE FACING THE SOUTH. ANOTHER WINDOW WAS SET IN A DOOR OPENING FACING THE EAST. AN OPENING WAS CUT IN THE WALL FACING THE NORTH SIDE TO INSTALL ANOTHER WINDOW.
- 5. THE REMAINING THREE APARTMENTS WERE REMODELED WITH NEW KITCHEN AND BATHROOM CABINETS WITH ALL THE FIXTURES.
- 6. THE KITCHENS SLIDING DOOR OPENINGS FACING THE NORTH SIDE WERE ENCLOSED AND AN EXTERIOR DOOR WAS INSTALLED IN PLACE.
- 7. THE WINDOWS IN THE LIVING ROOM AREAS WERE REPLACED IN EACH APARTMENT.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. THE EXISTING THREE BATHROOMS AND KITCHENS WERE REMODELED WITH NEW FIXTURES.
- 2. A FOURTH BATHROOM AND KITCHEN WERE BUILT INSIDE THE ILLEGAL APARTMENT.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. REMODELING OF THE THREE EXISTING APARTMENTS WITH ELECTRICAL FIXTURES IN THE KITCHENS AND BATHROOMS.
- 2. IN THE NEW APARTMENT THAT WAS BUILT, THE METER HAS BEEN JUMPED AND IS FEEDING FROM APARTMENT #2. THIS EXCEEDS THE CAPACITY OF THE EXISTING 150 AMPS CIRCUITRY IN THE APARTMENT AND IS A FIRE HAZARD.

FBC(2007) 105.4.11

THE MECHANICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. THREE CENTRAL A/C'S WERE INSTALLED IN THE APARTMENTS WITH PERMITS, BUT THE CONDENSER UNITS WERE REPLACED (OUTSIDE UNIT) WITHOUT OBTAINING THE REQUIRED PERMIT AND INSPECTION.
- 2. A NEW SYSTEM WAS INSTALLED IN THE ILLEGAL APARTMENT WITH DUCTS AND ELECTRICAL HEATER.

FBC(2007) 105.10.3.1

THERE ARE FIVE BUILDING PERMITS WHICH FAILED INSPECTION AND/OR WERE LEFT TO EXPIRE:

- 1. P#02030631 INSTALL 11 SMOKE DETECTORS, NO INSPECTIONS.
- 2. ATF P#01081794 NEW KITCHEN FOR TRIPLEX, 24 WINDOWS, 4 DOORS.
- 3. ATF P#01080013 ELECTRIC FOR FOUR KITCHENS AND BATHROOMS.
- 4. ATF P#01080011 PLUMBING FOR FOUR KITCHENS AND BATHROOMS.
- 5. ATF P#01080010 APARTMENT 4. NEW KITCHENS, BATHROOM, NEW WALLS.

FBC(2007) 109.10

THE WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS THROUGH THE PERMITTING AND INSPECTION PROCESS.

FBC(2007) 1612.1.2

ALL THE WINDOWS AND DOOR INSTALLATIONS HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS.

OCTOBER 25, 2011 - 9:00 AM

FBC(2007) 1626.1

THE NEW WINDOWS NEED TO BE IMPACT RESISTANT OR BE PROTECTED BY AN APPROVED HURRICANE PROTECTION SYSTEM.

CASE NO: CE11052306 CASE ADDR: 2645 SW 6 CT

OWNER: HOUSING FOUNDATION OF AMERICA INC

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

A STOP WORK ORDER WAS ISSUED ON MAY 26,2011

- 1. THE INTERIOR OF THE PROPERTY IS BEING REMODELED WITHOUT THE PROPER PERMITS.
- 2. THE SUPPORTING TIE BEAM HAS BEEN CUT IN DIFFERENT AREAS.
- 3. ELECTRICAL WORK IS BEING DONE.
- 4. NEW FRAMING WITH DRYWALL WORK IS BEING DONE.
- 5. PLUMBING WORK IN THE KITCHEN AND BATHROOM.
- 6. THE WINDOWS AND DOORS ARE BEING REPLACED WITH A PERMIT APPLICATION ONLY.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. REMODELING WORK OF THE KITCHEN AND BATHROOM WITH NEW PLUMBING FIXTURES.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. THE ELECTRICAL OUTLETS, SWITCHES AND LAMPS ARE BEING REMOVED. SOME ARE BEING RELOCATED THROUGHOUT THE DWELLING, THE ONE INSIDE THE KITCHEN AND BATHROOM MUST MEET THE NEC 210.8 REQUIREMENTS.

FBC(2007) 105.14

- 1. THE WORK TO REPLACE THE WINDOWS AND EXTERIOR DOORS BEGAN WITH AN APPLICATION #11051449 DATED MAY 19,2011 FOR A PERMIT THAT FAILED THE PLANS EXAMINER REVIEW ON MAY 24, 2011 FOR NOT BEING COMPLETED.
- 2. A STOP WORK ORDER WAS ISSUED AND THE CONTRACTOR WAS N.T.A. BY DET. JORGE MAURA OF THE FLPD.

FBC(2007) 1604.1

THE SUPPORTING CONCRETE TIE BEAM FOR THE ROOF WAS CUT IN DIFFERENT LOCATIONS INSIDE THE CENTER HALLWAY OF THE DWELLING COMPROMISING THE DESIGNED GRAVITY AND DEAD WEIGHT LOADING RATE OF THE SUPPORTING CONCRETE BEAM.

FBC(2007) 1612.1.2

ALL THE WINDOWS AND DOOR INSTALLATIONS HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING AND INSPECTION PROCESS.

FBC(2007) 1626.1

THE WINDOWS AND DOORS WITH GLASS PANELS THAT HAVE BEEN INSTALLED DO NOT PROVIDE THE REQUIRED RESISTANCE TO THE IMPACT OF WINDBORNE DEBRIS. AN APPROVED SHUTTER SYSTEM HAS NOT BEEN PROVIDED.

CASE NO: CE10101100

CASE ADDR: 1033 NE 16 TER OWNER: MAINI, ARCHANA SHETH, KISHOR

INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC(2007) 105.1

THE FOLLOWING WORK HAS BEEN PERFORMED ON THE MULTI-FAMILY DWELLING WITHOUT OBTAINING THE REOUIRED PERMITS:

- 1. NEW COUNTERTOPS AND CABINETS HAVE BEEN INSTALLED.
- 2. A NEW PVC FENCE HAS BEEN INSTALLED.
- 3. REFRAMING AND BRACING FOR WINDOWS IS IN PROGRESS.

FBC(2007) 105.4.4

THE FOLLOWING PLUMBING WORK HAS BEEN COMPLETED OR IN PROGRESS WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. A NEW WATER HEATER WAS INSTALLED.
- 2. KITCHEN SINKS HAVE BEEN INSTALLED.
- 3. NEW BATHROOM FIXTURES HAVE BEEN INSTALLED.

FBC(2007) 105.4.5

LIGHTING AND WIRING HAVE BEEN ALTERED AND A NEW WATER HEATER HAS BEEN CONNECTED WITHOUT OBTAINING THE REQUIRED PERMITS.