

CITY OF FORT LAUDERDALE

SPECIAL MAGISTRATE HEARING AGENDA

May 20, 2010

9:00 A.M.

COMMISSION MEETING ROOM CITY HALL

100 N ANDREWS AVE

ROSE-ANN FLYNN PRESIDING

CITY OF FORT LAUDERDALE Page 1 AGENDA SPECIAL MAGISTRATE CITY COMMISSION MEETING ROOM - CITY HALL MAY 20, 2010 9:00 AM _____ NEW BUSINESS _____ CE10032006 CASE NO: CASE ADDR: 5810 NE 14 RD PINETREE LOFTS LLC OWNER: INSPECTOR: STEPHANIE BASS VIOLATIONS: 8-91(b) THE BOAT DOCK LOCATED AT THE REAR OF THE PROPERTY IS NOT BEING MAINTAINED IN A SAFE CONDITION. ONE SECTION OF THE BOAT DOCK IS FALLING INTO THE WATERWAY. THE DEFECTIVE BOAT DOCK IS A HAZARD TO NAVIGATION, ADJACENT BOATS AND DOCKS. _____ _____ CASE NO: CE10022141 CASE ADDR: 2020 E OAKLAND PARK BLVD OWNER: BELADI, SEYED EBRAHIM & JAVID, SAFIEH INSPECTOR: MARY RICH VIOLATIONS: 47-34.2.B. THE REQUIRED BUFFERWALL IS MISSING FROM THIS CB (COMMERCIAL BUSINESS) ZONED PROPERTY. THE PROPERTY LOCATED DIRECTLY TO THE SOUTH OF THIS LOCATION IS ZONED RMM-25. THE SUBJECT PROPERTY IS IN VIOLATION OF NEIGHBORHOOD COMPATIBILITY REQUIREMENT 47-25.3.A.3.d.iv WHERE A BUFFERWALL IS REQUIRED ON A NON-RESIDENTIAL PROPERTY, WHICH IS CONTIGUOUS TO ANY RESIDENTIAL PROPERTY. _____ CASE NO: CE10020645 CASE ADDR: 2507 ANDROS LN OWNER: LORUSSO, SANDRA J INSPECTOR: BARBARA UROW VIOLATIONS: 9-280(b) THERE IS A WHITE TARP, WHEELBARROW AND BRICKS LOCATED ON THE ROOF. _____ _____ CASE NO: CE10040962 CASE ADDR: 3251 SW 1 TER FANTOM REALTY LLC OWNER: INSPECTOR: BARBARA UROW VIOLATIONS: 47-20.10.A. THERE IS TANDEM PARKING PRESENT AT THIS BUSINESS. DUE TO THE RECURRING NATURE OF THE VIOLATION THIS CASE WILL BE PRESENTED TO A SPECIAL MAGISTRATE REGARDLESS IF THE PROPERTY COMES INTO COMPLIANCE BEFORE THE HEARING. _____

| OWNER: | CE09100879 601 NE 3 AVE HAYES, PATRICIA S & HAYES, CHERYLLE A WILSON QUINTERO |
|-------------|---|
| VIOLATIONS: | 9-280(b) WITHDRAWN. |
| | 9-306 THERE IS STRUCTURAL DAMAGE AND PORTIONS OF THE BUILDING IN DISREPAIR ON THE EXTERIOR OF THE STRUCTURE OF THIS PROPERTY, INCLUDING BUT NOT LIMITED TO WINDOW FRAMES IN DISREPAIR AND CRACKS ON THE WALLS IN THE FRONT AND AT THE NORTH SIDE OF THE BUILDING. |
| OWNER: | CE10020274 436 NW 15 WY BAYVIEW LOAN SERVICING LLC WILSON QUINTERO |
| VIOLATIONS: | 18-7(b) THERE IS A VACANT MULTIFAMILY DWELLING WHOSE DOORS, WINDOWS, OR OTHER OPENINGS ARE SECURED BY BOARDING OTHER THAN THE CONVENTIONAL METHOD, WHICH IS NOT SECURED IN COMPLIANCE WITH THIS ARTICLE, AND NO PERMIT HAS BEEN OBTAIN FOR THE BOARDING. |
| | 1126 NW 4 AVE BUTLER, ANDRE |
| VIOLATIONS: | 18-4(c) THERE IS AN UNLICENSED BLACK HONDA CIVIC IN THE DRIVEWAY OF THIS PROPERTY. |
| | 1217 NW 6 AVE AMERICAN TEXTILE GROUP LLC |
| VIOLATIONS: | 18-12(a) THERE IS TRASH AND DEBRIS ON THIS PROPERTY INCLUDING BUT NOT LIMITED TO OLD TREE TRIMMINGS. |
| | |

Page 2

CITY OF FORT LAUDERDALE Page 3 AGENDA SPECIAL MAGISTRATE CITY COMMISSION MEETING ROOM - CITY HALL MAY 20, 2010 9:00 AM CASE NO: CE10022232 CASE ADDR: 2130 SW 33 AVE GONZALEZ, IVETH C & GONZALEZ, KENFOR OWNER: INSPECTOR: MARK CAMPBELL VIOLATIONS: 47-39.A.1.b.(7)(a)1. THERE IS A WHITE BOX TRUCK PARKED IN THE DRIVEWAY OF THIS PROPERTY. THIS COMMERCIAL VEHICLE WEIGHING MORE THAN 5000 POUNDS AND NOT COMPLETELY HIDDEN FROM VIEW IS THEREFORE NOT PERMITTED IN THIS RS-5 ZONED DISTRICT. _____ CASE NO: CE10032246 CASE ADDR: 3780 SW 14 ST AMERICAN ONE RENTALS INC OWNER: INSPECTOR: MARK CAMPBELL VIOLATIONS: 18-12(a) THERE IS OVERGROWTH, RUBBISH, TRASH AND DEBRIS SCATTERED ALL AROUND THE PROPERTY AND SWALE AREA, INCLUDING BUT NOT LIMITED TO YARD WASTE, FURNITURE, AND UNMAINTAINED BUSHES AND SHRUBS. _____ CASE NO: CE10032417 CASE ADDR: 3761 SW 18 ST PEART, CAROL C 1/2 INT EA PEART, BRIAN OWNER: INSPECTOR: MARK CAMPBELL VIOLATIONS: 18-12(a) THERE IS OVERGROWTH, RUBBISH, TRASH AND DEBRIS SCATTERED ALL AROUND THE PROPERTY AND SWALE AREA, INCLUDING BUT NOT LIMITED TO YARD WASTE AND UNMAINTAINED BUSHES AND SHRUBS. _____ CASE NO: CE10032663 CASE ADDR: 3400 DAVIE BLVD OWNER: HL HOLDINGS LC INSPECTOR: MARK CAMPBELL

VIOLATIONS: 18-12(a) THERE IS OVERGROWTH, RUBBISH, TRASH AND DEBRIS SCATTERED ALL AROUND THIS VACANT PROPERTY AND SWALE AREA, INCLUDING BUT NOT LIMITED TO YARD WASTE AND UNMAINTAINED BUSHES AND SHRUBS.

CITY OF FORT LAUDERDALE Page 4 AGENDA SPECIAL MAGISTRATE CITY COMMISSION MEETING ROOM - CITY HALL MAY 20, 2010 9:00 AM CASE NO: CE10012055 CASE ADDR: 1181 SW 25 AVE GIRALT, ELIO & FERNANDEZ, MIRIAM OWNER: INSPECTOR: ARETHA DAVIS VIOLATIONS: 18-12(a) NUISANCE - THERE ARE PILES OF MISCELLANEOUS RUBBISH, TRASH, AND DEBRIS ON THIS OCCUPIED RESIDENTIAL PROPERTY INCLUDING BUT NOT LIMITED TO WOOD PLANKS, BOARDS AND BUILDING MATERIALS ON THE REAR AND SIDE YARDS. _____ CASE NO: CE10030334 CASE ADDR: 2620 SW 5 ST PILZ, PETER JASON OWNER: INSPECTOR: ARETHA DAVIS VIOLATIONS: 18-12(a) NUISANCE - THERE IS OVERGROWTH AND MISCELLANEOUS RUBBISH, TRASH, AND DEBRIS ON THIS OCCUPIED RESIDENTIAL PROPERTY. _____ CASE NO: CE10030910 CASE ADDR: 301 SW 29 AVE OWNER: PAUL, FRANCOEUR J & FRANCINE D INSPECTOR: ARETHA DAVIS VIOLATIONS: 18-12(a) NUISANCE - THERE IS AN ACCUMULATION OF OVERGROWTH, RUBBISH, TRASH, AND DEBRIS ON THIS RESIDENTIAL PROPERTY THAT APPEARS TO BE OCCUPIED ESPECIALLY IN THE REAR AND NORTH SIDE YARD. _____ CASE NO: CE10031745 CASE ADDR: 111 SW 27 TER BRISSETT, E N & BRISSETT, VALRENE % F OWNER: INSPECTOR: ARETHA DAVIS VIOLATIONS: 9-280(b) THIS OCCUPIED RESIDENTIAL PROPERTY HAS MULTIPLE AREAS IN THE CEILING IN NEED OF REPAIR DUE TO WATER DAMAGE FROM ROOF LEAKS INCLUDING BUT NOT LIMITED TO THE FRONT ENTRANCE AREA, THE LIVING AREA, THE DINING AREA, AND 2 BEDROOMS. THERE ARE AREAS OF THE CARPORT CEILING AND FASCIA BOARDS THAT HAVE ROTTING WOOD AND CHIPPING/PEELING PAINT. _____

CASE NO: CE10032655 CASE ADDR: 3310 NW 64 ST GONZALEZ, EFRAIN/GONZALEZ, JHOSEPH OWNER: INSPECTOR: SAL VISCUSI VIOLATIONS: 18-12(a) THERE IS LAWN OVERGROWTH PRESENT ON THIS PROPERTY AND THE PROPERTY IS LITTERED WITH TRASH/RUBBIH/DEBRIS. _____ CASE NO: CE10032782 CASE ADDR: 3310 NW 64 ST OWNER: GONZALEZ, EFRAIN/GONZALEZ, JHOSEPH INSPECTOR: SAL VISCUSI VIOLATIONS: 18-11(a) THE POOL IN THE REAR YARD ON THIS PROPERTY IS FILLED WITH GREEN/STAGNANT WATER. THE POOL IN THIS CONDITION IS UNSANITARY, UNSIGHTLY, AND IS A POTENTIAL BREEDING GROUND FOR MOSQUITOES. THIS POOL ALSO POSES A THREAT TO THE HEALTH, SAFETY, AND WELFARE TO THE COMMUNITY _____ CASE NO: CE10032784 CASE ADDR: 3310 NW 64 ST GONZALEZ, EFRAIN/GONZALEZ, JHOSEPH OWNER: INSPECTOR: SAL VISCUSI VIOLATIONS: 9-304(b) THERE IS A JET SKI TRAILER WITH A JET SKI ON IT BEING PARKED/STORED IN THE REAR YARD ON A GRASS COVERED SURFACE. _____

CASE NO: CE10040748 CASE ADDR: 3335 NW 69 CT OWNER: DIAS, SILVANA & DIAS, VALERIA INSPECTOR: SAL VISCUSI VIOLATIONS: 18-12(a) THERE IS LAWN OVERGROWTH PRESENT ON THIS PROPERTY.

Page 5

CASE NO: CE10042338

CASE ADDR: 2900 NW 69 CT

OWNER: LASALA, GINA & LASALA, JOSEPHE INSPECTOR: SAL VISCUSI

VIOLATIONS: 18-12(a)

THERE IS TRASH/RUBBISH/DEBRIS LITTERING THIS PROPERTY THE ITMES INCLUDE BUT ARE NOT LIMITED TOO BEER BOTTLES, PLASTIC BOTTLES, CARDBOARD BEER BOTTLE BOXES, TREE DEBRIS, ETC... THIS IS A REPEAT VIOLATION ON THIS PROPERTY. THIS HAD BEEN A RECURRING VIOLATION ON THIS PROPERTY. THE PROPERTY HAS BEEN CITED FOR THIS VIOLATION 9 TIMES IN THE LAST YEAR. ON 3/18/10 CODE CASE CE10020157 WAS PRESENTED BEFORE SPECIAL MAGISTRATE PURDY, WHO RULED IN FAVOR OF THE CITY DECLARING THIS TO BE A RECURRING VIOLATION ON THIS PROPERTY AND ISSUED A FINDING OF FACT ON BEHALF OF THE CITY OF FORT LAUDERDALE. THIS CASE WILL BE PRESENTED TO THE SPECIAL MAGISTRATE WHETHER THE VIOLATION COMPLIES PRIOR TO THE HEARING DATE OR NOT.

| CASE NO. | CET002001/ |
|------------|-----------------------------------|
| CASE ADDR: | 2504 NW 21 ST |
| OWNER: | HSBC BANK USA N A TRSTEE |
| | <pre>% LITTON LOAN SERVICES</pre> |
| | |

INSPECTOR: INGRID GOTTLIEB

CAGE NO. CE10020017

VIOLATIONS: 9-276(b)(3) THERE IS EVIDENCE OF TERMITES ON THIS PROPERTY.

> 9-278(g) THERE ARE MISSING OR BROKEN SCREENS ON THE WINDOWS OF THIS RENTAL DUPLEX.

9-280(b)

THERE ARE BROKEN AND INOPERABLE WINDOWS ON THIS RENTAL DUPLEX PROPERTY. THERE IS ROTTED, WATER DAMAGED, AND TERMITE EATEN WOOD ON THE INSIDE AND OUTSIDE OF THE STRUCTURE. THERE ARE WALLS ON THE REAR OF THE STRUCTURE, WHICH HAVE LARGE GAPS, LEAVING THE INTERIOR EXPOSED TO THE ELEMENTS.THERE ARE DOORS AND DOOR FRAMES ON THE STRUCTURE, WHICH ARE NOT WEATHERPROOF AND WATERTIGHT, AS REQUIRED.

CONTINUED

9-280(f) THE WATER PIPES IN THE KITCHEN HAVE NOT BEEN MAINTAINED IN A GOOD, SAFE OPERATING CONDITION. THERE IS A LOUD NOISE EMANATING FROM THE PIPES WHEN TURNED ON. 9-280(q)THERE IS EXPOSED WIRING IN THE WALL OF A BEDROOM. THE AIR CONDITIONING UNIT IS NOT FUNCTIONING PROPERLY, LEAKS WHEN TURNED ON, AND DOES NOT ADEQUATELY COOL THE APARTMENT. _____ CASE NO: CE10030613 CASE ADDR: 2009 NW 21 AVE TUCHOW, TYLER OWNER: INSPECTOR: INGRID GOTTLIEB VIOLATIONS: 9-276(c)(3)THERE IS EVIDENCE OF TERMITES AND/OR OTHER INSECTS INSIDE THIS HOUSE. 9-278(h) THERE ARE SCREENS MISSING FROM WINDOWS ON THE STRUCTURE. 9-279(g) THERE ARE PIPES THAT ARE LEAKING, AND NOT BEING PROPERLY MAINTAINED. 9-280(b) THERE ARE WINDOWS ON THE STRUCTURE, THAT HAVE NOT BEEN INSTALLED IN A WORKMANLIKE MANNER, LEAVING GAPS AND ALLOWING FOR EXPOSURE TO THE ELEMENTS. THERE ARE OTHER WINDOWS THAT HAVE A PIECE OF PLYWOOD UNDERNEATH THEM, ARE NOT REASONABLY WEATHERPROOF AND WATERTIGHT, AND DO NOT MEET BUILDING REQUIREMENTS. THERE ARE OPENINGS IN THE WALLS, WHERE AC UNITS HAVE BEEN REMOVED, THAT ARE NOW JUST COVERED WITH PLYWOOD, AND ARE NOT WEATHERPROOF AND WATERTIGHT AS REQUIRED. THERE ARE CEILINGS THAT HAVE BEEN REPAIRED IN A NON WORKMANLIKE MANNER, AND ARE RIPPLED AND SAGGING. THERE ARE WALLS THAT ARE WET AND DAMAGED FROM WATER. 9-280(g) THERE IS EXPOSED WIRING AND ACCESSORIES IN THE HOUSE,

INCLUDING UNCOVERED ELECTRICAL OUTLETS AND SWITCHES, EXPOSED WIRES IN THE BREAKER BOX, AND IN A CEILING FAN.

| CE10040499 |
|------------------------------|
| 1810 NW 27 TER |
| SNELL, JESSIE % SNELL, JOE C |
| INGRID GOTTLIEB |
| |

VIOLATIONS: 18-4(c) THERE IS A RED LINCOLN WITH AN EXPIRED 2006 TAG, PARKED ON THIS PROPERTY.

CASE NO: CE10040963

| | CH10010909 |
|------------|------------------------------|
| CASE ADDR: | 1810 NW 27 TER |
| OWNER: | SNELL, JESSIE % SNELL, JOE C |
| INSPECTOR: | INGRID GOTTLIEB |

- VIOLATIONS: 9-279(e) THERE IS NO ELECTRICITY IN THIS HOUSE, TO SUPPLY THE REQUIRED HOT WATER.
 - 9-279(f) THIS HOUSE IS CURRENTLY OCCUPIED WITHOUT THE REQUIRED CITY WATER SERVICE.

| CASE NO: | CE10032489 |
|------------|-----------------|
| CASE ADDR: | 2308 NW 26 ST |
| OWNER: | WALKER, MAURICE |
| INSPECTOR: | INGRID GOTTLIEB |

- VIOLATIONS: 9-278(c) THERE ARE ELECTRICAL OUTLETS AND SWITCHES MISSING THE REQUIRED PLATE COVERS, LEAVING EXPOSED WIRING AND THE DANGER OF SHOCK.
 - 9-278(g) THERE ARE WINDOWS WITH BROKEN AND MISSING SCREENS.
 - 9-280(b) THERE ARE BROKEN WINDOWS AND WINDOWS AND DOORS THAT ARE IN DISREPAIR, AND NOT WEATHERPROOF AND WATERTIGHT AS REQUIRED, ON THIS RENTAL HOUSE.
 - 9-280(f) THERE ARE PIPES IN THE KITCHEN AND BATHROOM THAT ARE LEAKING.
 - 9-280(g) THERE ARE ELECTRICAL SWITCHES AND/OR LIGHTS IN DISREPAIR AND NOT FUNCTIONING.

| CASE NO: CASE ADDR: OWNER: INSPECTOR: VIOLATIONS: | 2124 SE 19 ST BIRNBAUM, LANE DICK EATON |
|---|---|
| | PROPERTY THAT ARE NOT PROPERLY GRADED AND MAINTAINED, CAUSING EROSION UNTO THE PUBLIC SIDEWALK AND COMPROMISING THE INTEGRITY OF AN EXISTING FENCE. |
| | 1222 SEABREEZE BLVD BHAKTA, RAVI D & SUDHA |
| VIOLATIONS: | 47-34.1.A.1- THIS RESIDENTIAL PROPERTY ZONED RS-4.4 IS BEING USED FOR COMMERCIAL PURPOSES IN THAT IT IS BEING RENTED ON A SHORT TERM/TRANSIENT BASIS. PURSUANT TO ULDR, SECTION 47-5.10, TABLE OF PERMITTED USES, THIS IS NOT A PERMITTED LAND USE IN THIS DISTRICT. |
| | 1510 SEABREEZE BLVD GADDH, SUMIT |
| VIOLATIONS: | 47-34.1.A.1- THIS RESIDENTIAL PROPERTY ZONED RS-4.4 IS BEING USED FOR COMMERCIAL PURPOSES IN THAT IT IS BEING RENTED ON A SHORT TERM/TRANSIENT BASIS. PURSUANT TO ULDR, SECTION 47-5.10, TABLE OF PERMITTED USES, THIS IS NOT A PERMITTED LAND USE IN THIS DISTRICT. |
| CASE NO: CASE ADDR: OWNER: INSPECTOR: | CE10031605 2625 GRACE DR WHEBLE, ANNERLEY DICK EATON |
| VIOLATIONS: | 47-34.1.A.1- THIS RESIDENTIAL PROPERTY ZONED RS-8 IS BEING USED FOR COMMERCIAL PURPOSES IN THAT IT IS BEING RENTED ON A SHORT TERM/TRANSIENT BASIS. PURSUANT TO ULDR, SECTION 47-5.11, TABLE OF PERMITTED USES, THIS IS NOT A PERMITTED LAND USE IN THIS DISTRICT. |
| | |

Page 9

| | 2624 GRACE DR WHEBLE, ANNERLEY |
|----------------------------------|---|
| VIOLATIONS: | 47-34.1.A.1- THIS RESIDENTIAL PROPERTY ZONED RS-8 IS BEING USED FOR COMMERCIAL PURPOSES IN THAT IT IS BEING RENTED ON A SHORT TERM/TRANSIENT BASIS. PURSUANT TO ULDR, SECTION 47-5.11, TABLE OF PERMITTED USES, THIS IS NOT A PERMITTED LAND USE IN THIS DISTRICT. |
| OWNER: | |
| VIOLATIONS: | 47-39.A.1.b.(7)(a)1. THERE IS A DERELICT COMMERCIAL SEMI-CAB TRUCK BEING STORED ON THIS RESIDENTIAL PROPERTY IN OPEN VIEW AT ALL TIMES. |
| OWNER: | CE10032422 1370 SW 28 AVE PIERRE-LOUIS, PRADEL & PIERRE-LOUIS, MARIZANE ANDRE CROSS |
| VIOLATIONS: | 47-39.A.1.b.(7)(a)1. IT SHALL BE UNLAWFUL TO PARK OR STORE ANY COMMERCIAL VEHICLE OR EQUIPMENT ON PUBLIC OR PRIVATE PROPERTY IN ALL RESIDENTIAL ZONING DISTRICTS, THERE IS A COMMERCIAL GMC BOX TRUCK STORED ON THIS RESIDENTIAL PROPERTY AT ALL TIMES. |
| CASE NO: CASE ADDR: OWNER: | |
| INSPECTOR: | HIGGINBOTHAM, GLYN EST ANDRE CROSS |
| INSPECTOR: VIOLATIONS: | HIGGINBOTHAM, GLYN EST |

| OWNER: | CE10040404 1505 SW 21 TER ERWIN, PAULINE ANDRE CROSS |
|--|--|
| VIOLATIONS: | 18-12(a) THERE IS TRASH, RUBBISH AND DEBRIS SCATTERED ABOUT THE REAR OF THE PROPERTY INCLUDING BUT, NOT LIMITED TO PLYWOOD, GLASS, AND MISCELLANEOUS ITEMS. |
| CASE NO: CASE ADDR: OWNER: INSPECTOR: | CE10040568 624 SW 16 AVE RODRIGUEZ, ROGELIO ANDRE CROSS |
| VIOLATIONS: | 18-12(a) THERE IS TRASH, RUBBISH AND DEBRIS SCATTERED ABOUT THE PROPERTY INCLUDING BUT, NOT LIMITED TO TRASH BAGS, PAPERS, CUPS AND MISCELLANEOUS ITEMS. THE PROPERTY HAS BECOME OVERGROWN AND HAS NOT BEEN MAINTAINED. |
| OWNER: | CE10040588 2960 SW 17 ST LUCACIU, VALENTIN & ILDIKO ANDRE CROSS |
| VIOLATIONS: | 18-12(a) THERE IS TRASH, RUBBISH AND DEBRIS SCATTERED ABOUT THE PROPERTY INCLUDING BUT, NOT LIMITED TO A ROW OF TREE DEBRIS STORE IN THE REAR OF THIS PROPERTY, PAPERS AND MISCELLANEOUS ITEMS. |
| CASE NO: CASE ADDR: OWNER: INSPECTOR: | CE09120516 179 ROYAL PALM DR FUHRER, ESTHER C LE VAN DER VEER, CONSTANCE ETAL URSULA THIME |
| VIOLATIONS: | 8-91(b) THE SEAWALL AT THIS LOCATION HAS CRACKS AND A VOID BEHIND THE WALL, CREATING A SEVERE WASH OUT OF SOIL. THE SEAWALL HAS NOT BEEN MAINTAINED AND IS A HAZARD IN THIS CONDITION. |

CASE NO: CE10032267

CASE ADDR: 2201 SUNRISE KEY BLVD BERNAGENE, ROMANE OWNER: INSPECTOR: URSULA THIME

VIOLATIONS: 18-11(b)

THE SWIMMING POOL LOCATED AT THE BACK OF THIS UNOCCUPIED PROPERTY HAS STAGNANT WATER, TRASH AND DEBRIS. THE BUILDING DOES NOT HAVE THE REQUIRED UTILITY SERVICES AND SAFEGUARDS HAVE NOT BEEN TAKEN TO PREVENT THE PROLIFERATION OF MOSQUITOES OR ANIMALS FROM FALLING INTO OR HAVING ACCESS TO THE POOL PER CODE ORIDNANCE. THE PROPERTY IN THIS CONDITION IS A PUBLIC NUISANCE.

CASE NO: CE10032268 CASE ADDR: 801 NE 6 ST PAPERMAN, ELAINE OWNER: INSPECTOR: URSULA THIME

VIOLATIONS: 18-12(a) THE PROPERTY HAS BECOME OVERGROWN IN SOME AREAS OF THE YARD AND HAS NOT BEEN MAINTAINED.

| CE10032272 |
|------------------|
| 606 NE 8 AVE |
| PAPERMAN, ELAINE |
| URSULA THIME |
| |

VIOLATIONS: 18-12(a) THERE IS TRASH, RUBBISH AND DEBRIS SCATTERED ABOUT

THE PROPERTY, INCLUDING BUT NOT LIMITED TO PILES OF MANGO TREE TRIMMINGS AND YARD DEBRIS IN THE REAR. THE PROPERTY HAS BECOME OVERGROWN AND HAS NOT BEEN MAINTAINED.

_____ CASE NO: CE10032575 CASE ADDR: 124 HENDRICKS ISLE OWNER: SIDMAN, HUE KIM INSPECTOR: URSULA THIME

VIOLATIONS: 18-4(c)

THERE IS A LARGE DERELICT VESSEL STORED AT THIS LOCATION THAT HAS SUNK TO THE BOTTOM OF THE CANAL AND IS IN SEVERE CONDITION. THE VESSEL IN THIS CONDITION IS INOPERABLE AND ENDANGERS THE PUBLIC HEALTH, SAFETY AND WELFARE OF THE COMMUNITY.

Page 12

Page 13

CASE NO: CE10032959 CASE ADDR: 1271 SEMINOLE DR

OWNER:POSTMA, RANDALL F & POSTMA, DEBORAH JINSPECTOR:URSULA THIME

VIOLATIONS: 47-19.3 G. THE VESSEL "GOLDEN TOUCH" DOCKED BEHIND THIS PROPERTY EXTENDS BEYOND THE PROPERTY SET BACK LINES. PER TABLE 47-5.30 THE VESSEL EXCEEDS ZONING GUIDELINES IN THIS RS 4.4 DISTRICT. THE PROPERTY WAS IN VIOLATION ON 11/12/09 (CE09110972). DUE TO THE REOCURRING NATURE OF THE VIOLATION, THIS CASE WILL BE PRESENTED TO A SPECIAL MAGISTRATE WHETHER THE PROPERTY COMPLIES BEFORE THE HEARING OR NOT.

- CASE NO: CE10021303 CASE ADDR: 815 MIDDLE RIVER DR # 102 OWNER: PRIA, EDUARDO
- INSPECTOR: RON TETREAULT
- VIOLATIONS: NFPA 101:31.3.4.1.1 A FIRE ALARM SYSTEM IS NOT PROVIDED IN ACCORDANCE WITH NFPA 101:31.3.4.1.1.

- CASE NO: CE10021305 CASE ADDR: 815 MIDDLE RIVER DR # 104 OWNER: SCHMIDT, JANE DOROTHY INSPECTOR: RON TETREAULT
- VIOLATIONS: NFPA 101:31.3.4.1.1 A FIRE ALARM SYSTEM IS NOT PROVIDED IN ACCORDANCE WITH NFPA 101:31.3.4.1.1.

| CASE NO: | CE10022235 |
|------------|------------------------|
| CASE ADDR: | 5200 NW 31 AVE # F-101 |
| OWNER: | ROGAN, MICHAEL |
| INSPECTOR: | RON TETREAULT |
| | |

VIOLATIONS: NFPA 101:31.3.4.1.1 A FIRE ALARM SYSTEM IS NOT PROVIDED IN ACCORDANCE WITH NFPA 101:31.3.4.1.1.

CITY OF FORT LAUDERDALE Page 14 AGENDA SPECIAL MAGISTRATE CITY COMMISSION MEETING ROOM - CITY HALL MAY 20, 2010 9:00 AM CASE NO: CE10022237 CASE ADDR: 5200 NW 31 AVE # F-103 AXELROD, JACK AXELROD, SADIE OWNER: INSPECTOR: RON TETREAULT VIOLATIONS: NFPA 101:31.3.4.1.1 A FIRE ALARM SYSTEM IS NOT PROVIDED IN ACCORDANCE WITH NFPA 101:31.3.4.1.1. _____ CASE NO: CE10022259 CASE ADDR: 5200 NW 31 AVE # F-113 OWNER: MIKHAIL, DELON INSPECTOR: RON TETREAULT VIOLATIONS: NFPA 101:31.3.4.1.1 A FIRE ALARM SYSTEM IS NOT PROVIDED IN ACCORDANCE WITH NFPA 101:31.3.4.1.1. _____ CASE NO: CE10022264 CASE ADDR: 5200 NW 31 AVE # F-114 OWNER: CATES, JOANNE & WAUGH, IAN INSPECTOR: RON TETREAULT VIOLATIONS: NFPA 101:31.3.4.1.1 A FIRE ALARM SYSTEM IS NOT PROVIDED IN ACCORDANCE WITH NFPA 101:31.3.4.1.1. _____ CASE NO: CE10040027 CASE ADDR: 3061 NE 49 ST # 05 GARCY, DIMITRIJE OWNER: INSPECTOR: RON TETREAULT VIOLATIONS: NFPA 101:31.3.4.5.1 HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE WITH NFPA 31.3.4.5.1. NFPA 101:31.3.4.1.1 A FIRE ALARM SYSTEM IS NOT PROVIDED IN ACCORDANCE WITH NFPA 101:31.3.4.1.1. _____ CASE NO: CE10040428 CASE ADDR: 2200 S OCEAN LA # 3010 OWNER: SUNDARARAMAN, SRINATH & NITHYA INSPECTOR: RON TETREAULT VIOLATIONS: NFPA 1:12.7.3.5 GLASS AND/OR OTHER GLAZING MATERIALS ARE NOT FIRE RATED. _____

CITY OF FORT LAUDERDALE Page 15 AGENDA SPECIAL MAGISTRATE CITY COMMISSION MEETING ROOM - CITY HALL MAY 20, 2010 9:00 AM CASE NO: CE10040434 CASE ADDR: 2200 S OCEAN LA # 2206 ADRIANA WJW-V DEN BRINK LIV TR OWNER: DEN BRINK ADRIANA WJW-V TRSTEE INSPECTOR: RON TETREAULT VIOLATIONS: NFPA 1:12.7.3.5 GLASS AND/OR OTHER GLAZING MATERIALS ARE NOT FIRE RATED. _____ CASE NO: CE10040449 CASE ADDR: 3001 SW 3 AVE # 7 OWNER: EXTRA LLC INSPECTOR: RON TETREAULT VIOLATIONS: NFPA 1:1.7.6.1 UNABLE TO GAIN ENTRY TO PERFORM A FIRE SAFETY INSPECTION. _____ CASE NO: CE10040459 CASE ADDR: 100 E BROWARD BLVD # A NEW YORK LIFE INSURANCE CO & OWNER: CABOT EAST BROWARD I LLC ET AL INSPECTOR: RON TETREAULT VIOLATIONS: NFPA 101:7.9.2.1 THE EMERGENCY LIGHT DOES NOT ILLUMINATE AS DESIGNED. _____ CASE NO: CE10040465 CASE ADDR: 2005 SW 20 ST WEST YARD PARTNERS LLC OWNER: INSPECTOR: RON TETREAULT VIOLATIONS: NFPA 1:13.3.2.1 SPRINKLER PROTECTION IS REQUIRED. NFPA 1:13.3.1.1 THE FIRE SPRINKLER SYSTEMS IS IN NEED OF SERVICE. NFPA 1:43.1.7.1 THE SPRAY BOOTH DOES NOT HAVE A FIRE SUPPRESSION SYSTEM CONSISTENT WITH NFPA 1 CHAPTER 43. NFPA 33:9.1.1 THE FIRE SUPPRESSION SYSTEM IN THE SPRAY BOOTH HAS NOT BEEN CERTIFIED WITHIN THE PAST 6 MONTHS. CONTINUED

CITY OF FORT LAUDERDALE Page 16 AGENDA SPECIAL MAGISTRATE CITY COMMISSION MEETING ROOM - CITY HALL MAY 20, 2010 9:00 AM NFPA 101:7.9.2.1 THE EMERGENCY LIGHT DOES NOT ILLUMINATE AS DESIGNED. NFPA 1:11.1.2 ELECTRICAL WIRING NOT PER NFPA 70, NATIONAL ELECTRICAL CODE. NFPA 1:11.1.5 EXTENSION CORDS ARE BEING USED AS A SUBSTITUTE FOR PERMANENT WIRING. NFPA 1:1.12.1 WORK REQUIRES A PERMIT. NFPA 1:10.4.4 THE FIRE ALARM SYSTEM HAS NOT BEEN TESTED, INSPECTED AND/OR TAGGED IN ACCORDANCE WITH THE CODE. _____ CE10040471 CASE NO: CASE ADDR: 3061 NE 49 ST # 12 OWNER: SARIK, RAYMOND E INSPECTOR: RON TETREAULT VIOLATIONS: NFPA 101:31.3.4.5.1 HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE WITH NFPA 31.3.4.5.1. NFPA 101:31.3.4.1.1 A FIRE ALARM SYSTEM IS NOT PROVIDED IN ACCORDANCE WITH NFPA 101:31.3.4.1.1. _____ CASE NO: CE10040473 CASE ADDR: 3061 NE 49 ST # 14 OWNER: O'BRIEN, AUDREY A INSPECTOR: RON TETREAULT VIOLATIONS: NFPA 101:31.3.4.5.1 HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE WITH NFPA 31.3.4.5.1. NFPA 101:31.3.4.1.1 A FIRE ALARM SYSTEM IS NOT PROVIDED IN ACCORDANCE WITH NFPA 101:31.3.4.1.1. _____

| | CE10040476 3061 NE 49 ST # 15 GRINSTEIN, ANDREA N RON TETREAULT |
|-------------|---|
| VIOLATIONS: | NFPA 101:31.3.4.5.1 HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE WITH NFPA 31.3.4.5.1. |
| | NFPA 101:31.3.4.1.1 A FIRE ALARM SYSTEM IS NOT PROVIDED IN ACCORDANCE WITH NFPA 101:31.3.4.1.1. |
| | |
| OWNER: | CE10040477 3061 NE 49 ST # 16 RAMSEY, JAMES F RON TETREAULT |
| VIOLATIONS: | NFPA 101:31.3.4.5.1 HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE WITH NFPA 31.3.4.5.1. |
| | NFPA 101:31.3.4.1.1 A FIRE ALARM SYSTEM IS NOT PROVIDED IN ACCORDANCE WITH NFPA 101:31.3.4.1.1. |
| | |
| OWNER: | CE10040478 3061 NE 49 ST # 17 GIULINI, MICHAEL & VIOLA, MATTHEW RON TETREAULT |
| VIOLATIONS: | NFPA 101:31.3.4.5.1 HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE WITH NFPA 31.3.4.5.1. |
| | NFPA 101:31.3.4.1.1 A FIRE ALARM SYSTEM IS NOT PROVIDED IN ACCORDANCE WITH NFPA 101:31.3.4.1.1. |
| | |

| | CE10040479 3061 NE 49 ST # 18 DEGARA, ROBERT G RON TETREAULT |
|------------------------|---|
| VIOLATIONS: | NFPA 101:31.3.4.5.1 HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE WITH NFPA 31.3.4.5.1. |
| | NFPA 101:31.3.4.1.1 A FIRE ALARM SYSTEM IS NOT PROVIDED IN ACCORDANCE WITH NFPA 101:31.3.4.1.1. |
| CASE NO: CASE ADDR: | CE10040480 3061 NE 49 ST # 19 |
| OWNER: | DEUTSCHE BANK NATIONAL TR CO SECURITIZED ASSET BACKED REC |
| INSPECTOR: | RON TETREAULT |
| VIOLATIONS: | NFPA 101:31.3.4.5.1 HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE WITH NFPA 31.3.4.5.1. |
| | NFPA 101:31.3.4.1.1 A FIRE ALARM SYSTEM IS NOT PROVIDED IN ACCORDANCE WITH NFPA 101:31.3.4.1.1. |
| | g=1.00.4.0.4.0.0 |
| CASE NO: CASE ADDR: | CE10040482 3061 NE 49 ST # 20 |
| | MONTANI, LAWRENCE L & MONTANI, PATRICIA A RON TETREAULT |
| VIOLATIONS: | NFPA 101:31.3.4.5.1 HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE WITH NFPA 31.3.4.5.1. |
| | NFPA 101:31.3.4.1.1 A FIRE ALARM SYSTEM IS NOT PROVIDED IN ACCORDANCE WITH NFPA 101:31.3.4.1.1. |
| | |

CITY OF FORT LAUDERDALE AGENDA SPECIAL MAGISTRATE CITY COMMISSION MEETING ROOM - CITY HALL MAY 20, 2010 9:00 AM CASE NO: CE10040483 CASE ADDR: 3061 NE 49 ST # 21 PORZIO, STEVEN R INSPECTOR: RON TETREAULT VIOLATIONS: NFPA 101:31.3.4.5.1 HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE

NFPA 101:31.3.4.1.1 A FIRE ALARM SYSTEM IS NOT PROVIDED IN ACCORDANCE WITH NFPA 101:31.3.4.1.1.

CASE NO: CE10040484 CASE ADDR: 3061 NE 49 ST # 22 OWNER: DEFURIA, LAURENCE M & GOODING, SCOTT INSPECTOR: RON TETREAULT

WITH NFPA 31.3.4.5.1.

VIOLATIONS: NFPA 101:31.3.4.5.1 HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE WITH NFPA 31.3.4.5.1.

> NFPA 101:31.3.4.1.1 A FIRE ALARM SYSTEM IS NOT PROVIDED IN ACCORDANCE WITH NFPA 101:31.3.4.1.1.

| CASE NO: CASE ADDR: OWNER: INSPECTOR: | CE10040524 219 S FT LAUD BEACH BLVD EL-AD FL BEACH LLC RON TETREAULT |
|--|--|
| VIOLATIONS: | NFPA 1:13.3.1.1 THE FIRE SPRINKLER SYSTEMS IS IN NEED OF SERVICE. |
| | NFPA 25:12.7.1 THE FIRE DEPARTMENT CONNECTION (FDC) CAP(S)/PLUG(S) IS(ARE) MISSING. |
| | NFPA 101:7.2.1.5.2 LOCKS PROVIDED IN THE MEANS OF EGRESS REQUIRE A KEY, TOOL OR SPECIAL KNOWLEDGE OR EFFORT FOR OPERATION FROM THE EGRESS SIDE. |

CONTINUED

OWNER:

CITY OF FORT LAUDERDALE Page 20 AGENDA SPECIAL MAGISTRATE CITY COMMISSION MEETING ROOM - CITY HALL MAY 20, 2010 9:00 AM NFPA 101:7.2.1.4.5 EXIT DOOR REQUIRES TOO MUCH FORCE TO OPEN. NFPA 1:13.3.3.3 CEILING TILE(S) IS(ARE) MISSING/DAMAGED. NFPA 1:1.7.6.2 FA TROUBLE TROUBLE ALARM IS SHOWING ON THE FIRE ALARM PANEL. NFPA 1:1.12.1 WORK REQUIRES A PERMIT. _____ CASE NO: CE10040786 CASE ADDR: 3300 E COMMERCIAL BLVD STANS ON THE WATER INC % ATLANTA HO OWNER: INSPECTOR: RON TETREAULT VIOLATIONS: NFPA 1:13.3.1.1 THE FIRE SPRINKLER SYSTEMS IS IN NEED OF SERVICE. NFPA 1:13.2.3.1 THE STANDPIPE IS NOT BEING MAINTAINED IN AT LEAST THE SAME LEVEL OF PERFORMANCE AND PROTECTION AS DESIGNED. NFPA 1:13.1.4 MINIMUM CLEARANCE OF FIRE PROTECTION EQUIPMENT, FIRE DEPARTMENT INLET CONNECTIONS OR FIRE PROTECTION SYSTEM CONTROL VALVES IS NOT BEING MAINTAINED. _____ CASE NO: CE10040789 CASE ADDR: 928 N FEDERAL HWY OWNER: HUB ASSOCIATES LTD INSPECTOR: RON TETREAULT VIOLATIONS: NFPA 1:10.4.4 THE FIRE ALARM SYSTEM HAS NOT BEEN TESTED, INSPECTED AND/OR TAGGED IN ACCORDANCE WITH THE CODE. NFPA 1:1.7.6.2 TROUBLE ALARM IS SHOWING ON THE FIRE ALARM PANEL. NFPA 1:13.3.1.1 THE FIRE SPRINKLER SYSTEMS IS IN NEED OF SERVICE. NFPA 1:13.3.2.1 SPRINKLER PROTECTION IS REQUIRED. NFPA 101:7.2.1.4.5 EXIT DOOR REQUIRES TOO MUCH FORCE TO OPEN. _____

CITY OF FORT LAUDERDALE Page 21 AGENDA SPECIAL MAGISTRATE CITY COMMISSION MEETING ROOM - CITY HALL MAY 20, 2010 9:00 AM CASE NO: CE10040795 CASE ADDR: 3600 NW 54 ST FRANK RUFF REV LIV TR ANITA RUFF REV LIV TR ETAL OWNER: INSPECTOR: RON TETREAULT VIOLATIONS: NFPA 1:10.4.4 THE FIRE ALARM SYSTEM HAS NOT BEEN TESTED, INSPECTED AND/OR TAGGED IN ACCORDANCE WITH THE CODE. NFPA 1:13.6.6.8.3.1 THE FIRE EXTINGUISHER(S) HAS/HAVE NOT BEEN SERVICED AND TAGGED BY A STATE LICENSED COMPANY WITHIN THE PAST 12 MONTHS. NFPA 1:13.3.1.1 THE FIRE SPRINKLER SYSTEMS IS IN NEED OF SERVICE. NFPA 25:12.7.1 THE FIRE DEPARTMENT CONNECTION (FDC) CAP(S)/PLUG(S) IS(ARE) MISSING. NFPA 13:8.5.6.1 STORAGE IS WITHIN 18 INCHES (457 MM) OF THE SPRINKLER HEAD DEFLECTOR. NFPA 1:13.2.3.1 THE STANDPIPE IS NOT BEING MAINTAINED IN AT LEAST THE SAME LEVEL OF PERFORMANCE AND PROTECTION AS DESIGNED. NFPA 1:13.3.2.1 SPRINKLER PROTECTION IS REQUIRED. NFPA 1:14.4.1 THE PATH OF EGRESS IS OBSTRUCTED / BLOCKED. NFPA 1:1.12.1 WORK HAS BEEN DONE THAT REQUIRES A PERMIT. NFPA 101:7.2.1.5.2 LOCKS PROVIDED IN THE MEANS OF EGRESS REQUIRE A KEY, TOOL OR SPECIAL KNOWLEDGE OR EFFORT FOR OPERATION FROM THE EGRESS SIDE. _____ CASE NO: CE10041259 CASE ADDR: 4000 N FEDERAL HWY

OWNER: 4000 N FEDERAL HWY LLC INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 1:13.3.1.1 THE FIRE SPRINKLER SYSTEMS IS IN NEED OF SERVICE.

CITY OF FORT LAUDERDALE Page 22 AGENDA SPECIAL MAGISTRATE CITY COMMISSION MEETING ROOM - CITY HALL MAY 20, 2010 9:00 AM CASE NO: CE10040797 CASE ADDR: 1110 NE 8 AVE OWNER: S&S DOWNTOWN LLC INSPECTOR: RON TETREAULT VIOLATIONS: NFPA 1:13.3.1.1 THE FIRE SPRINKLER SYSTEMS IS IN NEED OF SERVICE. NFPA 1:10.4.4 THE FIRE ALARM SYSTEM HAS NOT BEEN TESTED, INSPECTED AND/OR TAGGED IN ACCORDANCE WITH THE CODE. NFPA 1:13.3.1.1 SPRINKLER HEAD IS DAMAGED. NFPA 1:1.7.6.1 UNABLE TO GAIN ENTRY TO PERFORM A FIRE SAFETY INSPECTION. _____ CASE NO: CE10041251 CASE ADDR: 77 SW 20 ST OWNER: ARDOX CORP INSPECTOR: RON TETREAULT VIOLATIONS: NFPA 1:13.3.1.1 THE FIRE SPRINKLER SYSTEMS IS IN NEED OF SERVICE. NFPA 1:18.3.4.3 FDC SIGN CONSISTENT WITH NFPA 1:18.3.4.3 IS NOT PROVIDED. NFPA 25:5.3.3.1 THE SPRINKLER SYSTEM ALARM BELL DOES NOT FUNCTION AS DESIGNED. NFPA 25:12.7.1 THE FIRE DEPARTMENT CONNECTION (FDC) CAP(S)/PLUG(S) IS(ARE) MISSING. _____

CASE NO: CE10041255

CASE ADDR: 301 HENDRICKS ISLE OWNER: PLACE DES ARTS HOLDING LLC INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 101:7.1.3.2.1(6) THERE IS(ARE) UNPERMITTED PENETRATION(S) AND/OR OPENING(S) INTO AND/OR THROUGH THE EXIT ENCLOSURE ASSEMBLY.

CITY OF FORT LAUDERDALE Page 23 AGENDA SPECIAL MAGISTRATE CITY COMMISSION MEETING ROOM - CITY HALL MAY 20, 2010 9:00 AM CASE NO: CE10041253 CASE ADDR: 300 SW 4 CT NEW LIFE ONE LLC OWNER: PARAGON PROPERTIES LLC ETAL INSPECTOR: RON TETREAULT VIOLATIONS: NFPA 101:31.3.4.5.1 HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE WITH NFPA 31.3.4.5.1. NFPA 1:13.6.6.8.3.1 THE FIRE EXTINGUISHER(S) HAS/HAVE NOT BEEN SERVICED AND TAGGED BY A STATE LICENSED COMPANY WITHIN THE PAST 12 MONTHS. NFPA 101:7.9.2.1 THE EMERGENCY LIGHT DOES NOT ILLUMINATE AS DESIGNED. _____ _____ CASE NO: CE10041256 CASE ADDR: 1625 CORDOVA RD OWNER: W D CORDOVA LLC ASSC TECH ATT WINN DIXIE INSPECTOR: RON TETREAULT VIOLATIONS: NFPA 1:13.3.1.1 THE FIRE SPRINKLER SYSTEMS IS IN NEED OF SERVICE. _____ CASE NO: CE10041260 CASE ADDR: 723 NW 6 AVE OWNER: LUMA PROPERTIES INC INSPECTOR: RON TETREAULT VIOLATIONS: NFPA 1:13.3.2.1 SPRINKLER PROTECTION IS REQUIRED. NFPA 1:1.12.1 WORK REQUIRES A PERMIT. NFPA 1:11.1.2 THERE IS A COVER MISSING ON AN ELECTRICAL BOX CAUSING ELECTRICAL WIRING TO BE EXPOSED. NFPA 1:13.6.6.8.3.1 THE FIRE EXTINGUISHER(S) HAS/HAVE NOT BEEN SERVICED AND TAGGED BY A STATE LICENSED COMPANY WITHIN THE PAST 12 MONTHS. CONTINUED

CITY OF FORT LAUDERDALE Page 24 AGENDA SPECIAL MAGISTRATE CITY COMMISSION MEETING ROOM - CITY HALL MAY 20, 2010 9:00 AM NFPA 1:13.3.1.1 THE FIRE SPRINKLER SYSTEMS IS IN NEED OF SERVICE. NFPA 25:12.7.1 THE FIRE DEPARTMENT CONNECTION (FDC) CAP(S)/PLUG(S) IS(ARE) MISSING. NFPA 25:5.3.3.1 THE SPRINKLER SYSTEM ALARM BELL DOES NOT FUNCTION AS DESIGNED. _____ _____ CASE NO: CE10041419 CASE ADDR: 1401 NE 53 ST # 101 VALUE DEVELOPMENT LLC OWNER: INSPECTOR: RON TETREAULT VIOLATIONS: NFPA 101:31.3.4.5.1 HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE WITH NFPA 31.3.4.5.1. NFPA 101:31.3.4.1.1 A FIRE ALARM SYSTEM IS NOT PROVIDED IN ACCORDANCE WITH NFPA 101:31.3.4.1.1. _____ CASE NO: CE10041420 CASE ADDR: 1401 NE 53 ST # 102 OWNER: RAGUSA, LOUIS GAUDIOMONTE, JOHN INSPECTOR: RON TETREAULT VIOLATIONS: NFPA 101:31.3.4.5.1 HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE WITH NFPA 31.3.4.5.1. NFPA 101:31.3.4.1.1 A FIRE ALARM SYSTEM IS NOT PROVIDED IN ACCORDANCE WITH NFPA 101:31.3.4.1.1. _____ CASE NO: CE10041421 CASE ADDR: 1401 NE 53 ST # 103 OWNER: VALUE DEVELOPMENT LLC INSPECTOR: RON TETREAULT VIOLATIONS: NFPA 101:31.3.4.5.1 HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE WITH NFPA 31.3.4.5.1. NFPA 101:31.3.4.1.1 A FIRE ALARM SYSTEM IS NOT PROVIDED IN ACCORDANCE WITH NFPA 101:31.3.4.1.1. _____

| OWNER: | CE10041422 1401 NE 53 ST # 104 BEAUCAGE, DANIEL RON TETREAULT |
|-------------|---|
| VIOLATIONS: | NFPA 101:31.3.4.5.1 HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE WITH NFPA 31.3.4.5.1. |
| | NFPA 101:31.3.4.1.1 A FIRE ALARM SYSTEM IS NOT PROVIDED IN ACCORDANCE WITH NFPA 101:31.3.4.1.1. |
| | |
| OWNER: | CE10041423 1401 NE 53 ST # 105 BARONE, MICHAEL RON TETREAULT |
| VIOLATIONS: | NFPA 101:31.3.4.5.1 HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE WITH NFPA 31.3.4.5.1. |
| | NFPA 101:31.3.4.1.1 A FIRE ALARM SYSTEM IS NOT PROVIDED IN ACCORDANCE WITH NFPA 101:31.3.4.1.1. |
| | |
| OWNER: | CE10041424 1401 NE 53 ST # 106 BENITEZ, EMILIO & RIVELLI, SCOTT M RON TETREAULT |
| VIOLATIONS: | NFPA 101:31.3.4.5.1 HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE WITH NFPA 31.3.4.5.1. |
| | NFPA 101:31.3.4.1.1 A FIRE ALARM SYSTEM IS NOT PROVIDED IN ACCORDANCE WITH NFPA 101:31.3.4.1.1. |
| | |

| OWNER: | CE10041425 1401 NE 53 ST # 107 VALUE DEVELOPMENT LLC RON TETREAULT |
|--|---|
| VIOLATIONS: | NFPA 101:31.3.4.5.1 HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE WITH NFPA 31.3.4.5.1. |
| | NFPA 101:31.3.4.1.1 A FIRE ALARM SYSTEM IS NOT PROVIDED IN ACCORDANCE WITH NFPA 101:31.3.4.1.1. |
| CASE NO: CASE ADDR: OWNER: INSPECTOR: | CE10041426 1401 NE 53 ST # 108 VALUE DEVELOPMENT LLC RON TETREAULT |
| VIOLATIONS: | NFPA 101:31.3.4.5.1 HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE WITH NFPA 31.3.4.5.1. |
| | NFPA 101:31.3.4.1.1 A FIRE ALARM SYSTEM IS NOT PROVIDED IN ACCORDANCE WITH NFPA 101:31.3.4.1.1. |
| CACE NO. | |
| CASE NO: CASE ADDR: | 1401 NE 53 ST # 109 |
| | VALUE DEVELOPMENT LLC RON TETREAULT |
| VIOLATIONS: | NFPA 101:31.3.4.5.1 HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE WITH NFPA 31.3.4.5.1. |
| | NFPA 101:31.3.4.1.1 A FIRE ALARM SYSTEM IS NOT PROVIDED IN ACCORDANCE WITH NFPA 101:31.3.4.1.1. |
| | |

| | CE10041429 1401 NE 53 ST # 110 VALUE DEVELOPMENT LLC RON TETREAULT |
|-------------|---|
| VIOLATIONS: | NFPA 101:31.3.4.5.1 HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE WITH NFPA 31.3.4.5.1. |
| | NFPA 101:31.3.4.1.1 A FIRE ALARM SYSTEM IS NOT PROVIDED IN ACCORDANCE WITH NFPA 101:31.3.4.1.1. |
| OWNER: | CE10041430 1401 NE 53 ST # 111 VALUE DEVELOPMENT LLC RON TETREAULT |
| VIOLATIONS: | NFPA 101:31.3.4.5.1 HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE WITH NFPA 31.3.4.5.1. |
| | NFPA 101:31.3.4.1.1 A FIRE ALARM SYSTEM IS NOT PROVIDED IN ACCORDANCE WITH NFPA 101:31.3.4.1.1. |
| | |
| OWNER: | CE10041431 1401 NE 53 ST # 112 VALUE DEVELOPMENT LLC RON TETREAULT |
| VIOLATIONS: | NFPA 101:31.3.4.5.1 HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE WITH NFPA 31.3.4.5.1. |
| | NFPA 101:31.3.4.1.1 A FIRE ALARM SYSTEM IS NOT PROVIDED IN ACCORDANCE WITH NFPA 101:31.3.4.1.1. |
| | |

| CE10041433 1401 NE 53 ST # 201 KRALJEVICH, ROBERT J RON TETREAULT |
|---|
| NFPA 101:31.3.4.5.1 HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE WITH NFPA 31.3.4.5.1. |
| NFPA 101:31.3.4.1.1 A FIRE ALARM SYSTEM IS NOT PROVIDED IN ACCORDANCE WITH NFPA 101:31.3.4.1.1. |
| CE10041434 1401 NE 53 ST # 202 VALUE DEVELOPMENT LLC RON TETREAULT |
| NFPA 101:31.3.4.5.1 HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE WITH NFPA 31.3.4.5.1. |
| NFPA 101:31.3.4.1.1 A FIRE ALARM SYSTEM IS NOT PROVIDED IN ACCORDANCE WITH NFPA 101:31.3.4.1.1. |
| CE10041435 1401 NE 53 ST # 203 VALUE DEVELOPMENT LLC RON TETREAULT |
| NFPA 101:31.3.4.5.1 HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE WITH NFPA 31.3.4.5.1. |
| NFPA 101:31.3.4.1.1 A FIRE ALARM SYSTEM IS NOT PROVIDED IN ACCORDANCE WITH NFPA 101:31.3.4.1.1. |
| |

| | HEARING TO IMPOSE FINES |
|-------------|--|
| OWNER: | CE07120387 3400 SW 12 PL AMERICAN ONE RENTALS INC RON TETREAULT |
| VIOLATIONS: | NFPA 101 31.3.4.5.1 HARDWIRED SMOKE DETECTORS NOT INSTALLED. |
| OWNER: | CE08042322 2810 NE 60 ST EUGENE, PATRICK STEPHANIE BASS |
| VIOLATIONS: | 18-1 THE POOL AT THIS LOCATION IS FILLED WITH GREEN, STAGNANT WATER. THE POOL IN THIS CONDITION IS A BREEDING PLACE FOR MOSQUITOS AND ENDANGERS THE PUBLIC HEALTH, SAFETY AND WELFARE OF THE COMMUNITY. |
| OWNER: | CE08090501 524 NW 13 AVE CIREUS, ROSAMENE ADAM FELDMAN |
| VIOLATIONS: | 9-280(b) THERE ARE SEVERAL WINDOWS/EXTERIOR DOORS, AND OPENINGS FROM MISSING AIR CONDITION UNITS ON THE PROPERTY THAT ARE IN DISREPAIR, IN THAT THEY ARE BOARDED AND IN NEED OF REPAIR/REPLACEMENT. THERE ARE SUPPORT BARS FROM SEVERAL HURRICANE SHUTTERS THAT WERE REMOVED THAT ARE IN DISREPAIR AND STILL CONNECTED TO THE EXTERIOR WALLS OF THE BUILDING. |
| | 9-280(g) THERE ARE SEVERAL LIGHT FIXTURES ON THE EXTERIOR OF THE PROPERTY THAT ARE IN DISREPAIR; SOME OF THE FIXTURES ARE MISSING, LEAVING WIRES EXPOSED. |
| | 9-306 THE EXTERIOR WALLS OF THE PROPERTY ARE IN DISREPAIR, IN THAT THERE ARE AREAS THAT HAVE DIRTY, STAINED PAINT. |
| | |

CITY OF FORT LAUDERDALE Page 30 AGENDA SPECIAL MAGISTRATE CITY COMMISSION MEETING ROOM - CITY HALL MAY 20, 2010 9:00 AM CASE NO: CE08100315 CASE ADDR: 524 NW 13 AVE CIREUS, ROSAMENE OWNER: INSPECTOR: ADAM FELDMAN VIOLATIONS: 9-329.(b) THE PROPERTY HAS BEEN BOARDED UP WITHOUT FIRST OBTAINING A CITY ISSUED BOARD-UP CERTIFICATE. _____ _____ CASE NO: CE08110538 CASE ADDR: 1625 NW 7 AVE OWNER: GAMBLE, LENORA INSPECTOR: TODD HULL VIOLATIONS: 9-280(h)(1) THE WOOD FENCE ON THIS PROPERTY IS FALLING OVER AND IN GENERAL DISREPAIR. _____ CASE NO: CE08110825 CASE ADDR: 5900 NW 9 AVE OWNER: CONWAY, W C & ELEANOR A INSPECTOR: SAL VISCUSI VIOLATIONS: 47-19.9.A.2.b. THERE IS OUTDOOR STORAGE OF GOODS AND MATERIALS ON THIS PROPERTY THAT IS NOT BEING COMPLETLY SCREENED FROM ABUTTING NON-RESIDENTIAL PROPERTY BY A WALL IN ACCORDANCE WITH THE REQUIREMENTS OF SEC. 47-19.5 OF THE U.L.D.R. SUCH A WALL SHALL BE A MINIMUM OF 6 1/2 FEET IN HEIGHT AND A MAXIMUM OF TEN FEET IN HEIGHT. IN AN INDUSTRIAL AREA, THE WALL MAY BE PERMITTED TO A MAXIMUM HEIGHT OF 15 FEET. 47-19.9.A.2.d. THE OUTDOOR STORAGE AREA, WHICH ENCOMPASSES THIS ENTIRE PROPERTY DOES NOT MEET THE REQUIRED PAVING AND DRAINING REQUIREMENTS. _____ CASE NO: CE08110829 CASE ADDR: 1313 NW 14 CT SASSON, SHAY OWNER: INSPECTOR: WANDA SAPPINGTON VIOLATIONS: 9-328(a) THIS BUILDING IS VACANT AND HAS BROKEN OR MISSING WINDOWS OR DOORS OR OTHER OPENINGS THAT ALLOW UNAUTHORIZED ACCESS TO THE INTERIOR.

| | CITY OF FORT LAUDERDALE AGENDA SPECIAL MAGISTRATE CITY COMMISSION MEETING ROOM - CITY HALL MAY 20, 2010 9:00 AM | Page | 31 |
|----------------------|--|--------|----|
| CASE ADDR: OWNER: | CE09011221 1313 NW 14 CT SASSON, SHAY WANDA SAPPINGTON | | |
| VIOLATIONS: | 9-328(b) THIS PROPERTY HAS BEEN BOARDED WITHOUT THE REQUIRED BOARDING CERTIFICATE. | | |
| OWNER: | CE09091486 1851 SE 10 AVE ASHANTI HOLDINGS LLC RON TETREAULT | | |
| VIOLATIONS: | F-21.1.3 THE SMOKE CONTROL SYSTEM HAS NOT BEEN CERTIFIED ANN A BROWARD COUNTY LICENSED TEST AND BALANCE COMPANY. | | |
| OWNER: | CE09111054 901 SW 15 AVE S & N DEVELOPMENT GROUP INC ANDRE CROSS | | |
| VIOLATIONS: | 18-7(b) THE PROPERTY IS BOARDED WITHOUT FIRST OBTAINING A BOARD-UP CERTIFICATE. | | |
| OWNER: | CE09120531 1407 SW 24 CT HERRRON, JAMES C RON TETREAULT | | |
| VIOLATIONS: | NFPA 101:31.3.4.5.1 HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCC WITH NFPA 31.3.4.5.1. | RDANCE | |
| OWNER: | CE09120532 1431 SW 24 CT PIRITA APARTMENTS INC RON TETREAULT | | |
| VIOLATIONS: | NFPA 101:31.3.4.5.1 HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCC WITH NFPA 31.3.4.5.1. | RDANCE | |

| CASE NO: CASE ADDR: | CE09120533 1433 SW 24 CT | |
|------------------------|--|----|
| OWNER: INSPECTOR: | PIRITA APARTMENTS INC RON TETREAULT | 7) |

VIOLATIONS: NFPA 101:31.3.4.5.1 HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE WITH NFPA 31.3.4.5.1.

CASE NO: CE09120655 CASE ADDR: 1460 SW 24 CT OWNER: SMITH, PIERRE-PAUL INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 1:13.6.6.8.3.1 THE FIRE EXTINGUISHER(S) HAS/HAVE NOT BEEN SERVICED AND TAGGED BY A STATE LICENSED COMPANY WITHIN THE PAST 12 MONTHS.

> NFPA 101:31.3.4.5.1 HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE WITH NFPA 31.3.4.5.1.

| CASE NO: | CE09120682 |
|------------|--------------------------------------|
| CASE ADDR: | 621 SE 5 AVE |
| OWNER: | ERIC JOHNSON TR JOHNSON, ERIC TRSTEE |
| INSPECTOR: | RON TETREAULT |

VIOLATIONS: NFPA 1:13.6.6.8.3.1 THE FIRE EXTINGUISHER(S) HAS/HAVE NOT BEEN SERVICED AND TAGGED BY A STATE LICENSED COMPANY WITHIN THE PAST 12 MONTHS.

> NFPA 101:31.3.4.5.1 HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE WITH NFPA 31.3.4.5.1.

MO Sec. 9-313. ADDRESS IS NOT POSTED ACCORDING TO THE CODE.

Page 32

AGENDA SPECIAL MAGISTRATE CITY COMMISSION MEETING ROOM - CITY HALL MAY 20, 2010 9:00 AM

CITY OF FORT LAUDERDALE

- CASE NO: CE10020404 CASE ADDR: 1721 NW 6 AVE OWNER: BURGOS, JIMMY INSPECTOR: TODD HULL
- VIOLATIONS: 18-4(c) THERE IS AN UNLICENSED/INOPERABLE MAZDA RX-7 BEING STORED ON THIS PROPERTY.

- CASE NO: CE09120688
- CASE ADDR: 3000 NW 59 ST OWNER: WHITTINGTON, DON
- WORLD JET, INC
- INSPECTOR: RON TETREAULT
- VIOLATIONS: NFPA 101:7.2.1.4.2 THE EXIT DOORS DO NOT SWING IN THE DIRECTION OF EGRESS.
 - NFPA 101:7.2.1.8.1 SELF-CLOSING OR AUTOMATIC-CLOSING DOOR(S) DON'T SELF CLOSE AND LATCH.
 - NFPA 101:7.9.2.1 THE EMERGENCY LIGHT DOES NOT ILLUMINATE AS DESIGNED.
 - NFPA 1:10.4.4 THE FIRE ALARM SYSTEM HAS NOT BEEN TESTED, INSPECTED AND/OR TAGGED IN ACCORDANCE WITH THE CODE.
 - NFPA 1:11.1.5 EXTENSION CORDS ARE BEING USED AS A SUBSTITUTE FOR PERMANENT WIRING.
 - NFPA 1:13.6.3.6 THE FIRE EXTINGUISHER(S) ARE NOT VISIBLE AND/OR OBSTRUCTED.
 - NFPA 1:13.6.6.8.3.1 THE FIRE EXTINGUISHER(S) HAS/HAVE NOT BEEN SERVICED AND TAGGED BY A STATE LICENSED COMPANY WITHIN THE PAST 12 MONTHS.
 - NFPA 1:14.4.1 THE PATH OF EGRESS IS OBSTRUCTED / BLOCKED.

| OWNER: | 1010 NW 51 CT 1011 LLC SAL VISCUSI |
|-------------|--|
| | THE DUMPSTER AND ENCLOSURE AREA. |
| OWNER: | CE09121429 3315 SW 15 AVE EDGEWATER LLC RON TETREAULT |
| VIOLATIONS: | NFPA 1:1.7.6.2 THE ELECTRICAL METER ROOM IS BEING USED FOR STORAGE. |
| | NFPA 1:13.6.6.8.3.1 THE FIRE EXTINGUISHER(S) HAS/HAVE NOT BEEN SERVICED AND TAGGED BY A STATE LICENSED COMPANY WITHIN THE PAST 12 MONTHS. |
| | NFPA 101:31.3.4.5.1 HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE WITH NFPA 31.3.4.5.1. |
| | |
| OWNER: | CE09121440 1625 SW 30 ST MOLINA, OSCAR S CARCAMO, YVONNE RON TETREAULT |
| VIOLATIONS: | NFPA 1:13.6.1.2 FIRE EXTINGUISHER(S) IS/ARE NOT PROVIDED IN ACCORDANCE WITH THE CODE. |
| | NFPA 1:13.6.3.10 THE FIRE EXTINGUISHER(S) IS/ARE NOT MOUNTED ACCORDING TO THE CODE. |
| | |

CITY OF FORT LAUDERDALE AGENDA SPECIAL MAGISTRATE CITY COMMISSION MEETING ROOM - CITY HALL MAY 20, 2010 9:00 AM

- CASE NO: CE10011228 CASE ADDR: 1200 N FEDERAL HWY OWNER: NORTH MIA INVESTMENTS LLC INSPECTOR: RON TETREAULT
- VIOLATIONS: 69A-46.041 THE FIRE PROTECTION SYSTEM IS NOT TAGGED IN ACCORDANCE WITH THE CODE.

NFPA 1:13.3.1.1 THE FIRE SPRINKLER SYSTEMS IS IN NEED OF SERVICE.

CITATION CASES

CASE NO: CT10040965 CASE ADDR: 3251 SW 1 TER OWNER: FANTOM REALTY LLC INSPECTOR: BARBARA UROW

VIOLATIONS: 9-304(b) THERE ARE VEHICLES AND TRAILERS PARKED ON THE GRASS AT THIS BUSINESS. DUE TO THE RECURRING NATURE OF THE VIOLATION THIS CASE WILL BE PRESENTED TO A SPECIAL MAGISTRATE REGARDLESS IF THE PROPERTY COMES INTO COMPLIANCE BEFORE THE HEARING.

| | RETURN HEARING (OLD BUSINESS) | |
|----------------------|---|--|
| CASE NO: | | |
| CASE ADDR: OWNER: | 819 NW 3 ST NEW MOUNT OLIVE MISSIONARY BAPTIST CHURCH INC | |
| | RON TETREAULT | |
| VIOLATIONS: | NFPA 101:31.3.4.1.1 A FIRE ALARM SYSTEM IS NOT PROVIDED IN ACCORDANCE WITH NFPA 101:31.3.4.1.1. | |
| | NFPA 101:31.3.4.5.1 HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE WITH NFPA 31.3.4.5.1. | |
| | NFPA 1:19.1.2 COMBUSTIBLE WASTE MATERIAL HAS ACCUMULATED IN A MANNER THAT CREATES A FIRE HAZARD TO LIFE OR PROPERTY. | |
| CASE NO: | CE09111019 | |
| | 247 SW 21 ST | |
| OWNER: | WELLS FARGO BANK TRSTEE % WILSHIRE CREDIT CORP | |
| INSPECTOR: | BARBARA UROW | |
| VIOLATIONS: | 18-7(b) THIS PROPERTY HAS BEEN BOARDED WITHOUT THE REQUIRED BOARD-UP CERTIFICATE. | |
| | | |

| INSPECTOR | PAGES |
|--------------------------|--|
| Bass, Stephanie | 1, 29 |
| Campbell, Mark | 3 |
| Champagne, Leonard | |
| Clements, Thomas | |
| Crase, Lynda | |
| Cross, Andre | 10, 11, 31 |
| Davis, Aretha | 4 |
| DelRio, Alejandro | |
| Eaton, Dick | 9, 10 |
| Feldman, Adam | 29, 30 |
| Gottlieb, Ingrid | 6, 7, 8, 35 |
| Hull, Todd | 2, 30, 33 |
| Lauridsen, Karl | |
| Nigg, Linda | |
| Patterson, Bridget | |
| Quintero, Wilson | 2 |
| Rich, Mary | 1 |
| Roque, Maria | |
| Sappington, Wanda | 30, 31, 35 |
| Snow, Bill | |
| Sotolongo, Mario | |
| Tetreault, Ron | 13,14,15,16,17,18,19,20,21,22,23,24,25,26,27,28,29,31,32, 33,34,36,37 |
| Thime, Ursula | 11, 12,13 |
| Urow, Barbara | 1, 36, 37 |
| Viscusi, Salvatore | 5, 6, 30, 34 |
| New Cases: | Pages: 1 - 28 |
| Citation Cases: | Page: 36 |
| Hearing to Impose Fines: | Pages: 29 - 36 |
| Return Hearing: | Page: 37 |