

SPECIAL MAGISTRATE HEARING AGENDA

December 16, 2010

9 A.M.

COMMISSION MEETING ROOM CITY HALL

100 N ANDREWS AVE

MEAH TELL
PRESIDING

CITY OF FORT LAUDERDALE

AGENDA

SPECIAL MAGISTRATE

CITY COMMISSION MEETING ROOM - CITY HALL DECEMBER 16, 2010 9:00 AM

NEW BUSINESS

CASE NO: CE10090438 CASE ADDR: 812 SW 8 AVE

OWNER: CHASE HOME FINANCE LLC

INSPECTOR: WILLIAM SNOW

VIOLATIONS: 9-308(b)

THE ROOF IS NOT MAINTAINED IN A CLEAN CONDITION.
THERE ARE ONE OR MORE TARPS ON THE ROOF. THE
TARP(S) ARE NOT A PERMANENT PART OF THE BUILDING
OR A FUNCTIONAL ELEMENT OF ITS MECHANICAL OR

ELECTRICAL SYSTEM.

CASE NO: CE10110060 CASE ADDR: 2012 S MIAMI RD

OWNER: MIAMI ROAD PARTNERS LLC

INSPECTOR: ARETHA DAVIS

VIOLATIONS: 9-279(e)

HOT WATER IS NOT BEING PROPERLY SUPPLIED TO THE KITCHEN AND BATHROOM SINKS OF THIS OCCUPIED RESIDENTIAL DUPLEX AS THE HEATING FACILITIES ARE NOT PROPERLY CONNECTED TO ELECTRIC SERVICE AND ARE NOT MAINTAINED IN SAFE CONDITION BEING THAT ELECTRIC POWER IS SUPPLIED BY AN ILLEGAL

CONNECTION TO FPL POWER.

9-280(b)

THERE IS AT LEAST ONE BROKEN WINDOW PANE ON THIS OCCUPIED RESIDENTIAL PROPERTY. THE FASCIA AND SOFFITS HAVE AREAS OF ROTTING AND DECAYING WOOD.

9-280(g)

THE ELECTRICAL WIRING AT THIS PROPERTY IS NOT IN GOOD, SAFE WORKING CONDITION AS THERE IS AN ILLEGAL CONNECTION TO FPL POWER. ILLEGAL TAMPERING WITH FPL POWER SOURCE AND ILLEGAL ELECTRICAL WIRING IS CONSIDERED TO BE A THREAT TO THE HEALTH, SAFETY, AND WELFARE OF THE COMMUNITY DUE TO THE POTENTIAL FIRE HAZARD.

9-306

EXTERIOR WALLS, FASCIA AND SOFFIT ARE DIRTY AND UNATTRACTIVE.

SPECIAL MAGISTRATE

CITY COMMISSION MEETING ROOM - CITY HALL DECEMBER 16, 2010

9:00 AM

CASE NO: CE10101669

CASE ADDR: 1351 HOLLY HEIGHTS DR

DEUTSCHE BANK NATL TR CO TRSTEE

% ALVAREZ, BRIAN ROBERT

INSPECTOR: ANDRE CROSS

VIOLATIONS: 18-12(a)

THE PROPERTY HAS BECOME OVERGROWN IN AREAS AND HAS

NOT BEEN MAINTAINED.

CASE NO: CE10110214 CASE ADDR: 301 NW 8 ST

KEYSTONE HALLS INC OWNER:

INSPECTOR: ANDRE CROSS

VIOLATIONS: 18-12(a)

THERE IS TRASH STORED ON THE PROPERTY INCLUDING

BUT, NOT LIMITED TO AN OLD COUCH.

CASE NO: CE10060952

CASE ADDR: 625 N FT LAUD BEACH BLVD

OWNER: MALLICK, NISHI INSPECTOR: MARIO SOTOLONGO

VIOLATIONS: 9-306

THE EXTERIOR OF THE BUILDING IS NOT PROPERLY MAINTAINED, IN THAT A SECTION OF THE THIRD FLOOR WINDOW CONCRETE OVERHANG HAS BECOME DETACHED FROM

THE FACADE, LEAVING THE STEEL REBAR

EXPOSED.

CASE NO: CE10110332

CASE ADDR: 4040 GALT OCEAN DR # L1

OWNER: TALERICO FAMILY LIMITED PARTNERSHIP

INSPECTOR: MARIO SOTOLONGO

VIOLATIONS: 18-12(a)

THERE IS ACCUMULATION OF RUBBISH, TRASH AND DEBRIS ON THE SOUTH SIDE OF THE PROPERTY, INCLUDING BUT NOT LIMITED TO, CORRUGATED STEEL SHEETS, ALUMINUM

AND STEEL CLIPPINGS, WOOD AND LUMBER.

SPECIAL MAGISTRATE

CITY COMMISSION MEETING ROOM - CITY HALL

DECEMBER 16, 2010

9:00 AM

CASE NO: CE10101531 CASE ADDR: 2832 NE 35 ST

OWNER: PRESERVATION LAND TR

NOVOA, ELIZABETH TRSTEE ETAL

INSPECTOR: URSULA THIME

VIOLATIONS: 18-12(a)

THE PROPERTY HAS BECOME OVERGROWN, INCLUDING THE

SWALE AND HAS NOT BEEN MAINTAINED.

CASE NO: CE10110199

CASE ADDR: 4100 N FEDERAL HWY OWNER: 4100 FEDERAL LLC INSPECTOR: URSULA THIME

VIOLATIONS: 9-306-

THERE IS GRAFFITI PAINTED ON THE EXTERIOR WALLS OF

THIS BUILDING.

CASE NO: CE10110215 CASE ADDR: 501 NW 1 AVE

OWNER: FLAGLER WAREHOUSE I LLC % DOUG MCCRAW

INSPECTOR: DICK EATON

VIOLATIONS: 18-12(a)

THERE IS A PILE OF LOOSE TRASH AND DEBRIS LOCATED

AT THE REAR OF THIS PROPERTY.

CASE NO: CE10110630 CASE ADDR: 921 NE 16 TER

LE JARDIN AT VICTORIA PARK LLC OWNER:

INSPECTOR: DICK EATON

VIOLATIONS: 9-279(e)

THERE IS NO POWER TO THIS OCCUPIED UNIT WHICH DOES NOT ALLOW FOR HOT WATER SERVICE TO THE TENANTS.

9-279(f)

THERE IS NO CITY WATER SERVICE TO THIS OCCUPIED

PROPERTY.

CASE NO: CE10090420 CASE ADDR: 519 SW 18 ST

WILLIS, BRIAN KEITH & CYNTHIA OWNER:

INSPECTOR: MARK CAMPBELL

VIOLATIONS: 47-34.1.A.1.

THERE IS A LARGE BLUE BOAT ON JACKS AND SUPPORTS

BEING STORED ON THE DRIVEWAY THIS PROPERTY.

SPECIAL MAGISTRATE

CITY COMMISSION MEETING ROOM - CITY HALL DECEMBER 16, 2010

9:00 AM

CASE NO: CE10051325 CASE ADDR: 3115 SW 2 AVE

OWNER: SLOMAN, HOWARD S JR

INSPECTOR: MARK CAMPBELL

VIOLATIONS: 47-19.9

WITHDRAWN.

47-34.1.A.1.

THERE IS OUTDOOR STORAGE MISCELLANEOUS ITEMS ON

THIS INDUSTRIAL ZONED PROPERTY WITHOUT THE

REQUIRED BUFFERWALL. PER ULDR TABLE 47-7.10, THIS

IS AN UNPERMITTED LAND USE.

9-280(b) COMPLIED.

CASE NO: CE10092115
CASE ADDR: 1725 SW 30 ST
OWNER: STRUNK, MAX
INSPECTOR: MARK CAMPBELL

VIOLATIONS: 18-11(b)

THE POOL ON THIS VACANT PROPERTY HAS GREEN

STAGNANT WATER, WHICH IS OR MAY REASONABLY BECOME INFESTED WITH MOSOUITOS AND IS ENDANGERING THE

PUBLIC HEALTH, SAFETY AND WELFARE.

CASE NO: CE10091873
CASE ADDR: 1407 NW 13 CT
OWNER: SHERMAN, AMY
INSPECTOR: SAL VISCUSI

VIOLATIONS: 9-280(b)

THE ROOF ON THE HOME ON THIS VACANT/ UNOCCUPIED PROPERTY IS IN DISREPAIR AND IS PARTIALY COVERED

WITH THE REMNANTS OF

A BLUE TARP.

CASE NO: CE10092024 CASE ADDR: 1431 NW 20 ST

OWNER: MAURICE, FRANKEL & MAURICE, LEXILIA

INSPECTOR: SAL VISCUSI

VIOLATIONS: 9-280(g)

THE AIR CONDITIONING SYSTEM AND ALL COMPONENTS RELATED TO THE AIR CONDITIONING SYSTEM IN THE RESIDENCE ON THIS PROPERTY ARE NOT WORKING

PROPERLY OR ARE IN DISREPAIR.

.....

SPECIAL MAGISTRATE

CITY COMMISSION MEETING ROOM - CITY HALL DECEMBER 16, 2010

9:00 AM

CASE NO: CE10101673 CASE ADDR: 2111 NW 28 TER

FERTIL, BERLANDE FERTIL, RIBERT & JOSEPH, TERESRE I OWNER:

INSPECTOR: SAL VISCUSI

VIOLATIONS: 18-12(a)

THERE IS LAWN OVERGROWTH PRESENT ON THIS VACANT/ UNOCCUPIED PROPERTY AND THE PROPERTY IS LITTERED

WITH TRASH/RUBBISH/ DEBRIS

CASE NO: CE10100435 CASE ADDR: 1470 NW 20 ST

OWNER: ETIENNE, JEAN ST JEAN, GEORGES

INSPECTOR: SAL VISCUSI

VIOLATIONS: 9-280(b)

THERE ARE SEVERAL BUILIDING COMPONENTS ON THE MULTI-FAMILY DWELLING ON THIS PROPERTY THAT ARE NOT BEING MAINTAINED AND OR ARE IN DISREPAIR. THOSE AREAS IN DISREPAIR ARE AS FOLLOWS: THE FRONT WINDOW IN UNIT B HAS BROKEN/ MISSING GLASS, THE SCREEN ENCLOSURE IN THE REAR YARD HAS MISSING/ TORN SCREENS AND A DAMAGED PLASTIC ROOF COVERING

THAT CONSISTS OF MULTIPLE PIECES THAT ARE LOOSE OR

FALLING OFF.

9-280(f)

THE POOL PUMP AND ALL MECHANICAL COMPONENTS

RELATED TO THE POOL PUMP FOR THE POOL IN THE REAR YARD ON THIS PROPERTY ARE MISSING OR ARE IN DISREPAIR.

CASE NO: CE10101747 CASE ADDR: 1040 SW 30 AVE

OWNER: LARIVIERE, ALFRED & PEREZ, AUGUST

INSPECTOR: STEPHANIE BASS

VIOLATIONS: 18-12(a)

THE LAWN AT THIS PROPERTY HAS BECOME OVERGROWN AND

IS NOT BEING MAINTAINED.

CASE NO: CE10100384

CASE ADDR: 3420 BERKELEY BLVD SINGH, DULARIE OWNER: INSPECTOR: STEPHANIE BASS

VIOLATIONS: 18-12(a)

THE LAWN AT THIS PROPERTY HAS BECOME OVERGROWN AND

IS NOT BEING MAINTAINED.

CITY OF FORT LAUDERDALE

AGENDA

SPECIAL MAGISTRATE

CITY COMMISSION MEETING ROOM - CITY HALL DECEMBER 16, 2010

9:00 AM

CASE NO: CE10101293 CASE ADDR: 2751 SW 4 ST

OWNER: LCWH LLC C/O JEFFREY J GALVAN P A

INSPECTOR: STEPHANIE BASS

VIOLATIONS: 18-12(a)

THE LAWN AT THIS PROPERTY HAS BECOME OVERGROWN AND

IS NOT BEING MAINTAINED.

CASE NO: CE10110057 CASE ADDR: 1041 SW 22 AVE

OWNER: US BANK NATIONAL ASSN TRSTEE

% CITI RESIDENTIAL LENDING INC

INSPECTOR: STEPHANIE BASS

VIOLATIONS: 18-11(b)

THE POOL AT THIS VACANT PROPERTY IS FILLED WITH GREEN STAGNANT WATER, THE POOL IN THIS CONDITION

ENDANGERS THE HEALTH, SAFETY AND WELFARE OF THE COMMUNITY.

CASE NO: CE10101462 CASE ADDR: 2691 NE 59 ST

OWNER: VILLA BAYVIEW PROPERTIES LLC

INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 101:31.3.4.5.1

HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE

WITH NFPA 31.3.4.5.1.

NFPA 1:1.7.6.2

THE ELECTRICAL METER ROOM IS BEING USED FOR STORAGE.

CASE NO: CE10111389

CASE ADDR: 623 NW 9 AVE
OWNER: CITIMORTGAGE INC

% LAW OFFICES OF DAVID J STERN PA

INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 101:31.3.4.5.1

HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE

WITH NFPA 31.3.4.5.1.

CASE NO: CE10111400
CASE ADDR: 4910 NE 18 TER
OWNER: ERCAN, EYYUP
INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 101:31.3.4.5.1

HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE

WITH NFPA 31.3.4.5.1.

AGENDA

SPECIAL MAGISTRATE

CITY COMMISSION MEETING ROOM - CITY HALL DECEMBER 16, 2010

9:00 AM

CASE NO: CE10111394 CASE ADDR: 700 NW 57 PL

OWNER: ROYAL PALM BEACH INVESTMENTS INC

INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 101:7.9.2.1

THE EMERGENCY LIGHT DOES NOT ILLUMINATE AS DESIGNED.

NFPA 101:7.10.5.2.1

THE EXIT SIGN DOES NOT ILLUMINATE AS DESIGNED.

NFPA 1:13.6.6.8.3.1

THE FIRE EXTINGUISHER(S) HAS/HAVE NOT BEEN SERVICED AND

TAGGED BY A STATE LICENSED COMPANY WITHIN THE PAST 12 MONTHS.

CASE NO: CE10111402 CASE ADDR: 1027 NW 9 AVE

OWNER: CROWN LIQUORS OF BROWARD INC

INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 101:7.9.2.1

THE EMERGENCY LIGHT DOES NOT ILLUMINATE AS DESIGNED.

NFPA 101:7.10.5.2.1

THE EXIT SIGN DOES NOT ILLUMINATE AS DESIGNED.

CASE NO: CE10111403 CASE ADDR: 1048 NW 10 AVE

OWNER: CROWN LIQUORS OF BROWARD INC

INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 101:7.2.1.5.2

LOCKS PROVIDED IN THE MEANS OF EGRESS REQUIRE A KEY, TOOL OR

SPECIAL KNOWLEDGE OR EFFORT FOR OPERATION FROM THE EGRESS

SIDE.

.-----

CASE NO: CE10111404 CASE ADDR: 1024 NW 10 AVE

OWNER: CROWN LIQUORS OF BROWARD INC

INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 101:7.2.1.5.2

LOCKS PROVIDED IN THE MEANS OF EGRESS REQUIRE A KEY, TOOL OR

SPECIAL KNOWLEDGE OR EFFORT FOR OPERATION FROM THE EGRESS

SIDE.

SPECIAL MAGISTRATE

CITY COMMISSION MEETING ROOM - CITY HALL DECEMBER 16, 2010

9:00 AM

CASE NO: CE10111405 CASE ADDR: 1018 NW 10 AVE

CROWN LIQUORS OF BROWARD INC OWNER:

INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 101:7.10.5.2.1

THE EXIT SIGN DOES NOT ILLUMINATE AS DESIGNED.

NFPA 101:7.9.2.1

THE EMERGENCY LIGHT DOES NOT ILLUMINATE AS DESIGNED.

NFPA 1:13.6.6.8.3.1

THE FIRE EXTINGUISHER(S) HAS/HAVE NOT BEEN SERVICED AND TAGGED BY A STATE LICENSED COMPANY WITHIN THE PAST 12 MONTHS.

NFPA 1:13.6.6.7.1

A K CLASS FIRE EXTINGUISHER IS NOT PROVIDED.

NFPA 1:11.1.2

BLANKS ARE MISSING IN THE ELECTRICAL PANEL CAUSING ELECTRICAL CIRCUITS TO BE EXPOSED.

NFPA 1:50.5.2.1

THE HOOD FIRE SUPPRESSION SYSTEM HAS NOT BEEN INSPECTED AND TAGGED BY A STATE LICENSED COMPANY WITHIN THE PAST 6 MONTHS.

NFPA 1:50.5.4.1

UPON INSPECTION, THE EXHAUST SYSTEM HAS BEEN FOUND TO BE CONTAMINATED WITH DEPOSITS FROM GREASE-LADEN VAPORS.

CASE NO: CE10111407 CASE ADDR: 1014 NW 10 AVE

OWNER: CROWN LIQUORS OF BROWARD INC

INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 101:7.2.1.5.2

LOCKS PROVIDED IN THE MEANS OF EGRESS REQUIRE A KEY, TOOL OR SPECIAL KNOWLEDGE OR EFFORT FOR OPERATION FROM THE EGRESS

SIDE.

CASE NO: CE10111412

CASE ADDR: 1510 SE 17 ST # 200A HEATON GROUP LLC OWNER: INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 101:7.10.5.2.1

THE EXIT SIGN DOES NOT ILLUMINATE AS DESIGNED.

SPECIAL MAGISTRATE

CITY COMMISSION MEETING ROOM - CITY HALL DECEMBER 16, 2010

9:00 AM

CASE NO: CE10111411 CASE ADDR: 1510 SE 17 ST

OWNER: MARINE EXEC CENTER CONDO ASSN INC

INSPECTOR: RON TETREAULT

VIOLATIONS: MO Sec. 9-313.

ADDRESS IS NOT POSTED ACCORDING TO THE CODE.

MO 13-64

KNOX BOX IS NOT PROVIDED WITH AT LEAST ONE(1) SET OF

FIREFIGHTER SERVICE KEYS FOR THE ELEVATOR(S)

NFPA 1:18.3.4.3

FDC SIGN CONSISTENT WITH NFPA 1:18.3.4.3 IS NOT PROVIDED.

NFPA 72:5.4.5

ALARM DEVICE NEEDS TO BE INSTALLED.

NFPA 101:7.9.2.1

THE EMERGENCY LIGHT DOES NOT ILLUMINATE AS DESIGNED.

CASE NO: CE10111409 CASE ADDR: 5811 NE 14 RD

OWNER: ZAPPIN, DONNA M & LACKNER, EDMUND K

INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 101:31.3.4.5.1

HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE

WITH NFPA 31.3.4.5.1.

NFPA 1:1.7.6.2

THE ELECTRICAL METER ROOM IS BEING USED FOR STORAGE.

MO SEC. 9-313.

ADDRESS IS NOT POSTED ACCORDING TO THE CODE.

.-----

CASE NO: CE10111413

CASE ADDR: 1470 N DIXIE HWY # 01

OWNER: WARD, LOY E JR INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 101:31.3.4.5.1

HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE

WITH NFPA 31.3.4.5.1.

SPECIAL MAGISTRATE

CITY COMMISSION MEETING ROOM - CITY HALL DECEMBER 16, 2010

9:00 AM

CASE NO: CE10111416

CASE ADDR: 1470 N DIXIE HWY # 02 1470 DIXIE LLC % KRONICK OWNER:

INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 101:31.3.4.5.1

HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE

WITH NFPA 31.3.4.5.1.

CASE NO: CE10111418

CASE ADDR: 1470 N DIXIE HWY # 03

OWNER: PATEL, BHAVESH B & PATEL, AMITA B

INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 101:31.3.4.5.1

HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE

WITH NFPA 31.3.4.5.1.

CASE NO: CE10111420

CASE ADDR: 1470 N DIXIE HWY # 04

36170 REALTY LTD % MICHAEL KATZ OWNER:

INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 101:31.3.4.5.1

HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE

WITH NFPA 31.3.4.5.1.

CE10111421 CASE NO:

CASE ADDR: 1470 N DIXIE HWY # 05 OWNER: STEVENSON, SUZANNE INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 101:31.3.4.5.1

HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE

WITH NFPA 31.3.4.5.1.

CASE NO: CE10111422

CASE ADDR: 1470 N DIXIE HWY # 06 1470 DIXIE LLC % KRONICK OWNER:

INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 101:31.3.4.5.1

HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE

WITH NFPA 31.3.4.5.1.

SPECIAL MAGISTRATE

CITY COMMISSION MEETING ROOM - CITY HALL DECEMBER 16, 2010

9:00 AM

CASE NO: CE10111423

CASE ADDR: 1470 N DIXIE HWY # 07 OWNER: 1470 DIXIE LLC % KRONICK

INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 101:31.3.4.5.1

HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE

WITH NFPA 31.3.4.5.1.

CASE NO: CE10111424

CASE ADDR: 1470 N DIXIE HWY # 08

OWNER: CAMPBELL, DAVID W WEBB, TIMOTHY G

INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 101:31.3.4.5.1

HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE

WITH NFPA 31.3.4.5.1.

CASE NO: CE10111426

CASE ADDR: 1470 N DIXIE HWY # 09

OWNER: TRACY, JAMES A & STOLFA, TODD A

INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 101:31.3.4.5.1

HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE

WITH NFPA 31.3.4.5.1.

CASE NO: CE10111427

CASE ADDR: 1470 N DIXIE HWY # 10

OWNER: PEREZ, LAWRENCE & ZAWOT, EDWARD

INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 101:31.3.4.5.1

HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE

WITH NFPA 31.3.4.5.1.

CASE NO: CE10111428

CASE ADDR: 1470 N DIXIE HWY # 11

OWNER: BATTIGE, HOLLY D
INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 101:31.3.4.5.1

HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE

WITH NFPA 31.3.4.5.1.

AGENDA

SPECIAL MAGISTRATE

CITY COMMISSION MEETING ROOM - CITY HALL DECEMBER 16, 2010

9:00 AM

CASE NO: CE10111429

CASE ADDR: 1470 N DIXIE HWY # 12

OWNER: CROSS, A J
INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 101:31.3.4.5.1

HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE

WITH NFPA 31.3.4.5.1.

CASE NO: CE10111430

CASE ADDR: 1470 N DIXIE HWY # 13
OWNER: PRG CAPITAL FL LLC

INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 101:31.3.4.5.1

HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE

WITH NFPA 31.3.4.5.1.

CASE NO: CE10111432

CASE ADDR: 1470 N DIXIE HWY # 14

OWNER: ROBERT W FRANCESKINO REV LIV TR ROB

INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 101:31.3.4.5.1

HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE

WITH NFPA 31.3.4.5.1.

CASE NO: CE10111433

CASE ADDR: 1470 N DIXIE HWY # 15 OWNER: STEVENSON, KENNETH J

INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 101:31.3.4.5.1

HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE

WITH NFPA 31.3.4.5.1.

CASE NO: CE10111434

CASE ADDR: 1470 N DIXIE HWY # 16

OWNER: KBS FLORIDA III TR SHETH, KETAN TRST

INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 101:31.3.4.5.1

HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE

WITH NFPA 31.3.4.5.1.

AGENDA

SPECIAL MAGISTRATE

CITY COMMISSION MEETING ROOM - CITY HALL DECEMBER 16, 2010

9:00 AM

CASE NO: CE10111435

CASE ADDR: 1470 N DIXIE HWY # 17

OWNER: RICHTER, ROBERT & STARR, DANIEL

INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 101:31.3.4.5.1

HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE

WITH NFPA 31.3.4.5.1.

CASE NO: CE10111436

CASE ADDR: 1470 N DIXIE HWY # 18

OWNER: STUART, STEVEN W INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 101:31.3.4.5.1

HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE

WITH NFPA 31.3.4.5.1.

CASE NO: CE10111437

CASE ADDR: 1470 N DIXIE HWY # 19 OWNER: 1470 DIXIE LLC % KRONICK

INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 101:31.3.4.5.1

HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE

WITH NFPA 31.3.4.5.1.

CASE NO: CE10111439

CASE ADDR: 1470 N DIXIE HWY # 20 OWNER: 1470 DIXIE LLC % KRONICK

INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 101:31.3.4.5.1

HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE

WITH NFPA 31.3.4.5.1.

CASE NO: CE10111440

CASE ADDR: 1470 N DIXIE HWY # 21

OWNER: LENNON, DONNA & SILVERMAN, DENISE

INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 101:31.3.4.5.1

HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE

WITH NFPA 31.3.4.5.1.

CITY OF FORT LAUDERDALE

Page 14

AGENDA

SPECIAL MAGISTRATE

CITY COMMISSION MEETING ROOM - CITY HALL DECEMBER 16, 2010

9:00 AM

CASE NO: CE10111441

CASE ADDR: 1470 N DIXIE HWY # 22 TUTTLE, JONATHAN E OWNER:

INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 101:31.3.4.5.1

HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE

WITH NFPA 31.3.4.5.1.

CASE NO: CE10111442 CASE ADDR: 1470 N DIXIE HWY # 23

OWNER: WATTERS, HARRY A INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 101:31.3.4.5.1

HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE

WITH NFPA 31.3.4.5.1.

SPECIAL MAGISTRATE

CITY COMMISSION MEETING ROOM - CITY HALL DECEMBER 16, 2010

9:00 AM

MASSEY HEARING SCHEDULED

CASE NO: CE10082107
CASE ADDR: 2790 SW 2 ST
OWNER: BROWNING, RANDALL
INSPECTOR: STEPHANIE BASS

VIOLATIONS: 18-12(a)

THE LAWN AT THIS PROPERTY HAS BECOME OVERGROWN AND

IS NOT BEING MAINTAINED.

CASE NO: CE10091499

CASE ADDR: 500 N FEDERAL HWY

OWNER: 5 STREET FTL PARTNERS LLC

INSPECTOR: DICK EATON

VIOLATIONS: 9-306-

THERE ARE SEVERAL AREAS OF GRAFFITI SPRAYED ON THE

EXTERIOR OF THIS VACANT BUILDING.

CASE NO: CE10091501

CASE ADDR: 490 N FEDERAL HWY

OWNER: 5 STREET FTL PARTNERS LLC

INSPECTOR: DICK EATON

VIOLATIONS: 9-306-

THERE ARE A COUPLE AREAS OF GRAFFIT1 SPRAYED ON THE REAR OF THE STRUCTURE ON THIS VACANT LOT.

CASE NO: CE10090616 CASE ADDR: 2764 NE 33 ST

OWNER: CUNNINGHAM, BERRIS JR CUNNINGHAM, ROB

INSPECTOR: URSULA THIME

VIOLATIONS: 9-305(a)

OVERGROWN FICUS HEDGE IS ENCROACHING ONTO PUBLIC SIDEWALK, HINDERING THE SAFE AND CONVENIENT

PASSAGE OF PEDESTRIANS ON THE SIDEWALK.

SPECIAL MAGISTRATE

CITY COMMISSION MEETING ROOM - CITY HALL DECEMBER 16, 2010

9:00 AM

CASE NO: CE07120555 CASE ADDR: 3316 NE 38 ST

COHEN, LAWRENCE E & BARBARA F OWNER:

INSPECTOR: URSULA THIME

VIOLATIONS: 9-278(e)

THE STORM SHUTTERS ARE CLOSED, COVERING WINDOWS

AND DOORS OF THE HOUSE.

9-280(b)

THE ROOF OVER THE HOUSE IS IN DISREPAIR. ALL THE

ROOF TILES ARE MISSING.

9-280(h) WITHDRAWN

9-306

THE EXTERIOR WALLS OF THE HOUSE ARE IN NEED OF PAINT. THERE ARE AREAS OF STAINED, PEELING AND

MISSING PAINT.

CASE NO: CE08051427 CASE ADDR: 2601 ACACIA CT

OWNER: WILLIAMS, CAROLYN L

INSPECTOR: URSULA THIME

VIOLATIONS: 18-27(a)

THE LANDSCAPE AT THIS PROPERTY IS NOT MAINTAINED.

PLANTS AND YARD ARE OVERGROWN.

9-305(a)

THE HEDGE ON THIS PROPERTY IS ENCROACHING UPON THE PUBLIC SIDEWALK HINDERING THE PEDESTRIAN MOVEMENT.

9-306

THE EXTERIOR BUILDING WALLS ARE NOT MAINTAINED. GARAGE DOORS IN THE REAR AND DOORS HAVE PEELING PAINT. THE WALLS IN THE HOUSE ARE DIRTY AND

MILDEW STAINED.

CASE NO: CE10062120 CASE ADDR: 1444 NW 8 AVE

CWABS INC % COUNTRYWIDE HOME LOANS OWNER:

INSPECTOR: BARBARA UROW

VIOLATIONS: 47-20.20.H.

THE PARKING LOT ON THIS RENTAL PROPERTY IS NOT BEING MAINTAINED. THERE ARE OIL/DIRT STAINS,

ASPHALT CRACKS AND THE WHEELSTOPS ARE NOT SECURED.

SPECIAL MAGISTRATE

CITY COMMISSION MEETING ROOM - CITY HALL DECEMBER 16, 2010

9:00 AM

CASE NO: CT09091789

CASE ADDR: 1201 N ANDREWS AVE STANLEY, STEVEN OWNER: INSPECTOR: BARBARA UROW

VIOLATIONS: 18-1.

THERE IS OVERGROWTH, TRASH AND DEBRIS ON THIS

OCCUPIED PROPERTY.

CASE NO: CE10062322

CASE ADDR: 2531 GULFSTREAM LN OWNER: MINNICK, DONALD INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: 18-11(b)

THE POOL AT THIS LOCATION IS FILLED WITH GREEN, STAGNANT WATER. THE POOL IN THIS CONDITION IS A BREEDING PLACE FOR MOSQUITOES AND ENDANGERS THE

PUBLIC HEALTH, SAFETY AND WELFARE OF THE

COMMUNITY.

CASE NO: CE10031738

CASE ADDR: 4040 GALT OCEAN DR # L1

OWNER: TALERICO FAMILY LIMITED PARTNERSHIP

INSPECTOR: MARIO SOTOLONGO

VIOLATIONS: 47-34.1.A.1.

THERE IS OUTDOOR STORAGE OF ALUMINUM WINDOWS ON

THE SOUTH SIDE OF THE PROPERTY. THIS IS A

NON-PERMITTED LAND USE IN ZONING DISTRICT RMH-60 AS PER ULDR SECTION 47-5.21 TABLE OF PERMITTED USES.

CASE NO: CE10032584 CASE ADDR: 636 SW 14 TER

OB REAL ESTATE HOLDINGS 1695 LLC

INSPECTOR: TODD HULL

VIOLATIONS: 47-19.4.D.1.

ALL RESIDENTIAL PROPERTIES OF FOUR (4) OR MORE UNITS AND ALL BUSINESS AND INDUSTRIAL PROPERTIES WHICH ELECT TO USE BULK CONTAINERS, SHALL PROVIDE AN ON-SITE ENCLOSURE FOR BULK CONTAINERS OR WASTE

RECEPTACLES. THERE IS NO ON-SITE DUMPSTER

ENCLOSURE INSTALLED AT THIS MULTI-UNIT APARTMENT

COMPLEX.

SPECIAL MAGISTRATE

CITY COMMISSION MEETING ROOM - CITY HALL DECEMBER 16, 2010

9:00 AM

CASE NO: CE10081305 CASE ADDR: 505 SW 11 ST

DESMARIS, DERLYSE F OWNER:

INSPECTOR: WILLIAM SNOW

VIOLATIONS: 18-12(a)

THE PROPERTY IS OVERGROWN WITH GRASS, WEEDS AND OTHER PLANT LIFE. THERE IS AN ACCUMULATION OF TRASH, RUBBISH AND SOLID WASTE ON THE PROPERTY. THE TRASH, RUBBISH AND SOLID WASTE CONSISTS OF BUT

IS NOT LIMITED TO YARD WASTE.

CASE NO: CE10081343 CASE ADDR: 1201 NE 6 AVE SPERLING, BENJIE OWNER:

INSPECTOR: ANDRE CROSS

VIOLATIONS: 9-276(c)(3)

THE PROPERTY IS INFESTED WITH ROACHES.

9-279(i)

THE STOVE AT THE PROPERTY IS IN DISREPAIR, INCLUDING BUT NOT LIMITED TO THE BURNERS IN DISREPAIR.

9-280(b)

THERE IS A WINDOW IN THE REAR OF THE PROPERTY WHICH IS BROKEN AND IN DISREPAIR NOT ALLOWING TO OPEN OR CLOSE.

9-280(f)

THERE IS A MAJOR LEAK UNDER THE KITCHEN SINK, THE BOTTOM OF THE TOILET IS LEAKING, THERE IS WATER COMING FROM UNDER THE BASEBOARDS IN ONE OF THE REAR ROOMS, THE BATHROOM SINK IS NOT SECURED TO THE WALL, ALSO THERE IS A RAW SEWAGE LEAK IN THE REAR OF THE PROPERTY.

9-280(q)

THERE ARE ELECTRICAL ACCESSORIES IN DISREPAIR, INCLUDING BUT NOT LIMITED TO LIGHT FIXTURES THAT ARE NOT ABLE TO TURN ON.

AGENDA

SPECIAL MAGISTRATE

CITY COMMISSION MEETING ROOM - CITY HALL DECEMBER 16, 2010

9:00 AM

CASE NO: CE10071523
CASE ADDR: 3020 NW 23 ST
OWNER: BROWN, CYNTHIA L
INSPECTOR: SAL VISCUSI

VIOLATIONS: 18-12(a)

THERE IS LAWN OVERGROWTH PRESENT ON THIS PROPERTY

AND THE PROPERTY IS LITTERED WITH

TRASH/RUBBISH/DEBRIS.

CASE NO: CE09021499

CASE ADDR: 1470 N DIXIE HWY

OWNER: WISTERIA COURT CONDO ASSN INC

INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 101 31.3.4.5.1

HARDWIRE SMOKE DETECTORS ARE NOT INSTALLED OUTSIDE EVERY SLEEPING AREA IN THE IMMEDIATE VICINITY OF THE BEDROOMS AND ON ALL LEVELS OF THE DWELLING

UNIT, INCLUDING BASEMENTS.

NFPA 1:1.7.5.2

THE ELECTRICAL METER ROOM IS BEING USED FOR STORAGE.

CASE NO: CE09061055
CASE ADDR: 208 SE 21 ST
OWNER: RUBIN, ROBERT D
INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 101:31.3.4.5.1

HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE

WITH NFPA 31.3.4.5.1.

NFPA 1:13.6.6.8.3.1

THE FIRE EXTINGUISHER(S) HAS/HAVE NOT BEEN SERVICED AND

TAGGED BY A STATE LICENSED COMPANY WITHIN THE PAST 12 MONTHS.

CASE NO: CE09080341
CASE ADDR: 234 SW 19 ST
OWNER: EDEWAARD, LEAH D
INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 101:31.3.4.5.1

HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE

WITH NFPA 31.3.4.5.1.

SPECIAL MAGISTRATE

CITY COMMISSION MEETING ROOM - CITY HALL DECEMBER 16, 2010

9:00 AM

CASE NO: CE09061056 CASE ADDR: 200 SE 21 ST RUBIN, ROBERT D OWNER: INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 101:31.3.4.5.1

HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE

WITH NFPA 31.3.4.5.1.

NFPA 1:13.6.6.8.3.1

THE FIRE EXTINGUISHER(S) HAS/HAVE NOT BEEN SERVICED AND TAGGED BY A STATE LICENSED COMPANY WITHIN THE PAST 12

MONTHS.

CASE NO: CE09090747

CASE ADDR: 2201 N OCEAN BLVD

AMERICAN ONE RENTALS INC OWNER:

INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 101:31.3.4.5.1

HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE

WITH NFPA 31.3.4.5.1.

CASE NO: CE09091484

CASE ADDR: 4040 GALT OCEAN DR

OWNER: OCEAN MANOR CONDO ASSOC

INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 1:1.12.1

WORK REQUIRES A PERMIT.

CASE NO: CE10041843 CASE ADDR: 5110 NE 18 AVE OWNER: INGLIS, LAURA I INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 1:13.6.1.2

FIRE EXTINGUISHER(S) IS/ARE NOT PROVIDED IN ACCORDANCE WITH

THE CODE.

NFPA 1:1.7.6.2

THE ELECTRICAL METER ROOM IS BEING USED FOR STORAGE.

NFPA 101:31.3.4.5.1

HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE

WITH NFPA 31.3.4.5.1.

SPECIAL MAGISTRATE

CITY COMMISSION MEETING ROOM - CITY HALL DECEMBER 16, 2010

9:00 AM

CASE NO: CE10061047

CASE ADDR: 600 TENNIS CLUB DR
OWNER: THE TENNIS CLUB
INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 1:50.5.2.1

THE HOOD FIRE SUPPRESSION SYSTEM HAS NOT BEEN INSPECTED AND TAGGED BY A STATE LICENSED COMPANY WITHIN THE PAST 6 MONTHS.

NFPA 96 4.1.1

HOOD SYSTEM WITH FIRE SUPPRESSION SYSTEM IS NOT PROVIDED.

CASE NO: CE10062353 CASE ADDR: 2720 NE 15 ST

OWNER: RIO VILLAS OF CORAL RIDGE

INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 1962:4.3.2

OCCUPANT-USE HOSE HAVE NOT BEEN INSPECTED IN ACCORDANCE WITH

NFPA 1962 SECTION 4.6.

NFPA 1:13.2.3.1

THE STANDPIPE IS NOT BEING MAINTAINED IN AT LEAST THE SAME

LEVEL OF PERFORMANCE AND PROTECTION AS DESIGNED.

CASE NO: CE10081644
CASE ADDR: 717 SE 16 ST
OWNER: RAMADHAR LLC
INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 101:31.3.4.5.1

HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE

WITH NFPA 31.3.4.5.1.

CASE NO: CE10081645
CASE ADDR: 719 SE 16 ST
OWNER: RAMADHAR LLC
INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 101:31.3.4.5.1

HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE

WITH NFPA 31.3.4.5.1.

AGENDA

SPECIAL MAGISTRATE

CITY COMMISSION MEETING ROOM - CITY HALL DECEMBER 16, 2010

9:00 AM

CASE NO: CE10081648
CASE ADDR: 800 SE 16 ST

OWNER: AREA GROUP DEVELOPMENT LLC

INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 101:31.3.4.5.1

HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE

WITH NFPA 31.3.4.5.1.

MO Sec. 9-313.

ADDRESS IS NOT POSTED ACCORDING TO THE CODE.

CASE NO: CE10081649 CASE ADDR: 720 SE 16 ST

OWNER: AREA GROUP DEVELOPMENT LLC

INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 101:31.3.4.5.1

HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE

WITH NFPA 31.3.4.5.1.

MO Sec. 9-313.

ADDRESS IS NOT POSTED ACCORDING TO THE CODE.

NFPA 1:13.6.3.10

THE FIRE EXTINGUISHER(S) IS/ARE NOT MOUNTED ACCORDING TO THE

CODE.

CASE NO: CE10081653
CASE ADDR: 700 SE 14 CT
OWNER: BOTELL, MARIO
INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 101:31.3.4.5.1

HARDWIRED SMOKE DETECTORS ARE NOT INSTALLED IN ACCORDANCE

WITH NFPA 31.3.4.5.1.

CASE NO: CE10081688

CASE ADDR: 2500 MARINA BAY DR E
OWNER: FALLS AT MARINA BAY LP

INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 1:10.11.7

A(AN) HIBACHI, GAS-FIRED GRILL, CHARCOAL GRILL, OR OTHER SIMILAR DEVICE(S) USED FOR COOKING, HEATING, OR ANY OTHER PURPOSE, IS(ARE) BEING USED OR KINDLED ON A BALCONY OR UNDER AN OVERHANGING PORTION OR WITHIN 10 FT(3M) OF A STRUCTURE.

Page 23

CITY OF FORT LAUDERDALE

AGENDA

SPECIAL MAGISTRATE

CITY COMMISSION MEETING ROOM - CITY HALL DECEMBER 16, 2010

9:00 AM

CASE NO: CE10081692

CASE ADDR: 2520 MARINA BAY DR E OWNER: FALLS AT MARINA BAY LP

INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 1:10.11.7

A(AN) HIBACHI, GAS-FIRED GRILL, CHARCOAL GRILL, OR OTHER SIMILAR DEVICE(S) USED FOR COOKING, HEATING, OR ANY OTHER PURPOSE, IS(ARE) BEING USED OR KINDLED ON A BALCONY OR UNDER AN OVERHANGING PORTION OR WITHIN 10 FT(3M) OF A STRUCTURE.

CASE NO: CT09082544

CASE ADDR: 315 NE 3 AVE # 1001

OWNER: CLA STRADA UNIT OWNER LLC % RELATED GROUP

INSPECTOR: DICK EATON

VIOLATIONS: 17-7.5.c.

THE SOUND EMISSION FROM THE GENERATOR DURING TESTING, EXCEEDS THE ALLOWABLE LIMIT OF 68 DBA WHEN MEASURED AT THE REQUIRED DISTANCE OF

23 FEET. THE THREE TESTS CONDUCTED WITHIN THE REQUIRED ONE

(1) HOUR TIME FRAME EXCEEDED THIS ALLOWABLE LIMIT.

SPECIAL MAGISTRATE

CITY COMMISSION MEETING ROOM - CITY HALL

DECEMBER 16, 2010 9:00 AM

RETURN HEARING (OLD BUSINESS)

CASE NO: CE10050385 CASE ADDR: 201 SW 5 AVE

OWNER: PERFORMING ARTS CENTER

AUTHORITY OF BROWARD COUNTY

INSPECTOR: RON TETREAULT

VIOLATIONS: F-21.1.3

THE SMOKE CONTROL SYSTEM HAS NOT BEEN CERTIFIED ANNUALLY BY

A BROWARD COUNTY LICENSED TEST AND BALANCE COMPANY.

CASE NO: CE10081709
CASE ADDR: 1805 NW 51 PL
OWNER: ZELEY AVIATION

C/O ROBERT LETTMAN

INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 409:8.2.3

THE PARTITIONS AND CEILINGS SEPARATING AIRCRAFT STORAGE AND SERVICING AREAS FROM OTHER AREAS SUCH AS SHOPS, OFFICES, AND PARTS STORAGE AREAS ARE NOT AT LEAST A 1-HOUR FIRE RESISTANCE RATING WITH OPENINGS PROTECTED BY LISTED FIRE DOORS HAVING A

FIRE RESISTANCE RATING OF AT LEAST 45 MINUTES.

CASE NO: CE10081705

CASE ADDR: 1805 NW 51 PL # 2
OWNER: ZELEY AVIATION

C/O ROBERT LETTMAN

INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 409:8.2.3

THE PARTITIONS AND CEILINGS SEPARATING AIRCRAFT STORAGE AND SERVICING AREAS FROM OTHER AREAS SUCH AS SHOPS, OFFICES, AND PARTS STORAGE AREAS ARE NOT AT LEAST A 1-HOUR FIRE RESISTANCE RATING WITH OPENINGS PROTECTED BY LISTED FIRE DOORS HAVING A

FIRE RESISTANCE RATING OF AT LEAST 45 MINUTES.

SPECIAL MAGISTRATE

CITY COMMISSION MEETING ROOM - CITY HALL DECEMBER 16, 2010 9:00 AM

CASE NO: CE10081710

CASE ADDR: 1805 NW 51 PL # 4
OWNER: ZELEY AVIATION
C/O ROBERT LETTMAN

INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 409:8.2.3

THE PARTITIONS AND CEILINGS SEPARATING AIRCRAFT STORAGE AND SERVICING AREAS FROM OTHER AREAS SUCH AS SHOPS, OFFICES, AND PARTS STORAGE AREAS ARE NOT AT LEAST A 1-HOUR FIRE RESISTANCE RATING WITH OPENINGS PROTECTED BY LISTED FIRE DOORS HAVING A

FIRE RESISTANCE RATING OF AT LEAST 45 MINUTES.

CASE NO: CE10081708

CASE ADDR: 1805 NW 51 PL # 7 OWNER: ZELEY AVIATION

C/O ROBERT LETTMAN

INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 409:8.2.3

THE PARTITIONS AND CEILINGS SEPARATING AIRCRAFT STORAGE AND SERVICING AREAS FROM OTHER AREAS SUCH AS SHOPS, OFFICES, AND PARTS STORAGE AREAS ARE NOT AT LEAST A 1-HOUR FIRE RESISTANCE RATING WITH OPENINGS PROTECTED BY LISTED FIRE DOORS HAVING A

FIRE RESISTANCE RATING OF AT LEAST 45 MINUTES.

CASE NO: CE10081707

CASE ADDR: 1805 NW 51 PL # 8
OWNER: ZELEY AVIATION

C/O ROBERT LETTMAN

INSPECTOR: RON TETREAULT

VIOLATIONS: NFPA 409:8.2.3

THE PARTITIONS AND CEILINGS SEPARATING AIRCRAFT STORAGE AND SERVICING AREAS FROM OTHER AREAS SUCH AS SHOPS, OFFICES, AND PARTS STORAGE AREAS ARE NOT AT LEAST A 1-HOUR FIRE RESISTANCE RATING WITH OPENINGS PROTECTED BY LISTED FIRE DOORS HAVING A

FIRE RESISTANCE RATING OF AT LEAST 45 MINUTES.

INSPECTOR	PAGES
Arrigoni, Frank	
Bass, Stephanie	5, 6, 15
Campbell, Mark	3, 4
Champagne, Leonard	
Crase, Lynda	
Cross, Andre	2, 18
Davis, Aretha	1
DelRio, Alejandro	17
Eaton, Dick	3, 15, 23
Fein, Barry	
Feldman, Adam	
Gottlieb, Ingrid	
Hull, Todd	17
Lauridsen, Karl	
Margerum, Skip	
Nigg, Linda	
Patterson, Bridget	
Quintero, Wilson	
Rich, Mary	
Roque, Maria	
Sappington, Wanda	
Snow, Bill	1, 18
Sotolongo, Mario	2, 17
Tetreault, Ron	6 – 14, 19 – 24, 25
Thime, Ursula	3, 15, 16
Urow, Barbara	16, 17
Viscusi, Salvatore	4, 5, 19
New Cases:	Pages: 1 - 14
Hearing to Impose Fines:	Pages: 15 - 23
Return Hearing:	Page: 24 - 25